

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Medi-Physics  
dba GE Healthcare <sup>Gen</sup> Healthcare  
12300 Hubbard Road  
Livonia, Michigan 48150

REPORT NUMBER(S) 2015-001

2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-29642

4. LICENSE NUMBER(S)

21-24828-01MD

5. DATE(S) OF INSPECTION

July 21, 2015

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Geoffrey M. Warren		7/21/15
BRANCH CHIEF	Aaron T. McCraw		7/30/15

## Docket File Information

## SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

## 1. LICENSEE/LOCATION INSPECTED:

Medi-Physics  
dba GE Healthcare  
12300 Hubbard Road  
Livonia, Michigan 48150

REPORT NUMBER(S) 2015-001

## 2. NRC/REGIONAL OFFICE

Region III  
U. S. Nuclear Regulatory Commission  
2443 Warrenville Road, Suite 210  
Lisle, IL 60532-4352

## 3. DOCKET NUMBER(S)

030-29642

## 4. LICENSE NUMBER(S)

21-24828-01MD

## 5. DATE(S) OF INSPECTION

July 21, 2015

## 6. INSPECTION PROCEDURES USED

87127

## 7. INSPECTION FOCUS AREAS

03.01 - 03.07

## SUPPLEMENTAL INSPECTION INFORMATION

## 1. PROGRAM CODE(S)

02500

## 2. PRIORITY

2

## 3. LICENSEE CONTACT

Bradley Ambs, R.Ph., RSO

## 4. TELEPHONE NUMBER

(734) 425-0425

☒ Main Office Inspection

Next Inspection Date: July 2017

☐ Field Office Inspection☐ Temporary Job Site Inspection

## PROGRAM SCOPE

This was a routine, unannounced, inspection. This radiopharmacy employed three pharmacists, four pharmacy technicians, and ten drivers. The licensee distributed approximately 300-400 doses daily to 35 regular customers in southeastern Michigan and northwestern Ohio. The pharmacy was open weekdays from midnight through 5:30 pm, with limited hours on weekends. The weekday runs ran from 1:30-5 am and 7-9:30 am, with deliveries made as needed throughout the day. The licensee received three technetium-99m generators each week for preparation and distribution of unit doses and bulk technetium to clients. In addition, the licensee distributed occasional thallium-201, gallium-67, and indium-111 unit doses prepared from bulk materials. The pharmacy received and redistributed iodine-123 and iodine-131 capsules to customers; these capsules were received from a commercial supplier rather than being prepared locally. While the licensee was authorized to use a automated system for drawing iodine-131 doses, they had not yet acquired the system.

The licensee's corporate office and the site radiation safety officer conducted independent annual audits of the program. The maximum dose received by licensee personnel in calendar year 2014 was 174 mrem whole body and 13.0 rem extremity; and in January through May 2015, the maximum was 53 mrem whole body and 4.8 rem extremity. Licensee personnel used long-handled tools for handling of licensed materials.

Performance Observations: The inspector observed generator elution, molybdenum check, kit preparation, QC sampling and testing, dose and bulk technetium preparation, package assembly and survey, preparation and placement of shipping papers, verification of package contents, preparation of labels and shipping papers, shipment assembly, blocking and bracing of packages, package return surveys, survey of returned pigs, waste disposal, and use of syringe shields and long-handled tools. Licensee personnel demonstrated and described dose calibrator constancy, daily area surveys and wipes, package receipt surveys, spill procedures, indium blood labeling, effluent monitoring, waste disposal, and other procedures. The inspector noted no concerns with these activities. Interviews with licensee personnel indicated adequate knowledge of radiation safety concepts and procedures. The inspector performed independent and confirmatory radiation measurements which indicated results consistent with licensee survey records and postings. No violations were identified during this inspection.