

Part 21 (PAR)

Event # 51291

<b>Rep Org:</b> ALPHA-OMEGA SERVICES, INC		<b>Notification Date / Time:</b> 08/05/2015 19:02 (EDT)	
<b>Supplier:</b> ALPHA-OMEGA SERVICES, INC		<b>Event Date / Time:</b> 08/04/2015 (PDT)	
<b>Last Modification:</b> 08/05/2015			
<b>Region:</b> 4	<b>Docket #:</b>		
<b>City:</b> BELLFLOWER	<b>Agreement State:</b> Yes		
<b>County:</b>	<b>License #:</b>		
<b>State:</b> CA			
<b>NRC Notified by:</b> TROY HEDGER		<b>Notifications:</b> RAY AZUA	R4DO
<b>HQ Ops Officer:</b> JEFF ROTTON		PART 21 MATERIALS	EMAIL
<b>Emergency Class:</b> NON EMERGENCY			
<b>10 CFR Section:</b>			
21.21(d)(3)(i) DEFECTS AND NONCOMPLIANCE			

**PART 21 - POTENTIAL RADIOACTIVE MATERIAL TRANSPORT PACKAGING SHIELDING FAILING TO COMPLY WITH 10CFR71.47 AND/OR 10CFR71.51**

The following information is a summary that was excerpted from a facsimile received from Alpha-Omega Services, Inc.:

"Pursuant to 10CFR 21.21 (d)(3)(ii) Alpha-Omega Services, Inc. [AOS] is providing the USNRC with written notification of the identification of a potential failure to comply. The following information is required per 10CFR 21.21 (d)(4):

"Name and Address of the individual or individuals informing the Commission. Troy Hedger, President, Alpha-Omega Services, Inc., 9156 Rose Street, Bellflower, CA 90706

"Identification of the facility, the activity, or the basic component supplied for such facility or such activity within the United States which fails to comply or contains a defect. AOS Document Number FM9054, Rev. H, Radioactive Material Transport Packaging System Safety Analysis Report for Model AOS-025, AOS-050, and AOS-100 Transport Packages (Revision H, December 30, 2012; Docket No. 71-9136) Model AOS-100A Package, USA/9316/B(U)-96 (Certificate of Compliance #9316)

"Nature of the defect of failure to comply and the safety hazard which is created or could be created by such defect of failure to comply. There is a potential issue that shielding fails to comply with 10CFR 71.47 and/or 10CFR 71.51 (a)(2). This is not a 'defect' of the package, but rather an un-analyzed condition that could lead, if credible, to a safety hazard. DAHER-TLI Engineering Services notified AOS via telephone conversation on July 28, 2015 that there is a possible discrepancy in the original SAR shielding calculations originally performed. The potential discrepancy was discovered in conjunction with the independent preparation of a DAHER-TLI symposium

IE20  
NMSS

paper that they are working on for presentation for future use of the AOS Cask family products. Specifically, DAHER-TLI observed that the AOS SAR does not analyze the radiation levels on the exterior of the package when a point source is located in a corner of the cask cavity.

"In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, or may be supplied for, manufactured, or being manufactured for one or more facilities or activities subject to the regulations in this part. Currently, four (4) AOS-100A packages have been fabricated and three (3) were certified for use prior to August 4, 2015; one (1) is currently not in service. There are two (2) AOS-050 packages which are on hold for completion of fabrication activities. The following are the locations of the active units: AOS - Bellflower, CA, Serial no. AOS-100A-0001 (not currently in service); Elekta - Nordion Ottawa, Canada, Serial no: AOS-100A-0002; AOS - GE Vallecitos Sunol, CA, Serial no: AOS-100A-0003; Elekta - Nordion Ottawa, Canada, Serial no: AOS-100A-0004"

\*\*\*\*\*

# **FAX**

TRANSMISSION

To: [r\_company]  
From: [s\_company]  
Subject: AOS Report of Potential 10CFR Part 21 Failure to Comply (08-05-2015) with fax coversheet.pdf  
Message:

Troy Hedger, President  
Alpha-Omega Services, Inc.  
9156 Rose Street  
Bellflower, CA 90706

Phone: +1 (562) 804-0604 ext 124  
Em: thedger@alpha-omegaserv.com

The information in this email and subsequent attachments may contain legally privileged, proprietary and confidential information that is intended for a particular recipient. If you are not the intended recipient, you are hereby notified that any disclosure, copying, distribution, retention or use of the contents of this e-mail information is prohibited. When addressed to an Alpha-Omega Services customer or vendor, any information contained in this e-mail is subject to the terms and conditions in the governing contract. If you have received this e-mail in error, please immediately notify us by telephone or by return e-mail, and delete the e-mail.



**Alpha Omega Services**  
9156 E Rose St  
Tel: 562-804-0604 Fax: 562-804-0610  
Website: <http://www.alpha-omegaservices.com>



Alpha-Omega Services, Inc.

# FAX

**To: NRC Operations Center FAX (301) 816-5151**

**From: Troy Hedger, President AOS**

**Date: August 5, 2015**

**Subject: Notification to the NRC of possible Failure to Comply (10CFR21)**

**Letter from AOS to the NRC Operations Center dated August 5, 2015, attached (3 pages).**



August 5, 2015

NRC Operations Center  
Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

Subject: Report of Potential 10CFR Part 21 Failure to Comply, AOS SAR Document No. FM9054 Revision H

Pursuant to 10CFR 21.21 (d)(3)(ii) Alpha-Omega Services, Inc. is proving the USNRC with written notification of the identification of a potential failure to comply.

The following information is required per 10CFR 21.21 (d)(4):

- (i) *Name and Address of the individual or individuals informing the Commission.*  
Troy Hedger, President  
Alpha-Omega Services, Inc.  
9156 Rose Street  
Bellflower, CA 90706
- (ii) *Identification of the facility, the activity, or the basic component supplied for such facility or such activity within the United States which fails to comply or contains a defect.*  
AOS Document Number FM9054, Rev. H, *Radioactive Material Transport Packaging System Safety Analysis Report for Model AOS-025, AOS-050, and AOS-100 Transport Packages (Revision H, December 30, 2012; Docket No. 71-9136)*  
Model AOS-100A Package, USA/9316/B(U)-96 (Certificate of Compliance #9316)
- (iii) *Identification of the firm constructing the facility or supplying the basic component which fails to comply or contains a defect.*  
The basic component is supplied by Alpha-Omega Services, Inc. 9156 Rose Street  
Bellflower, CA 90706
- (iv) *Nature of the defect of failure to comply and the safety hazard which is created or could be created by such defect of failure to comply.*  
There is a potential issue that shielding fails to comply with 10CFR 71.47 and/or 10CFR 71.51(a)(2). This is not a "defect" of the package, but rather an un-analyzed condition that could lead, if credible, to a safety hazard.  
DAHER-TLI Engineering Services notified AOS via telephone conversation on July 28, 2015 that there is a possible discrepancy in the original SAR shielding calculations originally performed. The potential discrepancy was discovered in conjunction with the

Report of Potential 10CFR Part 21 Failure to Comply  
AOS SAR Document No. FM9054 Revision H

independent preparation of a DAHER-TLI symposium paper that they are working on for presentation for future use of the AOS Cask family products. Specifically, DAHER-TLI observed that the AOS SAR does not analyze the radiation levels on the exterior of the package when a point source is located in a corner of the cask cavity.

AOS Engineering has reviewed the potential discrepancy identified by DAHER-TLI against the SAR and related documents; and have concluded the following, in summary:

1. Chapter 5 of the SAR analyses point sources in two positions in the cavity: the top center and the side at mid-height. Paragraph 5.3.1 justifies this approach. "This is a more conservative approach than modeling a point source at the center of the cask, or explicitly modeling the internal source geometry and other internal structural components. Point sources do not account for the self-shielding effects due to the actual source geometry and density, nor for the shielding due to internal components, such as source racks. By placing the point sources directly against the cask cavity wall, the most likely source displacements are modeled in an appropriately conservative way... This choice is further justified by noting that an actual radioactive load in the container would be distributed over significantly more volume than a point source".
2. However, in Chapter 1 of the SAR (re. 1.2.2 Contents – 6<sup>th</sup> paragraph), the SAR states, "Radioactive contents can be in any location within the cask cavity, and unconstrained within the inner containers. Holders, fixtures, and packaging materials (shoring devices) must be used to secure the inner containers, so that the inner containers are immobilized."

Accordingly, it is possible that a user could locate a high activity source near a corner of the cavity. This was not assessed in Chapter 5.

- (v) *The date on which the information of such defect or failure to comply was obtained.*

August 4, 2015

- (vi) *In the case of a basic component which contains a defect or fails to comply, the number and location of these components in use at, supplied for, or may be supplied for, manufactured, or being manufactured for one or more facilities or activities subject to the regulations in this part.*

Currently, four (4) AOS-100A packages have been fabricated and three (3) were certified for use prior to August 4, 2015; one (1) is currently not in service. There are two (2) AOS-050 packages which are on hold for completion of fabrication activities.

The following are the locations of the active units:

<u>Customer</u>	<u>Location</u>	<u>Package Serial Number</u>
AOS	Bellflower, CA	AOS-100A-0001 (not currently in service)
Elekta	Nordion Ottawa, Canada	AOS-100A-0002
AOS	GE Vallecitos Sunol, CA	AOS-100A-0003
Elekta	Nordion Ottawa, Canada	AOS-100A-0004

Report of Potential 10CFR Part 21 Failure to Comply  
AOS SAR Document No. FM9054 Revision H

- (vii) *The corrective action which has been, is being, or will be taken; the name of the individual or organization responsible for the action; and the length of time that has been or will be taken to complete the action.*

Based on our initial evaluation, AOS has initiated CAPA No. FM9016.1-082015-001 for providing corrective action relating to the above-identified subject. A 10CFR Part 21 Applicability Form (re. FM9015.2-082015-001) has also been prepared and is currently under evaluation. The CAPA identifies the issue and begins the internal investigation process to determine the cause and to identify corrective action(s); this investigation is currently in progress.

1. AOS has initiated a Part 21 evaluation to determine applicability.
2. In parallel, AOS has contacted the NRC to inform the project manager of the concern; and to seek guidance/advice as to the direction that this evaluation needs to proceed.
3. Assuming that all of the activity is condensed in a point source in the corner of the cavity is a very conservative assumption.
4. In reality there may not be a problem due to self-shielding and distributed activity; i.e., it is very unlikely to have all of our activity in a single source and if we did, we would constrain it to the center of the cavity.

- (viii) *Any advice related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given to purchasers or licensees.*

In parallel to this notification, AOS is notifying the owners and users of the AOS-100 package of this potential failure to comply.

- (ix) *In the case of an early site permit, the entities to whom and early site permit was transferred.*

Not applicable

Sincerely,

Alpha-Omega Services, Inc.



Troy Hedger, President