

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9806100203 DOC. DATE: 98/06/01 NOTARIZED: NO DOCKET #
 FACIL: 50-270 Oconee Nuclear Station, Unit 2, Duke Power Co. 05000270
 AUTH. NAME AUTHOR AFFILIATION
 MCCOLLUM, W.R. Duke Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Submits number of tubes plugged/repaired during SG tube ISI
 for EOC 16 refueling outage. Quantity of tubes removed from
 svc by plugging are identified in tables.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	LABARGE, D	1 1		
INTERNAL:	ACRS	1 1	<u>FILE CENTER</u> 01	1 1
	NRR/DE/ECGB/A	1 1	NRR/DE/EMCB	1 1
	NRR/DRCH/HICB	1 1	NRR/DSSA/SPLB	1 1
	NRR/DSSA/SRXB	1 1	NUDOCS-ABSTRACT	1 1
	OGC/HDS2	1 0		
EXTERNAL:	NOAC	1 1	NRC PDR	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTTR 14 ENCL 0

C
A
T
E
G
O
R
Y

1

D
O
C
U
M
E
N
T



Duke Power Company
A Duke Energy Company

Oconee Nuclear Site
P.O. Box 1439
Seneca, SC 29679

W. R. McCollum, Jr.
Vice President

(864) 885-3107 OFFICE
(864) 885-3564 FAX

June 1, 1998

U.S. Nuclear Regulatory Commission
Attention Document Control Desk
Washington, DC 20555

Subject: Duke Power Company
Oconee Nuclear Station, Unit 2
Docket No. 50-270
Steam Generator Inservice Inspection
Steam Generator Tube Plugging and Repair 30 Day Report

As required by Technical Specification 4.17.6 (a), the number of tubes plugged or repaired during the Steam Generator Tube Inservice Inspection for the Unit 2 End of Cycle 16 refueling outage is submitted for review.

The tables below identify the quantity of tubes removed from service by plugging. There were no tubes repaired by sleeving in either steam generator. There were some tubes repaired by rerolling in the upper tubesheet.

<u>Steam Generator</u>	<u>Number of Tubes Plugged</u>
------------------------	--------------------------------

A	164
B	195

1/0

<u>Steam Generator</u>	<u>Number of Tubes Rerolled</u>
------------------------	---------------------------------

A	88 *
B	170

Adm

* 87 of these tubes remained in service, 1 was plugged.

9806100203 980601
PDR ADDCK 05000270
P PDR

0500060


NRC Document Control

June 1, 1998

Page 2

If there are any questions you may contact D. A. Nix at (864)
885-3634.

Very truly yours,



W. R. McCollum, Jr.
Site Vice-President

xc : Mr. L. A. Reyes
Regional Administrator, Region II
U. S. Nuclear Regulatory Commission

Mr. M. A. Scott
Senior NRC Resident Inspector
Oconee Nuclear Station

Mr. Max Batavia
Bureau of Radiological Health
SC Dept. of Health & Environmental Control
2600 Bull St. Columbia, SC 29201

Mr. D. E. LaBarge, Project Manager
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555