

**Virginia Electric and Power Company
North Anna Power Station
1022 Haley Drive
Mineral, Virginia 23117**

September 3, 2015

Attention: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Serial No.: 15-174A
NAPS: JHL
Docket No.: 50-338
License No.: NPF-4


Dear Sirs:

Pursuant to 10CFR50.73, Virginia Electric and Power Company hereby submits the following Licensee Event Report applicable to North Anna Power Station Unit 1.

Report No. 50-338/2015-002-01

This report has been reviewed by the Facility Safety Review Committee and will be forwarded to the Management Safety Review Committee for its review.

Sincerely,


Gerald T. Bischof
Site Vice President
North Anna Power Station

Enclosure

Commitments contained in this letter: None

cc: United States Nuclear Regulatory Commission
Region II
Marquis One Tower
245 Peachtree Center Ave., NE, Suite 1200
Atlanta, Georgia 30303-1257

NRC Senior Resident Inspector
North Anna Power Station

FE22
NRB

**LICENSEE EVENT REPORT (LER)**(See Page 2 for required number of
digits/characters for each block)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME

North Anna Power Station, Unit 1

2. DOCKET NUMBER

05000338

3. PAGE

1 OF 4

4. TITLE

Manual Reactor Trip Due to Inability to Maintain Main Generator Voltage in Specification

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
04	02	2015	2015	002	01	09	03	2015	FACILITY NAME	DOCKET NUMBER
										05000
										05000

9. OPERATING MODE	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)			
1	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
10. POWER LEVEL 100	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
	<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
	<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT

Gerald T. Bischof, Site Vice President

TELEPHONE NUMBER (Include Area Code)

(540) 894-2101

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANU-FACTORER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANU-FACTORER	REPORTABLE TO EPIX
B	TL	RG		Y					

14. SUPPLEMENTAL REPORT EXPECTED☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☒ NO**15. EXPECTED SUBMISSION DATE**

MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On April 2, 2015, at 0426 hours, with Unit 1 operating at 100 percent power, a manual reactor trip was initiated due to the inability to maintain main generator voltage in specification. This also resulted in a turbine trip. The operations crew entered the reactor trip procedure and stabilized Unit 1 in Mode 3 at normal operating pressure and temperature. All control rods fully inserted into the core following the reactor trip. The inability to maintain generator voltage in specification was due to a failure of a component in a firing circuit downstream of the automatic voltage regulator (AVR). The root cause of the event was firing circuit design vulnerabilities in the AVR were not identified during the design change due to lack of rigor. At 0655 hours, a 4-hour Non-Emergency Report was made to the NRC in accordance with 10 CFR 50.72(b)(2)(iv)(B) for "an event causing actuation of the Reactor Protection System when the reactor is critical" and an 8-hour report was also made in accordance with 10 CFR 50.72(b)(3)(iv)(A) for "an event causing actuation of the Auxiliary Feedwater System (AFW)." Two of the AVR gate firing modules (GFMs) were replaced and the third GFM was evaluated to not be required and was disabled. The health and safety of the public were not affected by this event.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollects.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REV NO.	
North Anna Power Station, Unit 1	05000338	2015	- 002	- 01	2 OF 4

NARRATIVE**1.0 DESCRIPTION OF THE EVENT**

On April 2, 2015, at 0426 hours, with Unit 1 operating at 100 percent power, a manual reactor trip was initiated due the inability to maintain main generator (EIS System TL, Component GEN) voltage in specification. Prior to the initiation of the manual reactor trip, the operations crew had entered abnormal procedure 1-AP-26, Voltage Regulator Failure, due to the Unit 1 main generator voltage being high. Several control room annunciators (EIS Component ANN) had locked in with the generator output greater than 600 MVARs out and manual actions to lower voltage were ineffective. As a result, the manual reactor trip was initiated. This also resulted in a turbine trip.

Troubleshooting subsequently revealed that the output from the number 2 gate firing module (GFM) (EIS Component IMOD) in the firing circuit downstream of the main generator automatic voltage regulator (AVR) (EIS Component RG) failed high causing the generator output to be greater than 600 MVARs out.

Following the reactor trip the Reactor Protection System (RPS) and all Engineered Safety Feature Actuation System (ESFAS) (EIS System JE) equipment actuated as designed, including the Auxiliary Feedwater (AFW) pumps (EIS System BA, Component P). The control room operators responded to the event in accordance with emergency procedure 1-E-0, Reactor Trip or Safety Injection. The operators then stabilized the plant using 1-ES-0.1, Reactor Trip Recovery.

At 0655 hours, a 4-hour Non-Emergency Report was made to the NRC in accordance with 10 CFR 50.72(b)(2)(iv)(B) for "an event causing actuation of the Reactor Protection System when the reactor is critical" and an 8-hour report was also made in accordance with 10 CFR 50.72(b)(3)(iv)(A) for "an event causing actuation of the Auxiliary Feedwater System (AFW)."

2.0 SIGNIFICANT SAFETY CONSEQUENCES AND IMPLICATIONS

No significant safety consequences resulted from this event because the RPS and ESFAS systems actuated as designed following initiation of the manual trip. The health and safety of the public were not affected by this event.

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REV NO.	
North Anna Power Station, Unit 1	05000338	2015	- 002	- 001	3 OF 4

NARRATIVE

3.0 CAUSE

The direct cause of the overexcitation of the generator was due to the single failure of a GFM #2 which resulted in a high output to the power amplifier drawer. GFM #2 failed due to high-output failure of an electrical component (op-amp) of the summing circuit.

The root cause of the event was firing circuit design vulnerabilities in the AVR were not identified during the design change due to lack of rigor. Design Changes 07-010 and 08-019 assumed full redundancy of the drawer firing circuits. However, the GFMs in the firing circuit were not postulated to fail high and this failure mode was not considered during the design of the AVRs.

4.0 IMMEDIATE CORRECTIVE ACTION(S)

The control room operators responded to the event in accordance with emergency procedure 1-E-0, Reactor Trip or Safety Injection. The operators then stabilized the plant using 1-ES-0.1, Reactor Trip Recovery. All safety systems responded appropriately. The unit was stabilized at no-load conditions, the Main Feedwater system was placed in service to all three SGs, and the AFW system was secured and returned to automatic.

5.0 ADDITIONAL CORRECTIVE ACTIONS

During the Unit 1 shutdown, two of the GFMs were replaced and the third installed GFM was evaluated to not be required and was disabled.

ODM #352 has been completed to address continued operation with GFM number 3 disabled for the Unit 1 AVR.

The failed number 2 GFM was shipped offsite for failure analysis to determine the reason for the module failure.

6.0 ACTIONS TO PREVENT RECURRENCE

The issues associated with Design Changes 07-010 and 08-019 for the AVR are considered legacy when compared to the current design change standards and procedures. In 2011, procedure CM-AA-RSK-1001, Engineering Risk Assessment, was revised to conduct third party reviews of contractor-generated design changes to ensure a more rigorous technical and programmatic review of design change documents for high-risk modifications. The standards and expectations implemented during the current design change process identify potential failure mode risks by the failure effects

LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
		YEAR	SEQUENTIAL NUMBER	REV NO.	
North Anna Power Station, Unit 1	05000338	2015	- 002	- 001	4 OF 4

NARRATIVE

and analysis guidelines described in CM-AA-DDC-201, Design Changes. Procedure revisions also updated the review aspects of the design change process such as including third-party reviews and challenge review milestones. In addition, DNES-AA-GN-1007, Digital Asset Modification Considerations, provides detailed guidance for digital modifications to include detailed procurement specifications, rigorous documentation for Failure Mode Effects and Analysis (FMEA) considerations, and additional oversight to review operating experience and testing results.

Additional corrective actions will be tracked in the Corrective Action Program to completion.

7.0 SIMILAR EVENTS

LER N2-2010-001-00 dated June 23, 2010, documents a Unit 2 automatic reactor trip from 74% power while testing a new digital automatic voltage regulator (AVR). A turbine trip due to a generator lockout caused the automatic reactor trip. The root cause of the generator lockout protective relay actuation was determined to be inadequate guidance for software validation for non-safety related equipment that can impact power generation.

8.0 ADDITIONAL INFORMATION

North Anna Unit 2 continued operating in Mode 1, 100 percent power during this event.

North Anna Unit 2 has the same GFMs in the AVR firing circuit, but there is no indication that these components have failed high. If one of the three GFMs in the AVR firing circuit failed high, an annunciator in the main control room would alarm.