

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9301250245 DOC. DATE: 93/01/20 NOTARIZED: NO
 FACIL: 50-269 Oconee Nuclear Station, Unit 1, Duke Power Co.
 AUTH. NAME: BENESOLE, S.G. AUTHOR AFFILIATION: Duke Power Co.
 HAMPTON, J.W. Duke Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION

DOCKET #
05000269

SUBJECT: LER 92-020-00: on 921220, discovered that inadequate cooling water flow to turbine driven emergency feedwater pump oil may occur during SBO. Suppl rept will be issued to address root cause of event. W/930120 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR / ENCL / SIZE: 2
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD2-3 LA	1 1	PD2-3 PD	1 1
WIENS, L	1 1		
INTERNAL: ACNW	2 2	ACRS	2 2
AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
AEOD/ROAB/DSP	2 2	NRR/DET/EMEB 7E	1 1
NRR/DLPQ/LHFB10	1 1	NRR/DLPQ/LPEB10	1 1
NRR/DOEA/OEAB	1 1	NRR/DREP/PRPB11	2 2
NRR/DST/SELB 8D	1 1	NRR/DST/SICB8H3	1 1
NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
REG FILE 02	1 1	RES/DSIR/EIB	1 1
RGN2 FILE 01	1 1		
EXTERNAL: EG&G BRYCE, J.H.	2 2	L ST LOBBY WARD	1 1
NRC PDR	1 1	NSIC MURPHY, G.A	1 1
NSIC POORE, W.	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 31

Handwritten signature

Duke Power Company
Oconee Nuclear Site
P.O. Box 1439
Seneca, SC 29679

J. W. HAMPTON
Vice President
(803)885-3499 Office
(803)885-3564 Fax



DUKE POWER

January 20, 1993

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


Subject: Oconee Nuclear Site
Docket Nos. 50-269, -270, -287
LER 269/92-20

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a)(1) and (d), attached is Licensee Event Report (LER) 269/92-20, concerning inadequate cooling water flow to the turbine driven emergency feedwater pump oil coolers.

This report is being submitted in accordance with 10 CFR 50.73 (a)(2)(i)(B). We expect to submit a supplement on February 19, 1993 to address root cause and other LER content requirements.

Very truly yours,


J. W. Hampton
Vice President

/ftr

Attachment

xc: Mr. S. D. Ebnetter
Regional Administrator, Region II
U.S. Nuclear Regulatory Commission
101 Marietta St., NW, Suite 2900
Atlanta, Georgia 30323

Mr. L. A. Wiens
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555


INPO Records Center
Suite 1500
1100 Circle 75 Parkway
Atlanta, Georgia 30339

Mr. P. E. Harmon
NRC Resident Inspector
Oconee Nuclear Site

250026

9301250245 930120
PDR ADOCK 05000269
S PDR

Printed on recycled paper



LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND RECORDS MANAGEMENT BRANCH (MNBB 7714), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

Oconee Nuclear Station, Unit 1

DOCKET NUMBER (2)

05000 269

PAGE (3)

1 OF 1

TITLE (4) Inadequate Cooling Water Flow To The Turbine Driven Emergency
Feedwater Pump Oil Cooler May Occur During A Station Blackout

EVENT DATE (5)			LER NUMBER (6)			REPORT NUMBER (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
12	19	92	92	20	00	01	20	93	Oconee, Unit 2	05000 270
									Oconee, Unit 3	05000 287

OPERATING MODE (9)	N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)			
POWER LEVEL (10)	-0-	20.402(b)	20.405(c)	50.73(a)(2)(iv)	73.71(b)
		20.405(a)(1)(i)	50.36(c)(1)	50.73(a)(2)(v)	73.71(c)
		20.405(a)(1)(ii)	50.36(c)(2)	50.73(a)(2)(vii)	OTHER
		20.405(a)(1)(iii)	X 50.73(a)(2)(i) (B)	50.73(a)(2)(viii)(A)	(Specify in Abstract below and in Text, NRC Form 368A)
		20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(viii)(B)	
		20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME

S. G. Benesole, Safety Review Manager

TELEPHONE NUMBER (Include Area Code)

(803) 885-3518

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
X			02	19	93

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

On December 20, 1992 at 1000 hours, during the performance of Unit 3's Turbine Driven Emergency Feedwater Pump (TDEFWP) Cooling Water Supply Valve Test, it was discovered that inadequate cooling water flow to its TDEFWP Oil Cooler would exist during a station blackout. Testing of Unit 1's and Unit 2's TDEFWPs indicated that inadequate cooling water flow to their respective TDEFWP Oil Coolers would also occur during a station blackout. Unit 1 was shutdown for a refueling outage, Units 2 and 3 were operating at 100% Full Power. Corrective actions were taken on all three units to throttle and lock HPSW-284 (TDEFWP Cooling Water Control Valve By-pass) to insure 15 gpm of cooling water flow to the TDEFWP Oil Cooler. This will insure adequate cooling water flow (7 gpm) to the oil cooler during a station blackout; however, past operability is still under review. A supplement to this LER will be issued to address root cause and other LER content requirements after further testing and a review of data is complete.