

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL**  
(TEMPORARY FORM)

CONTROL NO: 13628

FILE: INCIDENT REPORT FI

<b>FROM:</b> Duke Power Company Charlotte, N.C. 28242 Wm. O. Parker, Jr.		<b>DATE OF DOC</b> 12-8-75	<b>DATE REC'D</b> 12-16-75	<b>LTR</b> XX	<b>TWX</b>	<b>RPT</b>	<b>OTHER</b>
<b>TO:</b> Mr. Norman C. Moseley		<b>ORIG</b> 1 signed	<b>CC</b>	<b>OTHER</b>	<b>SENT AEC PDR</b> XX		
					<b>SENT LOCAL PDR</b> XX		
<b>CLASS</b>	<b>UNCLASS</b> XXXX	<b>PROP INFO</b>	<b>INPUT</b>	<b>NO CYS REC'D</b> 1	<b>DOCKET NO:</b> 50-287		

**DESCRIPTION:** Ltr trans the following:

**ENCLOSURES:** Unusual Event 50-287/75-12 on 11-5-75 re failure of gasket on personnel hatch inner door...

(1 cy encl rec'd)

**ACKNOWLEDGED**  
**Do Not Remove**

**PLANT NAME:** Oconee Unit 3

**FOR ACTION/INFORMATION**

**DHL 12-20-75**

<b>BUTLER (L)</b> W/ Copies	<b>SCHWENCER (L)</b> W/ Copies	<b>ZIEMANN (L)</b> W/ Copies	<b>REGAN (E)</b> W/ Copies
<b>CLARK (L)</b> W/ Copies	<b>STOLZ (L)</b> W/ Copies	<b>DICKER (E)</b> W/ Copies	<b>LEAR (L)</b> W/ Copies
<b>PARR (L)</b> W/ Copies	<b>VASSALLO (L)</b> W/ Copies	<b>KNIGHTON (E)</b> W/ Copies	<b>SPELS</b> W/ Copies
<b>KNIEL (L)</b> W/ Copies	<b>PURPLE (L)</b> W/3 Copies	<b>YOUNGBLOOD (E)</b> W/ Copies	<b>REID</b> W/ Copies

**INTERNAL DISTRIBUTION**

<del>REG FILE</del> NRC PDR OGC, ROOM P-506A GOSSICK/STAFF CASE  BOYD MOORE (L) DEYOUNG (L) SKOVHOLT (L) GOLLER (L) (Ltr) P. COLLINS DENISE REG OPR FILE & REGION (2) MIPC/PE (3) STEELE	<b>TECH REVIEW</b> <del>SCHROEDER</del> <del>MACCARY</del> KNIGHT PAWLICKI SHAO **STELLO **HOUSTON **NOVAK ROSS IPPOLITO TEDESCO J. COLLINS LAINAS BENAROYA VOLLMER	DENTON **GRIMES GAMMILL KASTNER BALLARD SPANGLER  ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR  HARLESS	<b>LIC ASST</b> R. DIGGS (L) H. GEARIN (L) E. GOULBOURNE (L) P. KREUTZER (E) J. LEE (L) M. RUSHBROOK (L) S. REED (E) M. SERVICE (L) S. SHEPPARD (L) M. SLATER (E) H. SMITH (L) S. TEETS (L) G. WILLIAMS (E) V. WILSON (L) R. INGRAM (L) M. DUNCAN (E)	<b>A/T IND.</b> BRAITMAN SALTZMAN MELTZ  <b>PLANS</b> MCDONALD CHAPMAN DUBE (Ltr) E. COUPE PETERSON HARTFIELD (2) KLECKER EISENHUT WIGGINTON F. WILLIAMS HANAUER
--	--	--	---	--

**EXTERNAL DISTRIBUTION**

1 - LOCAL PDR Walhalla, S.C.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN)
1 - Newton Anderson		Rm B-127 GT
16 ACRS SENT TO LIC ASST Sheppard 12-20-75		1 - J. D. RUNKLES, Rm E-201
** SEND ONLY TEN DAY REPORTS		GT

DUKE POWER COMPANY

POWER BUILDING


422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

Regulatory Docket File

WILLIAM O. PARKER, JR.  
VICE PRESIDENT  
STEAM PRODUCTION

TELEPHONE: AREA 704  
373-4083

December 8, 1975




Mr. Norman C. Moseley, Director  
U. S. Nuclear Regulatory Commission  
Suite 818  
230 Peachtree Street, Northwest  
Atlanta, Georgia 30303

Re: Oconee Unit 3  
Docket No. 50-287

Dear Mr. Moseley:

Pursuant to Sections 6.2 and 6.6.2 of the Oconee Nuclear Station  
Technical Specifications, please find attached Unusual Event Report  
UE-287/75-12.

Very truly yours,

  
William O. Parker, Jr.

EDB:mmb

Attachment

CC Mr. Benard C. Rusche



13628

Report No.: UE-287/75-12

Report Date: December 5, 1975

~~CONFIDENTIAL~~ 12-8-75

Event Date: November 5, 1975

Facility: Oconee Unit 3, Seneca, South Carolina

Identification of Event: Failure of gasket on personnel hatch inner door

Conditions Prior to Event: Unit at 95% full power

Description of Event:

On November 5, 1975, a leak rate test was performed on Oconee Unit 3 personnel hatch. After pressurizing the hatch to 50 psig, it was observed that the inner door gasket had failed. Further testing was immediately discontinued, and the outer personnel hatch door was locked in the closed position.

Apparent Cause of Event:

The personnel hatch leak rate test is performed by pressurizing the area between the inner and outer doors. The test tends to unseat the inner door; therefore, strongbacks are placed on the hatch side of the inner door to maintain the door in a closed condition. The apparent cause of this incident was the unseating of the inner door by the test pressure, resulting in failure of the gasket.

Analysis of Event:

The failure of the personnel hatch inner door gasket resulted in the loss of integrity of the inner door. However, it is highly probable that this door would have functioned properly during a loss-of-coolant accident since containment pressure tends to seat the inner door, compressing the gasket. Additionally, the outer door is capable of maintaining containment integrity. It is concluded that the health and safety of the public was not affected.

Corrective Action:

The personnel hatch outer door was locked closed pending approval of a change to Oconee Technical Specification 3.6.4. This change was received on November 11, 1975 and permitted the outer door to be opened during power operation for a maximum ten-minute interval to permit access for repair of the faulty inner door gasket. The inner door gasket was replaced, and the hatch successfully tested on November 12, 1975.