

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7901310042 DOC. DATE: 79/01/24 NOTARIZED: NO  
 FACIL: 50-287 Oconee Nuclear Station 3, Duke Power Co.  
 AUTH. NAME AUTHOR AFFILIATION  
 LEWIS, S.R. Duke Power Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 Region 2, Atlanta, Office of the Director

DOCKET #  
 05000287

SUBJECT: LER 78-023/03L-0 on 781220: Reactor Bldg Spray pump 3B  
 inoperable due to high vibration. Caused by impeller having  
 worked loose from impeller shaft.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+1  
 TITLE: INCIDENT REPORTS

NOTES: M. CUNNINGHAM - ALL AMENDS TO FSAR & CHANGES TO TECH SPECS.

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	05 BC <u>ORB #4</u>	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 VOLLMER	1	1	27 OPERA LIC BR	1	1
	28 ACIDENT ANLYS	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

FEB 1 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 45 ENCL 45

DUKE POWER COMPANY  
OCONEE NUCLEAR STATION

Report Number: RO-287/78-23

Report Date: January 24, 1979

Occurrence Date: December 20, 1978

Facility: Oconee Unit 3, Seneca, South Carolina

Identification of Occurrence: 3B Reactor Building Spray Pump Inoperable

Conditions Prior to Occurrence: 97% Full Power

Description of Occurrence:

On December 20, 1978, Reactor Building Spray Pump 3B was removed from the Engineered Safeguards (ES) lineup for performance test PT/3/A/0204/07. During initial testing, high vibration of the pump was detected. The pump was retested using better instrumentation which would have filtered out any vibration due to a background source. Nearly identical readings were obtained using the filtered instrument, so the pump was declared inoperable. The pump was replaced according to maintenance procedure MP/O/A/1300/01. The replacement pump was then tested according to PT/3/A/0204/07, declared operable, and returned to the ES lineup.

Apparent Cause of Occurrence:

The high vibration was due to the impeller having worked loose from the impeller shaft. No torque is specified for tightening the impeller locking device.

Analysis of Occurrence:

In the unlikely event that a loss-of-coolant accident would occur during the 24 hour maintenance period, two cooling units and one spray unit would be required to maintain Reactor Building pressure at no greater than 59 psig. During the maintenance period all three cooling units and spray pump 3A, which had been performance tested and declared operable immediately prior to testing pump 3B, were available. Therefore, public health and safety were not endangered.

Corrective Action:

Presently, no torque is specified for tightening the impeller locking device. The maintenance procedure, MP/O/A/1300/01, used to replace the pump, will be revised to provide an acceptable procedure for impeller locking.

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | S | C | N | E | E | 3 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 1 | 5  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

CONT

01 | L | 5 | 0 | 5 | 0 | 0 | 0 | 2 | 8 | 1 | 7 | 1 | 2 | 2 | 0 | 7 | 1 | 8 | 8 | 0 | 1 | 2 | 4 | 7 | 9 | 9  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 1424, during performance test PT/3/A/0204/01 Reactor Building Spray pump  
03 | 3B was determined to be inoperable due to high vibration. All three cooling  
04 | units and one spray unit were available to maintain Reactor Building pressure  
05 | below 59 psig in the unlikely event of a loss-of-coolant accident. Therefore,  
06 | the health and safety of the public were not endangered.  
07 |  
08 |

09 | S | B | 11 | D | 12 | Z | 13 | P | U | M | P | X | X | 14 | B | 15 | Z | 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
17 | LER/RO REPORT NUMBER | 7 | 8 | 21 | 22 | 23 | SEQUENTIAL REPORT NO. | 0 | 2 | 3 | 24 | 25 | 26 | OCCURRENCE CODE | 0 | 3 | 27 | 28 | 29 | REPORT TYPE | L | 30 | 31 | REVISION NO. | 0 | 32 | 33 |  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
18 | C | 19 | G | 20 | Z | 21 | Z | 22 | 0 | 0 | 0 | 0 | 23 | Y | 24 | N | 25 | L | 26 | I | 0 | 7 | 5 | 27  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The pump was retested to verify the high vibration, then replaced according  
11 | to procedure MP/0/A/1300/01 with a pump which was tested and declared oper-  
12 | able. Vibration was due to the impeller having worked loose from the impeller  
13 | shaft. The maintenance procedure will be revised to provide an acceptable  
14 | procedure for impeller locking.

15 | E | 28 | 0 | 9 | 7 | 29 | NA | 30 | 31 | Performance Test Observation  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
16 | Z | 33 | Z | 34 | 35 | NA | 36 | NA | 37 | NA | 38 | NA | 39 | NA | 40 | NA | 41 | NA | 42 | NA | 43 | NA | 44 | NA | 45 | NA | 46 | NA | 47 | NA | 48 | NA | 49 | NA | 50  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
17 | 0 | 0 | 0 | 37 | Z | 38 | NA | 39 | NA | 40 | NA | 41 | NA | 42 | NA | 43 | NA | 44 | NA | 45 | NA | 46 | NA | 47 | NA | 48 | NA | 49 | NA | 50  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
PERSONNEL INJURIES NUMBER DESCRIPTION  
18 | 0 | 0 | 0 | 40 | 41 | NA | 42 | NA | 43 | NA | 44 | NA | 45 | NA | 46 | NA | 47 | NA | 48 | NA | 49 | NA | 50  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
19 | Z | 42 | NA | 43 | NA | 44 | NA | 45 | NA | 46 | NA | 47 | NA | 48 | NA | 49 | NA | 50  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
PUBICITY ISSUED DESCRIPTION  
20 | N | 44 | NA | 45 | NA | 46 | NA | 47 | NA | 48 | NA | 49 | NA | 50  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35  
NAME OF PREPARER S. R. Lewis

PHONE: (704) 373-8285

7901310042