

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7902220024 DOC. DATE: 79/02/12 NOTARIZED: NO
 FACIL: 50-287 Oconee Nuclear Station, Unit 3, Duke Power Co.
 AUTH. NAME: LEWIS, S.R. AUTHOR AFFILIATION: Duke Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

DOCKET # 05000287

SUBJECT: LER 79-001/03L-0 on 790111: unidentified RCS leakage exceeded 1-GPM. Caused by package leakage from RCS valves 3RC-2 or 3RC-3 &/or pressurizer instrumentation valve. Caused by leaking valve, will be repaired at next shutdown.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 143
 TITLE: INCIDENT REPORTS

NOTES: M CUNNINGHAM - ALL AMOIS TO FSAR + CHANGES TO TECH SPECS.

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	05 BC ORB #4	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1	27 OPERA LIC BR	1	1
	28 ACIDENT ANLYS	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

FEB 23 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 45 ENCL 45

DUKE POWER COMPANY
OCONEE UNIT 3

Report Number: RO-287/79-1

Report Date: February 12, 1979

Occurrence Date: January 11, 1979

Facility: Oconee Unit 3, Seneca, South Carolina

Identification of Occurrence: RCS Leakage in Excess of 1.0 GPM

Conditions Prior to Occurrence:

At 0400 on January 11, 1979 it was determined that the Reactor Coolant System (RCS) had unidentified leakage in excess of 1.0 GPM, in violation of Oconee Nuclear Technical Specification 3.1.6.2. This determination was made as the result of an increase in the Reactor Building (RB) normal sump level, yielding an estimated leak rate of from .75 to 2.25 GPM over the period from 2330 January 10, 1979 to 0200 January 11, 1979. The increase was noted at 0254 on January 11, when the RB sump temperature alarm actuated and a significant increase in the RB particulate monitor (3RIA-47) activity was observed. At 0700 a safety evaluation was initiated, and the RB was entered to determine the origin of the leakage. In addition, a video camera inspection of inaccessible areas of the RB was made. The leakage was discovered to be the result of steam discharge into the drain funnels on the pressurizer side of the primary shield wall. No other leakage was observed. This discharge had previously been identified as packing leakage from RCS valves 3RC-2, 3RC-3, and/or several pressurizer instrumentation valves. Therefore, the excess leakage was reclassified as identified leakage. The safety evaluation regarding the nature and location of the leak was completed by 1000 on January 11, and since the leak rate was well below the 10 GPM limit specified for identified leakage, the decision was made to continue operation. The leaking valve or valves will be repaired at the next shutdown, and a determination as to the cause of the packing failure will be made at that time.

Apparent Cause of Occurrence:

The leakage was identified to be the discharge of steam into the drain funnels as a result of a valve packing leak. The valve will be repaired and the cause of the packing failure will be determined at the next unit outage.

Analysis of Occurrence:

The RCS leakage is due to a packing leak from RCS valve 3RC-2 or 3RC-3 and/or a pressurizer instrumentation valve and does not constitute a violation of the RCS strength boundary. The leak rate is well within the 10 GPM limit allowed by Technical Specification 3.1.6.1. Therefore, the leakage does not endanger the public health and safety.

7902220024

Corrective Action:

The leakage was identified to be the result of a previously observed discharge of steam into the drain funnels. The source of the discharge is a valve packing leak, which will be identified and repaired at the next available unit outage.

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE
L I C E N S E E | 3

LICENSE NUMBER
0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0 - 0

LICENSE TYPE
4 1 1 1 1

CAT 58

CONT
REPORT SOURCE
L 6 0 5 0 0 0 2 8 7 7 0 1 1 1 1 7 9 8 0 1 2 1 2 7 9 9

DOCKET NUMBER
EVENT DATE
REPT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES
At 0400 on January 11, 1979, it was determined that unidentified RCS leakage exceeded 1 GPM. The Reactor Building was inspected both in person and with a video camera, and the only leak observed was a previously identified discharge of steam into the drain funnels. The leakage was much less than the 10 GPM rate allowed by Specifications, and the health and safety of the public were not adversely affected.

SYSTEM CCDE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
C B F B V A L V E X X X

LER/RP REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO OCCURRENCE CODE REPORT TYPE REVISION NO.
7 9 0 0 1 0 3 L 0

ACTION TAKEN ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRA FORM SUB PRIME COM SUPPLIER COMPONENT MANUFACTURER
X B Z Z 0 0 0 Y Y L X 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS
The discharge is due to packing leakage from RCS valves 3RC-2 or 3RC-3 and/or a pressurizer instrumentation valve. The leaking valve will be repaired at the next unit shutdown.

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 0 9 8 NA Operator Observation

ACTIVITY CONTENT RELEASED AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z Z NA NA

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 Z NA

PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 NA

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z NA

PUBLICITY ISSUED DESCRIPTION
N NA

NRC USE ONLY

NAME OF PREPARER S. R. Lewis PHONE: (704) 373-8285