



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**

REGION III
2443 WARRENVILLE RD. SUITE 210
LISLE, IL 60532-4352

May 25, 2016

Mr. David Hamilton
Site Vice President
FirstEnergy Nuclear Operating Company
Perry Nuclear Power Plant
P. O. Box 97, 10 Center Road, A-PY-290
Perry, OH 44081-0097

SUBJECT: PERRY NUCLEAR POWER PLANT—REACTIVE INSPECTION REPORT
05000440/2016008

Dear Mr. Hamilton:

On February 25, 2016, the U.S. Nuclear Regulatory Commission (NRC) completed its initial assessment of events where two safety relief valves remained fully open after receiving a spurious initiation signal which occurred on February 8, 2016, and a loss of shut down cooling event while the reactor was shut down for corrective actions for the two safety relief valves remaining fully open, which occurred on February 11, 2016. Based on this initial assessment, the NRC sent a Special Inspection Team to your site on February 29, 2016.

The team presented the results of this inspection during an interim exit on March 28, 2016, and a final exit meeting on May 13, 2016, with you and other members of your staff. The results of this inspection are documented in the enclosed report. The basis for initiating the special inspection and the focus areas for review are detailed in the Special Inspection Charter (Attachment 4 of the Enclosure).

The enclosed report documents three findings of very low safety significance (Green). These findings involved a violation of NRC requirements. The NRC is treating these violations as Non-Cited Violations (NCVs) consistent with Section 2.3.2.a of the Enforcement Policy.

If you contest the violations or significance of these NCVs, you should provide a response within 30 days of the date of this inspection report, with the basis for your denial, to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, DC, 20555-0001; with a copies to the Regional Administrator, U.S. Nuclear Regulatory Commission, Region III; the Director, Office of Enforcement, U.S. Nuclear Regulatory Commission, Washington, DC, 20555-0001; and the NRC Resident Inspector at the Perry Nuclear Power Plant.

If you disagree with a cross-cutting aspect assignment in this report, you should provide a response within 30 days of the date of this inspection report, with the basis for your disagreement, to the Regional Administrator, Region III; and the NRC Resident Inspector at the Perry Nuclear Power Plant.

D. Hamilton

-2-

In accordance with Title 10 of the *Code of Federal Regulations* (CFR) 2.390, "Public Inspections, Exemptions, Requests for Withholding," of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response (if any) will be available electronically for public inspection in the NRC's Public Document Room or from the Publicly Available Records System (PARS) component of NRC's Agencywide Document Access and Management System (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Patrick L. Loudon, Director
Division of Reactor Projects

Docket No. 50-440
License No. NPF-58

Enclosures:

IR No. 05000440/2016008

w/Attachments:

1. Supplemental Information
2. List of Documents Reviewed
3. List of Acronyms Used
4. Special Inspection Charter
5. Event Timeline

cc: Distribution via LISTSERV®

D. Hamilton

-2-

In accordance with Title 10 of the *Code of Federal Regulations* (CFR) 2.390, "Public Inspections, Exemptions, Requests for Withholding," of the NRC's "Rules of Practice," a copy of this letter, its enclosures, and your response (if any) will be available electronically for public inspection in the NRC's Public Document Room or from the Publicly Available Records System (PARS) component of NRC's Agencywide Document Access and Management System (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Patrick L. Loudon, Director
Division of Reactor Projects

Docket No. 50-440
License No. NPF-58

Enclosures:

IR No. 05000440/2016008

w/Attachments:

1. Supplemental Information
2. List of Documents Reviewed
3. List of Acronyms Used
4. Special Inspection Charter
5. Event Timeline

cc: Distribution via LISTSERV®

DISTRIBUTION:

Jeremy Bowen
RidsNrrPMPerry Resource
RidsNrrDorLpl3-2 Resource
RidsNrrDirslrib Resource
Cynthia Pederson
Darrell Roberts
Richard Skokowski
ROPreports.Resource@nrc.gov

Allan Barker
Carole Ariano
Linda Linn
DRPIII
DRSIII

ADAMS Accession Number: ML16147A437

☒ Publicly Available ☐ Non-Publicly Available ☐ Sensitive ☒ Non-Sensitive

OFFICE	RIII		RIII		RIII		RIII	
NAME	BDickson for WSchaup:rj		BDickson		PLouden			
DATE	05/23/16		05/23/16		05/25/16			

OFFICIAL RECORD COPY

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Docket No: 50-440
License No: NPF-58

Report No: 05000440/2016008

Licensee: FirstEnergy Nuclear Operating Company (FENOC)

Facility: Perry Nuclear Power Plant

Location: North Perry, Ohio

Dates: February 29, 2016, through May 13, 2016

Inspectors: W. Schaup, Senior Resident Inspector, Clinton (Lead)
R. Baker, Operations Engineer
I. Hafeez, Reactor Inspector
J. Havertape, Reactor Engineer
D. Szwarc, Senior Reactor Inspector

Approved by: P. Loudon, Director
Division of Reactor Projects

Enclosure

SUMMARY

Inspection Report No. 05000440/2016008; 02/29/2016 – 05/13/2016; Perry Nuclear Power Plant; Special Inspection.

This report covers an 11-week period of inspection by the Clinton senior resident inspector and four regional inspectors. Based on the results of this inspection, two U.S. Nuclear Regulatory Commission (NRC) identified and one self-revealed finding of very-low safety significance (Green) were identified. The significance of most findings is indicated by their color (i.e., greater than Green, or Green, White, Yellow, Red) using Inspection Manual Chapter (IMC) 0609, "Significance Determination Process (SDP)." Cross-cutting aspects were determined using IMC 0310, "Aspects within the Cross Cutting Areas." Findings for which the SDP does not apply may be Green or be assigned a severity level after NRC management review. All violations of NRC requirements are dispositioned in accordance with the NRC's Enforcement Policy dated July 9, 2013. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NUREG-1649, "Reactor Oversight Process," Revision 5, dated February 2014.

NRC-Identified and Self-Revealed Findings

Cornerstone: Initiating Events

- **Green.** The inspectors identified a finding of very low safety significance and an associated non-cited violation (NCV) of Title 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures and Drawings," for the licensee's failure to follow fleet procedure NOP-SS-3001, "Procedure Review and Approval," and to ensure that a newly developed hardcard was properly reviewed and approved prior to implementation. Specifically, the licensee characterized the hardcard development and implementation as only an administrative change, and was thereby exempted from the fleet procedure review process for new procedures. The licensee entered this finding into the corrective action program (CAP) as condition report (CR) 2016-03033 and planned to perform a causal review to ensure that actions taken in response to information provided in operations administrative instruction, OAI-1703, "Hardcards," have received appropriate review under 10 CFR 50.59.

The inspectors determined that the failure to follow the licensee's fleet and site-specific procedures to ensure that a newly developed hardcard was properly reviewed and approved prior to implementation was a performance deficiency. The performance deficiency was more than minor because, if left uncorrected, the performance deficiency had the potential to lead to a more significant safety concern. Specifically, by not performing review and approval activities in accordance with established procedures, the licensee might unintentionally challenge the operators by requiring equipment manipulation that impose unnecessary plant transients, which would result in unwarranted challenges to safety related equipment. Additionally, the performance deficiency was more than minor because it was associated with the procedure quality attribute of the Initiating Events cornerstone and adversely affected the cornerstone objective of limiting the likelihood of those events that upset plant stability and challenge critical safety functions during shutdown, as well as power operations, and was therefore a finding. The finding was determined to be of very low safety significance because the finding did not cause a reactor trip and the loss of mitigation equipment relied upon to transition the plant from the onset of the trip to a stable shutdown condition. The

inspectors determined this finding had a cross-cutting aspect of conservative bias in the human performance area where individuals use decision making-practices that emphasize prudent choices over those that are simply allowable and a proposed action is determined to be safe in order to proceed, rather than unsafe in order to stop. Specifically, when the licensee determined to develop the hardcard procedure as an administrative change, the decision precluded the opportunity for the licensee to properly evaluate that the procedure actions did not adversely impact existing station procedures and equipment [IMC 0310, H.14]. (Section 4OA5.1.d(2))

- Green. A self-revealed finding and an associated NCV of Title 10 CFR Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was identified for the licensee's failure to prescribe instructions appropriate to the circumstance into procedures for an activity affecting quality. Specifically, the licensee failed to incorporate instructions into procedures to fill and vent all portions of the reactor water level reference leg purge system. This issue has been entered the issue into the CAP as CR 2016-02716 to provide a process for the activities.

The failure to prescribe instructions appropriate to the circumstance into procedures for an activity affecting quality was a performance deficiency. The performance deficiency was more than minor because it was associated with the configuration control performance attribute of the Initiating Events cornerstone and adversely affected the cornerstone objective of limiting the likelihood of those events that upset plant stability and challenged critical safety functions during shutdown as well as power operations and was therefore a finding. Specifically, gas left in the reactor water level instrument reference leg purge system during maintenance equipment alignment was known to have the potential to interfere with the proper operation of pressure and level indicators relied upon for safety functions, as documented in Generic Letter 93-03. The finding was determined to be of very low safety significance (Green) because the finding did not result in exceeding the reactor coolant system leak rate for a small loss of coolant accident (LOCA), cause a reactor trip, involve the complete or partial loss of a support system that contributes to the likelihood of, or caused, an initiating event and did not affect mitigation equipment. The inspectors determined this finding had a cross-cutting aspect of challenge the unknown in the human performance area where individuals stop when faced with uncertain conditions and risks are evaluated and managed before proceeding. Specifically, the technicians involved in the April 18, 2015, system recovery activities did not stop when faced with an uncertain condition, communicate with supervisors, nor consult system experts to resolve the condition prior to continuing work activities. Since this condition was not placed into the corrective action process at the time, no further consideration was given to venting the reference leg portion of the reactor water level reference leg purge system [IMC 0310, H.11]. (Section 4OA5.1.d(3))

Cornerstone: Mitigating Systems

- Green. The inspectors identified a finding of very low safety significance and an associated NCV of Title 10 CFR 50, Appendix B, Criterion VIII, "Identification and Control of Materials, Parts, and Components," for the licensee's failure to assure that identification of items was maintained by appropriate means, either on the item or on records traceable to the item, as required throughout fabrication, erection, installation, and use of the item. Specifically, the licensee failed to maintain traceability of safety related fuses installed in safety related systems. The licensee has entered this issue into the CAP as CR 2016-02048 and CR 2016-02258. Corrective actions being

performed by the licensee include evaluating implementation of procedure NOP-WM-4300 for documenting use of parts in safety related systems and issuing work orders to determine where the potentially defective fuses were installed in the Division 2 and 3 safety related buses for replacement.

The inspectors determined that the failure to assure that identification of items was maintained by appropriate means, either on the item or on records traceable to the item, as required throughout fabrication, erection, installation, and use of the item was a performance deficiency. Specifically, the licensee failed to maintain traceability of safety related fuses installed in safety related systems. The performance deficiency was more than minor because, if left uncorrected, the performance deficiency had the potential to lead to a more significant safety concern. Specifically, identification and control measures are designed to prevent the use of incorrect or defective materials, parts or components which could render safety systems inoperable. Additionally, the performance deficiency was more than minor because it is associated with the equipment performance attribute of the Mitigating Systems cornerstone and adversely affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences and was, therefore, a finding. The finding was determined to be of very low safety significance because the finding was not a deficiency affecting the design or qualification of a mitigating structure system or component, did not represent a loss of system safety function, did not represent an actual loss of function of a single train or two separate trains for greater than its allowed outage time, and did not represent an actual loss of safety function of one or more non-technical specifications trains of equipment during shutdown for equipment designated as high safety significant for greater than 24 hours. The inspectors determined this finding had a cross-cutting aspect of documentation in the human performance area where the organization creates and maintains complete, accurate and up-to-date documentation. Specifically, a review by the licensee of existing work orders that may have utilized the fuses did not clearly document if the fuses were installed, returned to the warehouse or scrapped [IMC 0310, H.7]. (Section 4OA5.1.d(4))

REPORT DETAILS

4OA5 Other Activities

.1 Special Inspection (93812)

a. Event Summaries

On February 8, 2016, at 1500 eastern standard time (EST) while at full power, thirteen safety relief valves (SRVs) opened; eleven of them immediately closed and two remained open on the low-low set point function. The opening of the valves caused suppression pool temperature to increase. At 1503 EST, suppression pool temperature reached 95 degrees Fahrenheit (°F), and plant operators took action to manually scram the reactor in accordance with their training and plant procedures.

All control rods fully inserted and plant equipment functioned as expected. Immediately after the scram, the two remaining SRVs closed and reactor pressure was stabilized via the turbine bypass valves to the main condenser. Reactor water level was maintained using the normal feedwater system.

On February 11, 2016, at 1504 EST with the plant shut down as part of the forced shut down from the previous SRV lifting event, the Division 1 safety bus lost power. Division 1 shut down cooling system was in service at that time. When the safety bus lost power, the division 1 shut down cooling pump 'A' tripped on a loss of power. The Division 1 emergency diesel generator (EDG) started and loaded the safety bus as designed. The emergency service water (ESW) pump that supplies cooling water to the EDG is powered from the safety bus but did not start as required. With no cooling water being supplied to the EDG, operators took actions to manually secure the EDG to prevent damage.

The Division 2 shut down cooling system was operable during the event and was placed into service by plant operators and cooling was re-established at 1544 (EST). During this time reactor coolant temperature rose from 89°F to 115°F.

b. Inspection Scope

A Special Inspection was initiated following the NRC's review of the deterministic and conditional risk criteria specified in Management Directive 8.3, "NRC Incident Investigation Program." The inspection was conducted in accordance with NRC inspection procedure (IP) 93812, "Special Inspection." The Special Inspection Team (SIT) Charter, dated February 25, 2016, is included as Attachment 4. The team reviewed technical and design documents, drawings, operating procedures, off normal procedures, emergency procedures, work orders, corrective action documents, operator logs, vendor documents, and training documents. In addition, the team interviewed the control room operations staff and station personnel to independently assess the events and actions taken in response to the events. The team performed plant walkdowns of the affected systems and spent time at the site control room simulator where the actual events and some postulated events were recreated with licensed operators responding to the events.

A list of specific documents reviewed is provided in Attachment 2.

c. Inspection Documentation

As detailed in the Special Inspection Charter (Attachment 4), the following items were reviewed and the associated results obtained.

- (1) Identify a timeline for both the events. Include relevant and major plant conditions, system lineups and operator actions.

The team completed the timeline and the detailed sequence of events is provided in Attachment 5.

- (2) Review plant data and records to confirm the adequacy of the licensee's assessment of the cause of the scram of the reactor and the loss of the Division 1 4.16 kV safety bus EH-11.

Scram of the reactor on February 8, 2016

The licensee completed a root cause analysis (RCA) on the manual reactor scram based on suppression pool temperature reaching 95°F from the SRVs opening. As part of the RCA, the licensee determined that the most likely cause for the SRVs opening was a pressure and level perturbation observed on reactor pressure vessel (RPV) instrumentation utilizing the 'B' RPV reference leg. The pressure perturbation was most likely caused by a bubble of non-condensable gas that was between the reference leg fill panel and the reference leg. A restricting orifice is located downstream of the reference fill panel feeding the RPV reference leg. Pressure on the upstream side of the restricting orifice was at or near 1500 pounds per square inch (psi) and the downstream pressure was at or near 1025 psi. Flow through the line is typically at 0.08 gallon per minute (gpm). As the bubble of non-condensable gas pressed through the restricting orifice, it rapidly expanded into the lower pressure on the other side. The momentary flow increase in a low flow line would be seen as a pressure spike by RPV instrumentation utilizing the 'B' RPV reference leg.

The resultant pressure increase from the gas bubble pressing through the restricting orifice was sufficient to provide pressure indication to the trip units that were part of the Division 2 logic sequence and provided an open signal to all SRVs. The SRVs responded to the pressure indication and, as designed, thirteen of the SRVs lifted. Eleven immediately reseated in response to the short duration of the pressure perturbation. Two SRVs remained opened as designed as part of the low-low set function of the system.

The inspectors validated the licensee's assessment by independently reviewing plant data gathered from the plant computer, operations logs, operating procedures, maintenance procedures and work orders and interviews with station personnel.

Based on the independent review of the event from plant data, plant records and plant documentation, the inspectors agreed with the licensee assessment that the likely cause of the gas bubble was improperly performed maintenance on the 'B' RPV reference leg fill panel during the previous refueling outage. The maintenance activity resulted in gas remaining in the 'B' RPV reference leg system. However, even after indications were noted that gas was in the system, inadequate actions were not taken to vent the system. The inspectors determined that restoration actions by the licensee after the improperly performed maintenance activity failed to incorporate instructions into procedures to fill

and vent all portions of the reactor water level reference leg purge system that later resulted in a reference leg perturbation. The details and enforcement of this issue are discussed in Section 4OA5.d(2) of this report.

The inspectors also agreed with the licensee's likely cause of the event being a pressure perturbation induced by gas in the 'B' RPV reference leg. Plant data and documentation reviewed by the inspectors was consistent with the event. The pressure perturbation was supported by either plant trace data records, where available, showing instrumentation response of the pressure perturbation or the actual activation of reactor protection logic, indicated in the control room, by all instrumentation supported by the 'B' RPV reference leg.

Loss of the Division 1 safety bus on February 11, 2016

The licensee performed an equipment apparent cause evaluation on the loss of power to the Division 1 safety bus, which resulted in a loss of the shutdown cooling system. As part of the investigation into the event, the licensee utilized a failure modes analysis and simple troubleshooting methods to determine that the cause of the event was the failure of a potential transformer (PT) secondary fuse that supplied power to the under voltage and degraded voltage protection scheme for the safety bus. This same failure also prevented the ESW pump from starting because the ESW pump uses the same protection scheme for under voltage and degraded voltage conditions.

The fuse was determined to be suspect during simple troubleshooting when performing continuity checks in the safety bus. The licensee performed a failure analysis on the suspect fuse at First Entergy's BETA Laboratory and discovered that the fuse internals were not correctly soldered on one end during manufacturing resulting in intermittent continuity. The licensee had a sample of similar fuses analyzed for comparison and all were found correctly assembled.

The inspectors independently reviewed the apparent cause evaluation, failure mode analysis, troubleshooting records, maintenance records, work orders, and fuse failure analysis report. The inspectors agreed with the licensee's conclusion that the apparent cause of the loss of the Division 1 safety bus was the intermittent continuity of the PT secondary fuse.

- (3) Review the circumstances of the safety relief valves opening. Evaluate the design of the SRV and the pressure sensing circuitry as designed in the single reference leg to verify whether the single-failure criterion for initiation of a safety system is met. Verify that inadvertent actuation of all 19 SRVs was analyzed for acceptable safety consequences. Include a review of relevant portions of the Updated Final Safety Analysis Report that discuss inadvertent opening of a safety relief valve. Evaluate the design of the pressure relief valve circuitry and verify that the operation of the SRVs is consistent with the design.

As defined in Title 10 CFR Part 50, Appendix A, a single failure means an occurrence which results in the loss of capability of a component to perform its intended safety functions. Multiple failures resulting from a single occurrence are considered to be a single failure. Fluid and electric systems are considered to be designed against an assumed single failure if neither (1) a single failure of any active component (assuming passive components function properly) nor (2) a single failure of a passive component

(assuming active components function properly), results in a loss of the capability of the system to perform its safety functions.

The inspectors determined that the occurrence of entrained gases in the 'B' RPV reference leg that affected both pressure instruments that utilize the reference leg did not prevent the fulfillment of the safety function of the SRVs. The SRVs have a safety function to open to prevent over pressurization of the RPV. The SRV's did open during the pressure perturbation; therefore, this would not be considered a single failure resulting in the loss of safety function of the SRVs.

The inspectors noted that the current design is a single point vulnerability. The licensee agreed with this position and entered the issue into the corrective action program (CAP) as condition report (CR) 2016–2976.

The inspectors reviewed the Perry Updated Safety Analysis Report (USAR) to determine if the inadvertent actuation of all 19 SRVs had been analyzed for acceptable safety consequences. The USAR only provided an analysis for the inadvertent actuation of a single SRV that remained open. The licensee ran the postulated event in the site control room simulator and the reactor operators utilizing station procedures were able to safely shut down the reactor. Additionally, the licensee performed a heat load calculation for all 19 SRVs opening to determine the effect on suppression pool temperature and determined the maximum temperature that would occur was bounded by the containment load analysis in the USAR and would not adversely affect containment. The inspectors concluded that even though the specific postulated event was not analyzed in the USAR, acceptable safety consequences would be achieved based upon the licensee demonstrating that the plant could be safely shut down if such an event occurred and other postulated events credited in the USFAR were bounding for the postulated event.

To evaluate the design of the SRV relief logic, the inspectors reviewed plant design documentation for both the mechanical safety function of the SRV as well as the operation of the Low Low Set (LLS) relief valve circuitry logic associated with the SRVs. The response of the SRVs to the momentary high reactor pressure perturbation was as designed. The high initial pressure actuated the Division 2 LLS master trip channels that reset the opening and closing solenoid set points for the six SRVs associated with the automatic depressurization system (ADS). The low subsequent pressure immediately closed all but the two lowest LLS set point SRVs that now remained open as the perturbation cleared (duration ~ 0.09 seconds) and reactor pressure remained stable at approximately 1010 psig. Once reactor pressure lowered following taking the unit off line, the remaining two SRVs closed and remained shut as designed.

Additionally, the inspectors observed the licensee's recreation of this event in the site control room simulator to validate that the operation of the SRV relief logic response to simulator modeling of the actual plant conditions was consistent with actual plant data collected during the event. The inspectors determined that the observed response of the SRVs was consistent with design requirements. The inspectors found no issues during their review.

- (4) Review and evaluate the suppression pool temperature response following the opening of the two safety relief valves. Following the opening of the two safety relief valves, suppression pool temperature increased to 95 degrees Fahrenheit. As required per licensee procedure, the operators manually scrambled the reactor at that temperature.

At the time of the event, the plant was operating at rated power in Mode 1, with an average suppression pool temperature (SPT) of 79°F. At 1500 EST, February 8, 2016, a momentary spurious high reactor pressure signal was sensed by the Division 2 SRV relief logic, resulting in multiple SRVs inadvertently opening. Two of the SRVs (1B21F0051C and 1B21F0051D) remained open, causing the average SPT to rise. At 1503 EST, with the two SRVs still open, the operators inserted a manual reactor scram when the average SPT reached 95°F. Following insertion of the manual scram, all control rods fully inserted, and as actual RPV pressure lowered below the set points for the LLS relief logic for closing the valves, both open SRVs closed as designed. The licensee entered emergency operating procedure EOP-02, "Primary Containment Control," Revision 3, due to SPT being greater than 95°F, and continued with actions to mitigate the event and shut down the plant.

Based on the independent review of available plant data, trace recordings showing instrumentation responses, and design documentation, the inspectors agreed with the licensee's assessment that the likely cause for the inadvertent opening of the SRVs was the result of a momentary pressure perturbation sensed by the Division 2 SRV LLS actuation logic.

To evaluate the SPT response during the event, the inspectors observed the licensee's recreation of this event in the plant simulator. The inspectors evaluated the simulator modeling of the actual plant conditions and a different operating crew's response to the event. The scenario was constructed to prevent the actual closure of the two open SRVs until a manual reactor scram was inserted from the crew response. The licensee's business practice PYBP-POS-0030, "Transient Strategies and Mitigating Actions," provided a thumb rule for estimating the plant impact from open SRVs at power. The thumb rule stated that the approximate suppression pool heat up rate was 3°F per minute per open SRV.

The inspectors' review of the plant data showed that the actual SPT rise during the event, with two SRVs open, was approximately 16°F in 3 minutes, or 5.3°F per minute. When the conditions were recreated in the plant simulator, the observed SPT heat up rate was slower, approximately 3.7°F per minute. The crew's response to the recreated event differed from the actual event response in only one aspect. The simulator crew was able to attempt to close the open SRVs using the associated control switches on the Division 2 ADS relay panel back panel, 1H13-P631, due to the longer time delay before reaching an average SPT of 95°F. Since the scenario was conditioned not to allow the open SRVs to close until after insertion of the manual scram, the simulator crew response was not significantly different from the actual event response. The inspectors determined that the actual plant SPT response met design expectations and the slower simulator model response was adequately addressed during operator training and did not negatively impact the licensee's response to the event. The licensee initiated CR 2016-03016 and a simulator work request to address the simulator fidelity issue.

Additionally, the inspectors assessed actions taken by the licensee to mitigate the inadvertent opening of two SRVs while at power by independently reviewing plant computer data, operations logs, and interviewing with the crew personnel who were on watch in the control room during the event. The inspectors also reviewed operation department off normal and emergency procedures relevant to mitigating the event.

The inspectors noted that the operating crew entered off normal instructions (ONIs) for the inadvertent opening of the SRVs and unplanned changes in reactor power. The operators were performing the actions to attempt to close the open SRVs in parallel with attempting to lower power to 96 percent. However, prior to being able to lower power to 96 percent and without an attempt to close the SRVs, the crew inserted a manual reactor scram as directed by the "Margins and Limits" hardcard posted in the control room when the average SPT reached 95°F.

Following the reactor scram and subsequent RPV pressure transient, the SRVs closed. The crew then entered procedure EOP-02, "Primary Containment Control" and stabilized the plant. The licensee subsequently performed a controlled plant cooldown to Mode 4 per plant procedures.

For this specific event response, the procedural action directed by the "Margins and Limits" hardcard did not permit sufficient time for the operating crew to attempt nor complete the immediate actions of the ONI mitigating strategy to close the open SRVs prior to taking the unit off line. Although the operating crew was already implementing the mitigating actions for SPT greater than 95°F but less than 110°F (as discussed in the EOP-2 bases document), the crew did not enter EOP-02 until after the manual scram was inserted. The implementation of the actions in the "Margins and Limits" hardcard, as originally written, required the operators to prematurely take the unit off line prior to attempting the approved ONI actions to terminate the event. This also precluded the crew from entering EOP-02 and implementing the basis of the EOP-02 actions to enter EOP-01, "RPV Control," prior to inserting a reactor scram. The details and enforcement associated with this issue are discussed in Section 4OA5.1.d(3) of this report.

- (5) Review the licensee's evaluation of the failure of the safety relief valve 41C to receive an open signal during the "B" reference leg upset condition.

The licensee performed troubleshooting that checked the SRV logic Initiation and computer points associated with SRV 41C. A signal was simulated into both trip units for the valve to verify the required relays actuated to energize the 'B' coils for SRV 41C and 41G. The same relays closed a set of contacts that energized a third relay that provided a signal to the plant computer point. The troubleshooting verified all the circuitry functioned properly.

Review of the plant data collected during the actual event sampling at a rate of 10 milliseconds indicated that the initiation signal for the 'B' coil for SRV 41G was present at 11 and 29 milliseconds, which were extremely short durations. The relays had a pick up time requirement of less than or equal to 30 milliseconds and a drop out time less than or equal to 25 milliseconds.

The licensee determined that based upon the pressure perturbation on the 'B' RPV reference leg being an extremely short duration and the tolerances of the pickup and drop out relay operating times coupled with the computer sampling rate, it is suspected

that if the perturbation had been slightly longer the computer point signal would have been observed.

The inspectors independently reviewed the licensee evaluation, troubleshooting documentation, applicable drawings and schematics and conducted interviews with station personnel and agreed with the licensee's assessment of why SRV 41C did not have indication of an open signal.

- (6) Review the licensee's evaluation of the intermittent continuity on a control power fuse for "A" phase. Evaluate whether the licensee's maintenance and testing program contributed to the installation of the faulty control power fuse and/or to the continued use of the defective fuse. Verify the design of the PT for the under voltage signal. Verify the adequacy of the design of the PT and fuse(s) considering its ability to cause a loss of both the plant's offsite Division 1 alternate current (AC) source and its onsite Division 1 AC sources.

The licensee's evaluation of the intermittent continuity for the control power fuse for the 'A' phase is discussed in detail in Section 4OA5.c(2) of this report.

The inspectors reviewed the applicable maintenance and testing programs associated with the fuse that failed in the Division 1 safety bus and determined that neither program contributed to installing or continued use of a defective fuse in the Division 1 safety bus.

To verify the adequacy of the design of the PT and fuses for under voltage protection, the inspectors reviewed electrical drawings, schematics and design basis documents to verify compliance with applicable NRC requirements and industry standards.

The inspectors' review of the design for the under voltage protection scheme for the Division 1 safety bus identified that the failure of the single secondary PT fuse was the cause for the safety bus to separate (spuriously) from offsite power even though there were no deficient conditions with the offsite power voltage. Specifically, the licensee's design utilized a single voltage sensor that was shared between two relays in the under voltage trip logic. As a consequence of a shared voltage sensor between the under voltage relays, the overall under voltage protection did not constitute a coincidence logic as relative to the regulatory requirements contained in Branch Technical Position BTP PSB-1, "Adequacy of Station Electric Distribution System Voltages," Revision 0, dated July 1981 (Appendix A to Standard Review Plan Chapter 8). This document provided guidance on technical requirements of the degraded voltage scheme, which the licensee committed to in USAR Section 8.3.1.1.2.9.a.2. A single malfunction in the voltage sensing circuit resulted in a trip of the offsite power source and precluded the onsite power source from performing its safety related function. The details and enforcement of this issue are discussed in Section 4OA5.d(2) of this report.

It should be noted that this condition exists on all three safety related buses.

- (7) Based upon the licensee's initial inability to locate where the other 15 AMP, Ferraz Shawmut fuses purchased from the vendor were installed in the plant, evaluate the licensee's ability to verify plant configuration against their own standards and regulatory requirements. Evaluate the licensee's plans to address plant configuration control and/or extent of condition.

After the team arrived on site, an inspection of the licensee's programs for the control of purchased material, equipment, and services and identification and control of materials, parts, and components as prescribed in Title 10 CFR Part 50, Appendix B, began specific to the safety related fuses. Since the fuses were obtained from a vendor with an Appendix B quality assurance program, the inspection focused on those aspects associated with obtaining safety related parts from such vendors.

The inspectors reviewed the licensee's program for the control of purchased material, equipment, and services by reviewing the applicable program implementing procedures. Then, specific to the safety related fuses, the inspectors reviewed applicable purchase orders, quality control receiving inspection reports, the vendor's dedication plans, the vendor's certificate of conformance, and the vendor testing reports. From this review, the inspectors determined the licensee was in compliance with the requirements of Title 10 CFR Part 50, Appendix B with respect to how the safety related fuses were procured.

The inspectors reviewed the licensee's program for identification and control of materials, parts, and components by reviewing the applicable program implementing procedures. Then, specific to the safety related fuses, the inspectors reviewed the applicable warehouse control documentation and work orders that utilized the safety related fuses. The inspectors determined that the licensee failed to maintain traceability of safety related fuses installed in safety related systems. The details and enforcement of this issue are discussed in Section 4OA5.1.d(4) of this report.

- (8) Review the operators' performance following the loss of shutdown cooling, including the subsequent restoration of shutdown cooling. Include an evaluation of the impact of any impediments encountered due to equipment reliability issues. Additionally, validate the temperature trend and heat up rate reported by the licensee.

The detailed sequence of events is provided in Attachment 5 of this report. At the time of the event at 1505 EST, February 11, 2016, the plant was in a forced outage and in cold shutdown (Mode 4) with residual heat removal (RHR) 'A' (Division 1) operating in shutdown cooling mode. ESW pump 'A' was operating to provide cooling for RHR 'A'. A loss of shutdown cooling occurred when the plant lost offsite power to the Division 1 4160 V safety related bus, EH11, which resulted in a loss of power to the RHR 'A' and ESW 'A' pumps. The loss of offsite power caused the Division 1 EDG to start to restore power to the safety bus. However, ESW pump 'A' did not re-start to provide cooling water for the Division 1 EDG and operators manually shut down the EDG to prevent damage.

With the sustained loss of power to the Division 1 4160 V safety bus, the control room operators decided to shift shutdown cooling to the Division 2 RHR system rather than attempting restoration of Division 1 RHR system.

The inspectors validated the licensee's assessment and actions taken to restore shutdown cooling by independently reviewing plant data gathered from the plant computer, operations logs, and interviews with station personnel who were on shift and on watch in the control room during the event. The inspectors also reviewed procedures relevant to the shutdown cooling system operation and maintenance procedures applicable to activities performed during the forced outage.

Due to maintenance activities being performed to verify that the RPV instrumentation reference leg purge panel lines were properly filled and vented prior to startup, the Division 1 shutdown cooling common suction isolation valve (1E12F0008) was de-energized open. This valve would have to be shut to support operation of the Division 2 RHR system for shutdown cooling. Operators were dispatched to shut the valve using the local hand-wheel since control power was not available with the loss of the Division 1 safety bus. The additional operator action to manually shut the valve did not adversely impact placing the Division 2 RHR system into service and the licensee was able to restore shutdown cooling using Division 2 equipment in 42 minutes, which was within the time to boil calculations.

The inspectors performed an independent calculation of the time remaining to boil following the loss of shutdown cooling, based on plant data retained for the event to validate the time available for the operators to complete restoration of shutdown cooling. The calculated time to boil was 115 minutes with an average reactor coolant system (RCS) heat up rate of 40.8°F per hour, which was consistent with the licensee's assessment of the heat up during the event.

- (9) Relative to the loss of the Division 1 4.16kV safety bus, determine if the licensee performed an adequate extent-of-condition evaluation to assess if the contributing cause to the continuity of the control power fuses have the potential to affect other safety related structures, system and components.

The licensee performed an apparent cause evaluation and a failure analysis of the failed fuse and determined that the reason for the failure was a manufacturing defect. The licensee also determined that there were twenty-two such fuses received from a vendor under the same batch number and some of these fuses were potentially installed in safety related systems, including all three safety buses. The licensee developed a work order to replace the fuses in the three secondary PT circuits for the Division 1 safety bus. Additionally, the licensee concluded that the Division 2 and 3 safety related bus fuses would not be immediately replaced based on the low probability of failure, the overall good performance of these type of fuses over the life of the plant, and the risk to the inservice 'B' train of shutdown cooling.

The licensee's extent of condition evaluation focused primarily on the failed fuse batch but did examine other fuses of similar characteristics for manufacturing defects. However, the extent of condition evaluation did not evaluate other recent fuses failures in similar circuitry to identify the potential effect to other safety related structures, systems, or components.

The inspectors requested documentation on recent fuse failures including maintenance procedures, work orders, logs and condition reports for evaluation. Additionally, the inspectors requested drawings and schematics of selected safety related systems to review for potential vulnerabilities.

During this review, the inspectors examined CR 2016-02060. This CR documented that while operations attempted to restore the Unit 1 Division 1 normal charge to service on February 12, 2016, following the loss of the Division 1 safety bus event, the output voltage for the charger was low (123 VDC). Attempts to adjust the charger up to the normal float range were unsuccessful (did not generate more than 127.8 VDC output). To allow troubleshooting on the Unit 1 Division 1 normal charger, the licensee restored

the Unit 2 Division 1 normal charger. The troubleshooting discovered three failed fuses that were associated with the output of the primary power transformer which isolated the AC and direct current circuits and changed the input voltage to the required level. The fuses protected the circuit from a high overload condition. The licensee was performing a causal evaluation and developing corrective actions to address the issue. The inspection team lead discussed this issue with the senior resident inspector and the issue was turned over the resident staff for follow up inspection.

The inspectors had no additional issues with the licensee's extent of condition evaluation to assess if the contributing cause to the continuity of the control power fuses had the potential to affect other safety-related structures, system and components.

- (10) Review status and performance of the licensee's safety related battery charger, prior to, during and following the loss of Division 1 4.16kV safety bus. Include the licensee actions of declaring the station battery chargers operable. During the loss of Division 1 4.16kV safety bus, Division 2 battery charger was out of service due to planned maintenance. For some time following the event, both safety related Division 1 and Division 2 batteries were discharging.

After the team arrived on site, the inspectors began review of the performance and status related to the station safety related battery chargers during the loss of the Division 1 safety bus. It was discovered that the Division 2 battery charger was in service prior to, during, and after the Division 1 safety bus loss event. This was verified through interviews and review of plant records including the operations log. The Division 2 battery charger was switched from the normal charger to the swing charger earlier in the day to support a ground detection effort but had no effect on the operability of the Division 2 batteries.

The inspectors determined that during the time the Division 1 safety bus lost power, the Division 1 normal and swing chargers had no power and therefore not capable of charging the Division 1 batteries. Since the batteries were not charging, they began to discharge to power required instrumentation and equipment. Station operators recognized the batteries were discharging and lined up the Unit 2 Division 1 batteries in accordance with approved procedures to extend the time the instrumentation and equipment could be powered by batteries.

The inspectors determined there were no issues with respect to the Division 1 and 2 batteries and chargers during the loss of the Division 1 safety bus event.

d. Findings

- (1) Coincidence Logic to Preclude Spurious Trips of the Offsite Power Source

Introduction. The inspectors identified an unresolved item (URI) concerning the installed designed of the safety-related 4-kilovolt under voltage protection scheme.

Description. On February 11, 2016, while the plant was shut down, a fuse failure in a bus voltage detection scheme resulted in the actuation of associated under voltage relays and a trip of the safety related EH11 bus. With the under voltage condition locked in, the Division 1 safety-related equipment remained unavailable when the Division 1 EDG started and powered up the EH11 bus. As a consequence of the under voltage

scheme, the ESW pump for the EDG was not available to provide cooling water and the EDG was manually shut down by operators to prevent damage to the diesel engine.

By letter dated June 3, 1977, "Statement of Staff Positions Relative to Emergency Power Systems for Operating Reactors" (Agencywide Document Access and Management System (ADAMS) Accession No. 8111230342), the NRC requested all licensees, including Perry Nuclear Power Station, to assess the susceptibility of Class 1E electrical equipment to sustained degraded voltage conditions from offsite power sources and to the interaction between the offsite and onsite emergency power systems. In this same letter, the NRC requested that licensees compare the current design of the emergency power systems at plant facilities with the NRC staff positions and that licensees propose plant modifications, as necessary, to meet the NRC staff positions, or provide a detailed analysis which shows that the facility design has equivalent capabilities and protective features. The NRC staff subsequently issued BTP PSB-1, "Adequacy of Station Electric Distribution System Voltages," Revision 0, dated July 1981 (Appendix A to Standard Review Plan Chapter 8), which provided additional guidance on technical requirements of the degraded voltage scheme.

The NRC staff in addressing Perry's design for conformance with BTP PSB-1, stated in Section 8.2.4.1 of the Safety Evaluation Report (SER) for Perry (ADAMS Accession No. 8211120305 dated May 31, 1982) that the applicant states in the FSAR that "degraded voltage conditions for the Class 1E power system are detected by an under voltage protection system on each division... The system includes specific coincident logic for each bus." The staff also stated that the applicant has committed to provide the final design of the first and second level under voltage protection of the safety equipment in conformance with the staff position, before plant startup. Therefore, the staff finds this to be acceptable pending confirmation of the set point values and analysis. The staff identified this item as Confirmatory Issue (34) in the Section 1.0 of the SER. In Section 8.2.5 of this SER the staff also stated that on the basis of this review..., the staff concludes that the offsite power system for Perry meets the requirements of GDC 17 and 18 and is, therefore, acceptable.

By letters dated June 8, 1982, and August 26, 1982, (ADAMS Accession No. 8206170298 and 820310416) the licensee provided details of the degraded voltage relay scheme to be utilized at Perry. In the August 26, 1982, letter, the licensee provided details associated with set point for the first level of under voltage protection. Specifically the licensee stated that the first level of voltage protection had been changed to trip at 75 percent of motor rated voltage instead of 86 percent and the three second fixed time delay would still remain in effect. The licensee also stated the diesel generator start signal after the 15 second time delay for the second level of under voltage had been eliminated. The licensee attached sketches to clarify the logic for a typical bus under voltage protection scheme. However, the licensee did not provide a detailed description of how the attached sketch satisfied the requirements of BTP PSB-1. The August 1982 letter again states that the final design and set points will be established after a review of onsite preoperational test results. In a Supplemental Safety Evaluation Report (SSER 2) (ADAMS Accession No. 8301280169 dated January 13, 1983), the NRC staff acknowledged that based on information provided in the August 26, 1982 letter, the relays in the loss of power protection relays were arranged on a two-out-of-two coincident logic to initiate a timer with a 3-sec time delay. The SSER also acknowledged that in the degraded grid voltage protection, the relays were arranged in a two-out-of-two coincident logic to initiate two separate time-delay

relays. The staff stated that the applicant's final design of the first and second level under voltage protection of safety equipment was acceptable; thus Confirmatory Issue (34) listed in Section 1.10 of the SER, was satisfactorily resolved.

The licensee revised the USAR to document conformance with BTP PSB-1 and the requirements of Institute of Electrical and Electronics Engineers (IEEE) Std. 279-1971, "Criteria for Protection Systems for Nuclear Power Generating Stations." Specifically, USAR Section 8.3.1.1.2.9.2 states that under voltage protection shall include coincidence logic on a per bus basis to preclude spurious trips of the offsite power source. This is in conformance with staff guidance stating that improper voltage protection logic can itself cause adverse effects on the Class 1E systems and equipment such as spurious load shedding of Class 1E loads from the standby diesel generators and spurious separation of Class 1E systems from offsite power.

The inspection team noted that the licensee's installed design utilizes a single voltage sensor that is shared between two relays in the under voltage trip logic. As a consequence of a shared voltage sensor between both under voltage relays, the overall under voltage protection did not constitute a coincidence logic as stated in BTP PSB-1. A single malfunction in the voltage sensing circuit resulted in a trip of the offsite power source and precluded the onsite power source from performing its safety related functions. As evidence by the February 11, 2016, event, a secondary potential transformer fuse failure caused the EH11 bus to separate from offsite power (even though there were no deficiencies in offsite power voltage) and resulted in shutdown of the division 1 EDG bus due to ESW being unavailable. The inspectors believe that this design is deficient in that there is no coincident logic to ensure that spurious trips are precluded as delineated in BTP PSB-1 Section B.1.c.

The licensee agrees that the issue relative to the failure of a single fuse resulting in actuation of both relays, satisfying the under voltage protection scheme logic, represented a design vulnerability. However, the licensee contended that this original design had been maintained, and was approved by the NRC during the initial licensing. Specifically, the licensee concluded, in a white paper addressing the SIT concerns, that "The current design of the potential transformers fusing and the under voltage relays for the division 1 4160 V ESF bus is reflective of the original design and licensing basis. The NRC Staff reviewers clearly used PSB-1 in their review of the PNPP licensing and design bases. They were aided by the schematics contained in the following letter [First Energy Nuclear Operating Company (FENOC) letter docket Nos. (50-440; 50-441), dated August 26, 1982]. They recognized and approved of the relays' arrangement in a two-out-of-two coincident logic. (This is identified on the second schematic - reference Sheet 2 of 2 on lines 19 and 21, which address the time delay relays.) This design is reflective of PNPP's current design and is consistent with the original PNPP licensing basis. Additionally, the NRC stated in the SER that Perry meets the requirements of GDC 17 and 18."

This issue is considered an unresolved item (URI 05000440/201608-01) pending receipt of clarification of the design basis with respect to 4 Kilovolt safety bus under voltage protection scheme. **(URI 05000440/2016008-01: Coincidence Logic to Preclude Spurious Trips of the Offsite Power Source)**

(2) Failure to Provide Instructions to Completely Vent Reference Legs

Introduction. A green finding and an associated non-cited violation (NCV) of Title 10 CFR 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," was self-revealed when the licensee failed to prescribe instructions appropriate to the circumstance into procedures for an activity affecting quality. Specifically, the licensee failed to incorporate instructions into procedures to fill and vent all portions of the reactor water level reference leg purge system.

Description. On April 14, 2015, instrumentation and control technicians were performing surveillance instruction SVI-B21-T2223, "Reactor Pressure Vessel level Instrument Check Valve Operability Test for 1H51-P1432 B and D," on the reactor water level reference leg purge system. As part of the surveillance, a nitrogen test rig was used to test operability of the check valves on the 'B' and 'D' reference leg purge panels. During performance of the surveillance, the control room received numerous unexpected annunciators and a reactor protection system half scram on low reactor water level. Actual reactor water level was greater than 22 feet above the reactor flange when the unexpected annunciators and half scram signal were received.

The licensee determined the cause of the unexpected annunciators and half scram signal was a pressure perturbation on the instrumentation in the reference legs that was induced after the 'B' and 'D' reference leg purge panels were lined up to the respective reference legs without venting the panel. This put the system in an abnormal lineup, which was contrary to the procedural guidance. The licensee documented the issue in the CAP as CR 2015-05243.

As part of their corrective actions, the licensee determined that the panels would have to be filled and vented before returning the panels to service. On April 18, 2015, operators performed instrumentation maintenance instruction IMI-E2-55, -56, -57, and -58, "Reference Leg Purge Panel Operation," Revision 6, to fill and vent purge panels 'A', 'B', 'C', and 'D', respectively. The inspectors noted that the procedures did not include measures to fill and vent the reference leg portion or the detectors in the reference leg portion of the system. Since there was indication of adverse interaction between the purge panels and reference leg, as evidenced by the half scram received during the surveillance, the reference leg portion and the detectors in the reference leg portion of the system should have been filled and vented.

Additionally, the inspectors noted that technicians documented in the procedure that gas was removed from all three legs of the 'B' reference leg purge panel during the performance of IMI-E2-56. Contrary to guidance in maintenance administrative instruction MAI-0504, "Plant Instrument Calibration and Maintenance," Steps 4.1.5.2 and Step 4.1.5.4, technicians did not write a condition report following the discovery of gas in the 'B' purge panel and did not communicate with supervisors nor consult with system experts. The licensee supervision that reviewed the completed work order also did not question the documentation of gas removal from the system, which was an unexpected condition that needed to be resolved prior to continuing work activities. Since the condition was not placed into the corrective action process at the time, no further consideration was given to venting the remaining portions of the reactor water level reference leg purge system.

On February 8, 2016, a pressure perturbation occurred affecting the instrumentation connected to the 'B' reactor water level reference leg. The perturbation caused pressure and level indicators connected to the 'B' reference leg to read alternately high and low for a period of approximately 90 milliseconds. As a result, a half scram signal for low reactor water level was received; a half group one isolation signal for high reactor water level was received; and an open signal was received by 18 of 19 SRVs due to high indicated pressure. A total of 13 SRVs actually opened and 11 of those then immediately closed.

The inspectors determined that a likely cause of the perturbation on the 'B' reactor water level reference leg was air or gas introduction into the reactor water level reference leg purge system based on operational experience documented in Generic Letter 93-03.

As part of the corrective actions from the pressure perturbation on February 8, 2016, the 'A', 'B', 'C', and 'D' purge panels and the 'B' reference leg were filled and vented in accordance with instrument maintenance instructions. During these evolutions, three one-inch slugs of gas were found in the 'B' purge panel and gas was vented from two pressure transmitters in the 'B' reference leg.

Additionally, the licensee identified that there currently were no operating process existed to startup, secure, or fill and vent the reference leg purge system. The licensee documented this issue in CR 2016-02716 and assigned resolution of the issue in CR 2016-01866.

Analysis. The failure to prescribe instructions appropriate to the circumstance into procedures for an activity affecting quality was a performance deficiency. Specifically, the licensee failed to incorporate instructions into procedures to fill and vent all portions of the reactor water level reference leg purge system. The performance deficiency was more than minor in accordance with IMC 0612, "Power Reactor Inspection Reports," Appendix B, "Issue Screening," dated September 7, 2012, because it was associated with the configuration control performance attribute of the Initiating Events cornerstone and adversely affected the cornerstone objective of limiting the likelihood of those events that upset plant stability and challenge critical safety functions during shutdown as well as power operations and was therefore a finding. Specifically, gas left in the reactor water level instrument reference leg purge system during maintenance equipment alignment was known to have the potential to interfere with the proper operation of pressure and level indicators relied upon for safety functions, as documented in Generic Letter 93-03. Using IMC 0609, Attachment 4, "Initial Characterization of Findings," and Appendix A, "The Significance Determination Process for Findings at Power," issued June 19, 2012, the finding was screened against the Initiating Events cornerstone and determined to be of very low safety significance (Green) because the finding did not result in exceeding the RCS leak rate for a small loss of coolant accident (LOCA), cause a reactor trip, involve the complete or partial loss of a support system that contributes to the likelihood of, or caused, an initiating event and did not affect mitigation equipment.

The inspectors determined this finding had a cross-cutting aspect of challenge the unknown in the human performance area where individuals stop when faced with uncertain conditions and risks are evaluated and managed before proceeding. Specifically, the technicians involved in the April 18, 2015, system recovery activities did not stop when faced with an uncertain condition, communicate with supervisors, or consult system experts to resolve the condition prior to continuing work activities. Since

this condition was not placed into the corrective action process at the time, no further consideration was given to venting the reference leg portion of the reactor water level reference leg purge system [IMC 0310, H.11].

Enforcement. Title 10 of the CFR, Part 50, Appendix B, Criterion V, "Instructions, Procedures, and Drawings," requires in part, that activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, of a type appropriate to the circumstances and shall be accomplished in accordance with these instructions, procedures, or drawings. The licensee established instrument maintenance instruction IMI-E2-56, "B Reference Leg Purge Panel Operation," Revision 6 for filling and venting the 'B' reactor water level reference leg purge system, an activity affecting quality.

Contrary to the above, on April 18, 2015, technicians failed to have a procedure for filling and venting the 'B' reactor water level reference leg purge system appropriate to the circumstances. Specifically, the procedure used by the technicians, IMI-E2-56, did not include measures to fill and vent all portions of the 'B' reference leg purge system. The licensee had identified that there currently were no operating process to startup, secure, or fill and vent the reference leg purge system and entered the issue into the CAP for resolution. Because this violation is of very low safety significance and was entered into the licensee's CAP as CR 2016-01866, this violation is being treated as an NCV consistent with Section 2.3.2 of the NRC Enforcement Policy.

(NCV 05000440/2016008-02: Failure to Provide Instructions to Completely Vent Reference Legs)

(3) Hardcard Development Failed to Follow Procedure Review and Approval Process

Introduction. The inspectors identified a finding of very low safety significance and an associated NCV of 10 CFR 50, Appendix B, Criterion V, "Instructions, Procedures and Drawings," for the licensee's failure to follow fleet procedure NOP-SS-3001, "Procedure Review and Approval," Revision 20, to ensure that a newly developed hardcard was properly reviewed and approved prior to implementation. Specifically, the licensee characterized the hardcard development and implementation as only an administrative change, and was thereby exempted from the fleet procedure review process for new procedures.

Description. The inspectors performed an onsite review of the licensee's event response to two safety relief valves inadvertently opening and remaining fully open with the plant operating at 100 percent reactor power. This event occurred on February 8, 2016. The inspectors identified that during the event response, the operating crew entered the off normal instruction ONI-B21-1, "SRV Inadvertent Opening/Stuck Open," Revision 20, and was performing the required immediate actions to attempt to close the open SRVs. After approximately three minutes, the crew inserted a manual reactor scram when suppression pool average temperature reached 95°F, as directed by the "Margins and Limits" hardcard posted in the control room. Following the reactor scram and subsequent pressure transient, the SRVs closed and the crew entered procedure EOP-2, "Primary Containment Control," and stabilized the plant. The licensee subsequently performed a controlled plant cooldown to Mode 4 per plant procedures.

For this specific event response, the actions required by the hardcard did not permit sufficient time for the operating crew to attempt nor complete the immediate actions of

the ONI mitigating strategy to close the open SRVs prior to taking the unit off line. The operating crew was already implementing the mitigating actions of EOP-2 for suppression pool temperature greater than 95°F but less than 110°F as discussed in the EOP-2 bases document. However, the operating crew did not enter EOP-2 because the entry condition for EOP-2 is greater than 95°F for the suppression pool temperature. The licensee entered EOP-2 after the manual scram was inserted at 95°F and average pool temperature continued to rise.

The specific EOP-2 bases document states, in a caution note at the beginning of Section 5.0, that "Bases information SHALL NOT be used to direct plant operation. Bases information is for reference use only." However, the EOP-2 bases document also states that the bases information provided the reasoning behind the actions taken during the performance of EOP-2. If the EOP-2 actions taken were not successful in mitigating the rise in suppression pool temperature, EOP-2 would direct the operator to enter EOP-1, "RPV Control," BEFORE average suppression pool temperature reaches 110°F. At 110°F, a reactor scram is required by plant Technical Specifications.

Entering EOP-1 would ensure that, if possible, the reactor is scrammed before boron injection would be required and in anticipation of possible RPV depressurization in a subsequent EOP-2 step. The scram is effected indirectly, through entry of EOP-1, rather than through an explicit direction in EOP-2 to ensure that RPV water level, RPV pressure, and reactor power are properly coordinated following the scram.

The original "Margins and Limits" hardcard was developed as a corrective action from CR 2010-73493 to develop written guidance/strategy for response in a dynamic event to enhance crew performance. This included set points to take manual action prior to reaching automatic system initiation/actuation. Fleet procedure NOP-SS-3001, "Procedure Review and Approval, Revision 20, was the implementing procedure for development of new procedures. As part of the development process prescribed by the fleet procedure, the licensee performed the required regulatory applicability determination (RAD) for the new procedure. The information provided in the RAD would be used to support the applicability of 10 CFR 50.59, and as necessary, the applicability of other regulatory requirements. During completion of the new hardcard RAD information, the licensee characterized the development of the new procedure as an administrative change, which precluded the applicability of 10 CFR 50.59 and any additional procedure change process activities associated with the 10 CFR 50.59 review process.

The implementation of the "Margins and Limits" hardcard as written, precluded entering EOP-2 and implementing the EOP-2 actions to enter EOP-1 prior to inserting a reactor scram. Additionally, in this specific instance where two SRVs opened and remained open at power due to an invalid actuation of the Low-Level-Set logic associated with the SRV's relief function, the hardcard required the operators to scram the reactor prior to performing the approved ONI actions to terminate the event.

The inspectors determined that the implementation of the hardcard was more significant than simply an administration change since the listed actions on the hardcard prescribed specific critical parameter set points and directed operators to take manual actions when those set points were reached. The 10 CFR 50.59 process would apply and further review to determine if the new procedure actions adversely affected any existing station procedures or equipment was required.

The licensee entered this issue into their CAP as CR 2016–03033, and planned to perform a causal review to ensure that actions taken in response to information provided in operations administrative instruction OAI–1703, “Hardcards,” have received appropriate review under 10 CFR 50.59. Separate CRs were also written to determine if the “Margins and Limits” hardcard actions should be repeated/incorporated into applicable off normal instructions (CR 2016–02723), and to review the information provided in plant administrative procedure PAP–0507, “Perry Supplemental Procedure Requirements/Guidance,” to determine if review requirements for operation administrative instructions should be revised (CR 2016–03309).

Analysis. The inspectors determined that the failure to follow the licensee’s fleet procedure to ensure that a newly developed hardcard was properly reviewed and approved prior to implementation is a performance deficiency. Specifically, the licensee characterized the hardcard development and implementation as only an administrative change, and was thereby exempted from the fleet procedure review process for new procedures. The performance deficiency was more than minor in accordance with IMC 0612, “Power Reactor Inspection Reports,” Appendix B, “Issue Screening,” dated September 7, 2012, because, if left uncorrected, the performance deficiency had the potential to lead to a more significant safety concern. Specifically, by not performing review and approval activities in accordance with established procedures, the licensee may unintentionally challenge the operators by requiring equipment manipulation and by imposing unnecessary plant transients, which could result in unwarranted challenges to safety related equipment. Additionally, the performance deficiency was more than minor because it was associated with the procedure quality attribute of the Initiating Events cornerstone and adversely affected the cornerstone objective of limiting the likelihood of those events that upset plant stability and challenge critical safety functions during shutdown, as well as power operations, and was therefore a finding. Using IMC 0609, Attachment 4, “Initial Characterization of Findings,” and Appendix A, “The Significance Determination Process (SDP) for Findings at Power,” issued June 19, 2012, the finding was screened against the Initiating Events cornerstone and determined to be of very low safety significance because the finding did not cause a reactor trip and the loss of mitigation equipment relied upon to transition the plant from the onset of the trip to a stable shutdown condition.

The inspectors determined this finding had a cross-cutting aspect of conservative bias in the area of human performance where individuals use decision making-practices that emphasized prudent choices over those that were simply allowable and a proposed action was determined to be safe in order to proceed, rather than unsafe in order to stop. Specifically, when the licensee determined to develop the hardcard procedure as an administrative change, the decision precluded the opportunity for the licensee to properly evaluate that the procedure actions did not adversely impact existing station procedures and equipment [IMC 0310, H.14].

Enforcement. Title 10 of the CFR, Part 50, Appendix B, Criterion V, “Instructions, Procedures and Drawings,” requires in part, that activities affecting quality shall be prescribed by documented instructions, procedures, or drawings of a type appropriate to the circumstances, and shall be accomplished in accordance with these instructions, procedures, or drawings. The licensee established fleet procedure NOP–SS–3001, “Procedure Review and Approval, Revision 20, as the implementing activity for development of new procedures, an activity affecting quality.

Contrary to the above, around September 1, 2010, the licensee failed to comply with fleet procedure NOP-SS-3001, "Procedure Review and Approval," when the "Margins and Limits" hardcard was initially developed and approved, and during the following four revisions, and ensure that the newly developed hardcard was properly reviewed and approved prior to implementation. Specifically, the licensee incorrectly characterized the hardcard development and implementation as only an administrative change, and thereby exempted the hardcard from the fleet review process for completing the required regulatory applicability determination. The licensee planned to perform a causal review to ensure that actions taken in response to information provided in operations administrative instruction OAI-17-03, "Hardcards," have received appropriate review under 10 CFR 50.59. Because this finding was of very low safety significance and because the finding was entered into the licensee's CAP as CR 2016-03033, this violation is being treated as a NCV consistent with Section 2.3.2 of the NRC Enforcement Policy. **(NCV 05000440/2016008-03: Hardcard Development Failed to Follow Procedure Change Process).**

(4) Failure to Maintain Traceability of Safety Related Fuses

Introduction. The inspectors identified a finding of very low safety significance and an associated NCV of 10 CFR 50, Appendix B, Criterion VIII, "Identification and Control of Materials, Parts, and Components," for the licensee's failure to assure that identification of items was maintained by appropriate means, either on the item or on records traceable to the item, as required throughout fabrication, erection, installation, and use of the item. Specifically, the licensee failed to maintain traceability of safety-related fuses installed in safety-related systems.

Description. On February 11, 2016 with the plant shutdown, the Division 1, 4.16 kV safety bus EH-11 lost power. The Division 1 shutdown cooling system was in service at that time and the Division 1 shutdown cooling pump 'A' tripped on a loss of power. The Division 1 EDG started and loaded on safety bus EH-11 as designed. However, the ESW pump 'A,' which supplied cooling water to the EDG, did not start. Due to the absence of cooling water to the EDG, operators took manual action to secure the Division 1 EDG.

The licensee performed an investigation to determine why the Division 1 safety bus lost power. The licensee determined that intermittent continuity on the 'A' phase secondary PT fuse, which was part of the voltage sensing circuitry for the safety bus, was the cause for the safety bus normal supply breaker opening and removing power to the safety bus. Further investigation of the failed fuse revealed that the intermittent continuity was a result of a manufacturing defect where the fuse was not properly soldered at one end. The same voltage sensing circuitry is used by the starting circuitry for the "A" ESW pump. As a result, the "A" ESW pump could not start and the EDG was unable to perform its safety function.

The inspectors asked the licensee what other safety related components had fuses similar to the failed fuse potentially installed in them. The licensee determined that the fuse that had failed was one of 22 fuses procured from a vendor in a single batch. The licensee was able to find 8 of the fuses from the batch, including the failed fuse, either in the warehouse or in the electrical maintenance shops. The remaining 14 fuses could not be positively located. The licensee reviewed procedure NOP-WM-4300, "Order Execute Process," Revision 12, and existing work orders that may have utilized the

fuses and determined that workers did not clearly document if the fuses were installed, returned to the warehouse or scrapped. The licensee also determined that safety related components that could have potentially defective fuses installed included the Division 2 and 3 safety-related buses. The licensee documented the issue in the CAP as CR 2016-02048 and CR 2016-02258.

Corrective actions being performed by the licensee include evaluating implementation of procedure NOP-WM-4300 for documenting use of parts in safety related systems and issuing work orders to determine where the potentially defective fuses are installed in the Division 2 and 3 safety related buses and replace them.

Analysis. The inspectors determined that the failure to ensure that identification of items was maintained by appropriate means, either on the item or on records traceable to the item, as required throughout fabrication, erection, installation, and use of the item was a performance deficiency. Specifically, the licensee failed to maintain traceability of safety related fuses installed in safety-related systems. The performance deficiency was more than minor in accordance with IMC 0612, "Power Reactor Inspection Reports," Appendix B, "Issue Screening," dated September 7, 2012, because, if left uncorrected, the performance deficiency had the potential to lead to a more significant safety concern. Specifically, identification and control measures were designed to prevent the use of incorrect or defective materials, parts or components which could render safety systems inoperable. Additionally, the performance deficiency was more than minor because it was associated with the equipment performance attribute of the Mitigating Systems cornerstone and adversely affected the cornerstone objective of ensuring the availability, reliability, and capability of systems that respond to initiating events to prevent undesirable consequences and was, therefore, a finding. Using IMC 0609, Attachment 4, "Initial Characterization of Findings," and Appendix A, "The Significance Determination Process for Findings at Power," dated June 19, 2012, the finding was screened against the Mitigating Systems cornerstone and determined to be of very low safety significance because the finding was not a deficiency affecting the design or qualification of mitigating structure, system or component, did not represent a loss of system safety function, did not represent an actual loss of function of a single train or two separate trains for greater than its allowed outage time, and did not represent an actual loss of safety function of one or more non-technical specification trains of equipment during shutdown for equipment designated as high safety significant for greater than 24 hours.

The inspectors determined this finding affected the cross-cutting area of human performance in the aspect of documentation where the organization creates and maintains complete, accurate and up-to-date documentation. Specifically, a review by the licensee of existing work orders that may have utilized the fuses did not clearly document if the fuses were installed, returned to the warehouse or scrapped [IMC 0310, H.7].

Enforcement. Title 10 of the CFR, Part 50, Appendix B, Criterion VIII, "Identification and Control of Materials, Parts, and Components," states that measures shall be established for the identification and control of materials, parts, and components, including partially fabricated assemblies. These measures shall assure that identification of the item is maintained by heat number, part number, serial number, or other appropriate means, either on the item or on records traceable to the item, as required throughout fabrication, erection, installation, and use of the item.

Contrary to the above, on February 23, 2016, the licensee did not ensure the measures established by the licensee for identification of items was maintained by heat number, part number, serial number, or other appropriate means, either on the item or on records traceable to the item, as required throughout fabrication, erection, installation, and use of the item. Specifically, safety related fuses installed in safety related equipment were not identifiable either on the fuses or on traceable records to the fuses as required during the installation and use of the fuses. Corrective actions being performed by the licensee include evaluating implementation of procedure NOP-WM-4300 for documenting use of parts in safety related systems and issuing work orders to determine where the potentially defective fuses were installed in the Division 2 and 3 safety related buses to replace them. Because this violation was of very low safety significance and was entered into the licensee's CAP as CR 2016-02048 and CR 2016-02258, this violation was being treated as an NCV consistent with Section 2.3.2 of the NRC Enforcement Policy. **(NCV 05000440/2016008-04: Failure to Maintain Traceability of Safety Related Fuses).**

4OA6 Management Meetings

1. Exit Meeting Summary

The lead inspector conducted the following meetings with the licensee. The licensee acknowledged the issues presented. The inspectors confirmed that none of the potential report input discussed was considered proprietary.

- On March 28, 2016, the inspection results were presented to Mr. D. Hamilton and other members of the licensee staff in an interim exit.
- On May 13, 2016, the inspection results were presented to Mr. F. Payne and other members of the licensee staff in an exit.

ATTACHMENT: SUPPLEMENTAL INFORMATION

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee

D. Hamilton, Site Vice President
F. Payne, Plant General Manager
S. Benedict, Operations Superintendent
T. Veitch, Chemistry Manager
C. Elliot, Radiation Protection Manager
J. Tuffs, Outage Management Manager
B. Baumgardner, Special Projects Manager
J. Pry, Work Management Manager
T. Brown, Performance Improvement Director
N. Conicella, Regulatory Compliance Manager
R. Strohl, Training Manager
R. O'Connor, Emergency Planning Manager
D. Reeves, Site Engineering Director
D. Culler, Supervisor Mechanical Design
K. Nelson, Plant and Equipment Manager
P. Boissoneault, Program and Technical Services Manager
M. DeStefano, Fleet Oversight Manager
J. Archer, Supervisor Security Support
L. Zerr, Regulatory Compliance Supervisor
D. Lockwood, Regulatory Compliance Engineer
J. Severino, Regulatory Compliance Engineer
T. Kledzik, Regulatory Compliance Engineer
R. Briggs, Supervisor Design Engineering Electrical
M. McFarland, Superintendent Operations Training
P. Roney, Supervisor Nuclear Support Systems Engineering
B. Coad, Engineering Programs
B. Sutter, Superintendent Electrical Maintenance
T. Henderson, Fleet Licensing
S. Richardson, manager Supply Chain
D. Jenkins, First Energy Legal Department

U.S. Nuclear Regulatory Commission

B. Dickson, Division of Reactor Projects, Branch 5, Chief
L. Kozak, Division of Reactor Projects, Senior Reactor Analyst
W. Schaup, Division of Reactor Projects, Senior Resident Inspector, Clinton Power Station

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

Opened

05000440/2016008-01	URI	Coincidence Logic to Preclude Spurious Trips of the Offsite Power Source (Section 4OA5.d.(1))
05000440/2016008-02	NCV	Failure to Provide Instructions to Completely Vent Reference Legs (Section 4OA5.d.(2))
05000440/2016008-03	NCV	Hardcard Development Failed to Follow Procedure Change Process (Section 4OA5.d.(3))
05000440/2016008-03	NCV	Failure to Maintain Traceability of Safety Related Fuses (Section 4OA5.d.(4))

Closed

05000440/2016008-02	NCV	Failure to Provide Instructions to Completely Vent Reference Legs (Section 4OA5.d.(2))
05000440/2016008-03	NCV	Hardcard Development Failed to Follow Procedure Change Process (Section 4OA5.d.(3))
05000440/2016008-04	NCV	Failure to Maintain Traceability of Safety Related Fuses (Section 4OA5.d.(4))

Discussed

None

LIST OF DOCUMENTS REVIEWED

The following is a partial list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspector reviewed the documents in their entirety, but rather that selected sections or portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

CALCULATIONS

<u>Number</u>	<u>Description or Title</u>	<u>Revision</u>
2.1.6	Suppression Pool Response – MSIV Closure (MSIVC) and MSIVC with Small Break Accident SBA	6 A-01

CORRECTIVE ACTION DOCUMENTS GENERATED DUE TO THE INSPECTION

<u>Number</u>	<u>Description or Title</u>	<u>Date</u>
CR 2016-02976	NRC ID 2016 SIT: Need to re-assess B21 Nuclear Boiler Instrumentation System for Single Point Vulnerabilities Associated with Inadvertent Opening of Safety Relief Valves	
CR 2016-02980	NRC ID 2016 SIT: CR on Improved LOOP/LOCA Test Initiator	
CR 2016-03016	NRC ID 2016 SIT: The Perry Simulator Suppression Pool Temperature Response to an Open SRV is Slower than Actual Plant Response	3/3/16
CR 2016-03033	NRC ID 2016 SIT: OAI-1703 (Hardcards) Margins and Limits Card not Reviewed Under 10CFR50.59	3/4/16
CR 2016-03309	2016 NRC SIT: ID – OAI-1703 (Hardcards) Content may not Receive the Appropriate Cross Discipline Reviews due to the Procedure Type	3/10/16
CR 2016-03471	NRC ID 2016 SIT: Inconsistent Documentation of Panels 1H1P1432B and “B” Fill and Venting Tasks	3/15/16
CR 2016-03861	NRC ID 2016 SIT: Inaccurate Category Classification of Condition Report 2016-02060	
CR 2016-04016	NRC ID 2016 SIT: Potential NRC Finding Related to Compliance with Branch Technical Position PSB-1 C.3	

CORRECTIVE ACTION DOCUMENTS REVIEWED DURING THE INSPECTION

<u>Number</u>	<u>Description or Title</u>	<u>Date</u>
CR 2010-73493	CA-SA-10-02 Perry AFI Assessment – OPS OP.1.NNI	3/15/10
CR 2015-05243	Unexpected ½ Scram Eceived	4/15/15
CR 2015-05355	Re-performance of Steps Required for SVI-B21-T2223	4/16/15
CR 2016-01865	Perry Plant was Manually Scrammed Following SRV Actuation	2/8/16

CR 2016–01866	Manual Reactor Scram Based on Suppression Pool Temperature of 95 Degrees F Due to Open SRVs	2/8/16
CR 2016–01883	SRV 1B21F0041C is the Only SRV that did not get an Open Signal	2/9/16
CR 2016–01934	CR Tracking Completion of ODMI for Operation Following Pressure Transient on Reference Leg B	2/10/16
CR 2016–01936	SRV tailpipe temperatures	2/10/16
CR 2016–01983	Post Event Critique Ops Crew 2 SRV Opening Event and Manual Reactor Scram	2/10/16
CR 2016–02011	1B21N0062B Pressure Spike for 10 Milliseconds	2/10/16
CR 2016–02031	EDG1B Ground Fault Locked In	2/11/16
CR 2016–02048	Loss of EH11 Divisional Bus Results in a Loss of Shutdown Cooling	2/11/16
CR 2016–02049	Division 1 Diesel Generator Ran Approximately 3 Minutes Without Emergency Service Water Cooling	2/11/16
CR 2016–02051	Emergency Service Water Pump “A” Failed to Start on Automatic Start Signal	2/11/16
CR 2016–02052	Unplanned Change in Shutdown Safety Risk – from Green to Yellow	2/11/16
CR 2016–02056	Abnormal Indications on RCIS Following Power Restoration to EH11	2/12/16
CR 2016–02059	Not all Valves Closed During Expected BOP Isolation	2/12/16
CR 2016–02060	Division 1 DC Normal Charger Did Not Respond as Expected	2/12/16
CR 2016–02070	Defect found with the ‘A’ Phase Secondary PT Fuse	2/12/16
CR 2016–02073	NRC Identified: Questions Regarding the 2/8/16 Plant Scram	2/12/16
CR 2016–02088	EH1103 Fuse had Inconsistent Resistance Readings	2/12/16
CR 2016–02093	NOBP–TR–1151 Crew Performance Critique – Loss of Bus EH11, Loss of Shutdown Cooling	2/12/16
CR 2016–02107	Tech Spec Bases and SOI–G40 (ADHR) Address the Availability of ADHR Using Different Terms	2/12/16
CR 2016–02128	Safety Relief Valve 1B21F0047H Seat Leakage	2/14/16
CR 2016–02131	Safety Relief Valve 1B21F0047H Discharge Leakage Identified During Startup	2/14/15
CR 2016–02506	RPV B Reference Leg Needed Adjustment	2/22/16
CR 2016–02558	Detailing of Parts Usage is not Consistently being Followed per NOP–WM–4300 Order Execute Process	2/23/16
CR 2016–02630	Shutdown Safety – Crediting ADHR as a Backup Decay Heat Removal Method Following Loss of Shutdown Cooling Event	2/25/16
CR 2016–02696	Review Loss of Shutdown Cooling Procedure Guidance for Improvement Opportunities	2/26/16
CR 2016–02715	Procedure Enhancement Opportunity for Startup, Securing, and when to Fill and Vent B21 Purge Panels for the Reactor Pressure Vessel Reference Legs	2/26/16
CR 2016–02716	Potential to Introduce Air into B21 Reference Leg Purge Panels when Performing a Fill and Vent or Starting up a Purge Panel	2/26/16

CR 2016-02717	Air was Found During the Process of Filling and Venting the Reference Leg and its Associated Purge Panel as a Result of Troubleshooting the 2/8/16 Scram	2/26/16
CR 2016-02719	Purge Panel Observed Issues	2/26/16
CR 2016-02723	Conservative Operator Action Values in Hardcard are not in the Off-normal Instruction	2/26/16

MISCELLANEOUS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
	Procedure Approval Form for OAI-1703, Rev. 5	9/5/10
10-03803	Regulatory Applicability Determination for OAI-1703, Rev. 5	00
	Procedure Approval Form for OAI-1703, Rev. 24	10/5/15
15-02798	Regulatory Applicability Determination for OAI-1703, Rev. 24	00
15-02798	10 CFR 50.59 Screen for OAI-1703, Rev. 24	00
93-156 (50.59 Evaluation)	Reactor Vessel Water Level Instrument Reference Leg Continuous Backfill Modification	3
Design Change Package 930075	Reactor Vessel Water Level Instrument Reference Leg Continuous Backfill Modification	11/29/93
Operations Standing order	Under Voltage Fuses in EH12 and EH13	2/29/16
OTLC-3058201302_PY-SGC1	Cycle 2 2013 Evaluated Scenario Guide C1	0
OTLC-3058201303_PY-SGD	Cycle 3 2013 EOP Training Scenario Guide D	0
OTLC-3058201304_PY-SGC1	Cycle 4 2013 Evaluated Scenario Guide C1	0
OTLC-3058201410_PY-SGC1	Cycle 10 2014 Evaluated Scenario Guide C1	0
OTLC-3058201503_PY-SGC1	Cycle 3 2015 Evaluated Scenario Guide C1	0
OTLC-3058201606_PY-SGD	Cycle 6 2016 EOP Training Scenario Guide D	0
PO Number 45225736	Fuse, General Purpose, 15 Amp, 250 VAC. Class K-5, UL-Standard 248-9 listed	3/21/07
Procurement Package G0000010019	Generic package for Safety Related Fuses Procured from an Appendix B Supplier United Controls INC	3

MISCELLANEOUS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
Procurement Package G0000010061	Fuses, UL and Non-UL Classified, Types Include One-time, Fast-acting, Slow-blow and Current-limiting	4
Procurement Package 17071425	Fuse, E-Rated, 5kV, 2 Amps, Medium Voltage	001
Quality Control Receiving Inspection Report	United Controls INTL INC PO Number 45225736	4/7/07
ADAMS Accession No. 8111230342	Statement of Staff Positions Relative to Emergency Power Systems for Operating Reactors	6/3/77
ADAMS Accession No. 8211120305	Perry Safety Evaluation Report (Perry)	5/31/82
ADAMS Accession No. 8206170298	SER Confirmatory Item-Undervoltage Protection	6/8/82
ADAMS Accession No. 820310416	SER Confirmatory Item-Undervoltage Protection	8/26/82
ADAMS Accession No. 8301280169	Perry Supplemental Safety Evaluation Report (SSER 2)	1/13/83

PROCEDURES

<u>Number</u>	<u>Description or Title</u>	<u>Revision</u>
EOP Bases	Emergency Operating Procedure Bases	5
EOP-02	Primary Containment Control Flowchart	D
EOP-02	Primary Containment Control (Bases)	3
FTI-F0036	Post-maintenance Test Manual	9
GEI-0105	Maintenance and Calibration of Type NGV-11 Relays	3
GEI-0106	Maintenance and Calibration of Single Phase Under Voltage Relay Type ITE-27N	4
IMI-E2-33	Reference Leg 'B' Operation	9
IMI-E2-55	Reference Leg Purge Panel 'A' Operation	6
IMI-E2-56	Reference Leg Purge Panel 'B' Operation	6
IMI-E2-57	Reference Leg Purge Panel 'C' Operation	6

PROCEDURES

<u>Number</u>	<u>Description or Title</u>	<u>Revision</u>
IMI-E2-58	Reference Leg Purge Panel 'D' Operation	6
MAI-0504	Plant Instrument Calibration and Maintenance	11
NOBP-MS-2005	Nuclear Warehousing	7
NOP-LP-4003	Evaluation of Changes, Tests, and Experiments	7
NOP-LP-2020	Quality Control Receipt Inspection	17
NOP-OP-1002	Conduct of Operations	11
NOP-SS-3001	Procedure Review and Approval	20
NOP-TR-1280	FENOC Simulator Configuration Management	00
NOP-WM-4300	Order Execute Process	12
OAI-1703	Hardcards	25
ONI-B21-1	SRV Inadvertent Opening/Stuck Open	11
ONI-C51	Unplanned Change in Reactor Power or Reactivity	27
ONI-C51	Unplanned Change in Reactor Power or Reactivity (Flowchart)	L
ONI-C71-1	Reactor Scram	19
ONI-E12-2	Loss of Decay Heat Removal	33 and 35
ONI-SPI A-11	RHR A Shutdown Cooling Emergency Startup	0 and 1
ONI-SPI B-11	RHR B Shutdown Cooling Emergency Startup	0 and 1
PAP-0507	Perry Supplemental Procedure Requirements/Guidance	37
PEI-B13	RPV Control (Non-ATWS) Flowchart	L
PEI-B13	RPV Flooding Flowchart	J
PYBP-POS-0030	Transient Strategies and Mitigating Actions	2
SOI-E12 Section 4.7	RHR System-Section 4.7 <u>Shutdown Cooling Startup for RHR A(B)</u>	66
SOI-E12 Section 7.6	RHR System-Section 7.6 <u>RHR Shutdown Cooling Operations for RHR A(B)</u>	66
SOI-G40 (ADHR)	Alternate Decay Heat Removal	3
SOI-R42 (Div. 1)	Div 1 DC Distribution, Buses ED-1-A and ED-2-A, Batteries, Chargers, and Switchgear	LU 18
SOI-R43	Division 1 and 2 Diesel Generator System	45
SVI-B21-T2223	RPV Level Instrument Check Valve Operability Test	5
SVI-B22-T5069	Division 1 4.16KV Bus EH11 Degraded Voltage Channel Functional Test	4

DRAWINGS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
206-0010-00000	Main One Line Diagram 13.8KV & 4.16KV	CC

DRAWINGS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
206-0017-00000	One Line Diagram Class 1E 4.16KV Bus EH11 & EH12	EE
200-0021-00000	One Line Diagram Class 1E 480V Bus EF1A	SSSS
206-0023-00000	One Line Diagram Class 1E 480V Bus EF1B	UUU
206-0053-00000	One Line Diagram Class 1E 120V Panels EB-1A1, EK-A1	HH
208-0046-00412	Emergency Response Information System Analog Inputs to Cabinet 1H22-P111A, Rack 1, Card Slot 10	K
208-0055-00017	Residual Heat Removal System RHR Pump C002A	X
208-0060-00004	Low Pressure Core Spray System LPCS Pump C001	AA
208-0060-00008	Low Pressure Core Spray System Relay Logic & Testable Check Valve F006	EE
208-0131-00001	Pump Room Cooling System RCIC Pump Room Cooler 1M39-B004	T
208-0173-00001	Emergency Closed Cooling System Pump A-C001A	S
208-0176-00001	Emergency Service Water System "A" Emergency Service Water Pump C001A	FF
208-0176-00004	Emergency Service Water System "A" Emergency Service Water Pump Discharge Valve F130A	DD
208-0178-00001	Control Complex Chilled Water Control Complex Chiller "A"	Z
208-0206-00023	Metal-Clad Switchgear (15KV & 5KV) 4.16KV Bus EH11 Stub Bus Tie Breaker EH1101	M
208-0206-00024	Metal-Clad Switchgear (15KV & 5KV) 4.16KV Bus EH11 Diesel Breaker EH1102	BB
208-0206-00025	Metal-Clad Switchgear (15KV & 5KV) Transformer EHF-1-A Supply Breaker	R
208-0206-00026	Metal-Clad Switchgear (15KV & 5KV) Transformer EHF-1-B Supply Breaker EH1113	S
208-0206-00027	Metal-Clad Switchgear (15KV & 5KV) 4.16KV Bus EH11 Preferred Supply BKR. EH1114	EE
208-0206-00028	Metal-Clad Switchgear (15KV & 5KV) 4.16KV Bus EH11 ALT. Preferred Supply BKR. EH1115	W
208-0206-00029	Metal-Clad Switchgear (15KV & 5KV) 4.16KV Bus EH11 Stub Bus Tie Breaker	T
208-0206-00046	Metal-Clad Switchgear (15KV & 5KV) 4.16KV Bus EH11 Under Voltage & Potential Circuits	Z

DRAWINGS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
208-0206-00066	Metal-Clad Switchgear (15KV & 5KV) 4.16KV Bus EH11 Under Voltage & Potential Circuits (Cont'd)	P
208-0206-00068	Metal-Clad Switchgear (15KV & 5KV) LOOP Signal	X
208-0216-00005	Standby Diesel Engine Control Panel 1H51-P054A Division 1 1R43-C001A	FF
208-0216-00007	Standby Diesel Engine Control Panel 1H51-P054A Division 1 1R43-C001A	T
208-0222-00202	Control Room Annunciator Diesel Gen BB (1H13-PB77) Section 1A	P
208-0229-00003	Diesel Generator Jacket Water Jacket Water Heater 1R46-D006A	P
208-0230-00003	Diesel Generator Lube Oil Lube Oil Heater 1R47-D004A	P
209-0206-00016	Metal-Clad Switchgear (15KV & 5KV) (1R22-S007) Bus EH11 Compartments 03, 04 and 05	W
209-0206-00111	Metal-Clad Switchgear (15KV & 5KV) (1R22-S007) Bus EH11 Unit EH103 Internal Wiring	T
D-302-0606	Nuclear Boiler System	FF
D-302-0607	Nuclear Boiler System	K
D-302-0608	Nuclear Boiler System	M
D-814-0605-926	Panel 1H51-P1432B Charging Line for 1H22-P027 (A-2)	-
D-814-0605-927	Instrument Reference Leg Purge Control Panel 1H51-P1432B Reactor Vessel Level (1H22-P027)	A

WORK DOCUMENTS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
SWO 16-0002	Perform a Simulator to Plant Comparison Suppression Pool Heat up with 2 SRVs Open (SWR 16-0005; Dated 3/2/16)	3/3/16
WO 200261191	Division 1 4KV Bus EH11 Under Voltage/Degraded Voltage Channel Calibration and Logic System Functional Test	3/19/09
WO 200262844	Division Standby Diesel Generator Loss Of Offsite Power	4/11/09
WO 200557751	Division 1 4KV Bus EH11 Under Voltage/Degraded Voltage Channel Calibration and Logic System Functional Test	4/8/15
WO 200560619	SVI-B21-T2223	4/14/15
WO 200636975	Division 1 4.16KV Bus EH11 Degraded Voltage Channel Functional Test	10/28/15

WORK DOCUMENTS

<u>Number</u>	<u>Description or Title</u>	<u>Date or Revision</u>
WO 200636977	Division 1 4.16KV Bus EH11 Degraded Voltage Channel Functional Test	12/30/15
WO 200636977	Division 1 4.16KV Bus EH11 Degraded Voltage Channel Functional Test	12/30/15
WO 200673070	Perform IMI-E2-33	2/9/16
WO 200673137	Perform IMI-E2-56	2/10/16

LIST OF ACRONYMS USED

AC	Alternating Current
ACE	Apparent Cause Evaluation
ADAMS	Agencywide Document Access and Management System
ADS	Automatic Depressurization System
CFR	<i>Code of Federal Regulations</i>
CR	Condition Report
° F	Degrees Fahrenheit
EDG	Emergency Diesel Generator
EOP	Emergency Operating Procedure
EST	Eastern Standard Time
ESW	Emergency Service Water
gpm	Gallon Per Minutes
IEEE	Institute of Electrical and Electronics Engineers
IEL	Initiating Event Logic
IMC	Inspection Manual Chapter
IP	Inspection Procedure
LERF	Large Early Release Frequency
LLS	Low-Low Set
LOCA	Loss of Coolant Accident
NCV	Non-Cited Violation
NRC	U.S. Nuclear Regulatory Commission
PARS	Publicly Available Records System
psi	Pound Per Square Inch
PT	Potential Transformer
RAD	Regulatory Applicability Determination
RCA	Root Cause Analysis
RCS	Reactor Coolant System
RHR	Residual Heat Removal
RPV	Reactor Pressure Vessel
SDP	Significance Determination Process
SIT	Special Inspection Team
SPT	Suppression Pool Temperature
SRA	Senior Reactor Analyst
SRV	Safety Relief Valve
SSC	Structure, System or Component
USAR	Updated Safety Analysis Report
WO	Work Order



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
REGION III
2443 WARRENVILLE RD. SUITE 210
LISLE, IL 60532-4352

February 25, 2016

MEMORANDUM TO: William Schaup, Senior Resident Inspector
Clinton Power Station
Region III

FROM: Patrick L. Loudon, Director */RA/*
Division of Reactor Projects
Region III

SUBJECT: SPECIAL INSPECTION CHARTER FOR PERRY NUCLEAR
POWER PLANT SAFETY RELIEF VALVES ACTUATION, AND
LOSS OF DIVISION 1 SAFETY BUS AND SHUTDOWN
COOLING

On February 8, 2016, at 1500 EST, with the Perry Nuclear Power Plant at 100 percent power, two safety relief valves (SRVs) fully opened upon a spurious initiation signal. This caused the suppression pool temperature to increase. At 1503 EST, operators at the plant manually scrammed the reactor when the suppression pool temperature reached 95 degrees Fahrenheit in order to ensure margin to the heat capacity limit required for shutdown reactor safety by Technical Specifications. During the scram, all control rods fully inserted and all equipment functioned normally. The SRVs closed immediately following the scram.

Based on the licensee's troubleshooting activities, the opening of the SRVs was caused by perturbations within the "B" reactor pressure vessel reference leg. The licensee determined that the cause of the reference leg perturbation was air entrainment in the system from the CRD purge panel. The licensee staff also discovered through review of control room event sequence information that 18 of the 19 SRVs received an open signal via the Division 2 SRV initiation logic. In addition to the 2 SRVs fully opened, 11 additional SRVs partially opened as they showed momentary increases in tailpipe temperatures. The initiation of all SRVs based on the hydraulic upset of a single RPV reference leg during this event could in itself represent a single failure to a pseudo large break LOCA and could have generic implications.

Furthermore, at 1504 EST on February 11, 2016, with the plant shutdown, the Division 1, 4.16 kV safety bus (EH11) lost power. Division 1 shutdown cooling was in service at the time and the Division 1 shutdown cooling pump "A" tripped. The Division 1 emergency diesel generator (EDG) started and loaded EH11 as designed. However, the emergency service water (ESW) pump "A," which supplies cooling water to the EDG did not start. Due to the absence of cooling water to the EDG, operators took manual action to secure the Division 1 EDG.

The licensee discovered a failed fuse in the voltage sensing circuitry for safety bus EH-11 caused the bus supply breaker to trip. The licensee found intermittent continuity on the "A" phase secondary potential transformer fuse. The licensee's investigation determined that the

CONTACT: Billy Dickson, RIII/DRP
630-829-9827

Enclosure 4

intermittent continuity was caused by manufacturing defect. With an intermittent connection, half of the undervoltage relays would have sagged in voltage resulting in their coils dropping out and creating the loss of safety bus EH11. The same voltage sensing circuitry is used in the starting circuitry for the ESW pump "A." As a result, the ESW pump "A" would not start resulting in the emergency diesel generator not being able to complete its safety function.

The voltage sensing circuitry also prevented control of RHR Injection valve E12F0042A, and starting control of the RHR pump "A". It further prevented starting control of the low pressure core spray pump "A" and injection valve 1E21F0005. In addition, the emergency closed cooling water chiller "A" tripped and the starting circuitry, as designed, prevented the system breaker from reclosing for restart. Therefore, multiple systems failed as a result of this event.

Based on the deterministic criteria provided in Management Directive (MD) 8.3, "NRC Incident Investigation Program," the spurious opening of the SRV met MD 8.3, Criterion b, "Involved a major deficiency in design, construction, or operation having potential generic safety implications," and Criterion e, "Involved possible adverse generic implications." In addition, the loss of the safety bus and the subsequent loss of shutdown cooling met Criterion d, "Led to the loss of a safety function or multiple failures in systems used to mitigate an actual event," and Criterion g, "Involved repetitive failures or events involving safety-related equipment or deficiencies in operations." A Region III senior reactor analyst completed a modified Perry SPAR model event assessment to provide risk insights for the two events. The assessment resulted in a preliminary Incremental Conditional Core Damage Probability (ICCDP) value of approximately $5E-8$ to $4E-6$ for the spurious opening of the SRV event and $1E-6$ for the loss of AC.

Accordingly, based on the deterministic and risk criteria in MD 8.3, and as provided in Regional Procedure 8.31, "Special Inspections at Licensed Facility," a special inspection team will commence an inspection on February 29, 2016. The special inspection team will be led by you and will include Randy Baker, Ijaz Hafeez, and Josh Havertape from the Region III office.

The special inspection will determine the sequence of events and will evaluate the facts, circumstances, and the licensee's actions surrounding the two events. Additionally, the special inspection team will identify lessons learned from the Special Inspection and, as appropriate, prepare a feedback form on recommendations for improving reactor oversight process (ROP) baseline inspection procedures. Finally, the special inspection will continuously assess the need to upgrade NRC response to these events to an augmented inspection team level. The specific charter for the team is enclosed.

Enclosure:
Perry Nuclear Power Plant Special
Inspection Charter

PERRY NUCLEAR POWER PLANT SPECIAL INSPECTION CHARTER

This Special Inspection Team is chartered to assess the circumstances surrounding the manual trip of the unit following the opening of two safety relief valves on February 8, 2016 and the loss of the Division 1 4.16 kV safety bus and subsequent loss of the Division 1 shutdown cooling on February 11, 2016. The special inspection will be conducted in accordance with Inspection Procedure 93812, "Special Inspection," and will include, but not be limited to, the items listed below.

1. Identify a timeline for both events. Include relevant and major plant conditions, system lineups, and operator actions.
2. Review plant data and records to confirm the adequacy of the licensee's assessment of the cause of the scram of the reactor and the loss of the Division 1 4.16 kV safety bus EH-11.
3. Review the circumstances of the safety relief valves opening. Evaluate the design of the SRV and the pressure sensing circuitry contain as designed in the single reference leg to verify whether the single-failure criterion for initiation of a safety system is met. Verify that inadvertent actuation of all 19 SRVs was analyzed for acceptable safety consequences. Include a review of relevant portions of the Updated Final Safety Analysis Report that discuss inadvertent opening of a safety relief valve. Evaluate the design of the pressure relief valve circuitry and verify that the operation of the SRVs is consistent with the design.
4. Review and evaluate the suppression pool temperature response following the opening of the two safety relief valves. Following the opening of the two safety relief valves, suppression pool temperature increased to 95 degrees Fahrenheit. As required per licensee procedure, the operators manually scrammed the reactor at that temperature.
5. Review the licensee's evaluation of the failure of safety relief valve 41C to receive an open signal during the "B" reference leg upset condition.
6. Review the licensee's evaluation of the intermittent continuity on a control power fuse for "A" Phase. Evaluate whether the licensee's maintenance and testing program contributed to the installation of the faulty control power fuse and/or to the continued use of the defective fuse. Verify the design of the potential transformer (PT) for the undervoltage signal. Verify the adequacy of the design of the PT and fuse(s) considering its ability to cause a loss of both the plant's offsite Division 1 AC source and its onsite Division 1 AC sources.
7. Based upon the licensee's initial inability to locate where the other 15 AMP, Ferraz Shawmut fuses purchased from the vendor were installed in the plant, evaluate the licensee's ability to verify plant configuration against their own standards and regulatory requirements. Evaluate the licensee's plans to address plant configuration control and/or extent of condition.
8. Review the operators' performance following the loss of shutdown cooling, including the subsequent restoration of shutdown cooling. Include an evaluation of the impact of any impediments encountered due to equipment reliability issues. Additionally, validate the temperature trend and heatup rate reported by the licensee.

9. Relative to the loss of the Division 1 4.16 kV safety bus, determine if the licensee performed an adequate extent-of-condition evaluation to assess if the contributing causes to the continuity of the control power fuse have the potential to affect other safety-related structures, systems or components.
10. Review status and performance of the licensee's safety-related battery charger, prior to, during and following the loss of the Division 1 4.16 kV safety bus. Include the licensee actions of declaring the station battery chargers operable. During the loss of Division 1 4.16 kV safety bus, Division 2 battery charger was out of service due to planned maintenance. For some time following the event, both safety-related Division 1 and Division 2 batteries were discharging.

Charter Approval

_____/RA/

Billy C. Dickson, Chief, Branch 5, DRP

_____/RA/

Patrick L. Loudon, Director, DRP

intermittent continuity was caused by manufacturing defect. With an intermittent connection, half of the undervoltage relays would have sagged in voltage resulting in their coils dropping out and creating the loss of safety bus EH11. The same voltage sensing circuitry is used in the starting circuitry for the ESW pump "A." As a result, the ESW pump "A" would not start resulting in the emergency diesel generator not being able to complete its safety function.

The voltage sensing circuitry also prevented control of RHR Injection valve E12F0042A, and starting control of the RHR pump "A". It further prevented starting control of the low pressure core spray pump "A" and injection valve 1E21F0005. In addition, the emergency closed cooling water chiller "A" tripped and the starting circuitry, as designed, prevented the system breaker from reclosing for restart. Therefore, multiple systems failed as a result of this event.

Based on the deterministic criteria provided in Management Directive (MD) 8.3, "NRC Incident Investigation Program," the spurious opening of the SRV met MD 8.3, Criterion b, "Involved a major deficiency in design, construction, or operation having potential generic safety implications," and Criterion e, "Involved possible adverse generic implications." In addition, the loss of the safety bus and the subsequent loss of shutdown cooling met Criterion d, "Led to the loss of a safety function or multiple failures in systems used to mitigate an actual event," and Criterion g, "Involved repetitive failures or events involving safety-related equipment or deficiencies in operations." A Region III senior reactor analyst completed a modified Perry SPAR model event assessment to provide risk insights for the two events. The assessment resulted in a preliminary Incremental Conditional Core Damage Probability (ICCDP) value of approximately 5E-8 to 4E-6 for the spurious opening of the SRV event and 1E-6 for the loss of AC.

Accordingly, based on the deterministic and risk criteria in MD 8.3, and as provided in Regional Procedure 8.31, "Special Inspections at Licensed Facility," a special inspection team will commence an inspection on February 29, 2016. The special inspection team will be led by you and will include Randy Baker, Ijaz Hafeez, and Josh Havertape from the Region III office.

The special inspection will determine the sequence of events and will evaluate the facts, circumstances, and the licensee's actions surrounding the two events. Additionally, the special inspection team will identify lessons learned from the Special Inspection and, as appropriate, prepare a feedback form on recommendations for improving reactor oversight process (ROP) baseline inspection procedures. Finally, the special inspection will continuously assess the need to upgrade NRC response to these events to an augmented inspection team level. The specific charter for the team is enclosed.

Enclosure:
Perry Nuclear Power Plant Special
Inspection Charter

ADAMS Accession Number: ML16057A039

☐ Publicly Available ☒ Non-Publicly Available ☐ Sensitive ☒ Non-Sensitive

OFFICE	RIII	RIII		RIII
NAME	BDickson:mz	PLouden		
DATE	02/24/16	02/25/16		

OFFICIAL RECORD COPY

Memo to William Schaup from Patrick L. Loudon dated February 25, 2016

SUBJECT: SPECIAL INSPECTION CHARTER FOR PERRY NUCLEAR POWER PLANT
SAFETY RELIEF VALVES ACTUATION, AND LOSS OF DIVISION 1 SAFETY BUS AND
SHUTDOWN COOLING

DISTRIBUTION:

Kimyata MorganButler
Michael Johnson
Michael Scott
Joseph Colaccino
Raymond Lorson
Brian Smith
Joel Munday
Mark Franke
Tony Gody
Mark Miller
Patrick Loudon
Julio Lara
Kenneth OBrien
Mohammed Shuaibi
Troy Pruett
Ryan Lantz
Anton Vogel
Jeff Clark
AnnMarie Stone
Doris Chyu
Nicholas Valos
Laura Kozak
NRR_Reactive_Inspection.Resource
Cynthia Pederson
Darrell Roberts
Harral Logaras
Allan Barker
Michael Johnson
William Schaup
Josh Havertape
Randy Baker
Ijaz Hafeez
RidsNrrPMPerry Resource

Event Timeline

Perry Nuclear Power Plant Spurious SRV Opening Timeline

<u>DATE</u>	<u>TIME</u>	<u>EVENT</u>	<u>SOURCE</u>
2/8/2016	1500	<ul style="list-style-type: none"> While at 100% power, spurious safety relief valve open signal was received to 18 of 19 SRVs. 	Plant narrative logs CR 2016-02011, 1B21N0062B pressure spike for 10 milliseconds CR 2016-01883, SRV 1B21F0041C is the only SRV that did not get an open signal CR 2016-01983, Post event critique ops crew 2 SRV opening event and manual reactor SCRAM
		<ul style="list-style-type: none"> 13 SRVs opened, 11 immediately closed. Two SRVs, 1B21F0051C and 1B21F0051D, remained open until 1503. 	
		<ul style="list-style-type: none"> Immediate actions taken per ONI-B21, SRV Inadvertent opening, to lower power to < 96% commences. Initial suppression pool temperature is 79° [F]. 	
2/8/2016	1503	<ul style="list-style-type: none"> Suppression pool temperature rises to 95° [F]. Manual SCRAM initiated per OAI-1703, margins and limits hard card, which directs a reactor SCRAM with two open SRVs if suppression pool temperature reaches 95° [F]. 	Plant narrative logs CR 2016-01865, Perry plant was manually scrammed following SRV actuation CR 2016-01866, Manual reactor SCRAM based on suppression pool temperature of 95 degrees F due to open SRVs SCRAM 1-16-02
		<ul style="list-style-type: none"> Unit supervisor entered ONI-C71, reactor SCRAM. 	
		<ul style="list-style-type: none"> SRVs 1B21F0051C and 1B21F0051D closed following the reactor SCRAM. RPV pressure lowering below the low-low set reset closure set points. 	
2/8/2016	1504	<ul style="list-style-type: none"> Completed immediate actions per ONI-B21, SRV Inadvertent Opening, to place the key lock switches in the closed position for SRVs 1B21F0051C and 1B21F0051D. 	Plant narrative logs

2/8/2016	1505	<ul style="list-style-type: none"> EOP-02 entered for high suppression pool temperature greater than 95° [F]. 	Plant narrative logs
2/8/2016	1514	<ul style="list-style-type: none"> Reactor SCRAM reset per SOI-C71 	Plant narrative logs
2/8/2016	1516	<ul style="list-style-type: none"> RHR 'A' placed in suppression pool cooling mode of operation. 	Plant narrative logs
2/8/2016	1521	<ul style="list-style-type: none"> RHR 'B' placed in suppression pool cooling mode of operation. 	Plant narrative logs
2/8/2016	1536	<ul style="list-style-type: none"> RHR 'B' secured from suppression pool cooling mode of operation. 	Plant narrative logs
2/8/2016	1557	<ul style="list-style-type: none"> Exited EOP-02 following action to lower suppression pool temperature to below 95° [F]. 	Plant narrative logs
2/8/2016	1611	<ul style="list-style-type: none"> RHR 'A' shutdown to standby, average suppression pool temperature is 83° [F]. 	Plant narrative logs
2/8/2016	1750	<ul style="list-style-type: none"> Report made under 10 CFR 50.72(b)(2)(iv)(B) for an RPS actuation while critical. 	Plant narrative logs EN 51716
2/8/2016	1832	<ul style="list-style-type: none"> Forced cool down commenced per IOI-005, Maintaining Hot Shutdown. 	Plant narrative logs
2/8/2016	1900	<ul style="list-style-type: none"> ONI-C71, Reactor Scram, exited. 	Plant narrative logs

Perry Nuclear Power Plant Loss of Safety Bus and SDC

<u>DATE</u>	<u>TIME</u>	<u>EVENT</u>	<u>SOURCE</u>
2/11/2016	1504	<ul style="list-style-type: none"> While in Mode 4 with Division I shutdown cooling (SDC) in service, the 'A' phase PT secondary fuse failed. This caused sensed voltage on the Division I 4.16kV safety bus, EH11, to indicate 1.14kV. 	Plant narrative logs CR 2016-02070, Defect found with the 'A' phase secondary PT fuse
		<ul style="list-style-type: none"> Breaker EH1115, the source to the EH11 bus, opened automatically to isolate the offsite supply. As a result, EH11 was de-energized. 	CR EH1103 fuse had inconsistent resistance readings
		<ul style="list-style-type: none"> Unit supervisor entered ONI-R12-2, loss of decay heat removal, and ONI-R22-1, loss of an essential bus. 	CR 2016-02048, Loss of EH11 divisional bus results in a loss of shutdown cooling
		<ul style="list-style-type: none"> Division I SDC was lost because RHR pump 'A' tripped on an under voltage condition. Initial reactor coolant temperature was 87° [F], reactor coolant temperature begins to increase. 	CR 2016-02093, NOBP-TR-1151 crew performance critique for loss of bus EH11 and loss of shutdown cooling
		<ul style="list-style-type: none"> The Division I emergency diesel generator (EDG) started, came up to rated speed and voltage, and the output breaker closed. Sensed EH11 bus voltage again read 1.12kV. 	CR 2016-02051, Emergency service water pump 'A' failed to start on automatic start signal
		<ul style="list-style-type: none"> Emergency service water (ESW) pump 'A', which supplies the cooling water to the Division I EDG, did not start as expected due to low sensed bus voltage on EH11. 	CR 2016-02052, Unplanned change in shutdown safety risk from green to yellow
2/11/2016	1506	<ul style="list-style-type: none"> Due to the absence of cooling water to the EDG, operators took manual action to secure the EDG. 	Plant narrative logs CR 2016-02049, Division 1 EDG ran approximately 3 minutes without ESW cooling
2/11/2016	1507	<ul style="list-style-type: none"> Preparation for shifting to Division II SDC was commenced. 	Plant narrative logs

<u>DATE</u>	<u>TIME</u>	<u>EVENT</u>	<u>SOURCE</u>
2/11/2016	1544	<ul style="list-style-type: none"> RHR pump 'B' is started, establishing Division II SDC. 	Plant narrative logs
		<ul style="list-style-type: none"> Reactor coolant temperature rise is arrested, temperature rose from approximately 87° [F] to 115° [F]. 	
2/11/2016	1938	<ul style="list-style-type: none"> Report made under 10 CFR 50.72(b)(3)(iv)(A) for a specific system actuation. 	Plant narrative logs EN 51729
2/12/2016	0032	<ul style="list-style-type: none"> EH11 re-energized per ONI-R22-1, Loss of an essential and/or a stub 4.16kV bus. 	Plant narrative logs
2/12/2016	0125	<ul style="list-style-type: none"> Division I ESW pump placed in standby. 	Plant narrative logs
2/12/2016	0948	<ul style="list-style-type: none"> RHR pump 'A' available for SDC following completion of fill and vent activities. 	Plant narrative logs
2/12/2016	1155	<ul style="list-style-type: none"> Division I EDG is operable and available following maintenance run. 	Plant narrative logs
2/12/2016	1300	<ul style="list-style-type: none"> Unit supervisor exits ONI-R12-2 and ONI-R22-1. 	Plant narrative logs
2/12/2016	1311	<ul style="list-style-type: none"> RHR pump 'A' operable and available following valve testing. 	Plant narrative logs