

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

COMO Tech Inspection, Inc.
27640 West 83rd Street
Lenexa, Kansas 66227

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Blvd
Arlington, Texas 76011-4511

REPORT NO: 2016-001

3. DOCKET NUMBER

030-30996

4. LICENSE NUMBER

15-26978-01

5. DATE OF INSPECTION

April 13, 2016

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- ☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 34.20(c)(3) states, in part, that the outlet fittings on each radiographic exposure device must be equipped with safety plugs which must be installed during storage and transportation.

for April 13, 2016
Contrary to this requirement, COMO Tech Inspection, Inc. transported a radiography camera and radioactive source without the safety plugs installed on the outlet fittings. Specifically, on April 13, 2016, the radiography camera and source were transported to a job site with the drive cable and crankout assembly attached to the SPEC-150 camera instead of the having the outlet fitting safety plugs in place. The licensee immediately corrected the condition and committed to transport of the material in accordance with the requirements.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Raymond E. Hiersche Jr	<i>Raymond E. Hiersche Jr</i>	4/27/16
NRC INSPECTOR	Donald Stearns	<i>Donald L Stearns</i>	4/27/16
BRANCH CHIEF	<i>Rag Heller</i>	<i>Rag Heller</i>	5/23/16

☐ Non-Public ☐ Sensitive in Security-Related

☒ Public

☒ Non-Sensitive

For 1913, 1914, 1915

1913

1914

1915

Stearns, Don

From: Stearns, Don
Sent: Wednesday, April 27, 2016 10:15 AM
To: 'raycti2000@aol.com'
Subject: Inspection Report
Attachments: COMO Tech.pdf

Mr. Hiersche; attached is the inspection report from my inspection conducted April 13, 2016. Please print your name, sign, and date in the blocks marked "Licensee's Representative" and return the document to me. This is considered a Severity Level IV violation, and since you have corrected the condition, no further response other than your signature on the report will be required.

Thank you for your time and cooperation during the inspection

Don Stearns
USNRC Region IV
817-200-1176