

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Professional Services Industries, Inc.
1901 South Meyers Road, Suite 400
Oakbrook Terrace, IL 60181
Location Inspected: Carolina, Puerto Rico

REPORT NUMBER(S) 2016002

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-11906

4. LICENSE NUMBER(S)

12-16941-01

5. DATE(S) OF INSPECTION

June 8, 2016

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Randolph Ragland, Senior HP (Region I)	<i>Def. Caffrey</i> FOR RR	6/20/16
BRANCH CHIEF	<i>Amos T. McCar</i>	<i>[Signature]</i>	6/24/16

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Professional Services Industries, Inc. 1901 South Meyers Road, Suite 400 Oakbrook Terrace, IL 60181 Location Inspected: Carolina, Puerto Rico REPORT NUMBER(S) 2016002	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-11906	4. LICENSE NUMBER(S) 12-16941-01	5. DATE(S) OF INSPECTION June 8, 2016
6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01 - 03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Pilar Ocampo, Rad Safety Contact	4. TELEPHONE NUMBER (954) 639-1695
---------------------------------	----------------------	---	---

☐ Main Office Inspection Next Inspection Date: No Change

☒ Field Office Inspection Mini Warehouse, Carolina, PR

☐ Temporary Job Site Inspection

PROGRAM SCOPE

This was a field office inspection of a consulting engineering and testing firm authorized to possess various portable gauging devices at numerous field offices, and to use those devices at temporary job sites, within NRC jurisdiction. The licensee possessed one Troxler 3430 portable moisture density gauge in Puerto Rico and stored it at a Mini Warehouse (storage unit no. 5818) in Carolina, PR. GPS Coordinates: N 18.418928, W 65.984676.

The licensee had not used the gauge since October 2015, and the frequency of work rose and fell with economic conditions in Puerto Rico. The site Radiation Safety contact was the only authorized gauge user, although the licensee intended to hire more people as necessary if the workload increased.

PERFORMANCE OBSERVATIONS

A review of records showed that the licensee had current leak test results, inventory records, utilization log, dosimetry records, annual program review, radiological postings, operating and emergency procedures, shipping papers, and transportation emergency response information. The licensee also utilized a minimum of two tangible barriers to secure the gauge. The inspector was unable to observe the conduct of any licensed activities, as no work was scheduled or in progress during the inspection. Instead, the Radiation Safety contact demonstrated use of the gauge to the inspector, who found the site Radiation Safety contact to be knowledgeable of radiation safety and security measures for the gauge.

No violations of NRC requirements were identified as a result of this inspection.