



Dennis R. Madison  
Vice President – Plant Farley

Southern Nuclear  
Operating Company  
Farley Nuclear Plant  
Post Office Drawer 470  
Ashford, AL 36312

Tel 334.814.4511  
Fax 334.814.4575

January 23, 2017

Docket Nos.: 50-348

NL-17-0005

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant – Unit 1  
Licensee Event Report 2016-008-00  
Manual Reactor Trip Due to Generator Voltage Swings

Ladies and Gentlemen:

This Licensee Event Report is being submitted pursuant to the requirements of the Code of Federal Regulations, 10 CFR 50.73(a)(2)(iv)(A) for a manual actuation of the Reactor Protection System and automatic start of the Auxiliary Feedwater system.

This letter contains no NRC commitments. If you have any questions regarding the submittal, please contact Ms. Julie Collier at (334) 814-4639.

Respectively submitted,

Mr. D. R. Madison  
Vice President – Farley

DRM/JAC

Enclosure: Unit 1 Licensee Event Report 2016-008-00

cc: Southern Nuclear Operating Company

Mr. S. E. Kuczynski, Chairman, President & CEO  
Mr. D. G. Bost, Executive Vice President & Chief Nuclear Officer  
Mr. M. D. Meier, Vice President – Regulatory Affairs  
Mr. B. J. Adams, Vice President – Engineering  
Mr. R.D. Gayheart – Fleet Operations General Manager  
Mr. C. R. Pierce, Regulatory Affairs Director  
Ms. B. L. Taylor, Regulatory Affairs Manager – Farley  
Mr. K. D. Miller, Operating Experience Coordinator - Farley  
RTYPE: CFA04.054

U. S. Nuclear Regulatory Commission

Ms. C. Haney, Regional Administrator  
Mr. S. A. Williams, NRR Project Manager - Farley  
Mr. P. K. Niebaum, Senior Resident Inspector - Farley

Joseph M. Farley Nuclear Plant – Unit 1  
Unit 1 Licensee Event Report 2016-008-00

Manual Reactor Trip Due to Generator Voltage Swings



## LICENSEE EVENT REPORT (LER)

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to Infocollections.Resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME		2. DOCKET NUMBER		3. PAGE	
Joseph M. Farley Nuclear Plant, Unit 1		05000 - 348		1 of 3	

## 4. TITLE

Manual Reactor Trip Due to Generator Voltage Swings

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	27	2016	2016	008	00	1	23	2017	FACILITY NAME	DOCKET NUMBER

9. OPERATING MODE	1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)							
		<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)				
		<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)				
		<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)				
10. POWER LEVEL	100	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input checked="" type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)				
		<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)				
		<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)				
		<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> 73.77(a)(1)				
		<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> 73.77(a)(2)(i)				
		<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input type="checkbox"/> 50.73(a)(2)(vii)	<input type="checkbox"/> 73.77(a)(2)(ii)				
		<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> OTHER Specify in Abstract below or in NRC Form 366A						

## 12. LICENSEE CONTACT FOR THIS LER

LICENSEE CONTACT	TELEPHONE NUMBER (Include Area Code)
Julie Collier, Licensing Engineer	334-814-4639

## 13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
E	EL	TD	C770	Y					

14. SUPPLEMENTAL REPORT EXPECTED	<input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE	MONTH	DAY	YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On 11/26/16 at 2357 while Unit 1 was operating at 100 percent reactor power the main generator began to experience voltage and load swings, which were caused by a problem with the main generator. The unit was manually tripped at 0026 on 11/27/16 to protect the generator from potential damage. All control rods fully inserted and Auxiliary Feedwater (AFW) auto-started as expected. The Turbine Driven AFW (TDAFW) was secured at 0037, with Motor Driven AFW pumps continuing to provide flow to ensure adequate heat sink. The TDAFW auto-started a second time at 0041 on a valid actuation signal when Steam Generator levels decreased to the TDAFW actuation setpoint. The TDAFW system was secured a second time at 0047. This event is reportable per 10 CFR 50.73(a)(2)(iv)(A) due to actuation of the reactor protection system and an automatic actuation of the AFW system.

The swings were caused by an intermittent failure of the voltage isolation transducer. The voltage isolation transducer was replaced prior to the plant restarting. The transducer module is being sent off for failure analysis to aid in determination of the cause of this failure.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to [Infocollects.Resource@nrc.gov](mailto:Infocollects.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Joseph M. Farley Nuclear Plant, Unit 1	05000- 348	YEAR	SEQUENTIAL NUMBER	REV NO
		2016	- 008 -	00

**NARRATIVE****A. PLANT AND SYSTEM IDENTIFICATION**

Westinghouse - Pressurized Water Reactor

**B. DESCRIPTION OF EVENT**

On 11/26/16 at 2357 while operating at 100 percent reactor power it was discovered that the Unit 1 main generator [GEN] was experiencing swings in voltage, amps, megawatts, megavars, and speed. The utility's control center assured the control room that the disturbance was emanating from plant Farley. The Power System Stabilizer (PSS) [RG] for the main generator was showing indications of the swings and was in alarm. At 0026 on 11/27/16 the unit was manually tripped to protect the generator from potential damage. All control rods fully inserted.

The voltage isolation transducer [TD] takes input from the system and uses this signal as an input to the exciter voltage regulator. Review of video taken during the event showed that the gage that reads the output of this isolation transducer was reading zero during the event instead of tracking properly. This was not repeated during troubleshooting, and an intermittent failure of the component was determined to be the cause of the voltage and load swings.

A valid AFW actuation signal started the 1A and 1B Motor Driven AFW (MDAFW) [BA] system and the Turbine Driven AFW system (TDAFW) [BA] at 0026. At 0037, steam generator [SG] levels were above the TDAFW actuation setpoint and the pump was secured. AFW flow was maintained using MDAFW [BA] to ensure an adequate heat sink per plant procedures, but the SG levels decreased to the TDAFW actuation setpoint at 0041. This was a valid actuation signal and the TDAFW system started a second time. This second start was attributed to TDAFW having been secured with little margin in steam generator narrow range levels in an effort to minimize reactor coolant system [AB] cool down and prevent manual closure of main steam isolation valves [ISV]. The TDAFW system was secured a second time at 0047.

**C. UNIT STATUS AT TIME OF EVENT**

Mode 1, 100 percent power

**D. CAUSE OF EVENT**

The cause of the voltage and load swings was an intermittent failure of the voltage isolation transducer.

**E. REPORTABILITY ANALYSIS AND SAFETY ASSESSMENT**

This event is reportable as required by 10 CFR 50.73(a)(2)(iv)(A) due to a manual actuation of the reactor protection system and automatic actuation of the AFW system. The reactor was shut down at 0026 and entered Mode 3. There was no loss of safety function and no radioactive release associated with this event. All required safety systems were available and responded as expected. There were no actual consequences detrimental to the health and safety of the public and the event is considered to be of very low safety significance.

**LICENSEE EVENT REPORT (LER)  
CONTINUATION SHEET**

Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA, Privacy and Information Collections Branch (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by Internet e-mail to [infocollections.Resource@nrc.gov](mailto:infocollections.Resource@nrc.gov), and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.

1. FACILITY NAME	2. DOCKET NUMBER	3. LER NUMBER		
Joseph M. Farley Nuclear Plant, Unit 1	05000- 348	YEAR	SEQUENTIAL NUMBER	REV NO.
		2016	- 008 -	00

**NARRATIVE****F. CORRECTIVE ACTION**

The voltage isolation transducer was replaced prior to the plant restarting. The transducer module is being sent off for failure analysis to confirm the cause of this failure.

**G. ADDITIONAL INFORMATION**

- 1) Previous Similar Events: No other similar previous events have been reported.
- 2) Commitment Information: This report does not create any licensing commitments