



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
ADVISORY COMMITTEE ON REACTOR SAFEGUARDS  
WASHINGTON, DC 20555 - 0001**

January 30, 2017

MEMORANDUM TO:           ACRS Members

FROM:                   Christopher L. Brown, Senior Staff Engineer */RA/*  
                              Technical Support Branch  
                              Advisory Committee on Reactor Safeguards

SUBJECT:                CERTIFICATION OF THE MINUTES OF THE ACRS  
                              METALLURGY AND REACTOR FUELS SUBCOMMITTEE  
                              MEETING ON NOVEMBER 16, 2016, IN ROCKVILLE,  
                              MARYLAND

The minutes for the subject meeting were certified on December 30, 2016. Along with the transcripts and presentation materials, this is the official record of the proceedings of that meeting. A copy of the certified minutes is attached.

Attachment: As stated

cc with Attachment: A. Veil  
                              M. Banks



**UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
ADVISORY COMMITTEE ON REACTOR SAFEGUARDS  
WASHINGTON, DC 20555 - 0001**

MEMORANDUM TO: Christopher Brown, Senior Staff Engineer  
Technical Support Branch  
Advisory Committee on Reactor Safeguards

FROM: Matthew Sunseri, Chairman  
Metallurgy & Reactor Fuels Subcommittee

SUBJECT: CERTIFICATION OF THE MINUTES OF THE ACRS  
METALLURGY AND REACTOR FUELS SUBCOMMITTEE  
MEETING ON NOVEMBER 16, 2016, IN ROCKVILLE,  
MARYLAND

I hereby certify, to the best of my knowledge and belief, that the minutes of the subject meeting on November 16, 2016, are an accurate record of the proceedings for that meeting.

**/RA/**

**December 30, 2016**

---

Matthew Sunseri, Chairman  
Metallurgy & Reactor  
Fuels Subcommittee

Dated

**Advisory Committee on Reactor Safeguards**  
**Meeting of the Subcommittee on Metallurgy & Reactor Fuels**  
Rockville, MD

**Recent Operating Experience with Baffle Bolt Degradation**  
November 16, 2016

The ACRS Metallurgy, and Reactor Fuels Subcommittee held a meeting on November 16, 2016, in T2B1, 11545 Rockville Pike, Rockville, MD. The meeting convened at 8:30 a.m. and adjourned at 11:55 a.m.

**ATTENDEES**

**ACRS Members/Staff**

Matt Sunseri, Chairman for this SC	Gordon Skillman, Member
Pete Riccardella, Member	John Stetkar, Member
Dana Powers, Member	Ron Ballinger, Member
Walt Kirchner, Member	

Christopher Brown, Designated Federal Official

Jeffrey Pohler, NRR  
William Burton, NRR  
CJ Fong, NRR  
Allen Hiser, NRR  
Dian Curran, Riverkeeper  
Carol Nove, RES

**SUMMARY**

The Subcommittee received an information briefing from the staff on baffle bolt degradation and recent events. Industry discussed recent actions taking on the issue. Baffle bolts affix a set of baffle plates to the reactor core barrel via a series of baffle former plates. The baffle plates provide the radial geometry of the reactor core.. Flow holes between the baffle former plates and the core barrel are designed to allow coolant flow in an upward direction (up-flow) or a downward direction (down-flow).

The meeting transcript and slides are attached and contains an accurate description of each matter discussed during the meeting.

DISCUSSION ISSUES	
Issue	Reference Pages in Transcript
1. Discussion on the design, functions and materials of PWR internals, baffle-former assembly, and baffle-former bolts. The following points /questions were raised: 1) failure history, 2) differences material type 347 and material type 316 bolt failure, 3) geometry of the bolts.	8 - 17
2. Discussion on the potential consequences of baffle former bolt degradation. Function of baffle-edge bolts is to ensure baffle plate integrity and reduce baffle jetting. The following points /questions were raised: 1) failure of the edge bolts, and 2) stuck fuel assembly, distinguishing between up-flow and down-flow plants.	17 - 22
3. Discussions on history of baffle bolt degradation.	22 - 23
4. Discussion on US plant inspections. Two two-loop down-flow plants. Question was raised on B&W plants (up-flow).	23 - 24
5. Discussions on MRP-227-A inspection requirements for baffle-former Bolts. D.C Cook, unit 2 was discussed.	24 - 28
6. Discussion of Inspections under MRP-227-A (2011-2015).	28 - 29
7. Review of Indian Point, Unit 2, Salem Unit 1, D.C. Cook, Unit 2 degradation and corrective actions. The following points /questions were raised: 1) reasoning for not using L grade stainless steel, 2) fracture morphology, 3) damage to a fuel assembly, and 4) more on baffle jetting.	30 - 48
8. Discussion on factors influencing baffle-former bolt degradation, such as, neutron fluence, stress, down-flow versus up-flow plants, and bolt failure clustering. The following points /questions were raised: 1) manufacturing issues, 2) lubrication, types of bolt threads, 3) plugging of core barrel holes, and 4) clustering degradation plant comparison.	48 - 64
9. Discussion on bolt inspection, replacement, evaluation and re-inspection intervals.	65 - 70
10. NRC response to baffle bolt degradation. Regional inspections at plants. Questions was raised concerning a specific inspection procedure for baffle-former bolts.	70 - 75
11. Discussion on the risk informed evaluation conducted by the staff. Risk criteria of $CDF < 1 \times 10^{-3}$ and $LERF < 1 \times 10^{-4}$ . Question was raised on the CDF and a LERF analysis.	75 - 85
12. Staff summary and future activities	85 – 87
13. Industry presented perspectives on U.S. plants operating experience and MRP 227 guidance. Questions was raised on an EDF (French)	88 - 105

operating experience and metallurgical difference in between U.S. and French bolts.	
14. Discussions on UT and PT indications, technique for examinations of bolts and plant design.	106 - 115
15. Further discussion on examinations of bolts and the Westinghouse Nuclear Safety Advisory Letter.	115 119
16. Discussion on factors influencing baffle-former bolt degradation (i.e., fluence, stress, material, time, plant design, and bolt design. Also, a discussion of failure patterns, i.e. clustering of bolt failures.	120 - 130
17. Industry communication and Westinghouse replacement bolts.	132 - 137
18. Public comments.	137 - 140
19. Roundtable Member comments and questions.	140 - 143

# **Official Transcript of Proceedings**

## **NUCLEAR REGULATORY COMMISSION**

Title:                   Advisory Committee on Reactor Safeguards  
                              Metallurgy and Reactor Fuels Subcommittee

Docket Number:     (n/a)

Location:             Rockville, Maryland

Date:                  Wednesday, November 16, 2016

Work Order No.:     NRC-2737

Pages 1-136

NEAL R. GROSS AND CO., INC.  
Court Reporters and Transcribers  
1323 Rhode Island Avenue, N.W.  
Washington, D.C. 20005  
(202) 234-4433

UNITED STATES OF AMERICA  
 NUCLEAR REGULATORY COMMISSION

+ + + + +

ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

(ACRS)

+ + + + +

SUBCOMMITTEE ON METALLURGY AND REACTOR FUELS

+ + + + +

WEDNESDAY

NOVEMBER 16, 2016

+ + + + +

ROCKVILLE, MARYLAND

+ + + + +

The Subcommittee met at the Nuclear  
 Regulatory Commission, Two White Flint North, Room  
 T2B1, 11545 Rockville Pike, at 8:30 a.m., Matthew  
 Sunseri, Chairman, presiding.

COMMITTEE MEMBERS:

MATTHEW W. SUNSERI, Chairman

RONALD G. BALLINGER, Member

WALTER L. KIRCHNER, Member

DANA A. POWERS, Member

PETER RICCARDELLA, Member

GORDON R. SKILLMAN, Member

JOHN W. STETKAR, Member

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
 1323 RHODE ISLAND AVE., N.W.  
 WASHINGTON, D.C. 20005-3701

## DESIGNATED FEDERAL OFFICIAL:

CHRIS BROWN

## ALSO PRESENT:

PAUL BESSETTE, Morgan Lewis

WILLIAM BURTON, NRR

GANESH CHERUVENKI, NRR

DIANE CURRAN, Riverkeeper

DAVID DIJAMCO, NRR

C.J. FONG, NRR

ALLEN HISER, NRR

MATTHEW HISER, RES

GREGORY KOLCUM, R-IV

MARVIN LEWIS (present via telephone)

SIVA LINGAM, NRR

HEATHER MALIKOWSKI, Exelon

CAROL NOVE, RES

JEFFREY POEHLER, NRR

MARY JANE ROSS-LEE, NRR

BERNIE RUDELL, Exelon

DAVID RUDLAND, NRR

BALWANT SINGAL, NRR

DONG WEAVER, Westinghouse

BRYAN WILSON, Westinghouse

**NEAL R. GROSS**COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

## TABLE OF CONTENTS

Opening Remarks and Objectives,	
Matt Sunseri, ACRS.....	4
Staff Opening Remarks, Mary Jane Ross-Lee, Deputy	
Director, NRR/DE.....	6
NRC Presentation on Baffle-Former Bolt	
Degradation, Jeffrey Poehler, NRR/DE/EVIB....	7
Industry Presentation on Baffle-Former Bolt	
Degradation, Heather Malikowski, Exelon/	
EPRI MRP; Bryan Wilson,	
Westinghouse/PWROG.....	84
Public Comments.....	130
Committee Discussion.....	130
Adjourn.....	136

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

## P R O C E E D I N G S

8:31 a.m.

CHAIRMAN SUNSERI: The meeting is now called to order. This is a meeting of the Metallurgy and Reactor Fuel Subcommittee, the Advisory Committee on Reactor Safeguards.

I am Matt Sunseri, chairman for this subcommittee.

ACRS members in attendance today are Ron Ballinger, Pete Riccardella, Dick Skillman, Dana Powers, John Stetkar, Walt Kirchner.

Christopher Brown is the Designated Federal Official for this meeting.

The purpose of today's meeting is for the subcommittee to receive a briefing from the NRC staff and industry regarding recent operating experience with baffle-former bolt degradation. In particular, discussions on the design, functions and materials of PWR internals, baffle-former assembly, consequences of baffle-former bolt degradation, history of baffle-former bolt degradation, factors influencing baffle-former bolt degradation, bolt inspection replacement, root cause analysis results and industry response.

The rules for participation in today's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

(202) 234-4433

(202) 234-4433

1 meeting were announced in the Federal Register on  
2 November 1, 2016. The meeting was announced as an  
3 open/closed to public. A portion of this meeting  
4 will be closed in order, may be closed in order to  
5 discuss and protect information designated as  
6 proprietary pursuant to 5 U.S.C. 552b(c)(4).

7 No requests for making a statement to  
8 the subcommittee has been received from the public.

9 A transcript of the meeting is being  
10 kept and will be made available as stated in the  
11 Federal Register notice. Therefore, we request  
12 that participants in this meeting use the  
13 microphones located throughout the meeting room  
14 when addressing the subcommittee. Participants  
15 should first identify themselves and speak with  
16 sufficient clarity and volume so that they can be  
17 readily heard.

18 We have one bridge line established for  
19 interested members of the public to listen in. The  
20 bridge number and password were published in the  
21 agenda posted on the NRC public website.

22 To minimize disturbance, this public  
23 line will be kept in a listen-in only mode. The  
24 public will have the opportunity to make a  
25 statement or provide comments at a designated time

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       towards the end of the meeting.

2               I request that meeting attendees and  
3 participants now silence their cell phones and  
4 other electronic devices.

5               Dr. Riccardella has co-authored a paper  
6 on the subject matter that presents a methodology  
7 for evaluating the probability of baffle-former  
8 bolt cracking for pressurized water reactors. This  
9 methodology recently was used as part of an EPRI  
10 MRP program to address new industry findings. Dr.  
11 Riccardella will not participate in matters related  
12 to technical areas of his past contributions.

13              I now invite M.J. Ross-Lee, Deputy  
14 Director of Engineering in NRR to introduce the  
15 presenters and start the briefing. M.J.

16              MS. ROSS-LEE: Good morning. So yes, I  
17 am M.J. Ross-Lee. I'm the current Deputy Director  
18 of Division of Engineering, Office of Nuclear  
19 Reactor Regulation. We are here to present to the  
20 subcommittee. I think we'll touch on all the parts  
21 as previously introduced, talk about baffle-former  
22 bolts, what they are, what they do, some past  
23 operating experience, current operating experience,  
24 what we've done, our path forward, and what we plan  
25 to do with those.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 Today's presenter is a member of my  
2 staff, Jeff Poehler. He is a materials engineers  
3 and he will be taking us through the presentation  
4 today.

5 In addition, beside me is Dave Rudland  
6 who is the current Branch Chief of that branch, so  
7 hopefully between us we'll be able to answer any  
8 questions you might have on our presentation. And  
9 because I know we have a number of slides, I'm  
10 going to turn it over now to Jeff and let him get  
11 started.

12 MR. POEHLER: Thank you, M.J. First, I  
13 just wanted to note the audience handouts, the  
14 titles came out a little dark at the top of the  
15 slide, so you might want to note on there what the  
16 title is for later reference, just so you don't  
17 confuse plants.

18 So I'm going to be talking about recent  
19 operating experience with baffle-former bolt  
20 degradation. What we're going to cover in this  
21 presentation and we already did introduction.  
22 First, we're going to cover design and function and  
23 materials of PWR internals, the baffle-former  
24 assembly and baffle-former bolts. We're going to  
25 talk about some potential consequences of baffle-

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 former bolt degradation. We're going to talk about  
2 the history of baffle-former bolt degradation,  
3 basically, the operating experience. We're going  
4 to talk about some of the factors that influence  
5 this type of degradation. We're going to talk  
6 about how the bolts are inspected and replaced, how  
7 baffle-former bolt degradation is evaluated, and  
8 how the NRC is responding to the recent operating  
9 experience. And then we're going to talk about the  
10 NRC's future activities.

11 So here's a couple of figures. You're  
12 going to see these again, probably. The one on the  
13 left is just a general overview of PWR internals.  
14 This is a Westinghouse-style PWR internals. The  
15 blue structure is the baffle-former assembly and it  
16 sits within the core-barrel assembly which is sort  
17 of the large cylindrical structure that is the  
18 largest component of the internals.

19 On the right is sort of a more detailed  
20 view, what you would see looking at the inside of  
21 the baffle-former assembly. You have a number of  
22 plates and they are attached with bolts to these  
23 horizontal plates which are called formers. And  
24 you can see that on the cross section there, the  
25 edge of the formers.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1                    Basically, the function of the baffle-  
2                    former assembly is to direct the coolant flow  
3                    through the core and also provide some lateral  
4                    support to the core during a seismic event or loss  
5                    of coolant accident. And basically, these plates  
6                    can form very closely to the outline of the core.

7                    Here's a view looking down into an  
8                    actual Westinghouse PWR which you would see when  
9                    the reactor is defueled. You can see some of the  
10                  openings in this. At the top would be the core  
11                  barrel where you can see these two openings for the  
12                  inlet, either inlet or outlet flows.

13                  So here on the left of this figure,  
14                  this is basically a plant view looking down of one-  
15                  eighth of the baffle-former assembly. And the  
16                  various different bolt locations are circled.  
17                  Here, these are the baffle-former bolts and then  
18                  you also have edge bolts which go in and connect  
19                  the corners of the plates and those sort of go in  
20                  here. And then on the outside -- this is the core  
21                  barrel and you have barrel-former bolts which  
22                  attach the formers to the core barrel.

23                  On the right here, this is what you  
24                  would see if you were inside the core looking out  
25                  towards the baffle plates. This is what the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       baffle-former bolt heads look like. They're inset.  
2       They're counter sunk into the plate and there is --  
3       this is a locking bar which is welded to the baffle  
4       plate on either side and that keeps the bolt from  
5       backing out. And also, if the bolt were to  
6       fracture, it would keep the bolt head from becoming  
7       a loose part, presuming this locking bar was still  
8       in place.

9                   MEMBER SKILLMAN: Jeffrey, let me ask  
10       this question, please. In this Figure 5, you show  
11       the baffle-former bolts, those are from the inside  
12       out.

13                  MR. POEHLER: Right.

14                  MEMBER SKILLMAN: You also show the  
15       core barrel to former bolt. Those are from the  
16       outside in.

17                  MR. POEHLER: Correct.

18                  MEMBER SKILLMAN: What is the failure  
19       history of the latter, of the core barrel to former  
20       bolt?

21                  MR. POEHLER: Barrel-former bolts,  
22       basically, there have not been any failures of  
23       those. There might have been maybe one or two.

24                  MEMBER SKILLMAN: But none or virtually  
25       none.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. POEHLER: Virtually none.

2 MEMBER SKILLMAN: So all the failures  
3 are on the inside out?

4 MR. POEHLER: Right.

5 MEMBER SKILLMAN: Is there a  
6 segregation of the shorter versus the longer shanks  
7 for the failures?

8 MR. POEHLER: You mean among the  
9 baffle-former bolts?

10 MEMBER SKILLMAN: Yes.

11 MR. POEHLER: Well, the shorter shanks  
12 have generally higher stresses. That is a factor.  
13 I'm going to talk about that a little bit later.

14 MEMBER SKILLMAN: I'd be curious if  
15 there is a binning of the failures of the short  
16 versus long.

17 MR. POEHLER: Yes, I'll talk about that  
18 a little later, but yes, that is a factor and  
19 different bolt materials tend to use a different  
20 length shank, so that is also a factor.

21 MEMBER SKILLMAN: Thank you.

22 MR. RUDELL: If I may also, one thing I  
23 wanted to point out on this particular photo  
24 because I don't think we have it, is that some  
25 baffle-former bolts have an internal hex design as

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 this one does with a locking bar or locking tab  
2 sometimes it's called, and welds associated with  
3 that. Some of them have an external hex with a  
4 locking bar and some of them have an internal hex  
5 with a locking washer. So between the different  
6 varieties of baffle-former bolts, there may be a  
7 half a dozen different designs. And of course,  
8 you've got to tailor, you need to tailor your  
9 examination for that particular design.

10 And as you can note here, they weren't  
11 made to get ultrasonic examination easily because  
12 the original requirements were not to do in-service  
13 inspection ultrasonic examination of these bolts,  
14 but industry has worked hard to develop and fairly  
15 recently demonstrated techniques to examine these  
16 bolts. But it is challenging with regards to bolt  
17 geography to do an ultrasonic examination with  
18 bolts.

19 MR. POEHLER: And I just wanted to note  
20 this is what -- this is like the type of bolt style  
21 that's used in the Westinghouse four-loop plant.  
22 And the bolts are about 5/8ths inch diameter shank  
23 and about 2 inches long, so they're about the size  
24 of your thumb. The heads are a little bigger.

25 So what are the materials used in

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       baffle-former bolts? In Westinghouse plants, type  
2       347 stainless steel is used in the older  
3       Westinghouse plants. The bolt design for the 347  
4       bolts has a sharper head-to-shank radius and  
5       shorter shank as we mentioned than in the Type 316  
6       cold worked bolts. Type 316 cold worked stainless  
7       steel is used in newer generation Westinghouse  
8       plants and all replacement bolts that are installed  
9       to replace degraded bolts.

10               In other NSSS designs like Babcock &  
11       Wilcox design PWRs use Type 304 baffle-former bolts  
12       and combustion engineering plants use Type 316  
13       annealed material. There are only two combustion  
14       engineering plants that have bolts. Most of them  
15       have a welded core shroud.

16               MEMBER KIRCHNER: Is this a good time  
17       to ask just from a technical basis or metallurgical  
18       basis, is there any reason why 347, have you seen  
19       any technical reasons why 347 is failing versus  
20       316, just based on materials?

21               MR. POEHLER: Just as far as  
22       metallurgically-wise, I don't know that we have a  
23       good explanation of why 347 is failing more. But  
24       it is -- the operating experience clearly shows  
25       that it's more susceptible.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1                   MR.     RUDELL:           Our     international  
2     experience early on was with 316 bolts in the EDF  
3     plants and so I wouldn't necessarily conclude that  
4     347 is significantly inferior material to 316  
5     because we've seen quite a few 316 bolts fail,  
6     mostly in international units in EDF.

7                   MEMBER RICCARDELLA:    Isn't there test  
8     data and doesn't test data show difference in the  
9     two?

10                  MR.     WILSON:    I don't believe there is  
11     very much test data that shows say a clear  
12     difference between the two. And I think that's the  
13     issues we run into.       There's enough design  
14     differences between the bolts, say we don't have a  
15     real good one-to-one comparison across the board to  
16     make a conclusion on relative susceptibility based  
17     purely on material.

18                  MEMBER RICCARDELLA:    And then what  
19     about the cold worked versus annealed on the 316?  
20     Is there any evidence of one being better than the  
21     other?

22                  MR.     WILSON:    I am not aware of any  
23     personally.

24                  MEMBER RICCARDELLA:    Cold worked would  
25     presumed to be higher strength?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. WILSON: Right, yes. Cold worked  
2 is. Again, as far as OE is concerned because you  
3 start out with different pre-loads, with one design  
4 versus another, it's again, you're fighting I'd say  
5 some design differences to make -- and it's making  
6 it difficult to make any material judgment between  
7 the two.

8 MEMBER RICCARDELLA: Between the three  
9 really.

10 MR. WILSON: What's that? Between the  
11 three, right, exactly right.

12 MEMBER RICCARDELLA: Thank you.

13 MR. POEHLER: The geometry of the type  
14 347 bolts is with a shorter shank and sharper  
15 radius creates higher stresses. So it may be a  
16 function where the geometry that was used with the  
17 347 bolts, but it's basically operating experience  
18 is showing they're more susceptible.

19 CHAIRMAN SUNSERI: Jeff, you said that  
20 the older Westinghouse plants had the 347 and the  
21 newer had the 316. Do we know what prompted that  
22 change? It must have come before the experience  
23 with the degradation?

24 MR. POEHLER: Yes. I'm not sure. I  
25 would have to defer to Westinghouse to answer that.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. WILSON: This is Bryan Wilson from  
2 Westinghouse. I can't answer directly why the  
3 change was made at the time. There was a change in  
4 the manufacturing processes that were intended to  
5 be used. I don't know -- the difference in the  
6 material follows that change in the manufacturing  
7 process very well. So it may have been an  
8 efficiency gain at the time, you know, given no  
9 other evidence of material differences.

10 CHAIRMAN SUNSERI: Okay. Thank you.

11 MEMBER RICCARDELLA: Is the cracking  
12 pretty much exclusively in the fillet radius or  
13 have we had any evidence of cracking in the thread  
14 regions?

15 MR. WILSON: There has been for some  
16 plants, yes, there's been indications either at the  
17 head-to-shank transition or the first thread.

18 MEMBER RICCARDELLA: Thank you.

19 MR. RUDELL: Bernie Rudell. It's  
20 overwhelmingly been at the head to shank, that's  
21 correct.

22 MEMBER RICCARDELLA: Thank you.

23 MR. POEHLER: So now I'm going to talk  
24 about some of the potential consequences of baffle-  
25 former bolt degradation. One of those is potential

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 movement or deflection of baffle plates. If you  
2 have large numbers of degraded bolts, that can  
3 allow detachment or deflection of the baffle bolts  
4 mainly during a LOCA or seismic event. And if that  
5 happens, the plates could impact on peripheral fuel  
6 assemblies and potentially cause fuel grid crush  
7 and localized fuel cladding damage.

8 Some plants also have control rods in  
9 peripheral locations which if the plate impact and  
10 the fuel assembly damage was severe enough, it  
11 could jeopardize capability to insert those  
12 peripheral rods. One mitigating factor is you have  
13 baffle-edge bolts which if they're intact they  
14 would help retain those plates and keep even with a  
15 lot of broken baffle-former bolts, it would help  
16 retain the plates from the moving. And we haven't  
17 seen any -- very little degradation of baffle-edge  
18 bolts I'll say.

19 Also, if you do get localized damage to  
20 peripheral fuel assemblies, you can perform a  
21 coolable geometry evaluation to show that core  
22 coolability would still be maintained.

23 Another consequence is baffle jetting  
24 which is basically flow leakage through the gaps  
25 between adjacent plates. You have baffle edge

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 bolts which basically help hold the corners of  
2 those plates together and that helps to prevent  
3 baffle jetting.

4           You can get -- but if you do get baffle  
5 jetting, basically the flow leakage out between the  
6 corners causes flow and just vibration of fuel pins  
7 resulting in localized -- which can result in  
8 localized fuel cladding damage. In some cases  
9 reaching the cladding. This can be detected by  
10 reactor coolant activity monitoring which can  
11 detect increases in flow and activity that can be  
12 indicative of fuel damage.

13           MEMBER KIRCHNER:       Jeff, did I  
14 understand you correctly to say that you have seen  
15 little baffle edge bolt damage versus the other  
16 bolts?

17           MR. POEHLER: Yes. They have seen very  
18 little, but I will be touching on that later that  
19 one plant has found a few degraded edge bolts.

20           MEMBER KIRCHNER: Again, I'm searching  
21 for is there a technical reason why the edge bolts  
22 wouldn't fail at the same probability or  
23 statistically at the same rate as the other baffle  
24 bolts?

25           MR. POEHLER: I can't really speak to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       that. There may be differences in stress.

2               MR. WILSON: I can help you out there,  
3       Jeff. There are differences in stress on those  
4       edge bolts. The edge bolts are generally not very  
5       highly loaded when all the baffle-former bolts are  
6       in plate. As you start getting degradation,  
7       significant degradation, you start to shift that  
8       load and create additional loads on those edge  
9       bolts.

10              MR. RUDELL: There is also less gamma  
11       heating on the edge bolts, right?

12              MR. POEHLER: They are influenced less  
13       by the gamma heating. I wouldn't say there's less  
14       gamma heat --

15              MEMBER SKILLMAN: But less dose?

16              MR. POEHLER: No, I wouldn't say that.  
17       Same dose. Another consequence is loose parts.  
18       Bolt heads and locking bars can become loose parts  
19       as the bolts completely fracture.

20              The clearances between the baffle  
21       plates and fuel assemblies are very small, probably  
22       in the order of that, which would tend to prevent -  
23       - the bolt heads really can't escape unless the  
24       reactor is de-fueled, but they can cause spreading  
25       of fuel assemblies because they're bearing right on

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 the fuel assemblies and they're caught in there.

2 MEMBER SKILLMAN: Jeffrey, has there  
3 been any experience where a peripheral fuel  
4 assembly has been blocked from removal because of  
5 the --

6 MR. POEHLER: There's parts wedged in  
7 there?

8 MEMBER SKILLMAN: No, because of the  
9 head of the bolt backing out and the fuel assembly  
10 not being able to slide freely out of that cell.

11 MR. POEHLER: Not that I'm aware of.

12 MR. WILSON: No, we have not had them  
13 experience that.

14 MR. POEHLER: But because these bolt  
15 heads are relatively small, if you had a few failed  
16 bolt heads, it's unlikely that the -- we don't  
17 think the loose part monitors would pick that up.  
18 If you had maybe a large number of loose heads, you  
19 might.

20 Baffle plates are unlikely to detatch  
21 during normal operation, but if they did, the  
22 potential for travel of the plate is limited by the  
23 type clearances and the large size of the plates.

24 Okay, now I'm going to go into the  
25 history of the operating experience or baffle bolt

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 degradation. So the early history, it was first  
2 identified in the late '80s in European plants, in  
3 the French 900 megawatts CPO plants, that should be  
4 a capital M, not a small M in front of the W.

5 Six plants found between about 1  
6 percent and 11 percent of the bolts degraded and  
7 the French plants -- the Belgian plants --

8 MEMBER SKILLMAN: Wait a minute. Not  
9 so fast, not so fast. I understand that those CPO  
10 plants all are downflow plants.

11 MR. POEHLER: They were originally  
12 downflow, but they did convert to upflow in the  
13 early '90s.

14 MEMBER SKILLMAN: Hold on. The  
15 experience that you are pointing to is experienced  
16 during the time those were downflow plants. Is  
17 that accurate?

18 MR. POEHLER: Some of the inspections  
19 were during the '90s after they converted.

20 MEMBER SKILLMAN: I don't feel like I'm  
21 getting a good answer to my question. My  
22 understanding is only the CPO plants had a  
23 significant number of baffle-bolt failures.

24 MR. POEHLER: Right.

25 MEMBER SKILLMAN: The upflow plants did

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 not, the CPY plants.

2 MR. POEHLER: That's correct.

3 MS. MALIKOWSKI: That's correct. This  
4 is Heather Malikowski. We have a slide on the EDF  
5 experience with a little more detail.

6 MEMBER SKILLMAN: So as you go through  
7 the rest of these slides, I'd like to know what is  
8 upflow and what is downflow.

9 MR. POEHLER: We will be covering that,  
10 yes.

11 MEMBER SKILLMAN: Thank you.

12 MR. POEHLER: So in the Belgian plant  
13 the one three-loop Framatome 900-megawatt design is  
14 basically very similar to the CPO design.  
15 Performed five examinations between '91 and 2014.  
16 They found a total of 74 bolts degraded or  
17 uninterpretable.

18 Three other plants performed one  
19 ultrasonic examination each, finding just a handful  
20 of degraded bolts. So the mechanism for this  
21 degradation was attributed to irradiation-assisted  
22 stress corrosion cracking, or IASCC.

23 In 1998, the NRC issued Information  
24 Notice 98-11 to alert U.S. plant licensees to this  
25 issue. And then the U.S. industry kicked off a

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 program which included pilot inspections of baffle-  
2 former bolts at several plants.

3 So I am going to talk about the pilot  
4 plant inspections that were done in the U.S. There  
5 were two two-loop downflow plants. These were  
6 Westinghouse designed plants, the Type 347 bolts.  
7 And those were ultrasonically examined in the late  
8 '90s. Those plants found in the neighborhood of  
9 seven to ten percent of the bolts in each site, in  
10 each unit were degraded. So it came out to around  
11 maybe 50 some bolts per reactor. They replaced  
12 degraded bolts. One plant replaced a number of  
13 additional non-degraded bolts for additional  
14 margin.

15 One of the plants, they performed  
16 tensile testing of bolts that were removed that had  
17 indications and those tensile tests were good which  
18 indicated that it seemed like some of the UT  
19 results were false positives or over calling the  
20 indications.

21 And also two three-loop downflow plants  
22 or reactors with Type 316 bolts did an inspection,  
23 same time frame. They found no indications, but  
24 they preemptively replaced about 200 bolts per each  
25 unit.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 And also, one B&W plant in 2005 found no  
2 indications.

3 MEMBER SKILLMAN: You identified that  
4 the two-loop 1990 Westinghouse plants are downflow.  
5 The three-loop are downflow.

6 MR. POEHLER: Yes.

7 MEMBER SKILLMAN: Are all B&W plants  
8 upflow? Is that accurate?

9 MS. MALIKOWSKI: Yes, that is correct.

10 MEMBER SKILLMAN: Thank you.

11 MR. POEHLER: Now we are going to talk  
12 about MRP-227-A. Around the year 2000 to 2011, we  
13 had a bunch of plants applying for license renewal,  
14 PWR plants now we're talking about. And at the  
15 time, there was the industry reactor vessel  
16 internals Aging Management Program was not  
17 developed yet, was under development, so a lot of  
18 those plants made commitments to implement the  
19 industry program when it was issued. That program  
20 was MRP-227 rev. 0 was received by the NRC in 2009.  
21 We were reviewing it in the 2009 to 2011 time  
22 period. And we issued a safety evaluation on it in  
23 2011. The approved or NRC-endorsed version of that  
24 topical report is MRP-227-A which is the inspection  
25 evaluation guidelines for PWR internals published

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 by EPRI.

2 So I'm going to talk about what MRP-  
3 227-A requires as far as inspection for baffle-  
4 former bolts. Basically, ultrasonic examination  
5 for the initial baseline examination. Westinghouse  
6 and CE have the same schedule and scope. It's 100  
7 percent of the bolts and it's to be done between 25  
8 and 35 effective full-power years. For B&W, it's  
9 slightly different. It's still 100 percent of the  
10 bolts, but the timing is no later than two  
11 refueling outages from the beginning of the license  
12 renewal period.

13 And then for both -- for all the  
14 different vendor-type of reactors, the follow-up  
15 inspections are going to be ten years, a maximum of  
16 ten years after the initial inspection. That's if  
17 you don't find -- now if you found significant  
18 degradation you might have to do it sooner, do the  
19 follow-up inspections sooner. And all PWRs have to  
20 do these inspections unless they don't have bolts.

21 So now in 2010, D.C. Cook Unit 2 found  
22 visual signs of failure in several -- a number of  
23 bolts. D.C. Cook is a four-loop Westinghouse  
24 downflow plant. Has Type 347 bolts. There are 832  
25 total bolts and they saw 18 bolts that had visual

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       indications of failure. They ended up replacing a  
2       total of 52 bolts with Type 316 bolts. Most of  
3       those were on one large baffle plate. And a total  
4       of the 52 they replaced, 42 were cracked. That  
5       also includes the original 18 that they saw  
6       visually in that 42.

7               To establish extent of condition, they  
8       were basically from the three similar large baffle  
9       plates. Basically, there's four of the baffle  
10      plates are big plates and have a lot of bolts. On  
11      all of the similar plates, the licensee performed a  
12      VT-3 visual examination. Didn't see any visual  
13      evidence of degradation and they tensile tested one  
14      bolt from each plate and that came out fine. So  
15      they concluded there was no degradation. They  
16      didn't perform ultrasonic testing on any bolts.  
17      And they left two bolt locations vacant when they  
18      started up.

19             Westinghouse issued a technical  
20      bulletin about this operating experience to alert  
21      licensees.

22             MEMBER RICCARDELLA: Why were two bolts  
23      left vacant? And was there a reason for that?

24             MR. WILSON: This is Bryan Wilson from  
25      Westinghouse. Yes, upon completion of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 replacement campaign, there was initially no  
2 intention to replace the bolts near the edge  
3 because we felt that they were supported  
4 appropriately by the replaced bolts.

5 During the campaign and after it was  
6 completed, we found there were say bolts that had  
7 pushed the lock bars out as a result of basically  
8 torquing up all the replacement bolts. So there  
9 was potentially some damage at those bolts that had  
10 caused the lock bars to pop out. So at that time,  
11 the tooling had already been removed from site and  
12 evaluations were done to show it's okay if we can  
13 remove them and leave them like that.

14 MEMBER RICCARDELLA: Okay, it wasn't  
15 for research purposes?

16 MR. WILSON: No, no, no. It was purely  
17 --

18 MEMBER RICCARDELLA: Okay.

19 MR. POEHLER: Now I am going to talk  
20 about in the 2011 to 2015 time period there were a  
21 number of plants performed their initial  
22 inspections as required by MRP-227-A. These were  
23 the Westinghouse two-loop, mostly Westinghouse two-  
24 loop designs and three-loop designs, also a few B&W  
25 designs. So the Westinghouse two-loop, as we

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 mentioned, they are Type 347 bolts. They did their  
2 inspections at around 30 to 40 EFPY. See, these  
3 are some of the oldest Westinghouse units. They  
4 found no more than about ten percent max of any of  
5 the units, the ten percent maximum of the bolts  
6 were degraded.

7 The Westinghouse three-loop plants were  
8 not quite as old, 30 to 32 EFPY. They also used  
9 Type 347 bolts. There were four reactors. Three  
10 of the units to the 100 percent inspections and  
11 found basically very few bolts, no more than eight  
12 per reactor and one of the units did a partial  
13 inspection, but didn't find any indications.  
14 They'll complete that at a subsequent outage.

15 Also, there were three B&W reactors  
16 that had the UT inspections and they found no more  
17 than -- the largest number of bolts failed per  
18 reactor or with indications I should say, was four.  
19 So really just a handful. None of the combustion  
20 engineering plants with bolts have performed their  
21 inspections to date.

22 MR. RUDELL: There is only one CE plant  
23 that has baffle-former bolts that's still  
24 operating.

25 MR. POEHLER: Yes, one of them is

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       shutting down or shut down.

2               MR. RUDELL:   Shut down.

3               MR. POEHLER:   But the other one has  
4 plans to do it in a few years, but they will meet  
5 the inspection time requirement.

6               MEMBER SKILLMAN:   So Jeffrey, just for  
7 consistency, in the first group, the Westinghouse  
8 two-loops, those are downflow plants, correct?

9               MR. POEHLER:   They are downflow --  
10 originally downflow.   Some of them may have  
11 converted at least one may have converted.

12              MEMBER SKILLMAN:   Is there data that  
13 shows pre and post conversion for baffle-bolt  
14 failure?

15              MR. POEHLER:   No.

16              MEMBER SKILLMAN:   Thank you.

17              MR. RUDELL:   That main data would be  
18 the EDF plants and we'll show you.

19              MR. POEHLER:   Now I'm going to talk  
20 about Indian Point Unit 2.   The 2016 refueling  
21 outage, they conducted the MRP 227-A inspection.  
22 The edge bolts were all acceptable.   UT and visual  
23 examination found about 227 potentially degraded  
24 bolts out of 832 total.   Some of those were found  
25 ultrasonically.   Some were visually detected and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 others, there were 14 inaccessible bolts and  
2 inaccessible bolts are considerably assumed to be  
3 degraded or failed.

4 So what did they do for corrective  
5 actions? They replaced 278 total bolts. That was  
6 all 227 of the potentially degraded. They also  
7 replaced 51 additional non-degraded bolts to  
8 provide additional margin. And they used Type 316  
9 stainless steel. They completed an analysis to  
10 support return to service. That was inspected by  
11 NRC Region I inspectors and they sent a number of  
12 bolts to the laboratory for testing to support root  
13 cause analysis.

14 For the other unit at Indian Point,  
15 Indian Point 3, there was an operability evaluation  
16 performed which considered information from Indian  
17 Point 2 and Salem 1 which I'll talk about in a  
18 minute.

19 MEMBER BALLINGER: I have a question.  
20 We're getting a little bit loose with the  
21 definition of 316. Are they L or standard grade?  
22 They're cold work 316L grade?

23 MR. WILSON: No, cold work 316  
24 standard.

25 MEMBER BALLINGER: Standard grade.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 Okay.

2 MEMBER RICCARDELLA: Excuse me, what  
3 were the EFPYs for Indian Point 2 and 3?

4 MR. POEHLER: It was about 31 for Unit  
5 2 and Indian Point 3 was about 27.

6 MS. MALIKOWSKI: It was just under 31  
7 for Indian Point 2.

8 MEMBER RICCARDELLA: Okay, and 27 for  
9 3.

10 Thank you.

11 MEMBER BALLINGER: Is there a reason  
12 for not choosing L? Because you can get the same  
13 strength for culvert no matter what. It's dual  
14 certified, right?

15 MR. WILSON: Yes. I can't comment on  
16 that, unfortunately.

17 MEMBER BALLINGER: Okay, and they're  
18 all standard grade, all the replacement 316s are  
19 standard grade?

20 MR. WILSON: That's correct. I'm  
21 sorry, for the Westinghouse replacement, yes.  
22 There are differences for other vendors.

23 MEMBER BALLINGER: But you're creating  
24 a whole separate database?

25 MR. WILSON: Right.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. POEHLER: At Indian Point 3, they  
2 rescheduled --- their baffle-former bolt  
3 examination had been scheduled for 2019. They  
4 moved it up to 2017.

5 Now I'm at Salem Unit 1. Also had a  
6 spring 2016 refueling outage. It's another four-  
7 loop Westinghouse downflow plant, with Type 347.  
8 They were conducting first visual examination,  
9 basically based on the Indian Point operating  
10 experience. Then they found about 11 bolts with  
11 visual indications of failure. Or actually, no, it  
12 was a total of about 30 bolts with visual  
13 indications failure. Eleven cracked at the head.  
14 Nine had lock bar. The lock bars were cracked and  
15 19 of the bolts were protruding, bolt heads were  
16 protruding. So they decided to UT all the  
17 remaining bolts. They found 135 more bolts that  
18 were degraded based on UT and there 16 bolts that  
19 were unable to be UT'd. So those were also assumed  
20 to be degraded. So overall, there was about 190  
21 bolts identified as potentially degraded and  
22 needing replacement.

23 There were significant clustering of  
24 bolts in several octants of the baffle-former  
25 assembly, so the bolts, the degraded bolts were

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 heavily concentrated in those areas and more sparse  
2 in the other areas.

3 MEMBER SKILLMAN: Jeffrey, what  
4 consideration was given to the meaning of that  
5 bullet? It seems to me that that's a very  
6 significant finding from all of the data coming out  
7 of Salem 1. So what is the conclusion of the  
8 Westinghouse team for the clustering?

9 MR. POEHLER: Yes, I'm going to talk a  
10 little about the clustering. It's definitely been  
11 seen at these four-loop plants and it was more  
12 severe at Salem. So I'm not sure we have an answer  
13 for why it was more severe at Salem than at Indian  
14 Point. I don't know if the Westinghouse team has  
15 an answer for that.

16 MEMBER SKILLMAN: Well, let me ask --  
17 are the reactor coolant pump flows and reactor  
18 coolant pump discharge heads the same for the two  
19 plants?

20 MR. WILSON: They are very similar, the  
21 two plants. Not enough to conclude a major  
22 difference.

23 MEMBER SKILLMAN: Are the loop  
24 geometries and the pipe diameters the same?

25 MR. WILSON: I can't answer that here.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 I'd have to confirm that one. I don't know off the  
2 top of my head.

3 MEMBER SKILLMAN: I'm obviously  
4 picking. Is there a standing wave or is there a  
5 resonance that comes from main passing frequency  
6 times four pumps, full power at the density that  
7 you're at full power?

8 MR. WILSON: Right.

9 MEMBER SKILLMAN: It just seems to me  
10 that there is information there that the very  
11 curious might try to mine.

12 MR. WILSON: Right. The one thing we  
13 do know is from looking at this, the flow into the  
14 baffle-former region has to go through a path that  
15 is a little bit more torturous than the norm. So  
16 it has to enter through a flow hole in the side of  
17 the barrel and then down through the formers. It  
18 doesn't -- usually what happens at that point is a  
19 lot of these say pressure variations and things get  
20 kind of washed out a bit by the time you make that  
21 path change.

22 So there hasn't been a strong  
23 correlation with say pump-induced related  
24 influences, but such as I think the disturbances  
25 you're mentioning. But that certainly is stuff

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       that we'll continue to look at as understanding the  
2       situation.

3                   MEMBER RICCARDELLA:   Does the fracture  
4       morphology show any signs of fatigue and is it  
5       conclusive, whether it be fatigue or stress  
6       corrosion?

7                   MR. RUDELL:    I can -- yes, there is  
8       fatigue in the bolts that we've looked at so far.  
9       Some have a significant amount of fatigue, maybe 50  
10      to 60 percent of the failed fracture surfaces  
11      appear to be fatigued, and then others nearly all  
12      is intergranular, appears to be irradiated as  
13      stress corrosion cracking. And we're trying to put  
14      those pieces together. That's why we don't have a  
15      whole lot of information in the destructive  
16      examination work that's ongoing right now.

17                  MEMBER RICCARDELLA:   But it should also  
18      tell you if it's high cycle versus low cycle.

19                  MR. RUDELL:    Yes. We're trying to get  
20      that out of it, but you're right. It could be high  
21      cycle or low cycle fatigue, depending on what comes  
22      first.

23                  MEMBER RICCARDELLA:   But the fracture  
24      morphology should identify that, right?

25                  MR. RUDELL:    Yes.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1                   MEMBER RICCARDELLA: I mean that would  
2 address your concerns about the vibration.

3                   MEMBER SKILLMAN: What I'm really  
4 thinking is that the CPY plants, the French plants  
5 that are four-loop that are different than the CPOs  
6 that are four-loop downflow, the CPY plants are  
7 four-loop upflow. And this problem has basically  
8 ceased for the CPY upflow. So my hunch is that  
9 there's a standing wave and that there's a  
10 resonance cavity back in the lower internals of the  
11 Westinghouse design where the clustering would  
12 occur.

13                   It's probably something envisioned, but  
14 it just strikes me that the downflow, upflow, and  
15 geometry of your baffles in the Westinghouse large  
16 plants invites a question that really gets to what  
17 Dr. Riccardella is talking about. If it's high-  
18 cycle fatigue and it's preponderance, then I would  
19 suspect that there's a standing wave and what  
20 you're really getting is tensile failure as a  
21 common -- as the consequence of fatigue.

22                   MR. WILSON: Right. So for the upflow  
23 and downflow, there's a significant difference in  
24 the -- I'd say steady pressure, you know, that's  
25 behind that plate. So any kind of influences of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       these     say     stress     fluctuation     or     pressure  
2       fluctuations     or     anything     would     even     be     further  
3       magnified     by     that     say     steady     difference.     I     mean  
4       it's     basically     an     order     of     magnitude     difference     in  
5       pressure,     in     Delta     P     across     that     plate     which     is  
6       enormous.

7                   MEMBER SKILLMAN:     The real issue is the  
8       area     because     those     plates     are     large     plates,     so     even  
9       small     Delta     P     magnifies     to     a     very     large     force  
10      around     those     bolts.

11                   MR. WILSON:     Right.

12                   MEMBER RICCARDELLA:     Because then you  
13      would -- would you see -- that's obviously worse at  
14      the top than at the bottom.

15                   MR. WILSON:     Right.

16                   MEMBER RICCARDELLA:     Are we seeing a  
17      trend of more cracking near the top?

18                   MR. WILSON:     Yes.     The patterns of  
19      failed bolts tend to be clustered in areas of the -  
20      - right, in the U.S., in areas of the highest  
21      pressure.     So there's a clear trend there.

22                   I'll touch on this clustering topic a  
23      little bit more in my presentation later.     I know  
24      Jeff has some additional thoughts on this.

25                   MR. POEHLER:     Okay, Salem, what did

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 they do? Correct actions. They replaced 189  
2 bolts, the Type 316. They also sent some bolts to  
3 the lab for analysis. They did a minimum bolting  
4 pattern analysis to determine or to confirm that  
5 their replacement scope was acceptable for one-  
6 cycle operation prior to reinspecting.

7 For the operating unit, Salem Unit 2,  
8 they performed an operability determination based  
9 on the extent of condition from Salem Unit 1. They  
10 also moved up the schedule UT examination of the  
11 bolts to next year from 2026.

12 MEMBER RICCARDELLA: Just to complete,  
13 what were the EFPYs for Salem, just two  
14 centimeters?

15 MR. POEHLER: It sounds a little less  
16 more in the 24 to 26 range.

17 MS. MALIKOWSKI: Salem 2 is in that  
18 range, and then Salem 1 is 28.

19 MEMBER RICCARDELLA: Salem 1 is 28 and  
20 Salem 2 is --

21 MS. MALIKOWSKI: Twenty-five.

22 MEMBER RICCARDELLA: Twenty-five.

23 MS. MALIKOWSKI: It will be 25 -- I  
24 believe in the spring.

25 MEMBER RICCARDELLA: Thank you.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 CHAIRMAN SUNSERI: I would like to  
2 remind the speakers to make sure you speak loud  
3 enough so the transcriber can hear you.

4 MS. MALIKOWSKI: My apologies.

5 MR. POEHLER: Now D.C. Cook Unit 2 was  
6 performing UT inspection during the fall outage and  
7 this is the first plant to do the UT in accordance  
8 with some interim guidance from the MRP, EPRI MRP  
9 which we'll talk a little bit more about later.

10 They found a total of 179 potentially  
11 degraded bolts. There were also, as I mentioned,  
12 the two vacant bolt locations from 2010.

13 Some notable new elements at D.C. Cook  
14 where there were six of the replacement bolts  
15 installed in 2010 had indications. At least --  
16 also, at least one of the vacant bolt hole  
17 locations correlated with some damage to a fuel  
18 assembly.

19 MEMBER SKILLMAN: Jeffrey, would you  
20 please explain that more?

21 MR. POEHLER: The damage to the fuel  
22 assembly?

23 MEMBER SKILLMAN: Yes.

24 MR. POEHLER: I mean it was basically  
25 damage to the fuel assembly that was suggested of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       baffle jetting type issues going on.

2                   MEMBER SKILLMAN:     So jetting from an  
3       empty hole?

4                   MR. POEHLER:   Apparently.

5                   MEMBER BALLINGER:   Now the replacement  
6       bolts were 316 though, right?

7                   MR. POEHLER:   Correct.

8                   MEMBER BALLINGER:   So this is 316 bolts  
9       that are cracked?

10                  MR. POEHLER:   Right.

11                  MEMBER SKILLMAN:   So wait a minute.  
12       Damage fuel assembly jetting from an empty hole, so  
13       what did the plant do? Did they remove this fuel  
14       assembly and correlate basically a shine on a fuel  
15       assembly or a set of pins or a spacer grid with a  
16       location of the adjacent hole? Is that what that  
17       means?

18                  MR. WILSON:   Yes, they had correlated  
19       the location. Actually, one of the fuel rods had I  
20       guess been displaced inward and they correlated the  
21       location of that fuel rod with the spacing from --  
22       or to that location of the hole.

23                  MEMBER SKILLMAN:   Of the hole.

24                  MR. WILSON:   Of the hole. Within like  
25       an inch or so of that location.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MEMBER SKILLMAN: Okay, thank you.

2 CHAIRMAN SUNSERI: So based on the  
3 experience with baffle jet fuel failures, why was  
4 that not anticipated? It seems like that that  
5 should have been anticipated as a potential  
6 consequence.

7 MR. WILSON: Right, at the time -- with  
8 the lack of UT available at the time of that  
9 inspection for that configuration of bolt, we did,  
10 I guess, as much of what we thought was an extent  
11 of condition at the time as we could, removing  
12 bolts in those locations, and then, I guess,  
13 expected that we had covered the range of failures  
14 of those bolts at the time.

15 And the conclusion was that if we had  
16 locked down the plate by putting these replacement  
17 bolts in, that the baffle plate would have been in  
18 contact with the former plate such that you  
19 wouldn't really have a path for flow to get out of  
20 that hole.

21 So the baffle jetting occurs when you  
22 have some flexibility that allows a joint to open,  
23 but we had expected that that joint would have been  
24 closed or mostly closed, at least to the point  
25 where you could accept the amount of bypass in

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 jetting that was occurring, could occur from that  
2 hole. What we come to find out later is that say  
3 to the left of that, those replacements could have  
4 potentially been an additional amount of failed  
5 bolts that were undiscovered by the path that was  
6 chosen for looking for an extent of condition. And  
7 if those bolts were already failed, there was a  
8 mechanism to kind of loosen that whole section of  
9 the plate and allow for flexibility that allowed  
10 flow to go through.

11 MR. RUDELL: To Bryan's point, those  
12 two holes were vacated in 2010, coming out of that  
13 outage. So there were prior cycles where there was  
14 not any damage to the fuel associated with those  
15 holes and there were other units that are operating  
16 with baffle-former bolts vacated and I know the one  
17 I'm familiar with does prescribed inspections. I  
18 suspect that this unit did, too, particularly  
19 looking at the fuel assembly in that area, and  
20 knowing that that has a vacated baffle-former bolt  
21 there.

22 And the inspections I'm familiar with  
23 have not seen any indications of any jetting  
24 associated with those vacant holes. So here we  
25 have in this past cycle, this past operating cycle

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 at this one plant discovered this issue with the  
2 jetting out of vacated hole.

3 MEMBER SKILLMAN: Did the primary  
4 chemistry, cesium and strontium, elevate,  
5 indicating a weaker --

6 MR. RUDELL: They indications of a  
7 failure. Yes.

8 MEMBER SKILLMAN: They did. Thank you.  
9 Thanks.

10 CHAIRMAN SUNSERI: Were these vacant  
11 holes near the top of the former plate or lower?

12 MR. POEHLER: I think the next slide.  
13 This is a diagram -- this is the diagram of the  
14 baffle former assembly at D.C. Cook showing the  
15 locations. This is showing the as-found condition  
16 in the 2016 outage. And the way this works is the  
17 green bolts were good bolts with no indications.  
18 Red bolts have indications. And I think the gray  
19 ones were the empty holes which are somewhere right  
20 about in that area. One of them is right here and  
21 the other one is over here.

22 So this is the large baffle plate,  
23 right here. This is where in 2010 they had  
24 replaced the 52 bolts or most of them. So you can  
25 see these sort of -- the ones with the square

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 symbol are the replacement bolts.

2 In this yellow box here, this is the  
3 six replacement bolts that were found degraded and  
4 this right here is where they found five degraded  
5 edge bolts as well, right here, on this seam here.

6 MR. RUDELL: So the sea of red.

7 MR. POEHLER: Yes, you note that  
8 there's quite a few degraded bolts around where the  
9 edge bolts were and these five edge bolts were all  
10 in a row right on this.

11 MEMBER KIRCHNER: How does the -- with  
12 your map here, just refresh my memory. How do the  
13 primary coolant loops line up with the orientation  
14 there? And in particular, where's the cold leg  
15 coming in? Is that immediately adjacent to the red  
16 field of degraded bolts?

17 CHAIRMAN SUNSERI: Before you answer  
18 that question, let me make a request here. I've  
19 got some feedback from the people listening on the  
20 public lines. Since this is kind of a -- NRC is  
21 leading this presentation, but we have other people  
22 speaking, please identify yourself so that the  
23 people on the line can understand who is talking.  
24 Thank you.

25 MR. WILSON: So this is Bryan Wilson of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 Westinghouse. Yes, the cold leg is in that  
2 vicinity. It's not exactly adjacent to those  
3 failures, but --

4 MEMBER KIRCHNER: This is where you  
5 would see the maximum pressure differentials,  
6 especially with the downflow?

7 MR. WILSON: Not necessarily. Because  
8 of the way the flow kind of has to go around the  
9 annulus and then into the flow holes, it doesn't  
10 necessarily line up always with the cold leg.

11 MEMBER KIRCHNER: But this is a  
12 downflow design?

13 MR. WILSON: Yes.

14 MEMBER KIRCHNER: I would expect this  
15 to be the point of highest pressure.

16 MR. WILSON: That is the elevation of  
17 highest pressure.

18 MEMBER KIRCHNER: Then going back to  
19 Dick's earlier comments on vibration --

20 MEMBER SKILLMAN: Let me push a little  
21 further on Dr. Kirchner's question. Is there  
22 history of operating with less than four pumps on  
23 this plant? In other words, could they have run  
24 for any extended time with two pumps on that loop  
25 where that is the cold leg dominant location?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. WILSON: No, I don't think there's  
2 any experience with operating for an extended  
3 period of time with that, with less than four  
4 pumps.

5 MEMBER SKILLMAN: I don't know the tech  
6 specs for this plant, but I know that you are  
7 permitted for a certain time period less than four,  
8 but it's a short time period. But I'm just  
9 wondering if this is on a loop closest to where  
10 there might have been an extended time period of  
11 less than four-loop operation for the standing wave  
12 on this corner of the internals might have been  
13 greatest from the pumps that were operating in the  
14 loop closest to that baffle.

15 MR. WILSON: Right, we have actually  
16 looked at -- we were primarily looking at pump  
17 sequence, end of start up and things like that.  
18 Related to your question, we were not able to come  
19 to a definitive conclusion that you would have  
20 expected a correlation between this. It certainly  
21 looks like there's a correlation, but from a fluid  
22 hydraulics standpoint, it doesn't, you know, the  
23 math doesn't work out, I guess, if you will.

24 MEMBER SKILLMAN: It could be  
25 manufacturing, too.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. WILSON: Right.

2 MEMBER SKILLMAN: So I understand that.  
3 But I just wanted to build on Walt's question.  
4 Thank you.

5 MEMBER RICCARDELLA: Just to complete  
6 the story, the EFPYs for Cook 2 and also I don't  
7 see much about Cook 1.

8 MS. MALIKOWSKI: This is Heather  
9 Malikowski. This is 28 EFPY for Cook 2.

10 MEMBER RICCARDELLA: Twenty-eight in  
11 2016?

12 MS. MALIKOWSKI: Correct.

13 MR. POEHLER: Okay, so the corrective  
14 actions for Cook 2 was -- they're still underway,  
15 but they plan to replace a minimum of 181 bolts  
16 with Type 316. And that includes all the degraded  
17 bolts, plus the missing vacant locations. And  
18 they're planning to replace additional bolts up to  
19 201 bolts as time permits in their outage.

20 They're investigating the indications  
21 in their replacement bolts. I just want to note  
22 that there have been replacement bolts in service  
23 for about 10 to 15 years from some of the late '90s  
24 inspection activities and they have seen no  
25 indications in those replacement bolts, Type 316

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 bolts.

2 The replacement bolts are going to be  
3 sent for laboratory analysis. I think that's being  
4 done very soon.

5 They're also having a sensitivity  
6 analysis performed to explore the effects on  
7 replacement bolt stresses from some of the failed  
8 original bolts in that area that would support the  
9 root cause for the replacement bolt failures.

10 So as far as the baffle edge bolts, the  
11 licensee is still determining what they're going to  
12 do about corrective actions for those. It's  
13 possible they may not remove them.

14 Now I'm going to go into factors that  
15 influence baffle-former bolt degradation. The  
16 first one is neutron fluence. So austenitic  
17 stainless steel is normally very resistant to  
18 stress corrosion cracking in a PWR chemistry  
19 environment. However, when you get high fluence,  
20 you get grain boundary and chemistry changes  
21 occurring.

22 The neutron fluence threshold for IASCC  
23 is 2 times 10 to the 20 per neutron per square  
24 centimeter or 3 dpa. Baffle plates and bolts, some  
25 baffle plates -- areas of the baffle plates and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 bolts are going to get up to 75 dpa over a 60-year  
2 life. However, the patterns of the bolt  
3 degradation we've seen it at Indian Point 2, Salem  
4 1, and Cook 2, don't seem to correlate with the  
5 highest fluence locations in the core.

6 Also, I'd like to note that the two and  
7 three-loop Westinghouse plants had similar higher  
8 fluence levels to the four-loop plants, but fewer  
9 degraded bolts.

10 CHAIRMAN SUNSERI: We need to be a  
11 little careful about fluence threshold at 2 or 3  
12 dpa. That also requires an environment. So the  
13 microstructure is susceptible after 2 or 3 dpa, but  
14 you still have to have the environment which is not  
15 a PWR environment, right? In a BWR 2 and 3 dpa,  
16 you're off to the races for this material.

17 MR. POEHLER: Yes, I mean it can  
18 happen, the PWR environment. But at a low dpa like  
19 3 dpa, you're going to need a very high stress.  
20 It's kind of a sliding scale of stress versus dpa,  
21 so the higher the dpa, you can have it at lower  
22 stress levels.

23 MEMBER RICCARDELLA: Could you also  
24 expect there to be a threshold at the other end,  
25 too, at the high end where you damage -- the damage

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 somewhat saturates and beyond that, additional dpa  
2 don't matter?

3 MR. POEHLER: Yes, I mean the  
4 mechanical properties at some point are going to  
5 saturate as it further increases in tensile and  
6 yield strength. Grain boundary chemistry might as  
7 well.

8 MEMBER RICCARDELLA: What's that dpa  
9 level?

10 MR. POEHLER: I don't know if I have a  
11 precise answer.

12 MEMBER RICCARDELLA: It doesn't have to  
13 be precise.

14 MR. POEHLER: I'm thinking something  
15 around 15 maybe.

16 MEMBER RICCARDELLA: Okay. Thank you.

17 MR. POEHLER: Also, one other thing,  
18 you know, most of the plants have switched to a low  
19 leakage core design so that's going to reduce the  
20 flux to the bolts which could slow initiation of  
21 new IASCC cracks. Some of these may have initiated  
22 earlier in life.

23 Let's talk about stress. So baffle-  
24 former bolts have stresses from a variety of  
25 sources. You have bolt pre-load early in life.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 That will relax due to radiation assistance stress  
2 relaxation in a fairly short time of operation.

3 At higher fluences, you get void  
4 swelling in the baffle plates and that can put  
5 different stresses on the bolts such as bending  
6 stresses as the plates grow vertically.

7 You also have differential pressure so  
8 in a downflow plant design it's greater than in an  
9 upflow design. And that's going to become more of  
10 a factor as your pre-loads relax.

11 You also have differing numbers of  
12 bolts per plate area. And a four-loop plant has a  
13 larger core, larger plate area, but it has --- a  
14 four-loop basically has the same or less bolts than  
15 a three-loop plant.

16 Also bolt geometry, the head-to-shank  
17 radius, different geometries were used for  
18 different bolt styles, especially the 347, as we  
19 mentioned, has the sharper head-to-shank radius  
20 than the 316 design.

21 Fatigue loads can also have an  
22 influence that's affected by the number of  
23 transients you've had over the life of the plant.

24 MEMBER RICCARDELLA: Jeffrey, there  
25 you're referring to low cycle fatigue as opposed to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 vibration fatigue that Dick is alluding to.

2 MR. POEHLER: Right.

3 MEMBER SKILLMAN: One thing that you  
4 didn't show and you may have considered, you just  
5 didn't write it down, is manufacturing tones. When  
6 you look at the map of the bolts, one can  
7 conceivably think that while the internals were  
8 being constructed, was constructed over a series of  
9 days as the bolts were inserted, torqued, and  
10 strapped, it may have had different crews,  
11 different materials, bolts from different lots.

12 So my question is what consideration  
13 did you give to manufacturing issues?

14 MR. POEHLER: Obviously, if the pre-  
15 load varies, if you had a higher pre-load or pre-  
16 load was out of spec or at the high end that --  
17 that could potentially be a factor early in life as  
18 far as stresses. But if pre-load is low, then it's  
19 going to relax faster, too. If you're on the low  
20 end, maybe you get fatigue occurring sooner because  
21 your pre-load relaxes. So that's -- those are  
22 factors that in the root cause for these plants  
23 they're going to need to look at if they have that  
24 history in the manufacturing.

25 MEMBER RICCARDELLA: Are these

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 lubricated when they're torqued?

2 MR. POEHLER: Yes, they generally are,  
3 yes.

4 MEMBER BALLINGER: These are machined  
5 bolts, not forged and then machined? Are they  
6 machined from bar or are they hot headed and then  
7 machined afterwards?

8 MR. WILSON: Yes.

9 MEMBER BALLINGER: Yes and yes and yes?

10 MR. WILSON: So this is Bryan Wilson  
11 from Westinghouse. It depends on which bolts  
12 you're referring to because there are differences  
13 between the 316 and the 347 and how they were  
14 manufactured. All of them were thread rolled.

15 MEMBER BALLINGER: So the threads are  
16 rolled threads?

17 MR. WILSON: Yes. But the heading was  
18 either done by machining like in a 316 or by hot  
19 heading for the 347.

20 MEMBER BALLINGER: Hot heading.

21 MR. WILSON: So that was -- when I said  
22 earlier about manufacturing differences between a  
23 347 and 316, there was a transition where they went  
24 from hot heading to machining these bolts. And so  
25 yes, the 347 to start with the nominal shank of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 bar and then hot head to -- you know.

2 MEMBER BALLINGER: That explains the  
3 347 actually.

4 MR. WILSON: Yes.

5 MEMBER BALLINGER: Okay. I get it.

6 MEMBER SKILLMAN: Will the review of  
7 the manufacturing records be conducted?

8 MS. MALIKOWSKI: This is Heather  
9 Malikowski, Exelon. Yes, they have reviewed what  
10 they can retrieve. And I believe Bryan can  
11 elaborate. I believe there's only a few heats of  
12 material that were supplied for the bolts, but we  
13 can't correlate them to where they were put in the  
14 plates. So we know there's only a few common  
15 heats, but there's nothing to help say we can say  
16 oh, it's just this heated material. Those records  
17 were looked for.

18 And I think as far as the manufacturing  
19 and assembly, I mean they found what they can, but  
20 there's not enough granularity to it to say you can  
21 say there's some sort of rework or something like  
22 that that may have also helped lead to a focusing  
23 of the failures.

24 MR. WILSON: Right, yes, there wasn't a  
25 smoking gun, if you will, you know, related to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 manufacturing defects.

2 And as Heather pointed out, these were  
3 supplied in batches and installed as such. There  
4 was control of the parts to a plant as far as what  
5 heats and stuff went to a plant, but not specific  
6 location on an individual plate.

7 MEMBER SKILLMAN: Let the record show  
8 that some of these plants were manufactured and  
9 constructed before there was an Appendix B to 10  
10 CFR 50. Now that doesn't mean that these  
11 individuals who assembled these plants were  
12 careless. They used the greatest caution and the  
13 best material and the best assembly practice that  
14 they knew. There might still be some lessons  
15 learned from digging in some of those old records  
16 is all I'm saying.

17 MR. WILSON: Understood.

18 MEMBER SKILLMAN: Thank you.

19 MR. POEHLER: Okay, now moving on, I'm  
20 going to explain the difference between downflow  
21 and upflow. So this diagram shows on the left,  
22 this is a downflow plant. And basically here's --  
23 the difference is flow direction in the space  
24 between the core barrel here and the baffle plates.  
25 Here are your former plates. You have holes in the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 former plates.

2 In a downflow, you have a hole up at  
3 the top of the core barrel, the OD of the core  
4 barrel where a flow comes in and flows down, a  
5 portion of the flow flows down to this space and  
6 then up out at the bottom and up through to join  
7 the rest of the core flow through the core.

8 In an upflow plant, these two flows are  
9 parallel. There's no hole up here, so between the  
10 baffle and the core barrel space, flow is also  
11 going the same direction. So the DP, differential  
12 pressure, is very little with these two. Pressures  
13 are very similar, whereas in the downflow, there's  
14 quite a bit of difference, especially in the top of  
15 the baffle-former assembly.

16 So this kind of shows if you did an  
17 upflow conversion, you would plug that hole there,  
18 but even with an original upflow plant, you just  
19 would never have a hole up there.

20 MEMBER SKILLMAN: What is involved in  
21 an upflow conversion? How many holes need to be  
22 plugged?

23 MR. WILSON: This is Bryan Wilson,  
24 Westinghouse. All of the core barrel holes are  
25 plugged.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MEMBER SKILLMAN: How many?

2 MR. WILSON: I'm not an upflow guy.

3 MEMBER SKILLMAN: In a fuel assembly  
4 plant, there are 168 holes in the bottom. I would  
5 imagine it's a number like that on the core barrel  
6 periphery.

7 MR. WILSON: No, it's on the order of  
8 like say 16 to 32.

9 MR. RUDELL: A couple dozen. It's  
10 going to vary between two, three, and four-loop and  
11 also the design for the holes that are now going to  
12 be added and upper former plate will vary. And the  
13 Delta Ps also vary after you do that design,  
14 depending on the design of the flow holes through  
15 the other plates that were there originally. And  
16 they vary. And the degree of reduction in Delta P  
17 that you get will vary depending on the design of  
18 the original plant and the flow holes in those  
19 baffle formers. So it gets complicated.

20 The work itself is all done, of course,  
21 under water and controlled, special tooling,  
22 special controls for foreign material and other  
23 things. And as well as all of the design analysis.  
24 Now your accident analysis need to be revisited.  
25 Many of them need to be revised with all of the new

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 core bypass values, even going back to your core  
2 physics specifications will be changed accordingly,  
3 so from an engineering standpoint, there's a lot of  
4 paperwork and design modifications, 50.59 reviews,  
5 and revisions to perhaps a lot of these accident  
6 analyses. So it's quite an undertaking to convert,  
7 but it is and can be done.

8 MEMBER RICCARDELLA: Is there a  
9 significant difference in power output in the fluid  
10 or not?

11 MR. RUDELL: I guess I wouldn't say  
12 significant with the higher core bypass flow. You  
13 will lose some of --

14 MEMBER RICCARDELLA: I mean a percent?

15 MR. RUDELL: About that.

16 MEMBER RICCARDELLA: Thank you.

17 MR. RUDELL: About that core bypass  
18 flow, I don't know what it comes out to in power.

19 MEMBER SKILLMAN: Thank you.

20 MR. POEHLER: Now I'm going to talk a  
21 little about the clustering effects. So the theory  
22 that clustering is -- you initially baffle-former  
23 bolts get random failures in random locations. You  
24 get a failure of one bolt, that leads to load being  
25 transferred to adjacent bolts and over several

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 operating cycles this can cause the adjacent bolts  
2 to the original bolt to crack which leads to  
3 clusters of failed bolts. Some people call that  
4 unzipping. That has been observed in French  
5 plants when they did successive examinations. And  
6 in the U.S., in the four-loop plants, the more  
7 severe clustering was seen at Salem Unit 1.

8 So to summarize, some of the factors --  
9 sorry.

10 MEMBER KIRCHNER: Jeffrey, may I  
11 interrupt?

12 MR. POEHLER: Sure.

13 MEMBER KIRCHNER: Have you looked at  
14 the patterns of clustering from plant to plant? Do  
15 they correlate and do they correlate, I'm thinking  
16 with the -- let's see, you have D.C. Cook, this  
17 diagram here. Do the other plants show the same  
18 clustering for degradation?

19 MR. POEHLER: You know, for Indian  
20 Point, the clustering was less pronounced than  
21 that. D.C. Cook, if you look at -- if you consider  
22 where the 2010 failures were and that was pretty  
23 clustered in that one plate. But Salem was  
24 probably even a little more clustered than D.C.  
25 Cook.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1                   MEMBER KIRCHNER: By clustering though,  
2                   could you give us a little more precision where was  
3                   it happening in the relative core location? At the  
4                   top, one would expect it, right?

5                   MR. POEHLER: Yes.

6                   MEMBER KIRCHNER: And in the smaller  
7                   plates?

8                   MR. POEHLER: Yes, both smaller -- I  
9                   mean yes, smaller and larger plates, but at Salem  
10                  it was more over about three of the octants --  
11                  basically three eighths of the total baffle-former  
12                  assembly had a lot of clustering. And it wasn't  
13                  necessarily -- I don't know, maybe Westinghouse  
14                  could comment. I don't -- I didn't think it was  
15                  really more either at the top or bottom or center  
16                  of the elevation of the plates.

17                  I think in Cook, as we definitely saw  
18                  that one cluster from 2010 was more toward the top  
19                  of the plate.

20                  MR. WILSON: Yes, this is Bryan Wilson  
21                  from Westinghouse. I mean for Indian Point and  
22                  Cook, there seemed to be more of a trend towards  
23                  the top. I think the Salem was a little bit more  
24                  widespread at the time whenever the indications  
25                  were discovered. Whether it started in a certain

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 location or not, is yet to be determined I think,  
2 but it did have -- I'd say as the clustering tailed  
3 off, it did have the trend to be say more towards  
4 the top, not focused necessarily on the bottom.

5 MEMBER KIRCHNER: And to follow up, was  
6 it more in the region of the smaller plates here,  
7 this part of the core?

8 MR. WILSON: There was both. Well, as  
9 far as -- coordinate location, you know, it was I'd  
10 say clocked similarly to Cook where it was a large  
11 patch in the wide plate, the 12 bolt wide plate and  
12 that it moved. I'd say clustering was occurring to  
13 say one side of that wide plate into the say  
14 narrower plates.

15 MEMBER KIRCHNER: The narrower plates  
16 having a higher Delta P across them?

17 MR. WILSON: No. They have the same  
18 Delta P, but because of their width, the load per  
19 bolt is slightly different.

20 MEMBER BALLINGER: The pre-load, back  
21 to the pre-load, you say they were lubricated?

22 MR. WILSON: Yes.

23 MEMBER BALLINGER: And they're torqued.  
24 Do you know what the uncertainty is on the pre-load  
25 stress?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 I've got some experience with bolt  
2 loads and sometimes that uncertainty can be  
3 enormous, even for the best of circumstances.

4 MR. WILSON: Right, yes, I mean that  
5 has all been studied many times in the variations,  
6 but I don't know at that time what the variations  
7 that they were measuring. I know a lot of testing  
8 has been done since then to look at those  
9 variations and account for them.

10 I can't comment specifically at that  
11 point in manufacture, in this history what the --

12 MEMBER BALLINGER: Typically, 50  
13 percent sometimes.

14 MR. WILSON: Right.

15 MEMBER RICCARDELLA: I've seen data  
16 where if you're shooting for 70 percent, you're  
17 getting anywhere between 50 percent and 90 percent  
18 of yield.

19 MEMBER BALLINGER: And since IASCC is a  
20 nonlinear function of stress.

21 MR. WILSON: Yes. Certainly, add to  
22 the list of contributors, right?

23 MEMBER SKILLMAN: Let me ask to go back  
24 to slide 25 just for a second, please? My question  
25 is for Bernie.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1                   Bernie, you used the word 50.59. I  
2 would think if a plant wanted to change from  
3 downflow to  
4 upflow, the 50.59 screening would very quickly push  
5 you into a license amendment request. Is that your  
6 understanding, too?

7                   MR. RUDELL: I actually don't know  
8 whether all these upflow conversions were done  
9 under license amendment or not.

10                  MEMBER SKILLMAN: Could you find that  
11 out? It would seem to me that if you were to  
12 decide in your going through the 50.59 which is  
13 really a screening, you would tumble one or two or  
14 several things, either a change in analysis, change  
15 in fuel temperature, or major change in plant  
16 design. And I would think number three would be  
17 the hook that would require a license amendment  
18 request. It's a curiosity question, but I concur  
19 with you. This is a very substantial undertaking  
20 and I'm not suggesting that anybody should do that  
21 because of the magnitude of the work that is  
22 involved. But I'm curious, there have been other  
23 examples in industry where the applicant has used  
24 50.59 and has suffered as a consequence by not  
25 going to a full LAR, license amendment request. So

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 would you get back to me, please?

2 MR. RUDELL: Okay.

3 MEMBER SKILLMAN: Thank you.

4 CHAIRMAN SUNSERI: Jeffrey, we are  
5 slightly behind schedule here, so I'm not asking  
6 you to speed up, but just be mindful of that. I  
7 suspect with the discussion that we're making up  
8 some time on the second part of this presentation,  
9 but let's try to move the pace along a little bit.  
10 Thank you.

11 MR. POEHLER: Yes, so just to summarize  
12 some of the factors influencing degradation of  
13 baffle-former bolts, it involves a complex  
14 interaction of stress, fluence, and fault material  
15 and design. You have some other aging mechanisms,  
16 void swelling, and stress relaxation can both  
17 influence IASCC bolts. Right now, the industry is  
18 working on predictive models for baffle-former bolt  
19 degradation which would account for all of these  
20 different variables.

21 Also, the staff observation is that the  
22 highest susceptibility to degradation seems more  
23 related to stress differences rather than  
24 differences in fluence between the various plant  
25 designs.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 I'm going to briefly talk about  
2 inspection replacement. I think we've talked a lot  
3 about it already. Inspection is either by  
4 ultrasonic or visual examination. Ultrasonic  
5 testing is right now only for detection of flaws.  
6 It's not demonstrated for sizing. Any bolt with a  
7 crack-like indication is called potentially  
8 defective.

9 Visual examination, VT-3, is not  
10 specified for baffle-former bolts. Some plants  
11 have performed voluntary VT-3s in response to  
12 operating experience. It is used for the baffle  
13 edge bolts as the primary inspection. VT-3 can  
14 find evidence of failed bolts such as displaced  
15 lock bars for treating or missing bolt heads. And  
16 some of the failed bolts have been detected by  
17 other visual inspections that were not VT-3  
18 inspections such as those at Cook in 2010.

19 Replacement bolts, I think she's going  
20 to talk a little more about this, but a lot of  
21 bolts can be removed intact when you cut the lock  
22 bar. The shanks, they're broken off. They can  
23 sometimes be removed mechanically, but might  
24 require electro-discharging machining.

25 The replacement bolt design uses an

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 expandable locking cup, so you don't have to weld  
2 on the highly irradiated baffle plate material.  
3 And those bolts are 316 as we mentioned. They may  
4 have been improved geometry or reduced stresses at  
5 head-to-shank transition.

6 Next. Okay, so the next part of this  
7 presentation I'm going to talk a little bit about  
8 evaluation of baffle-former bolt degradation, how  
9 do we evaluate when they find conditions that are -  
10 - that don't meet the acceptance criteria.

11 I'm going to talk about acceptable bolt  
12 pattern analyses. So there's WCAP-15029. That's  
13 the NRC approved generic methodology for  
14 determining acceptable patterns of intact baffle-  
15 former bolts and that goes back to around 2000 when  
16 they were doing the original pilot inspections.

17 The methodology uses the MULTIFLEX  
18 computer code to determine accident loadings. Some  
19 of the acceptance criteria include bolt stresses,  
20 fuel grid impact loads, momentum flux which is a  
21 parameter related to baffle jetting, also fatigue,  
22 but high and low cycle fatigue and core bypass  
23 flow.

24 When they evaluate, NES found bolt  
25 degradation, any degraded is assumed to carry no

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 load, no it's completely discounted in the  
2 acceptable bolt pattern analysis. It does use the  
3 irradiated material properties for bolts which  
4 increases the strength of the bolts. And plants  
5 have used this methodology both to evaluate as-  
6 found conditions, you know, if you have a few bolts  
7 degraded or it's okay to start up without placing,  
8 and also for potential replacement patterns to make  
9 sure that the stresses and other criteria are okay.

10 In some cases, you might not meet the  
11 stress and fuel grid impact criteria and if you do  
12 exceed those fuel grid impact criteria, you might  
13 need to demonstrate a coolable geometry with some  
14 damage to peripheral fuel assemblies. The WCAP-  
15 15029 provides some guidance on how you do that.

16 CHAIRMAN SUNSERI: I'm not sure where  
17 to ask this question. This might be a good place  
18 to do it, but I noticed a lot of the evaluation of  
19 acceptability has been based around stress and  
20 structural concerns.

21 I had a question that I got from  
22 looking at the Westinghouse Nuclear Safety Advisory  
23 Letter. It deals with the emergency flow cooling  
24 flow. I don't have a good sense for how much flow  
25 can get past this baffle and maybe bypass part of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 the core. It indicated it was nominal. It was  
2 dismissed as nominal, but I mean do we have more  
3 quantification of that and whether that could  
4 potentially be a problem in a severe unzipping if  
5 you will?

6 MR. WILSON: Yes, so we did look at --  
7 for the safety evaluation that was done by  
8 Westinghouse. I'll talk a little bit about this  
9 later, but we considered a condition where the  
10 baffle plate was basically had no baffle-former  
11 bolts intact. So I would say that's a very severe  
12 condition. We also -- regarding edge bolts, we  
13 assumed that the edges of the bolt -- of the baffle  
14 plate were simply supported, such that the baffle  
15 plate could flex inward towards the fuel assembly.

16 In that condition, it was evaluated at  
17 about 4.5 percent or 1.4 percent bypass flow could  
18 occur. That was looked at in these emergency core  
19 cooling scenarios, LOCA and non-LOCA, and was  
20 determined to be say within the bounds of margin,  
21 it was available in those evaluations and the  
22 levels of conservatism that were already built into  
23 those evaluations.

24 So we don't expect, under that  
25 circumstance, to be a concern with the amount of --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1                   CHAIRMAN SUNSERI:    So it's within the  
2 bounds of the margin, but I mean --

3                   MR. WILSON:       Yes, easily within.    It  
4 wasn't up against the edge.    It was -- I'd say  
5 dismissed as negligible with respect to what's  
6 available in conservatism and margin.

7                   CHAIRMAN SUNSERI:    Okay, thank you.

8                   MR. POEHLER:       And I'll talk about  
9 reinspection intervals.    So if you do find a large  
10 number of degraded bolts, there is another WCAP  
11 17096 which staff recently approved.   It's reactor  
12 internals acceptance criteria and methodology and  
13 data requirements.   And this provides guidance for  
14 engineering evaluation of baffle-former bolt  
15 degradation.   It actually covers all of the  
16 different PWR internals, but baffle-former bolts is  
17 one of them.

18                               So there's a numerical margin which can  
19 be determined which consists of additional bolts  
20 over and above the number and the minimum bolting  
21 pattern.   The minimum bolting pattern is that  
22 pattern that has the fewest number of bolts that  
23 would meet all the acceptance criteria and that  
24 also -- the location of the bolts is also a factor.  
25 Obviously, if they're severely clustered they may

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 not need certain stress criteria.

2 So what the WCAP 17096 says the number  
3 of degraded bolts you find is less than half the  
4 margin, you can continue -- you can start up and  
5 reinspect again in ten years without replacing  
6 those bolts. If the number of degraded bolts is  
7 greater than half the margin, you have to justify a  
8 different reinspection interval. So the plants  
9 with these outages in 2016 that had large numbers  
10 of degraded bolts, they would not have met the WCAP  
11 criteria. So those plants elected to replace  
12 essentially all, at least all the bolts that were  
13 degraded through historical structural margin.  
14 Industry is still developing models for failure  
15 rates of baffle-former bolts. So we do need to see  
16 reinspections of bolts at shorter intervals, at  
17 least now, to establish what are the failure rates  
18 of these bolts.

19 Okay, now I'm going to talk a little  
20 about the NRC response to this operating experience  
21 of baffle-former bolts. First thing is regional  
22 inspections. So the NRC staff performed targeted  
23 inspections at the three plants, Indian Point,  
24 Salem, and we're currently still in the inspection  
25 at D.C. Cook. Those inspections are focusing on

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 the quality and accuracy of the non-destructive  
2 evaluation. They're focused on the corrective  
3 actions including how you show the operating unit  
4 is still okay to continue operating. They focused  
5 on adequacy of their replacement bolt pattern  
6 including margin for additional failures during the  
7 next cycle.

8 There's also these inspections, at  
9 least for Indian Point or Salem are documented and  
10 publicly available inspection reports. And  
11 regional inspectors are engaging with other plants  
12 with regard to operability evaluations and plants  
13 with upcoming outages. And those are the plants  
14 that -- mainly the plants that are similar to the  
15 ones that have found the degradation.

16 MEMBER SKILLMAN: Jeffrey, how is the  
17 inspection protocol established for these  
18 inspections?

19 MR. POEHLER: How is the protocol  
20 established?

21 MEMBER SKILLMAN: Yes. Do you have an  
22 inspection procedure?

23 MR. POEHLER: They do.

24 MEMBER SKILLMAN: And how was that  
25 established?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. POEHLER: You mean specifically for  
2 baffle-former bolts?

3 MEMBER SKILLMAN: Yes. At the top of  
4 33, you're saying staff performed targeted  
5 inspections. What's their basis for the  
6 inspection? What does the inspection prove?

7 MS. ROSS-LEE: I'm sorry, wasn't the  
8 initial inspection -- sorry, this is M.J. Ross-Lee.

9 I think at least the inspections were  
10 done as part of the MRP 227A. So the aging  
11 management said hey, you should look at these in  
12 the certain EFPY for the plant. And so Indian  
13 Point did that so -- that's what the inspections  
14 were a part of was part of our aging management  
15 program. So in this period of time you should  
16 look, do this inspection, and that's what they were  
17 doing at Indian Point.

18 MEMBER SKILLMAN: So if I repeat back,  
19 it was part of the AMP for that plant?

20 MS. ROSS-LEE: Is that a correct  
21 characterization of the MRP 227?

22 MR. POEHLER: Yes, what the licensee --  
23 the physical inspections conducted by the licensee,  
24 yes, are part of the AMP. But then the activities  
25 of the NRC, I think you're asking about the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 activities of our NRC inspectors?

2 MEMBER SKILLMAN: I am. I'm referring  
3 back to the first bullet on Slide 33.

4 MR. POEHLER: Basically, I don't think  
5 they have a specific inspection procedure just for  
6 baffle-former bolts. But the type of inspections  
7 they were doing were -- they called it a problem  
8 identification resolution sample, so it's, you  
9 know, targeted at this specific issue, but --

10 MS. ROSS-LEE: We might have -- I'm  
11 sorry, this is M.J. Ross-Lee.

12 There might be regional people  
13 listening. We might have to get back to you. Yes,  
14 so I answered the question on why the industry was  
15 doing them. It was upon discover of the number of  
16 degraded bolts which was greater than what was  
17 expected that led our inspectors to engage and what  
18 we're, I guess, referring to there as a targeted  
19 inspection. But if you need more specific detail,  
20 I'll probably have to try to reach out to one of  
21 the regions to get those detailed answers.

22 MEMBER SKILLMAN: What I was really  
23 exploring was the formality of this inspection,  
24 whether it's a standing inspection procedure, or if  
25 this is a special inspection protocol that has been

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 developed between the NRC and industry, based on  
2 the MRP, for these specific findings or whether  
3 this is just a Keystone Cop showing up with a  
4 magnifying glass and a sounding pin.

5 I have a hunch, it's very formal. It's  
6 very well constructed. When you say it can be  
7 reviewed, that suggests to me a level of inspection  
8 formality that's very, very serious. So my  
9 question is what is that? Is that an IEP? Is that  
10 a special inspection? Is it just a PI&R? How  
11 formal is this for the NRC inspectors because if  
12 they have to do this at plants other than Salem and  
13 D.C. Cook and Indian Point, perhaps there needs to  
14 be a rigid formality to this.

15 MR. POEHLER: I mean I don't think it's  
16 not a special inspection. It is a PI&R. But they  
17 would have a test or an inspection plan ahead of  
18 time.

19 MS. ROSS-LEE: We might -- I'm sorry,  
20 this is M.J. Ross-Lee again. To get the answer to  
21 your question, we have to get -- it's a formal  
22 inspection. It's documented. There are inspection  
23 reports that are issued on it. I don't have access  
24 to those right here, but at least for the two that  
25 are done and public, we can pull those up, find the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 actual inspection procedure that was used. So we  
2 can get that information back for you. I just  
3 don't have it with me right here.

4 MEMBER SKILLMAN: Thank you.

5 MR. POEHLER: Another part of the NRC  
6 response was we performed what we call a LIC-504  
7 evaluation. LIC-504 is an office instruction. The  
8 title of it is Risk-Informed Evaluation of Emerging  
9 Issues. It's basically a process we use to  
10 evaluate the safety significance of new issues and  
11 so we look at different options for addressing the  
12 issue. Basically, it boils down to do you need to  
13 -- is this a safety issue that warrants shutting  
14 the plant down immediately or not?

15 But under the four options we looked at  
16 for the baffle-former bolt issue were immediate  
17 shutdown and inspection, or inspection next  
18 refueling outage. This is inspection of the  
19 baffle-former bolts. Doing a generic communication  
20 to gather more information, or just maintaining the  
21 status quo which would just be let them keep on  
22 inspecting as per the guidance to the MRP 227 on  
23 that schedule.

24 When you do the LIC-504 process, you  
25 look at five criteria and compliance with existing

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 regulations, consistency with defense-in-depth  
2 philosophy, maintenance of adequate safety margins,  
3 demonstration of acceptable levels of risk, and  
4 implementation of defined performance measurement  
5 strategies.

6 So what were the results of this LIC-  
7 504 evaluation? Well, the risk met the two LIC-504  
8 criteria are core damage frequency of less than 1  
9 times 10 to the minus 3rd and large early release  
10 frequency less than 1 times 10 to the minus 4 per  
11 year. So if you're above those risk levels, then  
12 that would indicate you probably need to shut down  
13 immediately. If you're below them, you don't.

14 The risk levels for LOCA, they're  
15 driven by basically the low frequency of large and  
16 medium LOCAs results in low core damage frequency  
17 due to LOCA. Small break LOCAs are more frequent,  
18 but we don't think they have the potential to  
19 detach or deflect baffle plates such that it would  
20 cause significant fuel damage.

21 Also, there was a separate seismic risk  
22 assessment performed that used bounding seismic  
23 hazard curves in U.S. based on recent updated  
24 seismic hazard submittals. And the seismic  
25 assessment also assumed a 75 percent reduction in

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 load-carrying capacity for the baffle-former bolts  
2 which is much greater than we've seen at any plant  
3 where it's been limited to about 25 percent  
4 degradation.

5 MEMBER POWERS: I don't contest your  
6 conclusion here, but it's -- I'm not understanding  
7 exactly how you arrive at a CDF and a LERF analysis  
8 here. You seem to be dependent on fairly large  
9 LOCAs  
10 to get an incremental risk. And so I'm wondering  
11 how you concluded that those LOCAs were worse than  
12 ordinary LOCAs, LOCAs without this problem? How  
13 did you do that?

14 MR. POEHLER: So we have C.J. Fong here  
15 from the Division of Risk Assessment. I think he  
16 wants to speak to this question.

17 MR. FONG: Sure. Thanks, Jeff.

18 Hi, Dr. Powers. This is C.J. Fong at  
19 NRR Division of Risk Assessment. I've got Steve  
20 Laur on the phone who performed the detail risk  
21 analysis. If we really want to get into the nuts  
22 and bolts, I'll ask that we patch him in, but I  
23 think I can at least take a shot at the initial  
24 question.

25 What Steve did was he made the very

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 conservative assumption that any initiating event  
2 with the capability of imposing additional load on  
3 the baffle-former bolts could deflect them such  
4 that core flow would be blocked.

5 Now Mr. Wilson at Westinghouse pointed  
6 out, we think that's probably not the case, but  
7 just as a first cut, we assigned a conditional core  
8 damage probability of one to any event that could  
9 deflect or significantly deform the baffle-former  
10 plates.

11 And so it turned out that it was large  
12 and medium LOCAs. And what Steve did was he looked  
13 at both your kind of traditional LOCA cost by long-  
14 term material degradation and also LOCA that was  
15 induced by seismic event. And as Jeff pointed out,  
16 we used the weight of seismic curves and  
17 fragilities and also Steve used the LOCA  
18 frequencies from NUREG-1829.

19 MEMBER POWERS: Thank you. That  
20 certainly illuminates what you did. It's certainly  
21 a conservative approach. I'm struggling mightily  
22 to understand how much of a public health and  
23 safety risk this particular issues covers it. And  
24 that kind of very conservative analysis is useful,  
25 I think, especially if we're going through your

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 process. It's not unreasonable, but it's not  
2 illuminating for me with a realistic risk to public  
3 health and safety is here.

4 I hope somebody can explore that a  
5 little for me.

6 MS. ROSS-LEE: This is M.J. Ross-Lee,  
7 NRR. So I think that based on the somewhat  
8 bounding, perhaps conservative analysis that was  
9 done, as well as other criteria that we looked at,  
10 for instance, when you look at the different  
11 options, we balance things like transience or  
12 burden if we were to make them shut down as well as  
13 well, if we don't do anything.

14 And I believe that considering the  
15 realistic risk to the public is what led us to pick  
16 the option that we did which is to have them do  
17 inspections at a more frequent interval or sooner,  
18 so everybody is committed to doing inspections at  
19 their next outage at the most susceptible plant.

20 So I think we've tempered what the  
21 actual numbers ran versus the other knowledge that  
22 we have to feel comfortable that the risk to the  
23 public is such that it is acceptable to do Option 2  
24 which is waiting for the next outage. At that  
25 point in time, perhaps based on those results that

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 are gleaned, we would maybe have to relook at our  
2 LIC-504, our choice in options.

3 So to quantify the realistic risk if  
4 that's what you're looking for as far as a number,  
5 we haven't done that. I do believe that we have  
6 put a number of factors together to believe is one,  
7 we don't need to shut them down right now, but  
8 Option 4, we're not going to ignore this and just  
9 wait and see what happens. So we picked what we  
10 thought was the realistic option and that is to  
11 have them move up the most susceptible plants in  
12 the initial tier to move up their inspections all  
13 of which will be completed by I believe the end of  
14 2017.

15 MEMBER POWERS: Well, I think I  
16 understand what you've done for now. What I am  
17 wondering is what do you do in the future? Is this  
18 a problem that we can say okay, problem resolved,  
19 licensees, your problem or is it a continuing risk  
20 to the public health and safety? I'm not getting  
21 an understanding of why it's a continuing risk to  
22 the public health and safety.

23 MR. FONG: Dr. Powers, I think the way  
24 I would respond to that is that we really have two  
25 separate risk-informed processes. LIC-504 is for

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 emerging conditions. Do we have an immediate  
2 safety issue where we need to have plant shutdown  
3 right away? We feel the analysis we performed,  
4 while conservative, was certainly sufficient to  
5 support that decision.

6 Down the road, if there's a different  
7 question, for example, should a licensee be allowed  
8 to just live with this for the life of the plant,  
9 that would be maybe a Reg. Guide 1.174 decision  
10 which has different acceptance guidelines and it's  
11 a different process.

12 So I think we used the right tool for  
13 this decision. I certainly understand what you're  
14 saying down the road, if there's a different issue  
15 or different question that we're trying to answer,  
16 we can enter a different process, like a license  
17 amendment using Reg. Guide 1.174.

18 MEMBER POWERS: Thank you. I  
19 understand exactly what you've done. My question  
20 is a little different.

21 MS. ROSS-LEE: Sorry, this is M.J.  
22 Ross-Lee. So I believe at this point in answer to  
23 your question have we reached a decision that we're  
24 just going to let industry do what they want with  
25 this, I would say the answer to that is no.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1           Again, this tool gave us an answer for  
2           now. It had a recommendation that they need to  
3           move up the inspections. We're going to look at  
4           those inspections as an agency. We'll look at what  
5           the results of those are. We're staying very  
6           plugged in with the root cause analysis. That will  
7           be looked at.                   At each of those steps  
8           along the way, we'll have to look at what our  
9           agency response is. We'll have to look at is the  
10          current aging management guidance in MRP-227A  
11          acceptable or do we need to, in fact, change the  
12          inspection frequency in there because every ten  
13          years isn't the right answer. So I certainly don't  
14          feel that at any point we would just make this an  
15          industry issue or problem. We'll continue to stay  
16          engaged and we'll look at the tools that we have to  
17          stay engaged and perhaps make changes as necessary,  
18          based on the results that we get.

19                 We have a couple of data points now.  
20                 We're aware of those. We'll get more data points  
21                 as we get inspections coming forward over the next  
22                 year. If our position on the safety significance  
23                 of this would change, we would react at that time.

24                         MEMBER POWERS: The problem is I really  
25                         don't understand the safety significance here. I

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 don't think you've outlined it. You've done a very  
2 conservative analysis and it's probably one I would  
3 have done to satisfy your immediate need. But to  
4 go forward and say what beyond this, I think I'd  
5 need a little more definitive, a little more  
6 realistic kinds of risk analysis to tell me how  
7 much effort I'm going to expend on this particular  
8 issue from a regulatory perspective.

9 MS. ROSS-LEE: Noted. I know that at  
10 the next point which we would have information to  
11 inform any sort of analysis would be following  
12 perhaps some of the bolt testing, some of the  
13 material information which currently we don't have.  
14 And we would have additional information from  
15 follow-on inspections that could --

16 MEMBER POWERS: I'm not sure that's  
17 your most formidable problem in getting to a  
18 realistic risk assessment. I think your most  
19 formidable problem is defending the idea you've got  
20 LOCA codes that can handle realistic deflections of  
21 the baffle-former plate to say there's any  
22 incremental risk associated with that. I think  
23 that's the challenge you're going to face is that  
24 you're burdened because of the limitations of your  
25 existing analytical capabilities to making pretty

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       Draconian conservative assumptions here. And I'm  
2       suspect of those. I think you'd have to come in  
3       and put a pretty stout defense on what you've done  
4       in your accident analysis tools. I don't know how  
5       you do that. I don't think you have the data to  
6       sustain an argument that there's a substantial risk  
7       to the public health and safety from this.

8               MR. FONG: Dr. Powers, I think I would,  
9       in general, agree with that. Risk, of course, if  
10      frequency times consequence. I think we've got a  
11      handle on the frequency of the different initiating  
12      events. We recognize there's some uncertainty  
13      there.

14             As far as the consequence goes, we had  
15      to make a very conservative assumption that hey, if  
16      the LOCA happens the baffle plates somehow enter a  
17      geometry where they're blocking flow completely and  
18      the core goes to core damage. I don't think that's  
19      really 100 percent chance of that happening, but  
20      right now don't have the information to assign a  
21      more realistic value.

22             As M.J. pointed out, we're gathering  
23      data. There's destructive engineering going on of  
24      bolts and things like that. We might, in the  
25      future, have a better way to model the consequences

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 as part of the risk equation, but right now --

2 MEMBER POWERS: I am not at all  
3 criticizing what you've done here. I am saying  
4 that you can research the bolts until the cows come  
5 home. You're not going to answer the real question  
6 on what's the risk to public health and safety from  
7 this particular event. That's not where the real  
8 technical issue is going to be. It is precisely  
9 the approximation that you found yourself forced to  
10 make to do this that's going to be the real  
11 question.

12 MS. ROSS-LEE: We are way behind. If  
13 you could try to move through. I think we've  
14 probably touched on this about as much as what  
15 information we can provide and then I think go on  
16 to the last slide.

17 MR. POEHLER: Yes. So second to the  
18 last slide. So just to summarize the NRC's  
19 evaluation of the recent operating experience. Our  
20 preliminary conclusion is that it's the  
21 Westinghouse four-loop design downflow plants with  
22 Type 347 bolts that are more susceptible to baffle-  
23 former bolt degradation than other PWR designs.

24 There are seven plants in that group  
25 which are listed here. Also, EPRI is going to talk

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 about -- industry is going to talk about this a lot  
2 more, but the EPRI and Materials Reliability  
3 Program has issued interim guidance that calls for  
4 UT inspection of all baffle-former bolts at the  
5 next refueling outage for these plants, these seven  
6 plants which they call Tier 1A.

7 The NRC is also monitoring inspections  
8 and other actions at all these plants. We feel  
9 that the immediate safety concern for these plants  
10 is addressed by our LIC-504 evaluation.

11 Finally, future activities for NRC,  
12 we're following the root cause investigation at  
13 D.C. Cook 2, focusing on the cause of degradation  
14 in the replacement bolts and also the baffle-edge  
15 bolts. We're going to look at the LIC-504 to  
16 determine if it needs to be revised based on the  
17 new developments at D.C. Cook Unit 2.

18 We are going to continue to engage with  
19 the industry, especially on the root cause for the  
20 three plants. We're going to discuss with the  
21 industry if they need to make changes to the  
22 interim guidance.

23 We plan to develop an information  
24 notice. We are going to document our staff  
25 assessment of the MRP's interim guidance. And

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 finally, we're going to determine if changes to the  
2 overall MRP-227-A guidance for baffle-former bolt  
3 inspections are needed.

4 So that concludes the NRC's  
5 presentation. If there are any further questions?

6 MEMBER KIRCHNER: I have a question  
7 getting at root cause. Do you have maps of each of  
8 the plants and where these baffle-bolt failures  
9 occurred like the nice presentation you gave us was  
10 Cook?

11 MR. POEHLER: Yes, we do.

12 MEMBER KIRCHNER: Have you looked at  
13 these patterns and do you see any repeats in terms  
14 of where you're finding clusters of bolt failures?

15 MR. POEHLER: I mean I think not  
16 necessarily exactly the same patterns are seen in  
17 all the plants. I don't know that we've done a  
18 detailed analysis of that.

19 MS. ROSS-LEE: This is M.J. Ross-Lee.  
20 I would say at least at this point we haven't --  
21 there's not an obvious correlation or similarity in  
22 those bolting patterns that we've been able to  
23 determine.

24 MEMBER KIRCHNER: Thank you.

25 CHAIRMAN SUNSERI: All right, at this

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 time, thank you for the presentation. Appreciate  
2 the information you provided.

3 At this time, we're going to take a 15-  
4 minute break. We will resume with the industry  
5 presentations at 20 'til based on that clock.

6 (Whereupon, the above-entitled matter  
7 went off the record at 10:25 a.m. and resumed at  
8 10:40 a.m.)

9 CHAIRMAN SUNSERI: All right, we're  
10 going to reconvene the Metallurgy Subcommittee  
11 briefing here. We'll begin with the industry  
12 presentation and Bernie Rudell is going to  
13 introduce the team and start us off.

14 Bernie?

15 MR. RUDELL: Yes. Thank you very much.  
16 It's a pleasure to be here with the Advisory  
17 Committee to share our experience so far with  
18 regards to this issue in the pressurized water  
19 reactor industry, specifically with the baffle-  
20 former bolt issues.

21 We have Heather Malikowski here today.  
22 She's the chairman of the PWR Owners Group Material  
23 Subcommittee. And Bryan Wilson, a member of that  
24 committee as well, but he represents Westinghouse  
25 and also a lot of the analysis that Westinghouse

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 has done for both the technical bulletin back in  
2 2012 and now additional analysis that's been done.  
3 And you'll hear about that in this presentation.

4 I also have on the line, I believe,  
5 Steve Fifitch. Are you there, Steve? He's there  
6 and if we need so, he can jump in. He's  
7 representing AREVA, also a member of the PWR Owners  
8 Group.

9 My name is Bernie Rudell. I'm the  
10 chairman of the Integration Committee of the EPRI  
11 Materials Reliability Program and we have the lead  
12 as an issue program under NEI-0308, the Materials  
13 Degradation Management Program for the PWR reactor  
14 vessel internals.

15 So we have representatives from both  
16 the Owners Group and MRP and some PWR suppliers  
17 here to present information.

18 Jeff did such an excellent job and I  
19 read through his draft slides the other day and I  
20 said there wasn't much left for us to present. So  
21 hopefully, we can go through our slides and just  
22 hit maybe some of the highlights where we heard  
23 some questions and elaborate on those and you can  
24 jump in with additional questions if they come to  
25 mind. And we can give you the information that we

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 know there or get back to you at a later time, for  
2 example, with the 50.59 evaluation question that we  
3 had earlier.

4 As I mentioned, baffle-former bolt,  
5 we'll call it BFB, examination is a subset of the  
6 PWR reactor vessel internals Aging Management  
7 Program and that's really under the NUREG-1801 GALL  
8 or General Aging Lessons Learned Program and the  
9 NEI-0308 Guidelines for Management of Material  
10 Issues and Inspections and Evaluation. That  
11 guidance is prescribed in, as Jeff pointed out, our  
12 MRP 227 and it's got the -A now because it also  
13 includes the NRC's safety evaluation which accepts  
14 that guidance on PWR internals and inspections.

15 This spring at two PWRs, a large  
16 percentage of baffle-former bolts failed  
17 examination that had typically been experienced  
18 before. Before we were seeing one to five, and  
19 maybe an occasional near ten percent failure of  
20 baffle-former bolts.

21 Fortunately, there's a lot of margin in  
22 the number of baffle-former bolts in these designs  
23 and that margin varies, dependent on the design and  
24 it depends on that particular station's LOCA  
25 analysis and so forth as well. And the leak before

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 break that has been adopted for that unit because  
2 it's typically the LOCA and seismic event that  
3 governs the minimum bolt pattern analysis which, as  
4 Jeff pointed out, is also performed by NRC safety  
5 evaluation accepted methodologies.

6 Although there's margin in the number  
7 of required bolts from what is there originally,  
8 these findings did trigger a substantial safety  
9 hazard look-see under 10 CFR 21. And it turned out  
10 that these findings do not constitute a substantial  
11 safety hazard status under 10 CFR 21. The large  
12 percentage did not meet the acceptance criteria  
13 though in our WCAP 17096 that Jeff also alluded to.  
14 And in these cases, the distribution of failures  
15 have caused further attention to the topic,  
16 particularly this clustering effect that we see.

17 In response to this experience, MRP  
18 invoked the protocol for potential generic material  
19 issue and that protocol is prescribed under NEI 03-  
20 08. Westinghouse has issued a Nuclear Safety  
21 Advisory Letter, NSAL. And AREVA has issued a  
22 Customer Service Notice. The PWR and Material  
23 Reliability Program formed a joint baffle-former  
24 bolt focus group and have issued NEI 03-08 interim  
25 guidance that was approved by the PWR Materials

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 Management Program which is our executive branch,  
2 if you will, under the NEI 03-08 issue program for  
3 PWRs.

4 We've got a lot of attention to this.  
5 The entire EPRI year emergent funds for emergent  
6 issues has been allocated to the baffle-former bolt  
7 work that's going on. We've redirected efforts  
8 from lower priority work that we were doing to the  
9 baffle-former bolt. There's a lot of research  
10 involved here going on and both where it fits under  
11 our appropriate jurisdiction in the PWR owners  
12 group area and the EPRI MRP area and then in some  
13 cases to the specific licensee and work they're  
14 having done to go through and address  
15 programmatically what they need to do as well.

16 So the guidance, as I mentioned, is  
17 approved. A lot of that guidance so far as matched  
18 up almost one for one with the NSAL, but the  
19 guidance carries the NEI 03-08 needed requirements  
20 there so that we would be informed as would the NRC  
21 if there was any deviation from that guidance. And  
22 for example, all of these Tier 1A plants have  
23 inspection scheduled now in their upcoming  
24 refueling outage.

25 Communications were had. We've had

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 several face-to-face meetings. In fact, we had a  
2 meeting with the focus group Monday this week in  
3 San Antonio and there were about 70 people that  
4 attended that meeting. So we're very interested in  
5 this subject and getting it behind us as an  
6 industry. And I think we're doing all of this in  
7 the spirit of the GALL and the fact that this is a  
8 living program. We're going to learn. We're going  
9 to look at what appears to be the material  
10 degradation areas that may pop up and adjust from  
11 the results that we see. And in this case, I  
12 believe we see a few plants, we hope limited to a  
13 particular subgroup because and that's what it  
14 appears to be. We'll show you evidence of that,  
15 that we can get through and then resume to an  
16 inspection and monitoring and replacement program  
17 that will not cause us to hit unacceptable  
18 conditions of the results in the future.

19 MEMBER POWERS: Is the apparent  
20 confinement to a subset of plants just an accident  
21 of time? That is, if I go out another 20 years,  
22 then I'll find a broadened subset?

23 MR. RUDELL: That's a good question.  
24 And our research is looking into that question.  
25 Right now, today, where we are in time it appears

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 to be a particular subset. But the information  
2 that we get from a lot of this evaluation that  
3 we're doing and we have a lot of very smart people  
4 working on it will tell us do we need to change our  
5 inspection on the other plants going forward? In  
6 fact, that's what we'll be looking for in the next  
7 set, perhaps, of interim guidance that will come  
8 out. But that's a very good question.

9 MEMBER RICCARDELLA: To be clear,  
10 inspections are planned under MRP 227 for all the  
11 plants?

12 MR. RUDELL: That's correct.

13 MEMBER RICCARDELLA: It's just the  
14 timing of them and whether you accelerate them.

15 MR. RUDELL: That's correct.

16 MEMBER RICCARDELLA: Thank you.

17 MEMBER KIRCHNER: Bernie, to frame the  
18 issue again, just you have only to date found this  
19 problem in the PWRs with downflow in the baffle  
20 region, is that a fair assessment?

21 MR. RUDELL: The Tier 1 Alpha plants  
22 are the four-loop design Westinghouse plants that  
23 have operated and continually -- and are continuing  
24 to operate in a downflow condition.

25 MEMBER KIRCHNER: Right, so those other

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 Westinghouse plants or other PWRS with upflow are  
2 not experiencing this problem based on outages and  
3 inspection?

4 MR. RUDELL: That's correct.

5 MEMBER KIRCHNER: Okay, so you describe  
6 the --

7 MR. RUDELL: Based on the inspections  
8 that have been performed.

9 MEMBER KIRCHNER: -- root cause as a  
10 metallurgy and materials issue. Is it not a fluid  
11 hydraulic design issue with the plants in Tier 1?  
12 And if you were to change out those plants to  
13 downflow in the baffle region, would you  
14 essentially solve this problem?

15 I think replacing bolts is less  
16 expensive than changing flow configuration for the  
17 plant, but I'm just -- getting at the root cause  
18 may not be materials because as Dana might have  
19 suggested will you see this with further aging in  
20 other plants or is it really a fluid hydraulic  
21 phenomenon problem that's inducing this?

22 MR. RUDELL: Well, can we hold off on  
23 answering that response because I think there's a  
24 lot of things at play here and what's leading and  
25 what's lagging may even vary from one plant, a

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 model, to another plant model as well.

2 Let me check -- so just in summary, we  
3 have MRP 227 is the leading guidance that we have  
4 now. We know that baffle-former bolts is one of  
5 the primary exams, the degradation mechanism under  
6 that, and the bases that back the creation of that  
7 guidance indicate that it irradiated assisted  
8 stress corrosion cracking and fatigue. Both of  
9 those degradation mechanisms are susceptible to  
10 occurring in baffle-former bolts.

11 We have expansion criteria that we  
12 believe some of these plants have triggered and  
13 they'll need to enter into the expansion  
14 examination. The examination for baffle-former  
15 bolts is 100 percent of the accessible baffle-  
16 former bolts. And there's a prescribed time line  
17 that we're changing with some of the interim  
18 guidance now.

19 The UT that we perform is generally  
20 capable of detecting large cracks on the order of  
21 30 percent of the volume. And as Jeff mentioned,  
22 the acceptance criteria is the WCAP 17096-NP-A  
23 approved and the minimum bolt pattern WCAP.

24 So without further ado, I'm going to  
25 turn it over to Heather, and we'll go through our

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 presentations.

2 MS. MALIKOWSKI: Thanks Bernie. Thank  
3 you, Bernie. This is Heather Malikowski. I am the  
4 chair of the PWR Owners Group Materials Committee.  
5 You'll see a lot of parallels in our slides with  
6 what Mr. Poehler presented, so I will try and just  
7 highlight certain points on some of them, but  
8 otherwise, unless there are specific questions,  
9 there's something you want to go back to on those  
10 particular figures, I'm going to move relatively  
11 rapidly.

12 As we discussed, I think we're pretty  
13 much grounded on the configuration of the assembly  
14 and this is where the baffle-former bolts are  
15 located. And as we've discussed, the material  
16 differences are there, mostly more correlated also  
17 to the design of the bolts amongst the different  
18 NSSS designs and the number of loops per plant. We  
19 said the shank lengths do vary depending on the  
20 design. And Bryan Wilson will probably go through  
21 some more details on that, how it affected our  
22 analyses.

23 We discussed the difference, obviously,  
24 downflow and upflow configuration is a big part of  
25 this discussion and so we'll continue to, as I go

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 through, I'll just point out we do try and document  
2 where for the plant inspections that have happened,  
3 which plants are downflow versus upflow. We don't  
4 have all the timing, say for the ones that have  
5 converted in all cases whether their exams were  
6 prior to conversion or not. If there's interest in  
7 that, we can follow up.

8 For your reference, I think this is a  
9 good time line to show. On the top it just gives  
10 the operating experience where we started from back  
11 in 1989 with the French OE and coming through to  
12 the present with our more recent findings at Indian  
13 Point, Cook, and Salem.

14 Down at the bottom it shows some of the  
15 guidance that's been issued by the industry  
16 including the NRC. We actually did -- I just want  
17 to basically show that when the response to the EDF  
18 OE in the late '80s, we did respond and review the  
19 issue, looking for commonalities to the fleet,  
20 comparisons of many parameters. At the time,  
21 Westinghouse Owners Group put together comparisons  
22 of all the different two, three, and four-loop  
23 designs at the Westinghouse plants, trying to  
24 understand relative risks in all of that to help  
25 inform future guidance and recommendations for the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 industry.

2 So as you'll see, we get up to the late  
3 '90s, that's when the pilot inspections that Jeff  
4 referenced earlier were performed by a voluntary  
5 selection of similar plants to the EDF plants to  
6 get some additional information on the impact to  
7 the U.S. fleet.

8 And you'll see that it looks like  
9 there's kind of a large gap there where nothing  
10 happened, but that is really not the case and I'll  
11 kind of explain that there was ongoing work during  
12 that time until between when we did inspections in  
13 the late '90s until the MRP 227 industry guidance  
14 came out.

15 MR. RUDELL: You can see this is almost  
16 one of the first issues that the MRP worked on.  
17 MRP-03 back in 1990 addressed the baffle-former  
18 bolt OE that the French saw. And that inspired the  
19 Owners Group to do a lot of inspections in 1990-  
20 2000 time frame that you'll see as well in our  
21 slides a little later.

22 CHAIRMAN SUNSERI: So it is a little  
23 curious that the French plants and the comparison  
24 to the U.S. plants, the similarities must be more  
25 than just the design. Were they the same fluence

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 and age of materials? So why were the French  
2 having the problem and U.S. plants weren't, I guess  
3 is my question.

4 MS. MALIKOWSKI: So moving up to our  
5 past operating experience, the slide here does have  
6 some summary of the EDF experience from the '80s.  
7 They are a three-loop essentially Westinghouse  
8 design. They do have definite design differences.  
9 I don't know if anyone wants to elaborate on them,  
10 but they are even within the CPO design as was  
11 mentioned earlier. There are differences amongst  
12 those design plants. So the plot here that EDF  
13 shows is their inspection history over the last  
14 several years, they use operating hours as their  
15 nomenclature on the bottom for time. So it's a  
16 little different than EFPY for us. So I don't have  
17 the exact EFPY numbers.

18 But it basically shows that these are  
19 all CPO plants shown, but they definitely have a  
20 very small trend of finding any baffle-bolt  
21 failures on was it Bugey 4 and 5 versus the  
22 Fessenheim or the other Bugey units. What it shows  
23 is that even though they did convert to an upflow  
24 configuration, they do have -- they do continue to  
25 find bolt failures, but not significant numbers and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 not -- I don't believe and the interest in the OE  
2 is not necessarily clustered per se, but they are  
3 continuing to get failures and it is generally  
4 focused towards the high fluence regimes, the areas  
5 down lower in the baffle region. So they're  
6 basically seeing a continuing trend of failures,  
7 but they're not seeing an accelerated trend because  
8 they are doing replacements as they go along and  
9 continuing a replacement in the inspection  
10 campaign. So now they basically are tracking their  
11 inspection requirements with an anticipated five  
12 bolts per year failure rate and really looking at  
13 more as an irradiated effect versus now we have the  
14 extreme, the stresses have been lowered.

15 As we kind of discussed earlier, they  
16 do have this 316 material, but obviously that was a  
17 difference, but I think we are saying that's not  
18 necessarily a big indicator that that's going to  
19 fail quicker, because obviously our domestic  
20 experience doesn't show that.

21 And so other than that, I think --  
22 other than we know there's operational differences  
23 of load following versus our more base load  
24 operation, but it's not clear the magnitude of  
25 impact they have on their failures. That's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 something that's being thought of as maybe a  
2 contributor to their seeing the accelerated  
3 failure, but I don't think we have a quantification  
4 of that.

5 MEMBER RICCARDELLA: Heather, when the  
6 French replace, are they replacing with 347 or 316?

7 MS. MALIKOWSKI: 316. And they have  
8 replaced some replacement bolts, but we did confirm  
9 that was not for -- because of failure. It was  
10 actually just to continue to maintain the minimum  
11 pattern and to continue to keep the overall age of  
12 the bolts at a low amount.

13 MEMBER RICCARDELLA: Thank you.

14 MR. RUDELL: These are 316 originally.

15 MEMBER RICCARDELLA: Oh.

16 MR. RUDELL: Yes, all the French are  
17 316 original baffle-former bolts.

18 MEMBER RICCARDELLA: Thank you.

19 MEMBER SKILLMAN: Heather, are the  
20 Bugey 4 and 5, the blue and the yellow, the only  
21 plants that are the three-loop upflows on this  
22 image?

23 MS. MALIKOWSKI: I believe they're all  
24 converted to upflow. I do not know if 4 and 5 are  
25 original upflow or not. Do you know, Bryan?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. RUDELL: They are all converted and  
2 there is not a significant difference between Bugey  
3 4 and Bugey 2, as I understand it, other than  
4 perhaps in the time of life that it got converted,  
5 but as far as I understand and as with a couple of  
6 presentations from EDF and their experience and the  
7 best information they brought with us, they were  
8 all converted basically in the same year time frame  
9 or within a few years and they don't have a big  
10 explanation as to why some of these are unaffected  
11 by this issue and some are.

12 Their rate going forward and their  
13 philosophy going forward has been approximately  
14 five bolts per year, their failure rate. And their  
15 inspections and replacement pattern have been to  
16 get to a point where they can go to an extended  
17 ten-year interval between inspection and  
18 replacement campaigns.

19 But basically, they've been using a straight five  
20 bolt per year for original bolts' failure rate,  
21 comparing it to their minimum bolt design analysis  
22 and the replacement bolts they also have a lower  
23 failure rate that they work with. And are even  
24 replacing replacement bolts in the future.

25 MEMBER RICCARDELLA: On the Bugey 2

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 curve, where approximately on that curve was the  
2 change from downflow to upflow?

3 MS. MALIKOWSKI: I knew you were going  
4 to ask. I can't say. Unfortunately, I'd have to  
5 follow up to find where they're at on the curve as  
6 far as the conversion time frame. I don't have  
7 that number.

8 MEMBER RICCARDELLA: Thank you.

9 MEMBER SKILLMAN: It seems like that's  
10 a key question during this whole presentation  
11 because it suggests that Bugey 4 and 5 are running  
12 almost flat and after 220,000 hours, just a couple  
13 of indications whereas the other plants continue.

14 MR. RUDELL: But they're going through  
15 large replacement campaigns in this time line also.  
16 So that's where you need to have that piece also.

17 MS. MALIKOWSKI: And it may be a factor  
18 of when they get their replacements done. Did they  
19 do it prior to large failures starting?

20 MEMBER BALLINGER: Again, these are all  
21 316 bolts?

22 MR. RUDELL: Yes, correct. 316 and  
23 Monday, they said they're 316 cold work.

24 MEMBER RICCARDELLA: But when you  
25 replace, you start to clock over again.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. RUDELL: Yes.

2 MS. MALIKOWSKI: And as far as our  
3 domestic experience, does help give some  
4 information as far as kind of helping correlate  
5 that yes, as far as upflow and downflow. And I'll  
6 explain that on another slide here.

7 Just to summarize, as we said, back in  
8 the late '90s, early 2000, we did have a Joint  
9 Owners Group Program to do voluntary inspections in  
10 relation to the Bugey OE. And so the selective  
11 plants, they were Ginna, Point Beach, Farley 1 and  
12 2. And as you note, from the results we note here,  
13 and these were done basically because we're trying  
14 to look for plants that were similar -- have the  
15 longest operating time, so they tend to be the two-  
16 and three-loop plants. And we're looking at  
17 similar plants to Bugey, so there being three-loop  
18 that we focused on those plants. We do not have a  
19 four-loop inspection, but those tend to be -- they  
20 were the younger plants and a different design. So  
21 at the time, these were the plants that we did  
22 inspect.

23 There were some UT indications found,  
24 but as we note here for Ginna we did actually do a  
25 metallurgical examination of 14 bolts after

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 removal. We did do a replacement at that station  
2 and there were no cracking found. So there at  
3 least is some -- I believe we have some over calls  
4 on our examination results which at least is  
5 conservative so we've kind of bounded our -- the  
6 concern there. But at the same time shows that  
7 we're not seeing, we weren't seeing huge amount of  
8 cracking in our fleet.

9 And you'll also note here, we did have  
10 proactive replacements also done at the Farley  
11 units even though they did not have any UT  
12 indications. Basically, because we saw very little  
13 indications from these examinations, that's where  
14 we were led to the conclusion of all right, this is  
15 not a current licensing period of concern for our  
16 fleet. We do need to develop an aging management  
17 guidance for license renewal and that's really  
18 where the industry transitioned to was all right,  
19 we need to develop that kind of guidance. So  
20 that's where from this point on, we did say all  
21 right, we need to develop inspection guides, but we  
22 weren't then recommending further plant inspections  
23 other than their normal in-vessel exams during  
24 refueling for ISI.

25 And then to show some of the more

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 recent inspection results now that we do have MRP  
2 227 as our inspection requirement which does, as  
3 Jeff had mentioned require UT inspection of 100  
4 percent in 25 through 35 EFY for the Westinghouse  
5 NSSS.

6 The two-loop plants' examination  
7 results are on the left-hand column. The three-  
8 loop plants are on the right. You can see that  
9 most of them are downflow configuration. The Point  
10 Beach units are upflow converted. So we do have  
11 some second inspection results on the two-loop side  
12 and we have new inspections on the three-loop side  
13 to show there really are very low amounts of  
14 inspection indications being found and we are  
15 seeing at least some amount of correlation that at  
16 least to this point we're not seeing a significant  
17 degradation effect. You can also see we do have  
18 reference here where most of them are 347 stainless  
19 steel in these plants.

20 For the other NSSSs, B&W and also some  
21 international results, we're obviously talking  
22 about EDF, but there are other results from other  
23 utilities shown there. Also, similarly, very low  
24 on inspection findings, and we do have actually  
25 several multiple -- the third inspection has been

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 done, just completed in August at Ringhals Unit 3  
2 and finding a very small number of indications.

3 And note, we kind of mentioned this  
4 briefly earlier, the B&W NSSS, their design is an  
5 original upflow configuration. There's also many  
6 slots and flow holes in the baffle plate, so  
7 there's a lot of reduction in differential pressure  
8 there. And as noted, there really was only one  
9 crack-like indication detected in the four units  
10 there, the three Oconee units, and actually  
11 Crystal River. It was mostly inaccessibility they  
12 called it, just saying because we couldn't inspect  
13 it, that was the only other degradation fact except  
14 for one bolt. So giving some a little credence to  
15 the upflow design having some benefit there. And  
16 also, as we note, the CE bolted design is also  
17 upflow as the original design as well. So that's  
18 why we've kind of seen -- the focus has been more  
19 to the Westinghouse NSSS.

20 So just the broader OE, what we've seen  
21 up until this spring, we basically noted that the  
22 international OE and our domestic OE has really  
23 reinforced that the failures are expected to be  
24 IASEC with a random distribution. We did not see  
25 any clustering or ready focused failures in one

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 location or the other. They were bounded by  
2 historic safety assessments we did the mid- to late  
3 '90s. So we had some confidence that we were  
4 within the bounds of analyses already performed.  
5 And we did actually have quite a bit of replacement  
6 campaigns executed in the utilities and  
7 internationally and domestically that has seemed to  
8 have been helping maintain those plants in going  
9 forward.

10 So at least the experience up to this  
11 point was we were seeing no major trends other than  
12 what we would expect as a standard degradation  
13 mechanism that would proceed randomly in the  
14 assembly.

15 MEMBER KIRCHNER: So from this slide  
16 would one conclude that downflow is the root cause  
17 for the larger failure rate in the plants that  
18 you're going to discuss next?

19 MS. MALIKOWSKI: I would say it's part  
20 of it, but we will discuss that.

21 MR. RUDELL: The oldest operating PWR  
22 in the U.S. is a downflow plant, a two-loop plant.  
23 And that was one of the plants that was inspected  
24 in 1999. It got 100 percent inspection. Now there  
25 was some inaccessible because of the lock and weld

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1        rollover. One hundred percent inspection with a UT  
2        technique that was at that time the best we had.

3                We found about 60 bolts. It's a 700  
4        and some odd bolt baffle-former design and they  
5        found about 60 bolts with UT indications. They  
6        went to a replacement campaign. They were able to  
7        replace 56 of those. During the 56 bolts' removal  
8        at that time, 5 broke and the others didn't. They  
9        took two of the broken bolts and 14 of the unbroken  
10       bolts that came out that had UT indications and  
11       sent them off to a hot cell for extensive  
12       destructive examination.

13               One of the broken bolt fracture  
14       surfaces was too destroyed by the removal operation  
15       to get any valuable information out. The other one  
16       showed 100 percent virtually intergranular, like  
17       irradiated assisted stress corrosion cracking  
18       fractography features.

19               The other 14, they were UT'd in the  
20       shop with the shear wave on the side of the bolt  
21       and they thought they saw indications in those  
22       bolts. The other 14 then were ultimately PT,  
23       fluorescent PT examination and they saw no  
24       indications in those bolts. Of the 14, 2 were cut  
25       up to do some tensile specimens and the other 12

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 were pulled to failure. No PT indications, pulled  
2 to failure, and they showed full strength expected  
3 for their irradiated strength and basically they  
4 were -- I'll just use the word flawless. So we  
5 from that found that the sample out of 14 bolts  
6 that came out whole, that had indications, all 14  
7 were flawless.

8 Another plant at the time did a lot of  
9 pull tests and in the pull at that time when they  
10 were pulling, removing bolts, and they all came out  
11 showing full strength. So here we are with a  
12 downflow unit. I'm just answering your question  
13 that as the oldest plant in the United States and  
14 the last inspection, by the way, where we didn't do  
15 100 percent inspection, but we inspected about 125  
16 bolts. We had one bolt with an indication out of  
17 100. So that's less than one percent. So it  
18 almost looks like we had -- although this slide  
19 said 7 percent or something like that, maybe really  
20 was 1 percent back in 1999 in that unit and in  
21 2011, when we looked at it under the MRP 227  
22 program, it looked like 1 percent failure at that  
23 downflow plant. So it's not downflow necessarily,  
24 I think.

25 MEMBER POWERS: Aside from the focus of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 your presentation, does it appear that our  
2 inspection technique is susceptible to a high level  
3 of false positives?

4 MR. RUDELL: Well, we're learning more.  
5 Of the bolts, we have about 30 bolts. I'm just  
6 going to talk round numbers. We have about 30  
7 bolts in the hot cell now out of Indian Point 2 and  
8 half a dozen or so out of Salem and we took six  
9 more of the bolts out of -- that were in the Ginna  
10 spent fuel pool that were removed in 2011 and  
11 they're in the hot cell also now.

12 We've only done of the bolts that were  
13 removed intact from Salem and Indian Point, we've  
14 only looked at four so far and it looks like those  
15 four are flawless. So that's four of the red bolts  
16 that appeared to note.

17 Now, on the other hand, I can't say  
18 that without saying this. There were some green  
19 bolts that were removed at one unit and they broke  
20 so we got some of those also in the lab and we'll  
21 look at those.

22 We know that UT is difficult. We know  
23 that -- you need to certainly assume a ten percent.  
24 Probably in most of our assumptions, we're assuming  
25 a 20 percent probability of a detection being

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 missed or a false call. So there is -- some of the  
2 effort needs to go into understanding what's the  
3 characteristic of these failures that are making  
4 NDE not as accurate as we would like it to be as  
5 well. And that's another element of our focus  
6 group.

7 MEMBER RICCARDELLA: Was there a  
8 significant improvement in the inspections from --  
9 you know, the Ginna was like 1999, 2000 versus what  
10 we're doing now 15 years later?

11 MR. RUDELL: I'd have to say yes. We  
12 have now MRP-228 which governs some of the  
13 inspection demonstration and qualification. The UT  
14 on bolts, I understand, it's not an Appendix 8 PDI  
15 qualification, but it's a low rigor qualification  
16 one might say demonstrated. And we actually have  
17 made a change going forward to increase the rigor  
18 slightly of that.

19 MEMBER RICCARDELLA: But your initial  
20 hot cell data at the Indian Point post is not --

21 MR. RUDELL: But I'm sure we're going  
22 to find some of them failed, but I'm just saying  
23 we're only four so far.

24 MEMBER RICCARDELLA: Yes.

25 MS. MALIKOWSKI: And I think you saw

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 the figure, the picture that Jeff had in his  
2 earlier presentation. This particular  
3 configuration bolt was very difficult to get an  
4 examination, a quality examination done. It's not  
5 -- it's probably one of the most challenge of all  
6 of the configurations we have. So unfortunately,  
7 they do what they can to improve on the technique,  
8 but it does still come down to being it's a  
9 challenge to get a sound bounced back and forth and  
10 read reliably so. I think calling it a little  
11 conservatively has been the preference at least to  
12 make sure that we're not missing things.

13 MEMBER RICCARDELLA: I understand.  
14 Thank you.

15 CHAIRMAN SUNSERI: Based on the amount  
16 of time that we have left today, I'm going to ask  
17 you to prioritize your remarks now and make sure  
18 you tell us the most important things that you want  
19 us to hear. Okay?

20 MS. MALIKOWSKI: I understand.

21 MEMBER RICCARDELLA: Maybe your lecture  
22 should be to the committee and not to the  
23 presenters.

24 (Laughter.)

25 CHAIRMAN SUNSERI: You guys are doing

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 good.

2 MS. MALIKOWSKI: That's fine. I mean I  
3 think we've discussed the reason we already as far  
4 as to just more for your reference we do have the  
5 EFPY counts at the time of these inspections. This  
6 was the 2010 OE from Cook 2.

7 As relating to UT, they did not do a UT  
8 examination that time because they did not have a  
9 qualified method and because it was one of these  
10 challenging configurations. So they did what they  
11 could with the availability at the time.

12 But I think to just jump to the  
13 conclusions as we've been discussing, as you said,  
14 the recent OE has been focused on -- and you said  
15 not just downflow, but four-loop downflow as it was  
16 kind of alluded to earlier, the larger reactor  
17 design. They do have less bolts than say the  
18 three-loop design has over a thousand. It's a  
19 little over 800 for the four-loop. And then this  
20 two has over 700. So there are design differences  
21 that we see or design commonalities amongst the  
22 most recent OE that do tend to give us some reason  
23 to believe there's some commonalities to cause the  
24 clustering that we've been discussing.

25 And we will, as we said, the most

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 recent Cook 2 UT results and their failures  
2 observed, we are as and Bryan will say, we're  
3 following the industry to understand them.  
4 Although I would say as you have the map in front  
5 of you, it's not necessarily completely surprising  
6 with that sea of red surrounding those replacement  
7 bolts that cause the failures not to surprise them,  
8 so to speak, but we will learn more from the --

9 MEMBER RICCARDELLA: I assume some of  
10 those are going to be examined in the hot cell as  
11 well, right?

12 MS. MALIKOWSKI: They are definitely  
13 taking replacement bolts, failed replacement bolts  
14 for analysis. Yes, this is the question of the  
15 edge bolts, what they're going to do with them.  
16 But yes, we want to learn from that.

17 MEMBER KIRCHNER: Just based on the  
18 prior presentation, it looks like for Cook in that  
19 time period that -- I hate to put precision on  
20 this, but 6 bolts that had been replaced out of  
21 about 50, so about 10 percent of the bolts were  
22 cracked or indicated some problem 6 years later.  
23 You changed from 345 to 316. So it seems to me  
24 going back to my issue whether this is a design  
25 problem that is more fluid mechanics, stress

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 induced than it is a materials problem.

2 MR. RUDELL: And here's a theory --

3 CHAIRMAN SUNSERI: Please remember to  
4 introduce yourself.

5 MR. RUDELL: Bernie Rudell.

6 CHAIRMAN SUNSERI: Thank yous.

7 MR. RUDELL: Here's a theory that goes  
8 with the new bolt failures. It's basically -- I'll  
9 sum it up, it's collateral damage associated with  
10 the number of failed original bolts in the vicinity  
11 of that -- of those new bolts and the flexure of  
12 that plate. Now we probably will see a different  
13 mode of failure to those new bolts when we look at  
14 to prove our theory. And the same thing goes with  
15 the edge bolts we saw there. We believe that's  
16 collateral damage from that.

17 MEMBER KIRCHNER: Being formally from  
18 Los Alamos, I would recommend a different  
19 phraseology than collateral damage.

20 (Laughter.)

21 MEMBER RICCARDELLA: You know, I think  
22 a significant point is that in 2010 when those  
23 replacements were done, there was no ultrasonic  
24 examinations done. And so they replaced some bolts  
25 based on visual, but a lot of those other red spots

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 around them might have been there at that time.

2 MEMBER BALLINGER: The replacement  
3 bolts, did they have the same head design?

4 MR. RUDELL: Yes. Well, I would say  
5 current replacement. Not the same as the  
6 originals.

7 MEMBER BALLINGER: These are the  
8 modified, supposedly less smaller stress  
9 concentration?

10 MR. WILSON: Yes.

11 MS. MALIKOWSKI: Bryan has a picture of  
12 that.

13 MR. WILSON: Yes, I have a picture of  
14 that.

15 MS. MALIKOWSKI: So in order to get to  
16 Bryan's discussion, just to pictorially show since  
17 we don't show necessarily the EFPY for all the  
18 other plants, and he'll describe as we kind of  
19 already mentioned Tier 1 related to Westinghouse  
20 Nuclear Safety Advisory Letter.

21 The inspections that have been done so  
22 far domestically are kind of applied here and  
23 Bernie will say we are developing an OE database to  
24 help look and try and find any other trends amongst  
25 various parameters. And this is just showing,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 based on the inspection timing what the number --  
2 it says "assume degraded bolts" because they are  
3 basically taking anything they couldn't inspect and  
4 assuming it degraded just for the purposes here to  
5 conservatively call them. But as you can see, for  
6 at least the inspection guidance, other than our  
7 four-loop downflow Tier 1 plants, the inspection  
8 results do tend to show that we're finding -- I  
9 think we have an appropriate inspection regime for  
10 at least part of our population so while we are, as  
11 we'll discuss, investigating what we need to alter  
12 in our MRP guidance, there is at least some feeling  
13 that we have some reasonable guidance for part of  
14 the industry. So we're continuing to look at it  
15 and we'll move forward.

16 I'll turn this over to Bryan so he can  
17 continue into his discussion.

18 MR. WILSON: Hello, this is Bryan  
19 Wilson, Westinghouse. So I guess -- I'm going to  
20 have to hustle, so the point of my discussion here  
21 is really going to be to provide a little bit of  
22 explanation for some of the things I think Walter  
23 has been kind of alluding to is what are the  
24 mechanisms that are really leading off to causing  
25 this degradation. And then pair that with what's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 the safety significance that we've evaluated as  
2 part of our safety evaluation and then how led into  
3 recommendations that were made through the NSAL to  
4 the industry.

5 So first is the factors influencing  
6 baffle-former bolt degradation. Jeff had covered a  
7 lot of these, so the high points really are that  
8 we've got bolts that are in a susceptible or an  
9 area or a region that's susceptible to IASCC. And  
10 that susceptibility is kind of common amongst  
11 various plants but what we're seeing in the OE is a  
12 differentiation from one plant to another. We're  
13 seeing much larger failures in one plant than  
14 another.

15 So the question is what's causing that  
16 differentiation? One theory is stress. Stress is  
17 the other contribution to propagating cracks. And  
18 there's a lot of different things that impact  
19 stress. I'd say some of the most important things  
20 are one, the stress relaxation. Stress relaxation  
21 is occurring in all of these baffle-former bolts or  
22 the majority of them.

23 MEMBER BALLINGER: That stress  
24 relaxation occurs most of it within five or so DPA?

25 MR. WILSON: Right.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1                   MEMBER BALLINGER:    So that's basically  
2                   two years or thereabouts?

3                   MR. WILSON:     Right, so my point with  
4                   that is that once you get rid of that, these  
5                   external loads, externally-applied loads become  
6                   important.  If you were to have a tight joint, then  
7                   we'd probably eliminate a lot of what we're talking  
8                   about here.  So that's one key point.

9                   The other is bolt design differences.  
10                  So head to shank transition radius, materials maybe  
11                  not so much because of our lack of data to support  
12                  that, but bolt length.

13                  I think the question was asked earlier  
14                  about what the bolt length, how that got segregated  
15                  between the plants.  A lot of the early plants did  
16                  use 347 bolt with a shorter shank and so some, I'd  
17                  say, not all of the two-loops.  And all of the  
18                  four-loop downflows and some of the other four-  
19                  loops, there's not -- again, it's not across the  
20                  board that all the four-loops use these shorter  
21                  shanks.  They started transitioning in later years  
22                  to a longer shank.  But I'd say the early plants  
23                  were using these shorter shank bolts.

24                  As you transition away, the bolt shanks  
25                  were going from like an inch and a half long to two

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 to three inches long and stresses were coming way  
2 down as a result because a lot of the stresses in  
3 these bolts are a result of thermal expansion of  
4 the plates basically, relative temperature between  
5 the barrel and the plate itself, and baffle plate.

6 MEMBER RICCARDELLA: And swelling  
7 differences.

8 MR. WILSON: And swelling differences.  
9 Yes, there's a lot of other extraneous things, but  
10 I'd say nominal stresses on the bolts are a result  
11 of that.

12 The other factor influencing stress on  
13 these bolts is the load, the hydraulic load on the  
14 bolts. So this speaks to the downflow versus  
15 upflow in the plant design. So four-loops, three-  
16 loops, two-loops, the pressure across the plate  
17 varies say consistently with the amount of flow,  
18 total flow in the plant. So it's not an exact, for  
19 instance, a four-loop plant, 50 DPA versus three-  
20 loops 30 and two-loops 20, but it's that same kind  
21 of trend. So that's one contributor, right? So  
22 that naturally says four-loops generally have  
23 higher load.

24 MEMBER RICCARDELLA: One thing that  
25 surprised me is counter intuitive is that the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 three-loop plants have more bolts than the four-  
2 loop plants?

3 MR. WILSON: That was exactly my next  
4 point. So if you look at the bolt distribution on  
5 a four-loop, versus a three-loop versus a two-loop,  
6 the order is that four-loop -- or two-loops  
7 actually have the least, the smallest plates,  
8 right? Followed by four-loops, followed by three-  
9 loops. Three-loops have considerably more bolts  
10 than a four-loop.

11 So in a bolt per plate load  
12 distribution, the four-loops generally see a  
13 significantly higher load than either the two or  
14 the three. So that also adds to the negative or  
15 depending on your perspective, deposited for  
16 identifying which ones are leading.

17 Other contributions are thermal, as I  
18 mentioned. There's a thermal gradient across the  
19 plate as well as a thermal gradient between the  
20 baffle plate and the core barrel which causes say  
21 more of a growth of the plate, relative growth  
22 difference. So those are -- keep that in mind, I  
23 guess.

24 Some other things that are affecting  
25 the failures or failure, say propagation is

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 clustering of bolts. So once one fails in a more  
2 highly susceptible plant that has say a high  
3 external load like a pressure differential, you  
4 have a better likelihood or a higher likelihood for  
5 load shed to the adjacent bolts. And then once you  
6 get that load shed, you're increasing your  
7 susceptibility to IASCC, you know, you're reducing  
8 the critical flaw size, right, for a bolt if you're  
9 looking at fracture mechanics base. So it all kind  
10 of starts to trend in one replacement.

11 So on the opposite of that is bolt  
12 replacement. Once you put bolt replacement, you're  
13 affecting the load distributions for all the  
14 different bolts that are in the system. So these  
15 all have to be considered. It's just that it's a  
16 very complex situation and a lot of things,  
17 different things going on.

18 But I think if you boil down what the  
19 deltas are between the plants and where we're  
20 seeing the high number of failures, I think what  
21 you're seeing is a trend towards the higher  
22 pressure, the plants with higher differential  
23 pressure which are downflow. And then four-loops  
24 which generally have a smaller number of bolts than  
25 say a three-loop or a two-loop. So those all seem

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 to trend in a direction that we're -- that is  
2 following the OE.

3 So what we're seeing from the OE is  
4 three different failure patterns, right? One is  
5 randomly distributed more IASEC is governing and  
6 you're getting kind of -- failures are occurring  
7 kind of in areas either you would expect because of  
8 the high fluence or they are say more well  
9 distributed and they can be representative from  
10 statistical evaluations like a Weibull distribution  
11 or something like that.

12 The next is dose related and this is  
13 more like what maybe EDF is seeing where the  
14 failures are say not necessarily cascading in  
15 nature, but they're more say focused on areas of  
16 high fluence, high load and maybe high amplitudes  
17 of like fatigue loads, for instance, if you're  
18 doing load follow.

19 And then you've got clustered which is  
20 kind of what we're seeing, I think, at Indian  
21 Point, Salem, Cook where you've got some failures  
22 that look like they're just spreading from a  
23 nucleus, right, and going out. And those are the  
24 ones I would say are the most concerning from a  
25 management -- a degradation management standpoint

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       because those are ones that you want to make sure  
2       you stay ahead of at the infantile stages so you  
3       don't let them expand.

4               So I can get into cluster --

5               CHAIRMAN SUNSERI:     Let me interject  
6       here.    I think based on the time, why don't you  
7       skip ahead to the consequences and evaluations of  
8       the baffle-bolt degradation because we kind of  
9       heard this story that you're about to tell and we  
10      might have more interest in some of the downstream  
11      topics.    I'm kind of reading ahead in your  
12      presentation.

13              MR. WILSON:    Excellent.    That's fine.  
14      I appreciate the suggestion.

15              So as I alluded to previously,  
16      Westinghouse had conducted a safety evaluation  
17      basically of the degraded condition looking at an  
18      extreme condition, a condition at which was not --  
19      did not have -- I said was well beyond the OE that  
20      was being experienced to look at what the potential  
21      of Part 21 reportability of this might be.   And so  
22      for the condition that we evaluated, we looked at  
23      basically a quadrant of the baffle-former assembly  
24      with all the bolts, all the baffle-former bolts  
25      degraded.   And the edge bolts were left.   I would

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 say in some state, we didn't necessarily define at  
2 the time what degraded state those were in, but we  
3 acknowledged that there's some overlapping of  
4 plates that would create a simple supported edge  
5 condition and the edge bolts would be in some  
6 condition that they would also support that simply  
7 supported condition, whether they're all there or  
8 some random distribution of failures occurring  
9 there as well. So that was say the basis for the  
10 evaluation.

11 Things we looked at were impact on core  
12 bypass, control rod insertability as a result of  
13 plate deflections and impact with the fuel and fuel  
14 assembly grid crush and core coolability. So for  
15 the control rod insertability grid crush  
16 evaluations, we looked at a dynamic analysis where  
17 we basically took a loose plate or plate that only  
18 had simple supports.

19 Yes, Peter? Oh, I'm sorry. I thought  
20 you were raising your hand. Okay.

21 So we took a plate that was simply  
22 supported, imposed the pressure distributions of a  
23 LOCA on this plate and had models of the fuel  
24 assembly stacks, you know, basically rose and  
25 looked at how those fuel assemblies interacted with

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 one another and how they interacted with the plate  
2 to predict both what the peak deflections of the  
3 fuel assemblies were at control rod locations and  
4 also looked at what the grid deformation looked  
5 like.

6 In those evaluations, what we found was  
7 that the grid deformations were more I'd say  
8 cellular in nature, so in an individual grid cell  
9 unit you would have some sort of say small  
10 deformation, shifting, making it more like a  
11 parallelogram rather than a square. But the  
12 overall configuration geometry didn't change such  
13 that you would block flow. And the control  
14 spacings didn't say get tremendously closer, much  
15 closer to one another such that you would have  
16 concerns from departure from nucleic boiling and  
17 things like that. So that was in grid crush.

18 For control rod insertability we  
19 looked at maximum deflections of the control or of  
20 the fuel assembly after the event had occurred to  
21 see if we can get the rods in in a bowed  
22 configuration. And in that configuration, we also  
23 looked at thimble tube stresses or guide tube  
24 stresses I should say that -- to make sure those  
25 didn't exceed allowables for the fuel assembly

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       because maybe all bets are off after -- you know,  
2       if those fracture, right?

3               So those evaluations showed that the  
4       fuel did not go to an amount that would impact  
5       control rod insertability. We have test data,  
6       historical test data, where we looked at pulling  
7       fuel assemblies, you know, by a significant amount  
8       and inserting rods and found that for that  
9       deflection that was applied and I won't state it  
10      necessarily here, for that deflection that was  
11      applied the control rod insertability times were  
12      only impacted by .02 seconds and it was a  
13      considerable amount of deflection.

14             So what we found was all of these  
15      evaluations that we did assuming a loose baffle  
16      plate, the fuel assembly, say bowing or lateral  
17      deflection, didn't exceed those numbers that were  
18      say bound by the test data that we had. So we felt  
19      comfortable that in this extreme condition that the  
20      fuel assembly, even in an bowed state would be an  
21      acceptable level of bowed state and that the grids  
22      would remain in a condition that were acceptable  
23      for core cooling.

24             And so we looked then deeper into LOCA,  
25      non-LOCA impacts on core coolability and safe

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 shutdown margin and things like that. I would say  
2 all came out positive with ample margin on those.  
3 So the control rods would be able to fully insert  
4 at all locations. There would be some amount of  
5 grid deformation at peripheral assemblies as well  
6 as some inboard assemblies, but to a lesser degree  
7 and core coolability would largely remain  
8 unaffected.

9 MEMBER RICCARDELLA: In the analysis,  
10 the baffle plates actually impinge on the fuel  
11 rods?

12 MR. WILSON: Yes, they push in.

13 MEMBER RICCARDELLA: Push in enough so  
14 that your deflections are big enough.

15 MR. WILSON: Yes.

16 MEMBER RICCARDELLA: Okay.

17 MR. WILSON: The deflections are, I'd  
18 say for that kind of a plate configuration, it's  
19 long and narrow and thin, right? And it can push  
20 in a good bit.

21 MEMBER SKILLMAN: What did you use as  
22 the basis for the number of bolts that you did have  
23 retaining load?

24 MR. WILSON: So we had zero baffle-  
25 former bolts retaining load.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. RUDELL: In a full quadrant.

2 MR. WILSON: In a full quadrant.

3 MR. RUDELL: Not just an octant, but  
4 just one plate.

5 MEMBER SKILLMAN: Got it. Thanks.

6 MEMBER POWERS: From a hydraulic  
7 colleagues' part of my mind rigorous in their  
8 evaluation of such analyses, could you defend them  
9 before that?

10 MR. WILSON: Could I defend them before  
11 that?

12 MEMBER POWERS: Could you defend these  
13 calculations before -- from a hydraulics'  
14 community? That is, do you have enough  
15 experimental data to say that you adequately  
16 simulated?

17 MR. WILSON: I personally can't speak  
18 to that, but I believe that yes, we do have  
19 adequate data to support this.

20 CHAIRMAN SUNSERI: You had involvement  
21 by your thermal hydraulics course?

22 MR. WILSON: Yes.

23 CHAIRMAN SUNSERI: I imagine. Okay.  
24 So I really hate that --

25 MEMBER POWERS: What was the case? One

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 from a hydraulicist is a very pleasant fellow. Two  
2 is the problem.

3 (Laughter.)

4 CHAIRMAN SUNSERI: I hate to ask you to  
5 do this, but we do have another subcommittee  
6 meeting following this one, so we have to really  
7 stick to the schedule and I apologize for rushing  
8 you, so I'm going to give you five minutes to hit  
9 your main points because we're going to allow some  
10 public comment period here and I need to do that.  
11 We may need to have some more committee follow-up  
12 questions and that's going to take some time to get  
13 through. So I apologize for putting you in there,  
14 but we do have the slides, so we are able to read  
15 it. So conclude what your main point is here.

16 MR. WILSON: Right. So I'll skip past  
17 this, but a couple of other fuel-related things we  
18 did look at is baffle jetting and loose parts as  
19 well, but Jeff, I think, covered that rather well.

20 Now this led to communication to the  
21 industry. So the industry was informed of all of  
22 what's going on. All of our evaluations and I'd  
23 say a culmination of what I talked about before  
24 about likely cause of the issue, apparent cause of  
25 the issue and what's leading to more susceptibility

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 ranking of the plants.

2 We were able to say tier the plants to  
3 address plants at an early enough time frame or as  
4 soon as we can. The most susceptible ones were  
5 addressed first and then progressively provide  
6 recommendations as you decrease in susceptibility.

7 Let's see, so yes, so the intent was to  
8 promote early identification of failures, as I  
9 said. You want to find this as soon as possible to  
10 prevent any expansion of the clustering.

11 And then we did allow freedom in our  
12 NSAL recommendations for evaluating extent of  
13 condition. We recognize that we don't know  
14 everything at the beginning, so this is where MRP,  
15 I think, picks up in looking at this issue more  
16 holistically from the data that's being gathered so  
17 that kind of speaks to the bottom. Two points  
18 there that we're using lessons learned to further  
19 grow on this topic.

20 I trust that you guys have maybe all  
21 read the NSAL or have knowledge of the NSAL so I  
22 won't go through, but essentially the big topic is  
23 Tier 1 plants here that Tier 1A plants are doing UT  
24 inspections at the next refueling outage and they  
25 will all be completed by end of next year. So that

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 is the near term.

2           There's a Tier 1 Bravo and the  
3 differentiation here is really the head-to-shank  
4 radius and the material difference. It's, I'd say,  
5 prior experience. And so there's a noted, say  
6 potentially less susceptibility for this plant. So  
7 NSAL does say that those plants will need to do a  
8 visual inspection and the idea there is that all of  
9 the other plants, when they had significant  
10 degradation had been able to find this through a  
11 visual inspection. It's not an optimum inspection  
12 necessarily, but it will identify if you've got say  
13 large quantities of failures.

14           MEMBER RICCARDELLA: You've got seven  
15 in the first group, seven units in the first group.

16           MR. WILSON: Yes.

17           MEMBER RICCARDELLA: How many in the  
18 second group?

19           MR. WILSON: Two.

20           MEMBER RICCARDELLA: Oh, okay.

21           MR. WILSON: So then Tier 2, largely  
22 Tier 2 has been inspected. So our recognizing  
23 that, our guidance was really that those plants  
24 should go back, consider the OE that we have now  
25 and look at how that impacts what their inspection

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 results and how they reacted to the issue or  
2 reacted to their initial inspections. And then  
3 adjust accordingly. And MRP went further with the  
4 recommendations with this as well in NEI-308 space.

5 And then Tier 3 and Tier 4, there's  
6 acknowledgment that there's, especially for  
7 converted upflow plants as it could have been early  
8 damage as a result of being downflow, but that has  
9 maybe been say reduced or you know, say corrected  
10 in the conversion upflow. So there's a kind of a  
11 time limit. If you had been downflow for a long  
12 period of time, then you would need to maybe take  
13 action there.

14 MEMBER SKILLMAN: Bryan, how many Tier  
15 3 plants are there, please?

16 MR. WILSON: Well, there's -- I don't  
17 have -- I think a large number of them are actually  
18 -- and there's really only one.

19 MS. ROSS-LEE: I think there's like  
20 three Tier 3 plants. There's more than three.

21 MR. RUDELL: It goes beyond four-loop.  
22 The first bullet there specifically, the four-loop  
23 set, but there's a lot of three-loops.

24 MEMBER SKILLMAN: That are converted  
25 upflow?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. RUDELL: Yes.

2 MEMBER SKILLMAN: Thank you.

3 MR. WILSON: So that's -- oh, wait, I  
4 don't want to skip my picture here. So here's the  
5 replacement bolt, right? So as we've discussed  
6 before, some of the -- the real design differences,  
7 the change in the material, but I'd say as far as  
8 improved susceptibility that one is -- I think the  
9 jury is still out on that one necessarily. The  
10 semi-parabolic head to shank transition fillet is  
11 really the key item there. And then the other  
12 changes or things you see on this bolt design are  
13 really related to install, ability to install the  
14 bolt and crimp it without welding to an irradiated  
15 baffle plate.

16 MR. RUDELL: And inspectability.

17 MR. WILSON: Right, and so the flat  
18 head here allows for ease of inspectability.

19 MEMBER RICCARDELLA: That looks like a  
20 relatively short shank. Is that prototypical?

21 MR. WILSON: Yes, that's standard for  
22 this short bolt. It's a really short shank.

23 MEMBER RICCARDELLA: Okay.

24 CHAIRMAN SUNSERI: All right, anything  
25 else?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. WILSON: Bernie, do you have  
2 anything to add?

3 MR. RUDELL: I think you summarized  
4 everything --

5 CHAIRMAN SUNSERI: Because we need to  
6 open up the phone lines here.

7 MR. RUDELL: I think I said everything  
8 that was in the other slides with regards to  
9 forming the focus group and working through that.  
10 That's in the rest of the slides.

11 CHAIRMAN SUNSERI: Okay, well, we  
12 appreciate your interaction with the committee.  
13 It's been really interesting.

14 So at this time, I'm going to ask for  
15 the phone line to be open and I hope that they are  
16 open. So if I could have somebody on the phone  
17 line at least speak something so we can confirm the  
18 phone line is open and once we confirm the phone  
19 line is open, we'll ask for comments. Is anybody  
20 out there?

21 MR. LEWIS: Marvin Lewis, a member of  
22 the public.

23 CHAIRMAN SUNSERI: Okay, great. So the  
24 phone lines are open. At this point, I will ask  
25 for any comments from the people on the line.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 MR. LEWIS: Marvin Lewis.

2 CHAIRMAN SUNSERI: Yes, go ahead.

3 MR. LEWIS: Look, I'm not saying that  
4 the testing and the statistics cited are in any way  
5 wrong or screwed up or anything else.

6 In the late 1950s, we had a place  
7 called Shoshone in Simi Valley of Los Angeles  
8 County. And it has a very similar problem. A  
9 baffle plate broke loose. I don't know why. I  
10 can't remember that out of my head, but 60 years is  
11 a long time, 70 years, almost. Yes, over 60 years.  
12 It was a long time to remember back to that, but I  
13 seem to remember that just about everything I heard  
14 today was said before we had that problem at  
15 Shoshone and I'm saying hey, 60 years and you've  
16 got the same problem? Come on. Don't we ever  
17 progress? Thank you.

18 CHAIRMAN SUNSERI: Thank you. Anyone  
19 else? Anybody else on the phone line?

20 All right, let's close the phone line  
21 then. And we'll turn to the audience now.

22 MS. CURRAN: Good morning. I'm Diane  
23 Curran representing Riverkeeper. In the Indian  
24 Point license renewal proceeding, we have an  
25 admitted contention, several admitted contentions

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 in conjunction with the New York State Attorney  
2 General's Office that deal with issues related to  
3 aging equipment.

4 I really appreciate the presentations  
5 this morning. They've been very helpful, very  
6 informative. And I have a concern that I'd like to  
7 express for Riverkeeper about what appears to be a  
8 lack of a plan to include consideration of the root  
9 cause analyses for plants other than D.C. Cook. I  
10 am thinking of page 37 of your presentation, Mr.  
11 Poehler, where you mentioned that the NRC is going  
12 to be following up with the D.C. Cook root cause  
13 analysis and I would just like to confirm that I'm  
14 assuming that root cause analysis will be done --  
15 well, one has been done for Indian Point and I  
16 don't know whether one has been done for Salem, but  
17 I would think that these would be very important  
18 studies that should be looked at together and  
19 integrated because it's clear that there's a lot of  
20 questions about what causes the degradation of  
21 these bolts and I wonder if I could confirm that  
22 with you and also see if these reports are all  
23 going to be submitted to the NRC.

24 CHAIRMAN SUNSERI: Unfortunately, this  
25 is not an opportunity to interact. It's just an

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 opportunity to make a comment. So we understand  
2 your concern has been expressed and is there  
3 anything else you would like to offer?

4 MS. CURRAN: Well, I was hoping since I  
5 seem to be the only person that is commenting that  
6 I could have a little interaction.

7 CHAIRMAN SUNSERI: We're obligated by  
8 the federal regulatory rules for this meeting, so I  
9 apologize for stifling that.

10 MS. CURRAN: Thank you.

11 CHAIRMAN SUNSERI: Any other members in  
12 the audience would like to make a comment?

13 All right, so let's go around the room  
14 here and hear from the ACRS members any further  
15 comments. And we'll start with Ron.

16 MEMBER BALLINGER: Thank you very much  
17 for the presentations. They're very informative  
18 and it brings everybody up to date on what's going  
19 on. So I thought it was a great job and thank you  
20 very much.

21 CHAIRMAN SUNSERI: Pete?

22 MEMBER RICCARDELLA: No comments other  
23 than to echo what Ron said.

24 CHAIRMAN SUNSERI: Dick?

25 MEMBER SKILLMAN: No further comment.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 Thank you.

2 CHAIRMAN SUNSERI: Dana?

3 MEMBER POWERS: Well, of course the  
4 presentations were very nice on the specific issue.  
5 And if we look at the specific issue, it's moved  
6 along since the first findings in France which may  
7 to some people seem slow, but for those of us that  
8 worry about some screen blockage, it's been at a  
9 blindingly fast pace.

10 What I expressed concern about is  
11 moving forward beyond what's now planned. And for  
12 that to happen within the NRC, we need to have a  
13 nexus to the protection of public health and  
14 safety. Some very conservative calculations were  
15 done following the processes at the NRC and those  
16 are fine. I have no troubles with that. That's  
17 probably the only thing you can do.

18 The industry has indicated, however,  
19 they can do calculations that are substantially  
20 more rigorous I would say. Whether those are  
21 defensible and in front of my thermal hydraulic  
22 colleagues I don't know. They're rather picky.  
23 But it's that kind of analysis we're going to have  
24 to do to show that there is a nexus to the  
25 protection of public health and safety that

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1 mandates continued NRC following of this issue  
2 beyond what's planned now.

3 As a parenthetical note, we continue to  
4 see that NDE techniques were not in a state of high  
5 reliability. This is certainly not an issue for  
6 the NRC to take on and may not even be an issue for  
7 the nuclear industry to take on, certainly show  
8 where the entire burden. I think this is a  
9 national issue that we need to recommend on a  
10 national basis as something to focus for the  
11 private sector, the academic sector and the  
12 government sector to take on.

13 CHAIRMAN SUNSERI: Thanks, Dana. John  
14 Stetkar?

15 MEMBER STETKAR: Nothing at all. Thank  
16 you.

17 CHAIRMAN SUNSERI: Walt.

18 MEMBER KIRCHNER: Thank you for the  
19 presentations. I can't pass up on Dana's earlier  
20 comments. I think I'm the only Thermal Hydraulics  
21 Subcommittee member here.

22 MEMBER POWERS: And proof that having  
23 one is a pleasant experience.

24 MEMBER KIRCHNER: Yes, exactly. Oh,  
25 two. So it did turn out pleasant. It might be

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1       worth considering hearing more detail about the  
2       actual calculations that are done, but I'll leave  
3       that to the chair of the Thermal Hydraulics  
4       Subcommittee.

5                   MEMBER POWERS:     Oh, you guys are in  
6       trouble now.

7                   CHAIRMAN SUNSERI:     I would like to  
8       extend my appreciation to both the NRC and the  
9       industry representatives here for the informative  
10      presentation. Looks like there's still plenty of  
11      work ahead. I'm going to speak in advance for the  
12      subcommittee, but I would imagine that we'll be  
13      interested in the hot-cell work and examinations  
14      that are forthcoming and we'll likely be seeking a  
15      further update as more information becomes  
16      available in the future.

17                   So thank you and at this point we will  
18      close this meeting.

19                   (Whereupon, the above-entitled matter  
20      went off the record at 11:55 a.m.)

21

22

23

24

25

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS  
1323 RHODE ISLAND AVE., N.W.  
WASHINGTON, D.C. 20005-3701

1  
2  
3  
4  
5  
6  
7  
8  
9



***U. S. Nuclear Regulatory Commission***

# **Recent Operating Experience with Baffle-Former Bolt Degradation**

**Jeffrey C. Poehler**

**Office of Nuclear Reactor Regulation  
Division of Engineering**

**Advisory Committee on Reactor Safeguards  
Meeting of the Subcommittee on Metallurgy & Reactor Fuels**

**November 16, 2016**





# **Contents**

- 1. Introduction - Objectives**
- 2. Design, Functions and Materials of PWR Internals, Baffle-Former Assembly, and Baffle-Former Bolts**
- 3. Potential Consequences of Baffle-former Bolt Degradation**
- 4. History of BFB Degradation**
- 5. Factors Influencing Baffle-Former Bolt Degradation**
- 6. Bolt Inspection and Replacement**
- 7. Evaluation of Baffle-Former Bolt Degradation**
- 8. NRC Response**
- 9. Future Activities for NRC**



# Design and Functions of the Baffle-former Assembly



Function of baffle-former assembly is to direct coolant flow through the core. It also provides lateral support to the core during a seismic event or loss-of-coolant accident (LOCA).



# ***Design and Functions of the Baffle-former Assembly***





Looking down into the core barrel of a Westinghouse-design PWR



# Design and Functions of the Baffle-former Assembly - Design of Baffle-former bolts

- Stainless steel bolts are 5/8" dia. x ~2" long and attach the baffle plates to the former plates to form the baffle-former assembly.





# ***Design and Functions of the Baffle-former Assembly - Baffle-former Bolt Materials***

- **Westinghouse (W) plants:**
  - Type 347 stainless steel
    - Most older Westinghouse plants
    - Bolt design has sharper head-to-shank radius and shorter shank than in Type 316 cold-worked bolts.
  - Type 316 cold-worked stainless steel
    - Newer Westinghouse plants
    - All replacement bolts
- **Other NSSS designs**
  - B&W plants use Type 304
  - CE plants use annealed Type 316 (2 plants – others have welded core shroud).



# ***Potential Consequences of Baffle-Former Bolt Degradation – Baffle Plate Movement***

- Large numbers of degraded baffle-former bolts could allow detachment or deflection of baffle plates, particularly during a LOCA or seismic event.
- Plates could impact peripheral fuel assemblies, potentially causing grid crush and localized fuel cladding damage.
- In plants with control rods in peripheral locations, plate impact could jeopardize capability to insert these rods .
- Intact baffle-edge bolts would help mitigate plate detachment or deflection.
- For localized damage to peripheral fuel assemblies, a coolable geometry evaluation can be performed.



# ***Potential Consequences of Baffle-Former Bolt Degradation – Baffle Jetting***

- **Baffle jetting is flow leakage through gaps between adjacent plates.**
- **Function of baffle-edge bolts is to ensure baffle plate integrity which prevents baffle jetting.**
- **Flow leakage causes flow-induced vibration of fuel pins resulting in localized fuel cladding damage, in some cases breaching cladding.**
- **Reactor coolant activity monitoring can detect increases in coolant activity that may be indicative of fuel damage.**



# ***Potential Consequences of Baffle-Former Bolt Degradation – Loose Parts***

- Bolt heads and locking bars can become loose parts if bolts completely fracture.
- The clearances between the baffle plates and fuel assemblies are very small, which would tend to prevent bolt heads from escaping until the reactor is defueled.
- Likely result of loose bolt heads is fretting causing localized fuel cladding damage.
- Due to small size, it is unlikely that a few failed bolts would be detected by the loose part monitor.
- Baffle plates are unlikely to detach during normal operation, but if they did, potential for travel is limited by tight clearances and large size of plates.



# ***History of Baffle-Former Bolt Degradation – Early History***

- **First identified in late 1980's in European plants**
- **French 900mW CPO Plants**
  - 6 plants found between 1% and 11% of bolts degraded
- **Belgian plants**
  - One 3-loop Framatome 900 mW design performed 5 examinations between 1991 and 2014 finding a total of 74 bolts degraded or uninterpretable.
  - Three other plants performed one UT examination each, finding a handful of degraded bolts.
- **Mechanism for degradation is irradiation assisted stress corrosion cracking (IASCC).**
- **NRC issued Information Notice 98-11 to alert U.S. plant operators.**
- **US Industry initiated a program which included pilot inspections of baffle-former bolts at several plants.**



# ***History of Baffle-Former Bolt Degradation – US Pilot Plant Inspections***

- **Two 2-loop downflow plants with Type 347 bolts (1998-1999)**
  - Plants found 7-10% of bolts degraded
  - Replaced degraded bolts, one plant replaced additional non-degraded bolts
  - Tensile testing of removed bolts performed at one unit, indicated number of defective bolts was less than indicated by UT results.
- **Two 3-loop downflow plants with Type 316 bolts (1998-1999)**
  - UT examined essentially all bolts – no indications
  - Pre-emptive replacement of >200 bolts each unit
- **One B&W plant (2005)**
  - No indications found



## ***History of Baffle-Former Bolt Degradation – MRP-227-A***

- **2000-2011, Most plants applying for license renewal made commitment to implement industry RVI program when it was issued.**
- **Industry program (MRP-227, Rev. 0) under review by staff 2009-2011.**
- **Industry program was approved by NRC staff in 2011 (MRP-227-A).**



# ***History of Baffle-Former Bolt Degradation – MRP-227-A Inspection Requirements for Baffle- Former Bolts***

- **Ultrasonic (UT) Examination**
- **Initial (baseline) Examination**
  - **Westinghouse and CE: 100% of bolts between 25-35 effective full power years**
  - **B&W: 100% of accessible bolts no later than two refueling outages from the beginning of the license renewal period**
- **Inspect every 10 years thereafter (or sooner if required by analysis of any observed degradation).**
- **All PWRs with baffle-former bolts must perform these inspections.**



# ***History of Baffle-Former Bolt Degradation — D.C. Cook, Unit 2 (2010)***

- D.C. Cook, Unit 2 is a 4-loop downflow plant with Type 347 bolts (832 total baffle-former bolts).
- Eighteen bolts had visual signs of failure.
- Licensee replaced a total of 52 bolts with Type 316 SS, most on one large baffle plate, 42 found to be cracked.
- To establish extent of condition, on the three similar (large) baffle plates, licensee:
  - performed VT-3, no degradation
  - Tensile tested one bolt from each plate, no degradation
- No UT performed
- Two bolts locations left vacant .
- Westinghouse issued Technical Bulletin TB-12-5 to alert licensees.




# ***History of Baffle-Former Bolt Degradation – Inspections under MRP-227-A (2011-2015)***

- **Westinghouse 2-loop (Type 347 bolts, 34 EFPY), five reactors**
  - Maximum defective bolts was 10.3%, 34 EFPY
  - One repeat inspection (plant inspected 1998), 15 additional degraded bolts, 2.7% of original bolts
  - One 2-loop plant that inspected in 1998 did a partial UT examination and replacement.
- **Westinghouse 3-loop (Type 347 bolts, 30-32 EFPY), four reactors**
  - UT examination of 100% of bolts at three units (1088 bolts each), number of potentially degraded bolts was 1, 2 and 8.
  - Partial UT examination of 305/1088 bolts at one unit, stopped due to equipment problems, no indications
- **B&W (Type 304 bolts, 30-32 EFPY) – Three reactors inspected, no more than 4 bolts with indications in each.**
- **CE – (Type 316 bolts, 27-28 EFPY) No inspections to date**



# ***History of Baffle-Former Bolt Degradation – Indian Point, Unit 2***

- IP2 is a 4-loop, downflow plant with Type 347 bolts
- During Spring 2016 refueling outage, IP2 conducted MRP-227-A inspection per license renewal commitment.
- Visual examination of 1232 baffle-edge bolts, all acceptable.
- UT and visual examination of 832 baffle-former bolts
  - 227 potentially degraded baffle-former bolts identified
    - 182 ultrasonic testing failures
    - 31 visually identified as protruding
    - 14 inaccessible, conservatively assumed failed



# ***History of Baffle-Former Bolt Degradation – Indian Point, Unit 2 Corrective Actions***

- **Indian Point Unit 2 (IP2)**
  - Replaced 278 baffle-former bolts (227 potentially degraded + 51 more to provide margin) with Type 316 SS
  - Completed analysis to support baffle-former assembly return to service - inspected by Region 1
  - Bolts sent to laboratory for testing to support root cause.
- **Indian Point Unit 3 (IP3)**
  - Operability evaluation of baffle-former assembly considering information from IP2 and Salem 1
  - Reschedule future baffle bolt examinations from 2019 to 2017



## ***History of Baffle-Former Bolt Degradation – Salem Unit 1***

- Salem, Unit 1 is a 4-loop, downflow plant with Type 347 bolts.
- During Spring 2016 refueling outage, licensee was conducting augmented visual inspection of baffle-former bolts due to known degradation issues (832 total baffle-former bolts).
- Identified 11 bolts cracked at head, 9 had visually cracked lock bar welds, 19 bolts protruding from counterbore
- Follow up UT of remaining baffle-former bolts determined 135 bolts were potentially degraded, plus 16 unable to be tested.
- Overall, ~190 bolts identified as needing replacement
- Significant clustering of degraded bolts in several octants
- No baffle-edge bolt degradation observed



# ***History of Baffle-Former Bolt Degradation – Salem, Unit 1 Corrective Actions***

- **Salem Unit 1**
  - 189 bolts replaced w/Type 316 SS
  - Analyzing selected bolts to confirm IASCC
  - Minimum bolting pattern analysis performed to determine replacement scope and justify operation for 1 cycle prior to re-inspection
- **Salem Unit 2**
  - Operability determination based on extent of condition from Unit 1
  - UT inspection of all bolts scheduled for spring 2017 (moved up from 2026)




# ***History of Baffle-Former Bolt Degradation – D.C. Cook, Unit 2 (2016)***

- During October 2016, D.C. Cook, Unit 2 performed UT examination of baffle-former bolts (832 total) on accelerated schedule in accordance with MRP interim guidance.
- Total of 179 potentially degraded bolts
  - 170 with UT indications
  - 9 untestable bolts
- 2 vacant bolt locations from 2010
- Six (6) replacement bolts installed in 2010 had indications.
- At least one vacant bolt location correlated with a damaged fuel assembly.
- Visual examination of baffle-edge bolts found 5 degraded bolts.

Location of Degraded Edge Bolts

Degraded Replacement Bolts



## As-Found Condition of D.C. Cook, Unit 2 Baffle-Former Bolts Fall, 2016 Refueling Outage



## ***History of Baffle-Former Bolt Degradation – D.C. Cook, Unit 2 (2016) – Corrective Actions***

- **Replace minimum of 181 bolts w/type 316 SS - all potentially degraded bolts (179) plus missing bolts (2), plus additional bolts up to 201 total as time permits**
- **Indications in replacement bolts will be further investigated.**
  - Previous plants that have re-inspected replacement bolts in service for 10-15 years found no indications.
  - Replacement bolts will be sent for laboratory analysis.
  - Performing sensitivity analysis to explore the effects on replacement bolt stress from failed original bolts in vicinity.
- **Corrective actions for baffle-edge bolts to be determined.**



# ***Factors Influencing Baffle-Former Bolt Degradation – Neutron Fluence***

- Austenitic stainless steels are normally resistant to SCC in a PWR environment.
- With high fluence, grain boundaries changes occur.
  - Neutron fluence threshold for IASCC is  $\geq 2 \times 10^{21} \text{ n/cm}^2$  (3 dpa) - Baffle plates and bolts receive up to 75 dpa in 60 years.
- Patterns of bolt degradation in IP2, Salem 1, and Cook 2 do not correlate with highest fluence locations in the core.
  - 2-loop and 3-loop plants also had similar or higher fluence levels but fewer degraded bolts.
- Switch to a low-leakage core design will reduce flux to bolts, may slow initiation of new IASCC cracks.




# ***Factors Influencing Baffle-Former Bolt Degradation - Stress***

- **Stresses on baffle-former bolts are from a variety of sources:**
  - Bolt preload stresses
  - Irradiation assisted stress relaxation
  - Void swelling of baffle plates
  - Differential pressure - greater in “downflow” than in “upflow”
  - Number of bolts per plate area
  - Bolt geometry –head-to-shank radius
- **Fatigue loads may have an influence.**
  - Affected by operating history – number of transients




# Factors Influencing Baffle-Former Bolt Degradation - “Downflow” vs. “Upflow”



DOWNFLOW CONFIGURATION

$P1 > P2$

Tries to force baffle plate inward = higher stress on bolts



UPFLOW CONFIGURATION

$P1 \approx P2$

Lower stress on bolts



## ***Factors Influencing Baffle-Former Bolt Degradation – Stress (Clustering)***

- **Baffle-former bolts initially crack randomly.**
- **Failure of a bolt leads to more load being carried by adjacent bolts.**
- **Over several operating cycles, this can cause the adjacent bolts to crack leading to clusters of failed bolts (“unzippering”).**
- **Observed in French plants in successive examinations**
- **Severe clustering seen at Salem, Unit 1**



# ***Factors Influencing Baffle-Former Bolt Degradation - Summary***

- **Degradation of baffle-former bolts involves a complex interaction of stress, neutron fluence, and bolt material/design**
- **Other aging mechanisms, such as void swelling and irradiation assisted stress relaxation influence IASCC of bolts**
- **Industry is developing predictive models for baffle-former bolt degradation accounting for neutron fluence, stress, and material**
- **Higher susceptibility to degradation seems more related to stress differences rather than fluence**



# ***Bolt Inspection and Replacement – Nondestructive Examination***

- **Ultrasonic examination (UT)**
  - Demonstrated for flaw detection only, not sizing
  - Any bolt with a detected cracklike indication is called defective.
- **Visual examination (VT-3)**
  - Not specified by MRP-227-A for baffle-former bolts, but some plants have performed voluntarily in response to OE
  - Specified for baffle-edge bolts
  - Can detect evidence of failed bolts such as displaced lock bars, protruding or missing bolt heads
  - Evidence of failed bolts has also been detected by non-VT-3 visual inspections.



# ***Bolt Inspection and Replacement – Replacement***

- **Removal**
  - Many bolts can be removed intact once lock bar is cut.
  - Broken shanks can sometimes be removed mechanically but may require electro-discharge machining (EDM).
- **Replacement**
  - Replacement bolt design uses an expandable locking cup so no welding on highly irradiated baffle plate material is necessary.
  - Replacement bolts are cold-worked Type 316 stainless steel.
  - Replacement bolts have improved geometry to reduce stress at the head-to-shank transition.



# ***Evaluation of Baffle-Former Bolt Degradation – Acceptable Bolt Pattern Analyses***

- **WCAP-15029-P-A describes the NRC- approved generic methodology for determining acceptable patterns of intact baffle-former bolts.**
- **Uses the MULTIFLEX computer code to determine accident loadings**
- **Acceptance criteria include bolt stresses, fuel grid impact loads, momentum flux, fatigue and core bypass flow.**
- **When evaluating as-found bolt degradation, any degraded bolt is assumed to carry no load.**
- **Irradiated material properties are used for bolts.**
- **Plants use this methodology to evaluate as-found conditions and potential replacement patterns.**



## ***Evaluation of Baffle-Former Bolt Degradation – Coolable Geometry***

- In some cases, as-found degradation may not meet stress and fuel grid impact criteria.
- If fuel grid impact criteria are exceeded, may need to demonstrate a coolable geometry with some damage to peripheral fuel assemblies
- WCAP-15029-P-A provides some guidance.



# ***Evaluation of Baffle-Former Bolt Degradation – Reinspection Interval***

- **WCAP-17096-NP-A, “Reactor Internals Acceptance Criteria Methodology and Data Requirements,” provides guidance for engineering evaluation of baffle-former bolt degradation.**
  - **Numerical margin consists of additional bolts over and above the number in the minimum bolting pattern.**
  - **If the number of degraded bolts is less than half the margin, may reinspect in ten years.**
  - **If the number of degraded bolts is greater than half the margin, a different reinspection interval must be justified.**
- **Plants with large numbers of degraded bolts would not have met the WCAP-17096-NP-A criteria so replaced all bolts to restore full structural margin.**
- **Industry is developing models for failure rates of baffle-former bolts – need reinspections of bolts at < 10 year interval to establish.**



## ***NRC Response – Regional Inspections***

- The NRC staff performed targeted inspections at Indian Point and Salem and is performing a similar inspection at D.C. Cook.
- Inspections focused on:
  - NDE quality and accuracy (VT, UT)
  - Corrective actions, including evaluation of operating units
  - Adequacy of replacement bolt pattern, including margin for additional failures during next cycle
- Results of the NRC inspections are documented in publically available inspection reports.
- Regional inspectors engaging with other plants with regard to operability evaluations and plans for upcoming outages.



## ***NRC Response – LIC-504***

- **Evaluated four options,**
  1. Immediate shutdown and inspection;
  2. Inspection next refueling outage;
  3. Generic communication;
  4. Maintain status quo
- **Acceptable options must meet five criteria:**
  1. Compliance with existing regulations;
  2. Consistency with the defense-in-depth philosophy;
  3. Maintenance of adequate safety margins;
  4. Demonstration of acceptable levels of risk;
  5. Implementation of defined performance measurement strategies



## ***NRC Response – LIC-504 - Results***

- Risk met LIC-504 criteria of  $CDF < 1 \times 10^{-3}$  and  $LERF < 1 \times 10^{-4}$ 
  - Low frequency of large and medium LOCAs results in low CDF due to LOCA
  - Seismic risk assessment performed using bounding seismic hazard curve for U.S. based on recent updated seismic hazard submittals. Seismic assessment assumed 75% reduction in load capacity for baffle-former bolts, much greater than observed in any plant.
- Determined both Options 1 and 2 meet the five criteria of LIC-504: Options 3 and 4 have more risk uncertainty
- Option 1, immediate shutdown, places an unnecessary burden on licensees, thus Option 2 was recommended.
- Interim industry guidance effectively implements Option 2.



# ***NRC Response – Operating Experience Summary***

- Based on NRC staff review of operating experience, preliminary conclusion is that Westinghouse 4-loop design, downflow plants with Type 347 bolts are more susceptible to baffle-former bolt degradation than other PWR designs.
- Plants in this group are:
  - D.C. Cook, Units 1 and 2
  - Diablo Canyon, Unit 1
  - Indian Point, Units 2 and 3
  - Salem, Units 1 and 2
- EPRI MRP Interim Guidance calls for UT inspection of all baffle-former bolts at the next refueling outage for these plants (designated Tier 1a). The NRC is monitoring inspections and other actions at these plants.
- The immediate safety concern for these plants is addressed by the LIC-504 evaluation.



## ***NRC Response – Future Activities***

- **Following root cause investigation at D.C. Cook 2, with focus on cause of degradation of replacement bolts and baffle-edge bolts**
- **Will determine if the LIC-504 requires revision based on new developments at D.C. Cook, Unit 2**
- **Continue to engage with industry focus group, especially on root cause from the three plants. Discuss with industry if changes to interim guidance are necessary**
- **Develop Information Notice**
- **Document assessment of MRP interim guidance**
- **Determine if changes to MRP-227-A guidance are needed**

# **NRC – ACRS Metallurgy Subcommittee Briefing**

Bernie Rudell, MRP Chair, Exelon

Heather Malikowski, PWROG MSC Chair, Exelon

Tim Wells, BFB Focus Group Chair, Southern


Kyle Amberge, Project Manager, EPRI

Bryan Wilson, Fellow Engineer, Westinghouse-PWROG


**Rockville, MD, November 16, 2016**



# Westinghouse NSSS Internals




# Baffle-Former Assembly



Source: ML15331A264

# Baffle-Former Assembly Details

- Core barrel, baffle and former plates
  - Type 304 austenitic stainless steel material
- Baffle-Former Bolts (BFBs)
  - Attach the baffle plates to the former plates in the reactor lower internals assembly
  - Type 347 or Type 316 cold worked austenitic stainless steel material
  - Bolt head designs and shank lengths vary from plant-to-plant




Source: ML15331A179

# Coolant Flow Configurations

## Downflow Configuration

Large Differential Pressure ( $\Delta P$ ) Across the Baffle Plate -> greater BFB bolt loads



Coolant Flow


Baffle Plate

Former Plate

## Upflow Configuration

Small Differential Pressure ( $\Delta P$ ) across the baffle plate -> lower BFB bolt load

\*Figure shows modification made for Upflow Conversion



New Flow Hole

Plug

Coolant Flow

Core Barrel

Coolant Flow

Thermal  
Neutron  
Shield

Source: ML073190376

# Operating Experience Overview

## Operating Experience

First UT baffle-former bolts (BFB) inspections in French PWR CP0 units and first cracks found

First degraded baffle-former bolts found in U.S.

DC Cook2 finds degraded bolts by visual inspection

Ginna performs first MRP-227 inspections

Indian Point 2, Salem 1, DCCook2 find degraded bolts (visual+UT)



WCAP-13266: BFB Program for the Westinghouse Owners Group - Plant Categorization

NRC Information Notice 98-11 on BFBs

MRP publishes assessment of French BFB OE (MRP-03)

MRP publishes Reactor Internals Inspection Guidelines (MRP-227)

NRC reviews & approves MRP-227

Westinghouse Technical Bulletin TB-12-5, related to the DC Cook OE

NSAL-16-1 AREVA CSB-16-02 Interim Guidance

## Guidance

***Per MRP-227-A, BFB UT exam is performed for WEC plants initially at 25-35EFPY and repeated every 10-years***

*Note: UT deployed as it becomes available and qualified for the various sites*

# Past Plant Operating Experience

EDF 1989-Present

Joint Owners Group Program 1998-2000

Westinghouse NSSS MRP-227-A Inspections

B&W NSSS and International Plant Results


# EDF Experience 1989-Present

- Baffle bolt failures reported - Limited to 'CP0' design
  - 3-loop (converted to upflow), with significant plant-to-plant variability (CPY design <5 indications over life of plant)
- EDF Periodic bolt replacement of failed original bolts, and periodic replacements included previously replaced bolts
  - Maintain sufficient number of “healthy bolts” to push next inspection to 10 years (based on observed failure rate of 5 bolts/year)



## Overall BFB Timeline – CP0 Units

- X-axis: number of operating hours
  - Y-axis: cumulative number of bolts found ‘failed’/‘unconclusive’
  - ----- : evolution trend, assuming 5 failed bolts per year
- BUG2-FES2-FES1-BUG3: 4/6 CP0 units are ‘affected’**  
**BUG5-BUG4: 2/6 CP0 units are ‘unaffected’**



# Joint Owners Group Program (15-22 EFPY)

- Sponsored Inspections of four plants (1998-2000)
  - Ginna: 2-loop, Downflow, Type 347SS
    - 9% UT Indications (Of these, 14 were sent for metallurgical examination. Results showed no indications of cracking, so this 9% likely contains a number of false calls)
    - Partial replacement program
  - Point Beach Unit 2: 2-loop, Upflow (converted) , Type 347SS
    - 8% UT Indications
    - Partial replacement program
  - Farley Unit 1: 3-loop, Upflow (converted), Type 316SS
    - No UT Indications
    - Proactive replacement of minimum pattern
  - Farley Unit 2: 3-loop, Converted Upflow (downflow at time of inspection), Type 316SS
    - No UT Indications
    - Proactive replacement of minimum pattern
- Inspection results and metallurgical exams of bolts removed during this program led to conclusion that BFB degradation was not a concern for the original plant operating period and that this could be addressed by an aging management program for license renewal (MRP-227-A).

# Westinghouse NSSS MRP-227-A BFB Inspections

through Sept. 2016 (excluding IP2, SAL1, DCCook2)

- Ginna: 2-Loop, Downflow, Type 347SS
  - 2nd Inspection (2011)(partial inspection of 123 original bolts and 56 replacement bolts): one additional UT Indication (Partial Replacement of 25 bolts)
- Point Beach Unit 1: 2-Loop, Upflow (converted), Type 347SS
  - 1st Inspection (2013): No UT Indications
- Point Beach Unit 2: 2-Loop, Upflow (converted), Type 347SS
  - 2nd Inspection (2014): 2% Additional UT Indications
- Prairie Island Unit 1: 2-Loop, Downflow, Type 347SS
  - 1st Inspection (2014): 6% UT Indications
- Prairie Island Unit 2: 2-Loop, Downflow, Type 347SS
  - 1st Inspection (2013): 10% UT Indications
- Surry Unit 1: 3-Loop, Downflow, Type 347SS
  - 1st Inspection (2010): <1% UT Indications
- Surry Unit 2: 3-Loop, Downflow, Type 347SS
  - 1st Inspection (2011): <1% UT Indications
- Robinson: 3-Loop, Downflow, Type 347SS
  - 1st Inspection (2013): <1% UT Indications
- Turkey Point Unit 3: 3-Loop, Downflow, Type 347SS
  - 1st Inspection (2015 - partial inspection of 305 bolts): No UT Indications
- North Anna Unit 1, 3-loop, Downflow, Type 347SS
  - 1st Inspection (2016): <1% UT indications

# B&W NSSS and International Plant Results

- Crystal River Unit 3, Type 304SS (2005)
  - No relevant UT indications - UT performed due to visual indication from baffle-to-baffle bolts Oconee Unit 1, Type 304SS (2012)
  - No relevant UT indications - Four BFBs uninspectable due to large welds on locking bars
- Oconee Unit 2, Type 304SS (2013)
  - No relevant UT indications - One BFB uninspectable due to UT probe not seating properly
- Oconee Unit 3, Type 304SS (2014)
  - One BFB identified with crack-like indications - One BFB uninspectable due to UT probe not seating properly
- ANO Unit 1, Type 304SS (2016)
  - UT exams currently underway as of 11/14/2016
- Doel 1: 2-Loop Downflow, Type 316SS
  - 1st Inspection: No relevant UT indications (1991)
  - 2nd Inspection (2005) and 3rd Inspection (2015): 2% UT Indications (replaced 9 bolts in 2015)
- Doel 2: 2-Loop Downflow, Type 316SS
  - 1st Inspection (2006) and 2nd Inspection (2015): <1% UT Indications (replaced 7 bolts in 2015)
- Krsko: 2-Loop, Downflow (prior to inspection), Type 316SS
  - 1st Inspection: <1% UT Indications (2013)
- Tihange 1: 3-Loop, Upflow (converted), Type 316SS
  - 960 of 1088 bolts inspected in each of the following inspections
  - 1st Inspection: 4% UT Indications (1995)
  - 2nd Inspection: 3% UT Indications (2002)
  - Most recent Inspection: No relevant UT Indications (5 bolts either not inspectable or not interpretable) (2014)
- Ringhals 3: 3-Loop Downflow, Type 316SS
  - 1st and 2nd Inspections: <1% UT Indications/uninspectable (2000 and 2007)
  - 3rd Inspection: <1% UT Indications/uninspectable (2016)

# Observations from Broader OE

- Excluding the OE at Cook Unit 2, Indian Point Unit 2, and Salem Unit 1 (discussed later in the presentation), the following observations can be made based on inspection OE gathered to date from international and domestic plants:
  - Bolts with UT indications tend to be randomly distributed
  - Distributions are consistent with expectations of IASCC failures and fluence effects
  - Quantity and distribution of bolts with indications bounded by historical generic safety assessment generated in mid-1990s (documented in report WCAP-15328)
  - Industry response to replacement of bolts with indications has been positive

# Recent Plant Operating Experience

DC Cook 2 – fall 2010

Indian Point 2 – spring 2016

Salem 1 – spring 2016

DC Cook 2 – fall 2016

# DC Cook Unit 2 (2010 / 22 EFPY) (4-Loop Downflow)

- Fuel failure in peripheral assembly attributed to wear against broken bolt head
- Bolt heads and lock bars found on lower core plate
- Visual inspections revealed 18 degraded bolts on 270° baffle plate in Rows 2-5
  - Additional bolts removed from plate with visual indications to define extent of localized degradation (approx. 40 bolts in single patch)
  - Additional test bolts removed from symmetrical locations to evaluate potential for degradation on other plates (all of these test bolts were found to be intact)
- No UT inspections performed in 2010 (at that time UT was not qualified or optimized for the Cook 2 bolt design)
- Degraded and test bolts replaced (total of 52 bolts and 2 open holes)
- Westinghouse issued Technical Bulletin TB-12-5
- 100% Visual VT-3 inspection conducted in 2012 with no additional indications

# Indian Point Unit 2 (2016 / 31 EFPY) (4-Loop Downflow)

- Degraded bolts/lock bars noted visually prior to planned MRP-227 100% UT exams
- Markings on periphery of neighboring fuel assembly identified (no fuel failure).
- Inspections identified 227 BFB with visual or UT indications (includes 14 uninspectable)
- UT indications were clustered
  - Spanned various quadrants, mostly in former Rows D through G
  - Multiple groups of 10+ adjacent failures / At least one cluster of 50+ adjacent failures
- Observed failures exceed WCAP-17096-A engineering acceptance criteria
- Site-specific response
  - Performed Acceptable Bolting Pattern Analysis (ABPA)
  - Performed Replacement Bolting Pattern Analysis
  - Performed engineering evaluations supporting Unit 3 Extent of Condition Evaluation
  - Performed engineering evaluations supporting Unit 2 Assessment of Potential Safety Impacts
  - Performed baffle-former bolt removal and replacement
  - Quarantined select bolts for future testing

# Salem Unit 1 (2016 / 28 EFPY) (4-Loop Downflow)

- Conducted visual exams every other refueling outage in response to DC Cook Unit 2 OE and TB-12-5; MRP-227 exams were not planned until 2017
- Degraded bolts/lock bars noted in visual exams followed by doing 100% UT exams
- Loose/protruding bolt heads resulted in fuel fretting and one fuel clad failure
- Inspections identified 182 BFB with visual degradation or UT indications (includes 18 uninspectable)
- UT indications were clustered
  - More concentrated (than Indian Point 2) to a few adjacent octants
  - Multiple groups of 10+ adjacent failures / At least one cluster of 50+ adjacent failures
- Observed failure pattern exceeds WCAP-17096-A engineering acceptance criteria
- Site-specific response
  - Performed Acceptable Bolting Pattern Analysis (ABPA)
  - Performed Replacement Bolting Pattern Analysis
  - Performed engineering evaluations supporting Unit 1 Justification for Past Operation
  - Performed engineering evaluations supporting Unit 2 Extent of Condition Evaluation
  - Performed baffle-former bolt removal and replacement
  - Quarantined select bolts for future testing


# DC Cook Unit 2 (2016 / 28 EFPY) (4-Loop Downflow)

- Two (2) on-line fuel leaks identified during the last fuel cycle associated with two (2) empty bolt-holes from bolts that were not replaced in 2010 (suspected damaged by jetting through a vacant BFB hole)
- Inspections identified 179 BFB with visual degradation or UT indications (includes 9 that were not inspectable, and three (3) with visibly degraded lock-bar welds)
  - Includes 6 replacement BFBs from 2010 event that exhibit UT indications
  - Five (5) Baffle-Edge-Bolts on one seam appear visually failed
- UT indications were clustered
  - Spanned various quadrants
  - Multiple groups of 10+ adjacent failures / At least one cluster of 50+ adjacent failures
- Observed failure pattern exceeds WCAP-17096-A engineering acceptance criteria
- Site-specific response currently being implemented
  - Performed Acceptable Bolting Pattern Analysis (ABPA)
  - Performed Replacement Bolting Pattern Analysis
  - Performed engineering evaluations supporting Unit 2 Justification for Past Operation
  - Performed engineering evaluations supporting Unit 1 Extent of Condition Evaluation
  - Performing baffle-former bolt removal and replacement, expect to replace 200 bolts and plan to complete by 12/5/2016
  - Plan to quarantine select bolts for potential future testing

# Conclusions from Recent OE

- These three plants share a common plant design configuration (4-loop downflow), bolt design, and bolt material
- Bolts with visual or UT indications tend to be clustered
- Distributions seem to indicate the presence of a mechanism causing adjacent bolts to become more susceptible to failure
- Assessing impact of new findings from DC Cook 2 exams:
  - Replacement 316 CW BFBs (6) from 2010 event with UT indications
  - Visually degraded edge bolts (5) on one panel, in the center of a large area/cluster of BFB failures

# US Trends – BFB Focus Group Industry OE Database



# Factors Influencing BFB Degradation

- Fluence, Stress, Material, and Time
  - Contribute to a condition conducive to IASCC crack initiation
  - Stress is influenced by plant design (loads), bolt design, stress relaxation, clustering (failure progression), and bolt replacement
- Plant design – number of loops, downflow/upflow
  - Impact the stresses that develop in the baffle-former bolts
- Bolt design
  - Bolts are either type 347 or cold-worked type 316 austenitic stainless steel material
  - While it is believed 316 has improved IASCC resistance based on our limited OE, insufficient direct comparative data exists at this point to make a definitive conclusion due to the introduction of additional variables (i.e. bolt design, plant operating parameters, etc.).
  - Type 347 bolts tend to have a sharper head to shank transition radius as compared to the type 316 designs
  - Type 347 bolts are generally shorter than the 316 bolts
  - Bolt length and head-to-shank transition radius (stress concentration) impact the average and peak stresses impacting IASCC and fatigue susceptibility and are believed to be more influential with respect to BFB degradation than material differences

# Factors Influencing BFB Degradation (cont.)

- Stress relaxation
  - Occurs over a relatively short duration at high temperature and fluence
  - Reduces joint efficiency causing increased bolt loads
- Clustering of bolts
  - As failures occur, stresses redistribute into surrounding bolts
  - Increased stress can enhance IASCC susceptibility and fatigue / propagate existing cracks
- Bolt Replacement
  - Modifies how stress is distributed across bolts in the structure
  - May slow the process of degradation for nearby original bolts by tightening the structure and reducing load carried by original bolts

# Explaining Failure Patterns

## 1. Randomly Distributed Failures

- Hypothesis: IASCC failure rate governed by stress, temperature, dose, time
- Key variables: Material, Plant Design, Bolt Design
- Simplified empirical representations and comparisons between plants can be used in this case: e.g. Weibull Distribution

## 2. Dose-Related

- Hypothesis: IASCC failure rate driven by temperature and stress from high dose rates which causes local acceleration
- Key variables: Fluence, Gamma Heating, Irradiation Creep, Void Swelling
- Good correlation with deterministic results from existing MRP aging model (IRRADSS Model): Predicted patterns similar to bolt failure experience in French CP0 plants

## 3. Clustered


- Hypothesis: IASCC failure rate still affected by same parameters as random distribution but local stress increases around groups of adjacent failed bolts due to transfer of primary loads
  - Particular issue for downflow configuration plants due to high baffle plate  $\Delta P$
- Current modeling efforts are underway with the goal of replicating and predicting this failure pattern

# Why Clustered Failures?


- **Answer 1:** Failures have a common cause that localizes the effects of IASCC or fatigue
  - Stress anomaly
  - Asymmetric fatigue
  - Local hot spot
  - Bolt source or installation sequence
- **Answer 2:** Failure propagates after initial random failures reach a critical level
  - Failures are random until adequate clusters of failed bolts form
  - Probability of failure in neighboring bolts increases with the increased load
  - Group of bolts “unzippers” as more and more adjacent bolts fail
- Possibly a combination of both of these answers

# Vertical Stress Variation in Downflow Design


Bolt load ( $L_{\text{bolt}}$ ) varies due to varying pressure differential across baffle plate



# Stress Redistribution to Adjacent Bolts - Secondary



0 Failed Bolts




1 Failed Bolt

Secondary stresses predominant in early life (bolt preload)

But do not redistribute with failure

Irradiation Induced Stress Relaxation diminishes secondary stresses over time

# Stress Redistribution to Adjacent Bolts - Primary



Primary stresses dominate after irradiation stress relaxation occurs.

Stress redistributes as bolts fail.

First order approach shown in figure:  $b > a > 1$

# Consequences and Evaluation of BFB Degradation

- Degraded condition assumed for safety evaluations
  - It was assumed that all baffle-former bolts in a quadrant were degraded and a pinned constraint of baffle edges remained due to the presence of some edge bolts and/or overlapping plates
- Safety evaluations considered the following:
  - Impact on core bypass flow for non-LOCA and LOCA safety analysis
  - Control rod insertability
  - Fuel assembly grid crush and core coolability
- Conclusion was that plants would remain in a safe condition
  - Non-LOCA and LOCA safety analysis showed acceptable results when considering the increased bypass flow associated with this condition
  - Fuel assembly grid crush could occur in the peripheral fuel assemblies and to a much lesser degree in inboard fuel assemblies; however, this would result in a negligible impact on core coolability
  - Control rods would be able to fully insert to shut down the plant
  - Therefore, the ability to cool the core, maintain reactor shutdown, and remove decay heat in the long-term after a LOCA, would not be compromised by baffle-former bolt degradation

# Consequences and Evaluation of BFB Degradation (cont'd.)

- Additional evaluations of BFB degradation included:
  - Baffle jetting
    - Loose baffle plates could result in opening up of baffle-to-baffle gaps or flow holes around broken bolts
    - Result would potentially be increased fuel rod vibration and wear
    - Monitoring of coolant activity will detect the presence of damaged fuel
  - Loose Parts
    - Heads of failed BFB generally remain trapped by the lock bar
    - Cracked lock bar welds and protruding bolt heads have been found in areas of large clusters of failed BFB
    - Loose bolt heads and lock bars can result in localized fretting of the fuel rod cladding
    - Monitoring of coolant activity will detect the presence of damaged fuel
    - Loose bolt heads will remain trapped by the adjacent fuel assembly
    - Lock bars can enter the reactor coolant systems but have been determined to have a negligible impact on safe operation

# Industry Communication

- Tech Bulletin, TB-12-5, was issued in March 2012 after the Fall 2010 Cook Unit 2 visual findings of damaged baffle-former bolts
- Nuclear Safety Advisory Letter, NSAL-16-1, released on July 5
  - Determination of leading and affected plants was consistent between TB-12-5 and NSAL-16-1
  - Westinghouse 4-loop downflow plants are most susceptible
  - All Westinghouse designed NSSS plants with baffle-former bolts and CE designed plants with bolted core shrouds are potentially affected by this issue
  - The Westinghouse AP1000® plant design does not utilize baffle-former bolts and is not affected by this issue
- Affected plants broken down into 4 Tiers



**AP1000** is a trademark or registered trademark of Westinghouse Electric Company LLC, its affiliates and/or its subsidiaries in the United States of America and may be registered in other countries throughout the world. All rights reserved. Unauthorized use is strictly prohibited. Other names may be trademarks of their respective owners.



# Intent of NSAL Recommendations

- Current working theory is that the cause of the failures is correlated more closely to key design features (previously discussed) rather than plant-specific operation or conditions
- Based on this, a tiered approach was chosen to rank plants based on how closely key design features matched design features of the plants that have experienced the OE
- The tiered approach also used past inspection data to inform a relative ranking between tiers and sub-tiers
- The NSAL Recommendations are intended to:
  - Promote early identification of failures (ideally before significant clustering has occurred) to retain safety margin
  - Progressively evaluate the extent of condition (this also helps to prove/disprove the working theory)
  - Enable lessons learned from initial inspections to be applied in developing future actions for plants that are perceived to be less susceptible

# NSAL Recommendations

- **Tier 1a (4-loop downflow plants with Type 347 bolt design):**
  - Complete a UT volumetric inspection of the baffle-former bolts at the next scheduled refueling outage
  - In preparation for this inspection, the plant should consider developing an ABPA and be prepared to replace any baffle-former bolts with visible damage or UT indications
  - Additional mitigation strategies include upflow conversion and preemptive bolt replacements
- **Tier 1b (4-loop downflow plants with Type 316 bolt design):**
  - Complete a VT3 (visual) inspection of the baffle-former bolts at the next scheduled refueling outage
  - If any visual indications are found, it is recommended that the plant completes a UT volumetric inspection of the baffle-former bolts
  - If no visual indications are found, it is recommended that the plant completes a UT volumetric inspection of the baffle-former bolts prior to the completion of the second refueling outage after the issuance of this NSAL

# NSAL Recommendations (cont'd.)

- **Tier 2a, 2b, and 2c (2- and 3-loop downflow plants):**
  - Plants that have previously completed UT inspections should review the inspection records to identify any indication of the onset of clustering before the next scheduled refueling outage
  - Clustering is defined as 3 or more adjacent bolts or a total number of failures in a single baffle plate > 40% of the total number of bolts on that baffle plate
  - Any indication of clustering should result in the consideration of an accelerated re-inspection schedule
- **Tier 3 (Converted upflow plants):**
  - 4-loop plants that have operated in a downflow configuration for more than 20 years should evaluate the need to perform a UT volumetric inspection of baffle-former bolts on an accelerated schedule
  - All other plants should follow the General Recommendations for all Tiers (see next slide)
- **Tier 4 (Designed upflow plants):**
  - Follow the General Recommendations for all Tiers (see next slide)

# NSAL Recommendations (cont'd.)

- **General Recommendations for all Tiers:**

- If visually damaged baffle-former bolts or lock bars are detected, it is recommended that the fuel assemblies that were adjacent to the baffle in the previous cycle, and are scheduled for use in the next cycle, be inspected for fretting wear on the face that was adjacent to the baffle
- It is recommended that the plant continues to follow the current MRP-227 guidelines and implement any revisions to the MRP-227 recommendations

# Acceptable Bolting Pattern Analysis (ABPA)

- Methodology based on PWROG report WCAP-15030-NP-A, “*Westinghouse Methodology for Evaluating the Acceptability of Baffle-Former-Barrel Bolting Distribution Under Faulted Load Conditions*,” February 1999.
- Acceptance criteria for MRP-227-A inspection of baffle-former bolts per WCAP-17096-NP-A, Rev. 2, “*Reactor Internals Acceptance Criteria Methodology and Data Requirements*,” August 2016.
- Bolting pattern is evaluated to satisfy normal, upset and faulted condition design qualification allowables from the ASME Section III and functional requirements.
- Bolting pattern is evaluated using 1/8<sup>th</sup> symmetric models of the baffle former assembly.
- Edge bolts are not credited in the demonstration for structural acceptance of the baffle-former assembly.
- Although the large percentage and clustering of BFB failures at the 4-loop downflow plants recently examined exceeded the acceptance criteria, there remained margin such that these findings did not trigger a substantial safety hazard status under 10CFR Part 21.

# Westinghouse Replacement Bolts

- Replacement bolt design improvements to reduce impact of factors influencing bolt degradation
  - Cold Worked Type 316
    - Past operating experience using this material for baffle-former bolts and guide tube support pins has generally been positive. However, insufficient direct comparative data exists at this point to make a definitive conclusion
  - Semi-Parabolic head-to-shank transition fillet radius to reduce stress concentration and increase flexibility
    - Improved fatigue resistance
    - Reduced susceptibility to IASCC initiation
- Additional design improvements made for installation efficiency and ease of examination



# BFB Focus Group Activities

# Industry Response

- The Industry Baffle-Former Bolt Focus Group (BFB FG) was formed in May 2016 to support an integrated approach among industry organizations to address recent operating experience
  - AREVA
  - EPRI
  - PWROG
  - Utility Staff
  - Westinghouse
  - Others
- Six focus areas with key actions defined

Focus Area	Lead Organization
#1 – /Extent of Condition, Interim Guidance, Technical Interfacing with the NRC	MRP
#2 – Plant/Fleet Operating Experience Assessment	PWROG
#3 – Repair/Replacement	PWROG
#4 – Inspection/NDE	MRP
#5 – Irradiated Testing Support	MRP
#6 – Aging Management Assessment	MRP

# Industry Response

Joint EPRI/PWROG BFB Focus Group established to determine how MRP-227 guidance will change as a result of recent OE

- *Focus Area #1: Cause and Extent of Condition, Interim Guidance*
  - Develop BFB OE database and verify data
  - Evaluate/trend BFB OE
  - Develop Interim Guidance
- *Focus Area #2: Plant and Fleet Operating Experience Assessment (PA-MS-1473) (PWROG Lead)*
  - Westinghouse to complete the 10CFR21 evaluation
  - Westinghouse to complete an NSAL; AREVA to produce a similar document for B&W plants (Customer Service Bulletin)
- *Focus Area #3: Repair and Replacement (PWROG Lead)*
  - Work with vendors to develop a contingency plan for tooling and bolt inventory for the upcoming outage seasons (Fall 2016 and Spring 2017)

# Industry Response

- *Focus Area #4: Inspection / NDE*
  - Review bolt inspection protocols to see if lessons learned suggest modifications
  - Understand UT Probability of Detection as related to UT-acceptable bolts
- *Focus Area #5: Irradiated Testing Support*
  - Establish an integrated testing plan to build upon the Indian Point 2 root cause evaluation/analysis and further advance IASCC susceptibility knowledge
  - Evaluate the need to include Salem 1 and Ginna BFBs into an integrated testing program
- *Focus Area #6: Aging Management Assessment*
  - Review previous aging management assessments and compare to current OE experiences
  - Evaluate prediction models like the Weibull distribution in MRP-03 (which is based on French data)
  - **Long term functionality of MRP-227-A**
  - Has merged with Focus Area #1

# Near Term Industry BFB FG Actions Completed

- Supported presentation to NSIAC on 5/23/2016
  - Westinghouse Technical Bulletin TB-12-5 remains valid
- Provided Industry Alert Letter from the PMMP Chairman to PWR site VPs on 6/1/2016
  - Expect that NEI 03-08 Interim Guidance will require the 4-loop plants identified in the Westinghouse TB-12-5 bulletin to perform UT inspections of all the BFBs or replace an acceptable pattern of bolts at their next outage.
  - Consideration should also be given to proceeding with procurement of replacement bolts prior to issuance of interim guidance due to potentially long manufacturing lead times.
- Westinghouse NSAL 16-1 issued 07/05/16 and revised 08/01/16
- AREVA CSB issued 07/14/16

# Near Term Industry BFB FG Actions Completed

- Issued NEI 03-08 “Needed” Interim Guidance regarding BFB inspections for Tier 1 plants (7/25/2016) and for Tier 2 plants (9/29/2016) as identified in Westinghouse NSAL 16-1
- Assessed Fall 2016 and Spring 2017 outage seasons for developing a contingency plan for tooling and BFB material needs
  - Fall 2016: 3 planned MRP-227 UT inspections (1 of 3 is a Tier 1a plant) and 1 VT-3 inspection (Tier 1b plant)
  - Spring 2017: 2 planned MRP-227 UT inspections (both Tier 1a plants), 1 planned UT inspection (non MRP-227 but a Tier 1a plant), and 1 VT-3 inspection (Tier 1b plant)
- Initiated Hot Cell Post Irradiation Examinations of Indian Point 2 BFBs
  - Microscopic examinations have begun and are currently underway

# Planned BFB FG Activities through Mid-2017

- Finalize BFB OE database by adding international data and UT inspection results from 2016-2017 exams in the US
- Continue with Hot Cell PIE work for IP2 and SAL1
- Explore providing additional NEI 03-08 Interim Guidance for the remainder of U.S. PWR fleet later in Fall 2016 or early 2017
- Establish fundamental understanding of BFB failure mechanism(s) and develop potential changes to MRP-227 inspection guidance as needed
  - Re-inspection frequency for UT exams
  - Allowance for proactive BFB replacement to manage aging



# Together...Shaping the Future of Electricity



*The Materials Committee is established to provide a forum for the identification and resolution of materials issues including their development, modification and implementation to enhance the safe, efficient operation of PWR plants.*