

February 20, 1980

Mr. Boyce H. Grier, Director  
United States Nuclear Regulatory  
Commission - Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

RE: Docket No. 50-220  
LER 80-06

Dear Mr. Grier:

Attached is Licensee Event Report 80-06, submitted in accordance with paragraph 5.6.2 Appendix B, DPR-63. The incidents reported constitute exceeding the Limiting Conditions for Operations given in Environmental Technical Specifications 2.1.1 and 2.1.5 and are described in detail in this letter. These have been investigated by the Site Operations Review Committee in accordance with ETS 5.4 and corrective action was initiated as stated.

Very truly yours,

- original signed by James Bartlett

James Bartlett  
Executive Vice President

MS:jl  
Attachments (3 copies)  
xc: Director, Office of I&E (30 copies)  
Director, Office of MIPC (3 copies)

COO3  
A-002  
5/11

8002260

648 S

**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	Y	N	M	P	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5			
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT		58

CON'T

0	1	REPORT SOURCE										L	6	0	5	0	0	0	2	2	0	7	0	1	2	4	8	0	8	0	2	2	0	8	0	9												
7	8											60	61	DOCKET NUMBER										68	69	EVENT DATE										74	75	REPORT DATE										80

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0 2 | Condensor inlet/circulating water discharge AT exceeded the 31.2°F Tech  
0 3 | Spec limit for more than 8 hours on Jan. 23-24 1980. Following flow  
0 4 | reversal on Jan. 24, 1980 the discharge temperature exceeded lake ambi-  
0 5 | ent by more than the tech spec limit of 50°F. Since the temperatures  
0 6 | were within a few percent of specifications, there should be no signi-  
0 7 | ficant additional environmental effect.  
0 8 |  
7 8 9 | 8

[illegible]

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Instrument failure and transitional plant maneuvers contributed to the

1 1 events. Operators have been instructed to regularly monitor redundant

1 2 instrumentation during normal and transitional operation. (See attached

1 3 narrative.)

1 4

7 8 9 80

FACILITY STATUS (28) 1 5 E 7 8 9  
 % POWER 0 9 8 (29) 10 12 13  
 OTHER STATUS (30) NA 44  
 METHOD OF DISCOVERY (31) B 45 46  
 DISCOVERY DESCRIPTION (32) Operational Event 80  
 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  
 1 6 Z (33) 7 8 9 10 11 12 13  
 (34) NA 44  
 LOCATION OF RELEASE (36) NA 45

PERSONNEL EXPOSURES									
NUMBER			TYPE	DESCRIPTION					
1	7	000	(37) Z	(38) NA					

PERSONNEL INJURIES										
NUMBER				DESCRIPTION						
1	8	0	0	0	40	NA				

1		9		7		8		9		10		80	
LOSS OF OR DAMAGE TO FACILITY (43)													
TYPE		Z (42)		DESCRIPTION NA									

PUBLICATION		ISSUED		DESCRIPTION		NRC USE ONLY	
2	0	N	44	45	NA		
7	8	9	10			68	69

**NRC USE ONLY**

NAME OF PREPARER Michael Hedrick

PHONE: 315-343-2110 Ext. 1395