



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920


October 17, 1978

BBS Ltr. #78-1386

REGULATORY DOCKET FILE COPY

James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Reportable Occurrence Report #78-053/03L-0, Docket #050-237 is hereby submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.


B.B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS/deb

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

REGULATORY DOCKET FILE COPY

7810270234

A002
5/11

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	L	D	R	S	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5
7	8	9					14	15											25	26							57	CAT	58
		LICENSEE CODE						LICENSE NUMBER													LICENSE TYPE								

REPORT

0	1	REPORT SOURCE		L	6	0	5	0	0	0	2	3	7	7	0	9	2	6	7	8	8	1	0	1	7	7	8	9		
7	8			60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During steady state operation an Equipment Attendent noted Main Steam Line (A) Flow

0 3 switch 261-2D (1 of 16) was valved out. Event had minimal safety significance since

0 4 all other flow switches were operable as required by Tech. Specs. There are no

0 5 previous occurrences of this type.

0 6

0 7

0 8

7 8 9 80

SYSTEM CODE C D		CAUSE CODE A		CAUSE SUBCODE C		COMPONENT CODE I N S T R U				COMP. SUBCODE E		VALVE SUBCODE Z	
EVENT YEAR 7 8		SEQUENTIAL REPORT NO. 0 5 3		OCCURRENCE CODE 0 3				REPORT TYPE L		REVISION NO. 0			
ACTION TAKEN X	FUTURE ACTION H	EFFECT ON PLANT Z	SHUTDOWN METHOD Z	HOURS 0 0 0 0	ATTACHMENT SUBMITTED N	NPRD-4 FORM SUB. N	PRIME COMP. SUPPLIER N	COMPONENT MANUFACTURER A 4 1 5					

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Cause for switch isolation unknown. Switch returned to service. Surveillance

1 1 DIS 250-1 for switches done 9/16/78, and checklist indicates switch returned to

1 2 service. Switch operation also not recorded as required by Equipment Attendant.

1 3 Control room surveillance sheets will be revised to include a daily check of these

1 4 switches and require a supervisory review.

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION									
1 5 E 28 0 9 8 29 NA										30										B 31										Operating Surveillance 32																			
ACTIVITY CONTENT										RELEASED OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																			
1 6 Z 33 Z 34 NA										35										NA 36																													
PERSONNEL EXPOSURES										NUMBER										TYPE										DESCRIPTION																			
1 7 0 0 0 37 Z 38										39										NA																													
PERSONNEL INJURIES										NUMBER										DESCRIPTION																													
1 8 0 0 0 40										41										NA																													
LOSS OF OR DAMAGE TO FACILITY										TYPE										DESCRIPTION																													
1 9 Z 42										43										NA																													
PUBLICITY										ISSUED										DESCRIPTION										NRC USE ONLY																			
2 0 N 44										45										7810270-236																													

Ralph E. Pullo

PHONE: X265