

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8009300415 DOC.DATE: 80/09/24 NOTARIZED: NO DOCKET #
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH.NAME AUTHOR AFFILIATION
 RENBERGER,D.L. Washington Public Power Supply System
 RECIP.NAME RECIPIENT AFFILIATION

mat,

SUBJECT: Deficiency rept re primary containment pressure monitoring
 instrumentation sensing line routing to initiate ECCS.PED.
 220-I-324 & -329 issued, re-assigning instrumentation sensing
 lines to penetrations below instrument rack elevation.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES:PM: 2 copies of all material.

05000397

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
ACTION:	A/D LICENSNG 04	1	1	YOUNGBLOOD,B 05	1	1
	RUSHBROOK,M.. 06	1	1	LYNCH,D. 07	1	1
INTERNAL:	AD/RCI/IE 17	1	1	AEOD 18	1	1
	ASLBP/J.HARD	1	1	D/DIR HUM FAC15	1	1
	EDO & STAFF 19	1	1	EQUIP QUAL BR11	1	1
	HYD/GEO BR 22	1	1	I&E 09	2	2
	LIC QUAL BR 12	1	1	MPA 20	1	1
	NRC PDR 02	1	1	OELD 21	1	1
	PROC/TST REV 13	1	1	QA BR 14	1	1
	<u>REG FILE</u> 01	1	1	RUTHERFORD,W.IE	1	1
	STANDRDS DEV 21	1	1			
EXTERNAL:	ACRS 16	16	16	LPDR 03	1	1
	NSIC 08	1	1			

OCT 1 1980

TOTAL NUMBER OF COPIES REQUIRED: LTTR 42 ENCL 42

R

RECEIVED
JAN 10 1964
U.S. DEPARTMENT OF AGRICULTURE
WASHINGTON, D.C.

TO THE DIRECTOR, U.S. DEPARTMENT OF AGRICULTURE
WASHINGTON, D.C.

FROM THE DIRECTOR, U.S. DEPARTMENT OF AGRICULTURE
WASHINGTON, D.C.

SUBJECT: [Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]


[Illegible]

[Illegible]

[Illegible]

[Illegible]

[Illegible]



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 988

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

September 24, 1980
G02-80-211

Docket No. 50-397

Nuclear Regulatory Commission
Region V
Suite 202, Walnut Creek Plaza
1900 North California Blvd.
Walnut Creek, CA 94596

Attention: Mr. R. H. Engelken, Director

Gentlemen:

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NO. 50-397, CPPR-93
REPORTABLE DEFICIENCY - 10CFR50.55(e)

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on August 27, 1980 of a reportable deficiency relative to Primary Containment pressure monitoring instrumentation sensing line routing. These lines were routed such that low points were formed which will fill with condensate resulting in non-conservative pressure indication.

Attached is our report on this deficiency.

Please contact us if you have any questions.

Very truly yours,

D. L. RENBERGER
Assistant Director,
Technology

DLR:GWB:cd

attachment

cc: JR Lewis - BPA
ND Lewis - EFSEC
V. Stello - NRC
RE Snaith - B&R
AD Toth - NRC
JJ Verderber - B&R
B. Wood - NUS
WNP-2 Files

B019
S
1/1

8009300 415

200
100

314

REPORTABLE DEFICIENCY AND CORRECTIVE ACTION

WPPSS NUCLEAR PROJECT NO. 2

PRIMARY CONTAINMENT PRESSURE MONITORING
INSTRUMENTATION SENSING LINE ROUTING

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

DOCKET NO. 50-397

LICENSE NO. CPPR-93

DESCRIPTION OF DEFICIENCY:

The reported deficiency involves the routing of the sensing lines for the Primary Containment pressure monitoring instrumentation used to initiate ECCS. The Containment penetrations originally assigned to these instrument sensing lines are located above the instrument rack elevations which house the pressure monitoring instrumentation. These lines were routed from the penetrations down to the bottom of the instrument racks and then back up to the instruments forming a low point. Condensate will then form in the line low point resulting in non-conservative pressure indication.

SAFETY IMPLICATIONS:

Non-conservative Primary Containment pressure indication will result in a delay of ECCS initiation.

CORRECTIVE ACTION:

PED's 220-I-324 and -329 have been issued to reassign the Containment Pressure monitoring instrumentation sensing lines to Containment penetrations located below the instrument rack elevation and to remove any low points in the line route.

