

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8203170221 DOC. DATE: 82/03/02 NOTARIZED: NO DOCKET #  
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397  
 AUTH. NAME: BOUCHEY, G.D. AUTHOR AFFILIATION: Washington Public Power Supply System  
 RECIP. NAME: SCHWENCER, A. RECIPIENT AFFILIATION: Licensing Branch 2

SUBJECT: Advises that Refs 3.5-21, 3.5-22 & 3.5-23 of turbine missile analysis are being transmitted under separate cover as proprietary info, per NRC 820226 request. Tabulation of pl probabilities & Westinghouse 820205 ltr encl.

DISTRIBUTION CODE: B001S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5  
 TITLE: PSAR/FSAR AMDTS and Related Correspondence

NOTES: 2 copies all matl: PM.

05000397

RECIPIENT		COPIES		RECIPIENT		COPIES	
ID	CODE/NAME	LTTR	ENCL	ID	CODE/NAME	LTTR	ENCL
A/D	LICENSNG	1	0	LIC	BR #2 BC	1	0
LIC	BR #2 LA	1	0	AULUCK, R.	01	1	1
INTERNAL:	ELD	1	0	IE	06	1	1
	IE/DEP/EPDB 35	1	1	IE/DEP/EPLB	36	3	3
	MPA	1	0	NRR/DE/CEB	11	1	1
	NRR/DE/eqB 13	3	3	NRR/DE/GB	28	2	2
	NRR/DE/HGEB 30	2	2	NRR/DE/MEB	18	1	1
	NRR/DE/MTEB 17	1	1	NRR/DE/QAB	21	1	1
	NRR/DE/SAB 24	1	1	NRR/DE/SEB	25	1	1
	NRR/DHFS/HFEB40	1	1	NRR/DHFS/LQB	32	1	1
	NRR/DHFS/OLB 34	1	1	NRR/DHFS/PTRB20		1	1
	NRR/DSI/AEB 26	1	1	NRR/DSI/ASB	27	1	1
	NRR/DSI/CPB 10	1	1	NRR/DSI/CSB	09	1	1
	NRR/DSI/ETSB 12	1	1	NRR/DSI/ICSB	16	1	1
	NRR/DSI/PSB 19	1	1	NRR/DSI/RAB	22	1	1
	NRR/DSI/RSB 23	1	1	NRR/DST/LGB	33	1	1
	<u>REG FILE</u> 04	1	1	RGNS		1	1
EXTERNAL:	ACRS 41	16	16	BNL (AMDTS ONLY)		1	1
	FEMA-REP DIV 39	1	1	LPDR	03	1	1
	NRC PDR 02	1	1	NSIC	05	1	1
	NTIS	1	1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR

64 59  
 62 ENCL 51

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.

2. Once the problem is identified, the next step is to define the objectives and goals of the project. This helps to clarify what needs to be achieved and provides a clear direction for the team.

3. The third step is to develop a plan or strategy to address the problem. This involves breaking down the problem into smaller, manageable tasks and determining the resources needed to complete each task.

4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress to ensure that the project is on track.

5. The final step is to evaluate the results of the project. This involves assessing the outcomes against the objectives and goals and identifying any areas for improvement.

...the ...  
...the ...  
...the ...

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99

[illegible]


## Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

March 2, 1982  
G02-82-284

Docket No. 50-397

Mr. A. Schwencer, Chief  
Licensing Branch No. 2  
Division of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555



Dear Mr. Schwencer:

Subject: NUCLEAR PROJECT NO. 2  
TURBINE MISSILE ANALYSIS

Reference: Letter G02-82-33, G.D. Bouchey (SS)  
to A. Schwencer (NRC), Same Subject,  
dated January 13, 1982

The reference letter transmitted results of the turbine missile study for WNP-2. In a phone call with the NRC staff on February 26, 1982, copies of References 3.5-21, 3.5-22 and 3.5-23 were requested. These are being transmitted under separate cover as proprietary information. The NRC also requested a tabulation of P1 probabilities, as calculated in Reference 3.5-23, as a function of inspection interval. These are provided in the attachment, for the rated speed (R) and the design over-speed (O) condition.

Also attached is a letter from Westinghouse recommending inspection intervals for the three (3) low pressure turbines at WNP-2 ranging from 55.7 months to 57.8 months. This is based on a deterministic evaluation using actual material properties and chemistry to calculate critical crack size and postulated crack growth rates, based on the methodology in Westinghouse Report MSTG-1-P, "Criteria for Low Pressure Nuclear Turbine Disc Inspection", dated June, 1981.

Boo!  
s  
1/1



Mr. A. Schwencer

Page Two

March 2, 1982

G02-82-284

The Supply System commits to performing inspections on low pressure turbine discs in accordance with the Westinghouse recommendations in the attached letter.

Very truly yours,



G. D. Bouchey  
Deputy Director, Safety and Security

EAF/jca

- Attachments:
1. Westinghouse Letter to Burns and Roe, WEBR-1-82-001, dated February 5, 1982
  2. Table of P1 Probabilities from Westinghouse Report CT-24870, Rev. 1

cc: R Auluck - NRC  
WS Chin - BPA  
R Feil - NRC Site





Westinghouse  
Electric Corporation

Power Generation  
Group

February 5, 1982

Steam Turbine Division

Lester Branch Box 9175  
Philadelphia Pennsylvania 19113

Mr. R. E. Snaith  
Senior Project Engineer  
Burns & Roe, Inc.  
185 Crossways Park Drive  
Woodbury, New York 11797

Washington Public Power Supply System  
WPPSS Nuclear Project No. 2  
B&R Reference Contract No. 2808-1  
(W) Order No. NYPO-13501-T1  
Turbine Generator & Accessories  
WEBR 1-82-001

Dear Mr. Snaith:

In August 1981 the Nuclear Regulator Commission issued their position related to keyway and bore cracks in low pressure nuclear turbine discs to licensees.

Westinghouse supports that NRC position and recommends that WPPSS commit to this criteria. Westinghouse is now supplying inspection intervals which comply with the NRC criterion. These intervals are based on the attached "Westinghouse Inspection Criterion for Discs on Nuclear Low Pressure Turbine Rotors".

A deterministic evaluation has been completed on the WNP#2 low pressure rotors using actual material properties and chemistry. As a result of that evaluation:

		<u>Calculated Inspection Interval</u>
LP#1	S/N 23A3682 Rotor Test #TN-6799	57.8 months
LP#2	S/N 23A3683 Rotor Test #TN-6800	55.7 months
LP#3	S/N 23A3684 Rotor Test #TN-6801	56.3 months

Mr. R. E. Snaith  
February 5, 1982  
Page 2

It should be noted that if a crack is measured at any inspection, the inspection interval will become subject to other criteria as outlined in the "Safety Evaluation Report".

Also attached only to the WPPSS copy of this letter are the following reports for their use and information:

- 1) MSTG-1-P "Criteria for Low Pressure Nuclear Turbine Disc Inspection," June, 1981.
- 2) Topical Report WSTG-1-NP "Procedures for Estimating the Probability of Steam Turbine Disc Rupture from Stress Corrosion Cracking," May, 1981.
- 3) Topical Report WSTG-2-NP "Missile Energy Analysis Methods for Nuclear Steam Turbines," May, 1981

Please note the proprietary nature of all the attachments with the exception of topical reports WSTG-1-NP and WSTG-2-NP.

Very truly yours,



R. W. Ek  
Project Administrator  
Steam Turbine Generator Division

cc: WNP-2 Project Engrg. Manager (3)

attachments

2PR108a





TABLE IV (CONT'D)

DISK	LP	END	DEL T	PROB(R)	PROB(O)
4	2	GOV	43800.0	1.66-011	4.26-013
4	2	GOV	87600.0	5.10-009	9.06-011
4	3	GOV	87600.0	3.36-014	1.60-015
4	3	GOV	17520.0	2.26-011	6.62-013
4	3	GOV	26280.0	6.45-010	1.45-011
4	3	GOV	35040.0	5.70-009	1.07-010
4	3	GOV	43800.0	2.77-008	4.55-010
4	3	GOV	87600.0	2.06-006	2.35-008
5	1	GEN	87600.0	7.97-019	7.86-020
5	1	GEN	17520.0	3.61-015	2.28-016
5	1	GEN	26280.0	3.02-013	1.48-014
5	1	GEN	35040.0	5.63-012	2.31-013
5	1	GEN	43800.0	4.81-011	1.72-012
5	1	GEN	87600.0	1.92-008	4.49-010
5	2	GEN	87600.0	4.17-019	4.14-020
5	2	GEN	17520.0	2.07-015	1.32-016
5	2	GEN	26280.0	1.84-013	9.00-015
5	2	GEN	35040.0	3.57-012	1.45-013
5	2	GEN	43800.0	3.16-011	1.11-012
5	2	GEN	87600.0	1.40-008	3.16-010
5	3	GEN	87600.0	2.86-018	2.72-019
5	3	GEN	17520.0	1.09-014	6.67-016
5	3	GEN	26280.0	8.34-013	3.93-014
5	3	GEN	35040.0	1.45-011	5.72-013
5	3	GEN	43800.0	1.18-010	4.04-012
5	3	GEN	87600.0	4.00-008	9.07-010
5	1	GOV	87600.0	4.97-019	5.16-020
5	1	GOV	17520.0	2.37-015	1.57-016
5	1	GOV	26280.0	2.05-013	1.05-014
5	1	GOV	35040.0	3.89-012	1.67-013
5	1	GOV	43800.0	3.38-011	1.26-012
5	1	GOV	87600.0	1.41-008	3.45-010
5	2	GOV	87600.0	9.53-020	1.05-020
5	2	GOV	17520.0	5.56-016	3.91-017
5	2	GOV	26280.0	5.40-014	2.94-015
5	2	GOV	35040.0	1.11-012	5.06-014
5	2	GOV	43800.0	1.03-011	4.07-013
5	2	GOV	87600.0	5.24-009	1.35-010
5	3	GOV	87600.0	4.96-019	5.07-020
5	3	GOV	17520.0	2.37-015	1.55-016
5	3	GOV	26280.0	2.05-013	1.04-014
5	3	GOV	35040.0	3.90-012	1.65-013
5	3	GOV	43800.0	3.38-011	1.25-012
5	3	GOV	87600.0	1.42-008	3.43-010

## OUTPUT SUMMARY

DEL T = 8760.0	PROB(R) = 1.16-007	PROB(O) = 1.70-009
DEL T = 17520.0	PROB(R) = 1.07-005	PROB(O) = 1.13-007
DEL T = 26280.0	PROB(R) = 1.01-004	PROB(O) = 9.04-007
DEL T = 35040.0	PROB(R) = 4.18-004	PROB(O) = 3.34-006
DEL T = 43800.0	PROB(R) = 1.14-003	PROB(O) = 8.35-006
DEL T = 87600.0	PROB(R) = 1.47-002	PROB(O) = 8.49-005

