

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9006200446 DOC.DATE: 90/06/13 NOTARIZED: NO DOCKET #
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH.NAME AUTHOR AFFILIATION
 FIES,C.L. Washington Public Power Supply System
 POWERS,C.M. Washington Public Power Supply System
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 90-010-00:on 900517,secondary containment ESF actuation
 caused by inadequate work control.

W/9 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	SAMWORTH,R	1 1		
INTERNAL:	ACNW	2 2	ACRS	2 2
	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2	DEDRO	1 1
	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB9H3	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB11	1 1	NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	REG EMBE 02	1 1	RES/DSIR/EIB	1 1
	RGN5 FILE 01	1 1		
EXTERNAL:	EG&G STUART,V.A	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS,G	1 1	NSIC MURPHY,G.A	1 1
	NUDOCS FULL TXT	1 1		

THIS DOCUMENT
 HAS BEEN SCANNED

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 36 ENCL 36

A/0-4
 [Signature]

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

Docket No. 50-397

June 13, 1990

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2
LICENSEE EVENT REPORT NO. 90-010

Dear Sir:

Transmitted herewith is Licensee Event Report No. 90-010 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Very truly yours,

CMP Powers

C. M. Powers (M/D 927M)
WNP-2 Plant Manager

CMP:lr

Enclosure:
Licensee Event Report No. 90-010

cc: Mr. John B. Martin, NRC - Region V
Mr. C. J. Bosted, NRC Site (M/D 901A)
INPO Records Center - Atlanta, GA
Ms. Dottie Sherman, ANI
Mr. D. L. Williams, BPA (M/D 399)

9006200446 900613
PDR ADOCK 05000397
S PDC

*IF22
11*

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Washington Nuclear Plant - Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 3 9 7 1 OF 0 3										PAGE (3) 1 OF 0 3	
TITLE (4) Secondary Containment Engineered Safety Feature (ESF) Actuation Caused by Inadequate Work Control																					
EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)												
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES						DOCKET NUMBER(S)						
0	5	17	90	09	01	0	06	13							0 5 0 0 0						
OPERATING MODE (9) 5			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																		
POWER LEVEL (10) 0 0 0			20.402(b)			20.405(c)			X 50.73(a)(2)(iv)			73.71(b)									
			20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)									
			20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vii)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
			20.405(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)												
			20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)												
			20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)												
LICENSEE CONTACT FOR THIS LER (12)																					
NAME C. L. Fies, Compliance Engineer										TELEPHONE NUMBER 5 0 9 3 7 7 - 2 0 3 9											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs											
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR					
YES (If yes, complete EXPECTED SUBMISSION DATE)												X NO									

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During the reactor refueling outage on May 17, 1990, at 1438 hours a Secondary Containment isolation occurred. This Engineered Safety Feature (ESF) actuation resulted in the shutdown of non-safety related HVAC equipment, the actuation of containment isolation valves, and the startup of various safety related systems such as Standby Gas Treatment. Plant maintenance workers were replacing auxiliary relays as part of the normal preventative maintenance program when they inadvertently placed two channels in the tripped condition which initiated the ESF actuation.

The root cause for this event was inadequate work control which allowed work to proceed simultaneously on two safety-related divisions when no provisions had been made for such an activity.

Immediate corrective action was taken to place the Secondary Containment systems in their normal configuration.

There is no safety significance associated with this event. ESF isolations and actuations occurred as designed for the plant configuration at the time of the event. Accordingly, this event posed no threat to the health and safety of the public or plant personnel.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7	9 0	— 0 1 0	— 0 0	0	2	OF 0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Plant Conditions

Power Level - 0%
Plant Mode - 5

Event Description

During the reactor refueling outage on May 17, 1990, at 1438 hours a Secondary Containment Isolation Engineered Safety Feature (ESF) Actuation occurred. At the time of the actuation maintenance work was being performed by Plant Maintenance workers on General Electric Model HFA auxiliary relays. This ESF Actuation initiated a Balance of Plant (BOP) isolation involving Group 3 (Primary and Secondary Containment Ventilation and Purge Systems) and part of Group 4 (Miscellaneous Balance of Plant Systems). These two Groups are part of the Nuclear Steam Supply Shutoff System (NSSSS) that provides overall isolation of plant systems in response to various process parameters. During refueling (Mode 5) the Primary Containment can be open to the Secondary Containment and this isolation function is limited to Secondary Containment although Primary Containment isolations will occur if components have not been deactivated. In addition to the isolations, the Secondary Containment ESF actuation causes the normal Reactor Building (Secondary Containment) heating and ventilating supply and exhaust fans to stop and Reactor Building pressure control is transferred to the safety-related Standby Gas Treatment (SGT) system which was initiated by this event.

Immediate Corrective Action

Plant operators took immediate corrective action to place the systems back in their normal configuration. The restoration of systems, including the shutdown of SGT, was completed at 1520 hours.

Further Evaluation and Corrective Action

A. Further Evaluation

1. This event is being reported per the requirements of 10CFR50.73(a)(2)(iv) as an "..... event or condition that resulted in manual or automatic actuation of an Engineered Safety Feature (ESF).....".
2. Further evaluation showed work was in progress on the Division I manual actuation relay (MS-RLY-K35A) which put the "A" channel in the tripped condition. When work started on the "B" channel relay (MS-RLY-81B) this caused a full trip on the outboard relay cabinet (RC-1) which resulted in the Secondary Containment Isolation.

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

100-100000

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7	9 0	— 0 1 0	— 0 0 0	3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

3. The root cause was inadequate work control which allowed work to proceed simultaneously on two safety related divisions when no provisions had been made for such an activity.
4. There were no structures, components or systems that were inoperable prior to the start of this event which contributed to the event.

B. Further Corrective Action

1. Work control procedures will be reviewed to determine if additional steps need to be added to control Division related work.
2. The current work control administrative process will be reviewed with Plant Maintenance Department Supervisor and Engineering personnel.

Safety Significance

There is no safety significance associated with this event. ESF isolations and actuations occurred as designed for the plant configuration at the time of the event. Accordingly, this event posed no threat to the health and safety of the public or plant personnel.

Similar Events

None

EIIS Information**Text Reference****EIIS Reference**

	<u>System</u>	<u>Component</u>
Secondary Containment	C	--
Nuclear Steam Supply Shutoff System	--	--
Primary Containment	C	--
Standby Gas Treatment	BH	--
Main Steam Relay K35A (MS-RLY-K35A)	SB	RLY
Main Steam Relay K81B (MS-RLY-K81B)	SB	RLY

12-1-31

1. The first part of the report deals with the general situation of the country and the position of the various groups.

2. The second part of the report deals with the economic situation and the measures taken to improve it.

B. The second part of the report deals with the economic situation and the measures taken to improve it.

3. The third part of the report deals with the social situation and the measures taken to improve it.

4. The fourth part of the report deals with the political situation and the measures taken to improve it.

5. The fifth part of the report deals with the cultural situation and the measures taken to improve it.

6. The sixth part of the report deals with the international situation and the measures taken to improve it.

7. The seventh part of the report deals with the future of the country and the measures taken to improve it.

8. The eighth part of the report deals with the conclusion of the report.

9. The ninth part of the report deals with the appendix of the report.

10. The tenth part of the report deals with the bibliography of the report.

11. The eleventh part of the report deals with the index of the report.

12. The twelfth part of the report deals with the list of figures of the report.

13. The thirteenth part of the report deals with the list of tables of the report.

14. The fourteenth part of the report deals with the list of maps of the report.

15. The fifteenth part of the report deals with the list of references of the report.

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9006200446 DOC.DATE: 90/06/13 NOTARIZED: NO DOCKET #
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH.NAME AUTHOR AFFILIATION
 FIES,C.L. Washington Public Power Supply System
 POWERS,C.M. Washington Public Power Supply System
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 90-010-00:on 900517,secondary containment ESF actuation
 caused by inadequate work control.

W/9 ltr.

DISTRIBUTION CODE: IE22T. COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	SAMWORTH,R	1 1		
INTERNAL:	ACNW	2 2	ACRS	2 2
	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2	DEDRO	1 1
	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB9H3	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB11	1 1	NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	<u>REG FILE</u> 02	1 1	RES/DSIR/EIB	1 1
	RGN5 FILE 01	1 1		
EXTERNAL:	EG&G STUART,V.A	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS,G	1 1	NSIC MURPHY,G.A	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 36 ENCL 36

Ally

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

Docket No. 50-397

June 13, 1990

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2
LICENSEE EVENT REPORT NO. 90-010

Dear Sir:

Transmitted herewith is Licensee Event Report No. 90-010 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Very truly yours,

C. M. Powers (M/D 927M)
WNP-2 Plant Manager

CMP:lr

Enclosure:
Licensee Event Report No. 90-010

cc: Mr. John B. Martin, NRC - Region V
Mr. C. J. Bosted, NRC Site (M/D 901A)
INPO Records Center - Atlanta, GA
Ms. Dottie Sherman, ANI
Mr. D. L. Williams, BPA (M/D 399)

9006200446 900613
PDR ADOCK 05000397
S FDC

IF22
11

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Washington Nuclear Plant - Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 3 9 7 1										PAGE (3) 1 OF 0 3						
TITLE (4) Secondary Containment Engineered Safety Feature (ESF) Actuation Caused by Inadequate Work Control																										
EVENT DATE (5)			LER NUMBER (6)						REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)														
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES					DOCKET NUMBER(S)												
0	5	1	7	9	0	9	0	0	1	0	0	0	6	1	3	9	0	0	5	0	0	0				
OPERATING MODE (9) 5			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																							
POWER LEVEL (10) 0 0 0			20.402(b)						20.405(c)						X 50.73(a)(2)(iv)						73.71(b)					
			20.405(a)(1)(i)						50.38(c)(1)						50.73(a)(2)(v)						73.71(c)					
			20.405(a)(1)(ii)						50.38(c)(2)						50.73(a)(2)(vi)						OTHER (Specify in Abstract below and in Text, NRC Form 366A)					
			20.405(a)(1)(iii)						50.73(a)(2)(i)						50.73(a)(2)(vii)(A)											
			20.405(a)(1)(iv)						50.73(a)(2)(ii)						50.73(a)(2)(viii)(B)											
			20.405(a)(1)(v)						50.73(a)(2)(iii)						50.73(a)(2)(ix)											
LICENSEE CONTACT FOR THIS LER (12)																										
NAME C. L. Fies, Compliance Engineer																	TELEPHONE NUMBER 5 0 9 3 7 7 - 2 0 3 9									
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																										
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC																
SUPPLEMENTAL REPORT EXPECTED (14)																	EXPECTED SUBMISSION DATE (15)					MONTH	DAY	YEAR		
YES (If yes, complete EXPECTED SUBMISSION DATE) X NO																										

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During the reactor refueling outage on May 17, 1990, at 1438 hours a Secondary Containment isolation occurred. This Engineered Safety Feature (ESF) actuation resulted in the shutdown of non-safety related HVAC equipment, the actuation of containment isolation valves, and the startup of various safety related systems such as Standby Gas Treatment. Plant maintenance workers were replacing auxiliary relays as part of the normal preventative maintenance program when they inadvertently placed two channels in the tripped condition which initiated the ESF actuation.

The root cause for this event was inadequate work control which allowed work to proceed simultaneously on two safety-related divisions when no provisions had been made for such an activity.

Immediate corrective action was taken to place the Secondary Containment systems in their normal configuration.

There is no safety significance associated with this event. ESF isolations and actuations occurred as designed for the plant configuration at the time of the event. Accordingly, this event posed no threat to the health and safety of the public or plant personnel.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7	9 0	- 0 1 0	- 0 0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Plant Conditions

Power Level - 0%
Plant Mode - 5

Event Description

During the reactor refueling outage on May 17, 1990, at 1438 hours a Secondary Containment Isolation Engineered Safety Feature (ESF) Actuation occurred. At the time of the actuation maintenance work was being performed by Plant Maintenance workers on General Electric Model HFA auxiliary relays. This ESF Actuation initiated a Balance of Plant (BOP) isolation involving Group 3 (Primary and Secondary Containment Ventilation and Purge Systems) and part of Group 4 (Miscellaneous Balance of Plant Systems). These two Groups are part of the Nuclear Steam Supply Shutoff System (NSSSS) that provides overall isolation of plant systems in response to various process parameters. During refueling (Mode 5) the Primary Containment can be open to the Secondary Containment and this isolation function is limited to Secondary Containment although Primary Containment isolations will occur if components have not been deactivated. In addition to the isolations, the Secondary Containment ESF actuation causes the normal Reactor Building (Secondary Containment) heating and ventilating supply and exhaust fans to stop and Reactor Building pressure control is transferred to the safety-related Standby Gas Treatment (SGT) system which was initiated by this event.

Immediate Corrective Action

Plant operators took immediate corrective action to place the systems back in their normal configuration. The restoration of systems, including the shutdown of SGT, was completed at 1520 hours.

Further Evaluation and Corrective ActionA. Further Evaluation

1. This event is being reported per the requirements of 10CFR50.73(a)(2)(iv) as an "..... event or condition that resulted in manual or automatic actuation of an Engineered Safety Feature (ESF).....".
2. Further evaluation showed work was in progress on the Division I manual actuation relay (MS-RLY-K35A) which put the "A" channel in the tripped condition. When work started on the "B" channel relay (MS-RLY-81B) this caused a full trip on the outboard relay cabinet (RC-1) which resulted in the Secondary Containment Isolation.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7	9 0	- 0 1 0	- 0 0	0 3	OF 0 3	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

3. The root cause was inadequate work control which allowed work to proceed simultaneously on two safety related divisions when no provisions had been made for such an activity.
4. There were no structures, components or systems that were inoperable prior to the start of this event which contributed to the event.

B. Further Corrective Action

1. Work control procedures will be reviewed to determine if additional steps need to be added to control Division related work.
2. The current work control administrative process will be reviewed with Plant Maintenance Department Supervisor and Engineering personnel.

Safety Significance

There is no safety significance associated with this event. ESF isolations and actuations occurred as designed for the plant configuration at the time of the event. Accordingly, this event posed no threat to the health and safety of the public or plant personnel.

Similar Events

None

EIIS InformationText ReferenceEIIS Reference

	<u>System</u>	<u>Component</u>
Secondary Containment	C	--
Nuclear Steam Supply Shutoff System	--	--
Primary Containment	C	--
Standby Gas Treatment	BH	--
Main Steam Relay K35A (MS-RLY-K35A)	SB	RLY
Main Steam Relay K81B (MS-RLY-K81B)	SB	RLY

