

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9110280241 DOC.DATE: 91/10/16 NOTARIZED: NO DOCKET #
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH.NAME AUTHOR AFFILIATION
 ARBUCKLE,J.D. Washington Public Power Supply System
 BAKER,J.W. Washington Public Power Supply System
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 91-026-00:on 910918,main control room received alarms,
 indicating RWCU HX room high temp & RWCU outboard isolation
 valve automatically closed.Caused by failed electric
 component.Circuit input card replaced.W/911016 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 5
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1		PD5 PD	1 1
	ENG,P.L.	1 1			
INTERNAL:	ACNW	2 2		ACRS	2 2
	AEOD/DOA	1 1		AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2		NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB 7E	1 1		NRR/DLPQ/LHFB10	1 1
	NRR/DLPQ/LPEB10	1 1		NRR/DOEA/OEAB	1 1
	NRR/DREP/PRPB11	2 2		NRR/DST/SELB 8D	1 1
	NRR/DST/SICB8H3	1 1		NRR/DST/SPLB8D1	1 1
	NRR/DST/SRXB 8E	1 1		REG FILE 02	1 1
	RES/DSIR/EIB	1 1		RGN5 FILE 01	1 1
EXTERNAL:	EG&G BRYCE,J.H	3 3		L ST LOBBY WARD	1 1
	NRC PDR	1 1		NSIC MURPHY,G.A	1 1
	NSIC POORE,W.	1 1		NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 33 ENCL 33

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

Docket No. 50-397

October 16, 1991

G02-91-189

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2
LICENSEE EVENT REPORT NO. 91-026

Dear Sir:

Transmitted herewith is Licensee Event Report No. 91-026 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Very truly yours,



J. W. Baker
WNP-2 Plant Manager

Enclosure:
Licensee Event Report No. 91-026

cc: Mr. John B. Martin, NRC - Region V
Mr. C. Sorensen, NRC Resident Inspector (M/D 901A)
INPO Records Center - Atlanta, GA
Ms. Dottie Sherman, ANI
Mr. D. L. Williams, BPA (M/D 399)
NRC Resident Inspector - walk over copy

9110280241 911016
PDR ADOCK 05000397
S PDR

Cent No
P085602791
IF22
11

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-630), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Washington Nuclear Plant - Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 3 9 7										PAGE (3) 1 OF 0 4	
TITLE (4) Reactor Water Cleanup System Isolation Due To Failed Component In The Leak Detection System																					
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)									
0	9	18	91	026	00	1	0	16				0 5 0 0 0									
OPERATING MODE (9) 4			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																		
POWER LEVEL (10) 0 0 0			20.402(b)			20.405(c)			X 50.73(a)(2)(iv)			73.71(b)									
			20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)									
			20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vii)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
			20.405(a)(1)(iii)			50.73(a)(2)(i)			50.73(a)(2)(viii)(A)												
			20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)												
			20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(ix)												
LICENSEE CONTACT FOR THIS LER (12)																					
NAME J. D. Arbuckle, Compliance Engineer										TELEPHONE NUMBER 5 0 9 3 7 7 - 4 1 4 5											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC											
X	I, J	M, O, N	G, O, 8, 0	Y																	
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)									
YES (If yes, complete EXPECTED SUBMISSION DATE)												X NO									

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On September 18, 1991 at 2351 hours, with the Plant shutdown for an outage, the Main Control Room received alarms indicating Reactor Water Cleanup (RWC) System heat exchanger room high temperature, Leak Detection (LD) System high differential flow rate and LD System Division I trouble. At the same time, RWC Outboard Isolation Valve RWC-V-4 automatically closed, an Engineered Safety Feature (ESF) actuation, and pump RWC-P-1B tripped. The reason for RWC-V-4 closure was due to a failed electronic component in a Leak Detection (LD) System monitor, which provides input into the RWC isolation logic.

Following the RWC System isolation, Plant personnel performed a system walkdown and an investigation. After verifying that no actual leakage existed, Plant Control Room Operators bypassed the high temperature trip for RWC-V-4 and restored the RWC System to service.

Further corrective actions consisted of replacing a printed circuit input card in Leak Detection Monitor LD-MON-1A and sending the defective input card to the manufacturer (General Electric) for further analysis.

This event posed no threat to the health and safety of either the public or Plant personnel.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7 9 1	1	0 2 6	0 0 0	2	OF 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Plant Conditions

Power Level - 0%

Plant Mode - 4 (Cold Shutdown).

Event Description

On September 18, 1991 at 2351 hours, with the Plant shut down for an outage, alarms were received in the Main Control Room indicating Reactor Water Cleanup (RWCU) System heat exchanger room high temperature, Leak Detection (LD) System high differential flow rate and LD System Division I trouble. The room high temperature and system high flow alarms cleared after annunciation, and the LD trouble alarm remained sealed-in. Immediately following the alarms, RWCU Outboard Isolation Valve RWCU-V-4 automatically closed and pump RWCU-P-1B tripped. The closure of RWCU-V-4 is an Engineered Safety Feature (ESF) actuation.

Following the isolation, a walkdown and investigation were performed to verify system integrity. No leakage was observed during the system walkdown. However, upon further investigation, Plant Instrument and Control (I&C) Technicians discovered that Leak Detection Temperature Element LD-TE-3E display was reading upscale. Temperature Element LD-TE-3E is the RWCU Heat Exchanger Room sensor and that is designed to isolate RWCU-V-4 on a room high ambient temperature signal. During troubleshooting efforts, Plant I&C Technicians determined that the reason for the upscale reading of LD-TE-3E was due to a failed thermocouple input module (one of six identical printed circuit cards) in Leak Detection Monitor LD-MON-1A. The failure of the card caused LD-MON-1A to incorrectly detect a high temperature condition in the RWCU Heat Exchanger Room and, by design, RWCU-V-4 automatically closed.

Following the system walkdown and subsequent investigation, Plant Control Room Operators bypassed the high temperature trip for RWCU-V-4, issued a Maintenance Work Request (MWR) to repair LD-MON-1A, and returned the RWCU System to service.

Immediate Corrective Action

After a thorough investigation, Plant Control Room Operators restored the RWCU System to service at 0105 hours on September 19, 1991.

Further Evaluation and Corrective Action

A. Further Evaluation

1. This event is reportable under 10CFR50.73(a)(2)(iv) as an event that resulted in the automatic actuation of an Engineered Safety Feature.
2. There were no structures, systems or components that were inoperable prior to the event that contributed to the event.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7 9 1	—	0 2 6	— 0 0	0 3	OF 0 4

TEXT (If more space is required, use additional NRC Form 368A's) (17)

3. The cause of this event is equipment failure pertaining to thermocouple input module "A3" in LD-MON-1A. The function of this module (a printed circuit card) is to receive signals from thermocouple output, and provide input to the alarm and isolation logic within the monitor panel. There are six identical thermocouple input modules within LD-MON-1A ("A1" through "A6"). The manufacturer of LD-MON-1A (Model No. 304A3714) is General Electric. The purchase part drawing for the input card is GE 213A9364G001. Due to a previous event, it is suspected that the input module failure is due to the failure of an electronic component (isolation amplifier) on the printed circuit board. However, the specific cause of the failure is unknown at this time and the failed input module has been sent to General Electric for further analysis.

This is the second failure of this nature at WNP-2. Licensee Event Report 91-001 described an event where Reactor Core Isolation Cooling Valve RCIC-V-8 isolated due to a failed electronic component on thermocouple input card "A1" in LD-MON-1A. As a further corrective action for that LER, the failed card was sent to General Electric for further analysis. The General Electric failure report noted that the reason for the isolation was a failure of an electronic component (isolation amplifier "AR-3") on the input card. However, the reason for the specific failure mode of the isolation amplifier (e.g., defective chip, high temperature, etc.) was indeterminate.

4. Both this event and the situation described in LER 91-001 were reviewed against the requirements of 10CFR, Part 21, and were determined to be not reportable under that regulation because neither event represented a substantial safety hazard. In both cases, the failure of the input cards resulted in the actuation of Engineered Safety Features, which conservatively isolated the components/systems involved. In addition, the actuations were in accordance with Plant design.

B. Further Corrective Action

1. On September 19, 1991 Plant I&C Technicians replaced the defective input card in LD-MON-1A.
2. As with LER 91-001, discussions with General Electric are ongoing and the vendor's analysis of this new failure will be evaluated for any necessary additional actions. If any significant changes to the root cause are made, or additional corrective actions are warranted, a supplemental LER will be submitted.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7	9 1	0 2 6	0 0	0 4	0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Safety Significance

There is no safety significance with this event in that there was no actual RWCU System leak and the event was limited to the failure of a temperature monitoring component within the Leak Detection System. Furthermore, the RWCU System isolated as designed on the instrument-sensed high ambient temperature in the heat exchanger room area. Accordingly, this event posed no threat to the health and safety of either the Public or Plant personnel.

Similar Events

LER 91-001, "RCIC-V-8 Automatic Closure ESF Actuation Due To Failed Electronic Component In Leak Detection System."

EIIS InformationText ReferenceEIIS Reference
System Component

Reactor Water Cleanup (RWCU) System	CE	---
Leak Detection (LD) System	IJ	---
RWCU-V-4	CE	ISV
RWCU-P-1B	CE	P
LD-TE-3E	IJ	TE
LD-MON-1A	IJ	MON
RCIC-V-8	BN	ISV