

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9112300329 DOC.DATE: 91/12/18 NOTARIZED: NO DOCKET #
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
 AUTH.NAME AUTHOR AFFILIATION
 ARBUCKLE,J.D. Washington Public Power Supply System
 BAKER,J.W. Washington Public Power Supply System
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 91-034-00:on 911123,residual heat removal sys
 differential pressure indicating switch found isolated.Cause
 indeterminate.Surveillance completed.RHR-DPIS-12B restored
 to svc.W/911218 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 5
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

| | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL | RECIPIENT ID CODE/NAME | COPIES LTTR ENCL |
|-----------|---------------------------|---------------------|---------------------------|---------------------|
| | PD5 LA | 1 1 | PD5 PD | 1 1 |
| | ENG,P.L. | 1 1 | | |
| INTERNAL: | ACNW | 2 2 | ACRS | 2 2 |
| | AEOD/DOA | 1 1 | AEOD/DSP/TPAB | 1 1 |
| | AEOD/ROAB/DSP | 2 2 | NRR/DET/ECMB 9H | 1 1 |
| | NRR/DET/EMEB 7E | 1 1 | NRR/DLPQ/LHFB10 | 1 1 |
| | NRR/DLPQ/LPEB10 | 1 1 | NRR/DOEA/OEAB | 1 1 |
| | NRR/DREP/PRPB11 | 2 2 | NRR/DST/SELB 8D | 1 1 |
| | NRR/DST/SICB8H3 | 1 1 | NRR/DST/SPLB8D1 | 1 1 |
| | NRR/DST/SRXB 8E | 1 1 | REG-FILE 02 | 1 1 |
| | RES/DSIR/EIB | 1 1 | RGN5 FILE 01 | 1 1 |
| EXTERNAL: | EG&G BRYCE,J.H | 3 3 | L ST LOBBY WARD | 1 1 |
| | NRC PDR | 1 1 | NSIC MURPHY,G.A | 1 1 |
| | NSIC POORE,W. | 1 1 | NUDOCS FULL TXT | 1 1 |

Cont No
 P4147368:77

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 33 ENCL 33

Ro
 gch



1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

December 18, 1991
G02-91-230

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2
LICENSEE EVENT REPORT NO. 91-034

Dear Sir:

Transmitted herewith is Licensee Event Report No. 91-034 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Very truly yours,



J. H. Baker
WNP-2 Plant Manager

JNB:ac

Enclosure:
Licensee Event Report No. 91-034

cc: Mr. John B. Martin, NRC - Region V
Mr. C. Sorensen, NRC Resident Inspector (M/D 901A)
INPO Records Center - Atlanta, GA
Ms. Dottie Sherman, ANI
Mr. D. L. Williams, BPA (M/D 399)
NRC Resident Inspector - walk over copy

Cent No
P 414 736877
IF22
11

273373
9112300329 971018
ADF ADOCK 05000397
FDR



1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

29

30

31

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| FACILITY NAME (1) | DOCKET NUMBER (2) | LER NUMBER (6) | | | PAGE (3) | | |
|-----------------------------------|-------------------|----------------|-------------------|-----------------|----------|---|-------|
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |
| Washington Nuclear Plant - Unit 2 | 0500039791 | — | 034 | —00 | 0 | 2 | OF 05 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Plant Conditions

- a) Power Level - 65%
- b) Plant Mode - 1 (Power Operation)

Event Description

On November 26, 1991 it was determined (during a reportability review) that a problem discovered on November 23, 1991 was reportable in accordance with the requirements of 10CFR50.73 as a condition prohibited by the Technical Specifications. On November 23, 1991 at 1858 hours, Residual Heat Removal (RHR) System Differential Pressure Indicating Switch RHR-DPIS-12B was found to be isolated. This condition was discovered by Plant Instrument and Control (I&C) Technicians during the performance of Plant Procedure (PPM) 7.4.3.2.1.63, "Residual Heat Removal System Shutdown Cooling Mode High Flow Isolation - CFT/CC." The function of RHR-DPIS-12B is to provide an auto-close signal to RHR-V-9, the RHR System shutdown cooling inboard isolation valve, upon receipt of a high flow (high differential pressure) indication in the shutdown cooling line.

During the performance of the procedure, the I&C Technicians discovered the high pressure valve, the low pressure valve and the equalizing valve to be in the closed position. This configuration rendered RHR-DPIS-12B inoperable and, therefore, incapable of providing an RHR inboard isolation signal on shutdown cooling line excess flow.

Following discovery of the isolated pressure switch, Plant I&C Technicians completed the surveillance procedure and returned RHR-DPIS-12B to service at 1924 hours.

Immediate Corrective Action

There was no additional immediate corrective action other than the Plant I&C Technicians successfully completing the RHR Shutdown Cooling Mode High Flow Isolation CFT/CC and returning RHR-DPIS-12B to service.

Further Evaluation and Corrective ActionA. Further Evaluation

1. This event is reportable in accordance with the requirements of 10CFR50.73(a)(2)(i)(B), "Any operation or condition prohibited by the plant's Technical Specifications." The Technical Specifications require RHR-DPIS-12B to be operable during Operational Modes 1, 2 and 3.
2. There were no other structures, systems or components that were inoperable prior to the start of the event that contributed to the event.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| FACILITY NAME (1) | DOCKET NUMBER (2) | LER NUMBER (6) | | | PAGE (3) | |
|-----------------------------------|-------------------|----------------|-------------------|-----------------|----------|--------|
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | |
| Washington Nuclear Plant - Unit 2 | 0 5 0 0 0 3 9 7 | 9 1 | 0 3 4 | 0 0 | 0 3 | OF 0 5 |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

3. Two redundant differential pressure switches (RHR-DPIS-12A and RHR-DPIS-12B), one for each trip logic, monitor the RHR shutdown cooling suction line. Circuit logic operation is such that the output trip signal of each sensor initiates a logic trip and closure of either the inboard or outboard isolation valve in the event of an excess flow condition in the RHR suction line. Pressure switch RHR-DPIS-12A controls the outboard valve (RHR-V-8) and RHR-DPIS-12B controls the inboard valve (RHR-V-9).
4. The cause of this event is indeterminate. A comprehensive review of previous surveillances and work history associated with the instrument, and interviews of Plant personnel, did not reveal a reason for RHR-DPIS-12B to be isolated.

The calibration surveillance procedure (PPM 7.4.3.2.1.63) was last performed on October 22, 1991 and no discrepancies were identified. The procedure is clear and specific as to the steps for returning the instrument to service, and requires that a second person independently verify proper alignment. The procedure also requires a sign-off of these steps by the I&C Technicians who perform the surveillance test. In this particular case, the procedure was appropriately signed and the I&C Technicians who performed the surveillance recalled restoring the instrument to service as required.

Furthermore, during the time period of October 22 to November 23, 1991, no maintenance or operational activities were identified as having been performed that would have required RHR-DPIS-12B to be valved out of service. This determination was made following 1) a comprehensive review of Maintenance Work Requests, Clearance Orders, Radiation Work Permits and Control Room Logs, and 2) discussions with Plant personnel.

5. There has been one other similar event (LER 89-037) in which RHR-DPIS-12B was found to be isolated. The LER is discussed in further detail in the "Similar Events" section of this LER. A review of that event was performed in an attempt to determine if there was a common link between the cases where the pressure switch was found to be inoperable. In both instances, the events either occurred or were discovered following Plant startup from an outage. Accordingly, startup procedures were reviewed for activities that may have required RHR-DPIS-12B to be valved out of service.

One procedure that is referenced in the startup Procedures is PPM 2.4.2, "Residual Heat Removal System."

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| | | | | | | | |
|--|---|----------------|-------------------|-----------------|----------|--|--|
| FACILITY NAME (1) Washington Nuclear Plant - Unit 2 | DOCKET NUMBER (2) 0 5 0 0 0 3 9 7 9 1 — 0 3 4 — 0 0 0 4 OF 0 5 | LER NUMBER (6) | | | PAGE (3) | | |
| | | YEAR | SEQUENTIAL NUMBER | REVISION NUMBER | | | |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The purpose of PPM 2.4.2 is to provide instructions for operation of the RHR System during various Plant configurations. One of the actions in this procedure is to have I&C Department personnel vent instrumentation when required by Operations. However, this procedure does not require signatures for either valve positioning or completion of the procedural steps. As a result, it was not possible to verify if RHR-DPIS-12B had been manipulated during the performance of this procedure. However, it should also be noted that instrument valve manipulations are considered to be within the "skill of the craft" for Plant I&C Technicians. Therefore, in those situations where they are requested by Operations to perform evolutions such as venting, procedural signoffs for valve manipulations have not been required.

B. Further Corrective Action

1. Plant Procedure (PPM) 1.3.1, "Conduct of Operations," will be revised to expand the use of a Component Status Change Order to include evolutions such as instrument valve manipulations for venting and line flushes when a procedure is not utilized. The Component Status Change Order is a form that is currently used to provide instructions for aligning more than two valves or circuit breakers during those situations where a procedure or checklist is not used.
2. The use of the Component Status Change Order will be 1) included in the I&C Department Work Practices Guide, and 2) discussed during I&C Department shop meetings.
3. A letter describing this event and the other similar event will be issued to Operations, Maintenance and Plant Technical personnel. The intent of this letter will be to provide an increased awareness of the situations where RHR-DPIS-12B was found to be isolated and to solicit additional suggestions on potential causes and methods to prevent recurrence.

Safety Significance

There are no unacceptable consequences associated with this event. Valve RHR-V-9 was already in the closed position at the time of the event as required when the Plant is in Operational Mode 1. Had the Plant been required to enter Cold Shutdown during the time the pressure switch was out of service, Differential Pressure Indicating Switch RHR-DPIS-12A was available to provide an auto-close signal to RHR Shutdown Cooling Outboard Isolation Valve RHR-V-8 in the event that a high flow condition had occurred in the shutdown cooling line. Furthermore, the Reactor Pressure Vessel Low Level (Level 3) isolation signal was operable and serves as a backup to the high flow (RHR-DPIS-12A/RHR-DPIS-12B) isolation signal. In addition, an RHR System isolation would also occur from a Leak Detection System-initiated RHR Area High Temperature signal.

Accordingly, this event posed no threat to the health and safety of either the public or Plant personnel.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

| | | | | | | |
|--|--|----------------|-------------------------------|-----------------------------|----------|--|
| FACILITY NAME (1) Washington Nuclear Plant - Unit 2 | DOCKET NUMBER (2) 0 5 0 0 0 3 9 7 | LER NUMBER (6) | | | PAGE (3) | |
| | | YEAR 9 1 | SEQUENTIAL NUMBER 0 3 4 | REVISION NUMBER 0 0 0 | 5 OF 5 | |

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Similar Events

LER 89-037, "Residual Heat Removal System Differential Pressure Indicating Switch (RHR-DPIS-12B) Discovered to be Isolated and Equalized - Cause Unknown." This LER described an identical event where, during the performance of the RHR Shutdown Cooling Mode High Flow Isolation CFT/CC, Plant I&C Technicians found RHR-DPIS-12B to be isolated and equalized (both high and low pressure isolation valves were closed and the equalizing valve was open). The root cause for this event was indeterminate. A review of previous surveillances and work history associated with the instrument also did not reveal a reason for RHR-DPIS-12B to be isolated. Corrective actions consisted of 1) developing an I&C Work Practices Manual which specifically described the independent verification process, and 2) providing training on the independent verification process to Plant I&C Technicians.

EIIS InformationText ReferenceEIIS Reference

| | System | Component |
|------------------------------------|--------|-----------|
| Residual Heat Removal (RHR) System | BO | --- |
| RHR-DPIS-12B | BO | PDIS |
| RHR-V-9 | BO | ISV |
| RHR-V-8 | BO | ISV |
| RHR-DPIS-12A | BO | PDIS |
| Reactor Pressure Vessel | NH | RPV |
| Leak Detection System | IJ | --- |

