

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9110160168 DOC.DATE: 91/10/07 NOTARIZED: NO DOCKET #  
 FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397  
 AUTH.NAME AUTHOR AFFILIATION  
 ARBUCKLE,J.D. Washington Public Power Supply System  
 BAKER,J.W. Washington Public Power Supply System  
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 91-022-00:on 910905,inboard RHR sys shutdown cooling  
 supply valve automatically isolated on high suction line  
 flow signal.Caused by instrumentation drift.Sys realigned &  
 loop B placed back in svc.W/911007 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 6  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD5 LA	1 1	PD5 PD	1 1
ENG,P.L.	1 1		
INTERNAL: ACNW	2 2	ACRS	2 2
AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
AEOD/ROAB/DSP	2 2	NRR/DET/ECMB 9H	1 1
NRR/DET/EMEB 7E	1 1	NRR/DLPQ/LHFB10	1 1
NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB	1 1
NRR/DREP/PRPB11	2 2	NRR/DST/SELB 8D	1 1
NRR/DST/SICB8H3	1 1	NRR/DST/SPLB8D1	1 1
NRR/DST/SRXB 8E	1 1	REG FILE 02	1 1
RES/DSIR/EIB	1 1	RGN5 FILE 01	1 1
EXTERNAL: EG&G BRYCE,J.H	3 3	L ST LOBBY WARD	1 1
NRC PDR	1 1	NSIC MURPHY,G.A	1 1
NSIC POORE,W.	1 1	NUDOCS FULL TXT	1 1

Cont no p085602801

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 33 ENCL 33

AD  
 [Signature]

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • 3000 George Washington Way • Richland, Washington 99352

Docket No. 50-397

October 7, 1991

Document Control Desk  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Subject: NUCLEAR PLANT NO. 2  
LICENSEE EVENT REPORT NO. 91-022

Dear Sir:

Transmitted herewith is Licensee Event Report No. 91-022 for the WNP-2 Plant. This report is submitted in response to the report requirements of 10CFR50.73 and discusses the items of reportability, corrective action taken, and action taken to preclude recurrence.

Very truly yours,



J.W. Baker  
WNP-2 Plant Manager

Enclosure:  
Licensee Event Report No. 91-022

cc: Mr. John B. Martin, NRC - Region V  
Mr. C. Sorensen, NRC Resident Inspector (M/D 901A)  
INPO Records Center - Atlanta, GA  
Ms. Dottie Sherman, ANI  
Mr. D. L. Williams, BPA (M/D 399)  
NRC Resident Inspector - walk over copy

*Cert No 1085602501*  
*IF22*  
*11*

9110160168 911007  
PDR ADCK 05000397  
S PDR

## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) Washington Nuclear Plant - Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 3 9 7				PAGE (3) 1 OF 0 5								
TITLE (4) Residual Heat Removal (RHR) System Shutdown Cooling Isolation On High Suction Line Flow Due To Differential Pressure Instrumentation Drift																						
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)												
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)									
0	9	0	5	9	1	9	1	0	2	2	0	0	1	0	0	7	9	1	0 5 0 0 0			
OPERATING MODE (9)		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																				
4		20.402(b)				20.405(c)				<input checked="" type="checkbox"/> 50.73(a)(2)(iv)				73.71(b)								
POWER LEVEL (10)		0 0 0				20.405(a)(1)(i)				50.73(a)(2)(v)				73.71(c)								
		20.405(a)(1)(ii)				50.38(c)(1)				50.73(a)(2)(vii)				OTHER (Specify in Abstract below and in Text, NRC Form 366A)								
		20.405(a)(1)(iii)				50.38(c)(2)				50.73(a)(2)(viii)(A)												
		20.405(a)(1)(iv)				50.73(a)(2)(i)				50.73(a)(2)(viii)(B)												
		20.405(a)(1)(v)				50.73(a)(2)(ii)				50.73(a)(2)(ix)												
LICENSEE CONTACT FOR THIS LER (12)																						
NAME J. D. Arbuckle, Compliance Engineer										TELEPHONE NUMBER												
										AREA CODE		5 0 9 3 7 7 - 4 1 4 5										
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																						
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS												
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR						
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)												<input checked="" type="checkbox"/> NO										

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

Abstract

On September 5, 1991 at 1122 hours while the Plant was shut down for an outage, the inboard Residual Heat Removal (RHR) System Shutdown Cooling Supply Valve (RHR-V-9) automatically isolated on a high suction line flow signal while Plant Operators were realigning RHR System shutdown cooling from Loop B to Loop A. Closure of RHR-V-9, a Nuclear Steam Supply Shutoff System (NSSSS) containment isolation valve, isolated and tripped RHR Shutdown Cooling Loops A and B which were in service at the time.

The cause of this event was instrumentation drift pertaining to Differential Pressure Indicating Switch RHR-DPIS-12B (RHR Shutdown Cooling Supply Leak Detection High Flow Indicator). As an immediate corrective action Plant Control Room Operators took appropriate steps to re-align the system and, at 1202 hours, one loop of RHR Shutdown Cooling (Loop B) was placed back into service, well within the two hours allowed for shutdown cooling to be out of service.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Washington Nuclear Plant - Unit 2	0   5   0   0   0   3   9   7	9   1   -	0   2   2	-   0   0	0   2	OF 0   5

TEXT (If more space is required, use additional NRC Form 365A's) (17)

Further corrective actions consisted of 1) recalibrating pressure switches RHR-DPIS-12A and RHR-DPIS-12B, and 2) revising the RHR-DPIS-12B calibration procedure to require that a channel functional test be performed monthly.

This event posed no threat to the health and safety of either the public or Plant personnel.

Plant Conditions

Power Level - 0%  
Plant Mode - 4 (Cold Shutdown)

Event Description

On September 5, 1991 at 1122 hours while the Plant was shut down for an outage, the inboard Residual Heat Removal (RHR) System Shutdown Cooling Supply Valve (RHR-V-9) automatically isolated on a high suction line flow signal during efforts associated with realigning the RHR System. Closure of RHR-V-9, a Nuclear Steam Supply Shutoff System (NSSSS) containment isolation valve, isolated and tripped RHR Shutdown Cooling Loops A and B which were in service at the time.

At the time of the event, Plant Operators were in the process of realigning RHR System shutdown cooling from Loop B to Loop A. At 1120 hours, with Loop B (RHR-P-2B) in service, Plant Operators started Loop A (RHR-P-2A) in preparation for changing the in-service RHR Shutdown Cooling System. However, within two minutes while Plant Operators were in the process of securing RHR-P-2B, RHR-V-9 automatically isolated with both loops of RHR shutdown cooling being in service. By design, the closure of RHR-V-9 also caused RHR-P-2A and RHR-P-2B to trip.

Plant design is such that RHR-V-9 will isolate on Reactor Pressure Vessel (RPV) low level (Level 3), Drywell pressure greater than 1.68 psig, or RHR Shutdown Cooling line excess flow. After verifying that there were no level or pressure transients during the event, Plant Operators concluded that the isolation of RHR-V-9 was most likely due to exceeding the high suction flow setpoint. The reason for the isolation was instrumentation drift pertaining to Differential Pressure Indicating Switch RHR-DPIS-12B (RHR Shutdown Cooling Supply Leak Detection High Flow Indicator).

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Washington Nuclear Plant - Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 3 9 7	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 1	0 2 2	0 1	0 0	3 OF 0 5	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Immediate Corrective Action

Plant Control Room Operators took appropriate action to re-align the system and, at 1202 hours, one loop of RHR Shutdown Cooling (Loop B) was placed back into service, well within the two hours allowed for shutdown cooling to be out of service.

Further Evaluation and Corrective Action

## A. Further Evaluation

1. This event is reportable under 10CFR50.73(a)(2)(iv) as an event or condition that resulted in manual or automatic actuation of an Engineered Safety Feature.
2. There were no structures, systems or component that were inoperable prior to the start of the event that contributed to the event.
3. Two redundant differential pressure switches (RHR-DPIS-12A and RHR-DPIS-12B), one for each trip logic, monitor the RHR shutdown cooling suction line. Circuit logic operation is such that the output trip signal of each sensor initiates a logic trip and closure of either the inboard [RHR-V-9 (RHR-DPIS-12B)] or outboard [RHR-V-8 (RHR-DPIS-12A)] isolation valve in the event of an excess flow condition in the RHR suction line.
4. The root cause of this event was instrument drift. On September 6, 1991 Plant Instrument and Control (I&C) Technicians checked the as-found trip settings of RHR- DPIS-12A and RHR-DPIS-12B and determined that the high excess flow trip setting for RHR-DPIS-12A had drifted to 147.5 inches (H2O) and the setting for RHR-DPIS-12B had drifted to 141.0 inches (H2O). The normal setpoint for these instruments is 174 inches (H2O). The inaccuracy of these mechanical instruments is 1.5 percent. As a result, with both loops of RHR in service and a combined flow of approximately 15,000 gpm, the drift value was close enough to the nominal process flow variances for RHR-DPIS-12B to sense a high flow condition in the RHR suction line and, by design, RHR-V-9 automatically isolated.

A contributing factor was that the calibration procedure for RHR-DPIS-12A and RHR-DPIS-12B is only required by the Plant Technical Specifications to be performed during Operational Modes 1, 2 and 3. Although the instrument drift (which is common to Barton mechanical instruments) has been tracked by the Plant Technical Department since 1987, the calibration surveillance

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Washington Nuclear Plant - Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 3 9 7 9 1 - 0 2 2 - 0 0 0 4 OF 0 5	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		

TEXT (If more space is required, use additional NRC Form 366A's) (17)

had not been performed since April, 1991 due to RHR system configuration during the extended outage (a prerequisite of the procedure is to ensure that the RHR system is not performing any core cooling function). However, during non-outage periods, both instruments are calibrated monthly in accordance with Technical Specification surveillance requirements.

## B. Further Corrective Action

1. On September 6, 1991 pressure switches RHR-DPIS-12A and RHR-DPIS-12B were recalibrated by Plant I&C Technicians.
2. Plant Procedure (PPM) 7.4.3.2.1.63, "RHR Shutdown Cooling Mode High Flow Isolation - CFT/CC," will be revised to require that a channel functional test be performed monthly during all Operational Modes.

Safety Significance

There is no safety significance with this event. Plant Control Room Operators took appropriate and timely action to re-align the RHR System. In addition, shutdown cooling was isolated for only 40 minutes, well within the time-frame (two hours) allowed by the Technical Specifications. Furthermore, during the event period there was no increase in reactor primary cooling loop temperature, which was 126 degrees at the start of the event. Accordingly, this event posed no threat to the health and safety of either the public or Plant personnel.

Similar Events

There have been several LERs pertaining to the loss of RHR shutdown cooling; however, none with a similar root cause.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  Washington Nuclear Plant - Unit 2	DOCKET NUMBER (2)  0 5 0 0 0 3 9 7	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 1	0 2 2	0 0	0 5	OF	0 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

EIIS InformationEIIS Reference

	<u>System</u>	<u>Component</u>
Residual Heat Removal (RHR) System	BO	---
RHR-V-9	BO	ISV
Nuclear Steam Supply Shutoff System (NSSSS)	BO	---
RHR-P-2A	BO	P
RHR-P-2B	BO	P
RHR-DPIS-12A	BO	DPIS
RHR-DPIS-12B	BO	DPIS
Reactor Pressure Vessel	NH	RPV