

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9705060047      DOC. DATE: 97/04/28      NOTARIZED: NO      DOCKET #  
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Power      05000397  
 AUTH. NAME      AUTHOR AFFILIATION  
 ARBUCKLE, J.D.      Washington Public Power Supply System  
 BEMIS, P.R.      Washington Public Power Supply System  
 RECIP. NAME      RECIPIENT AFFILIATION

SUBJECT: LER 97-004-00: on 970327, TS required manual scram of reactor due to unanticipated interaction of sys or components. Plant operators maneuvered plant to safe shutdown condition. W/ 970428 ltr.

DISTRIBUTION CODE: IE22T      COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 6  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD4-2 PD	1 1	COLBURN, T	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2
	AEOD/SPD/RRAB	1 1	<u>FILE CENTER</u>	1 1
	NRR/DE/ECGB	1 1	<del>NRR/DE/EEEB</del>	1 1
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1
	RES/DET/EIB	1 1	RGN4 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1

### NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED

TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25



WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • Richland, Washington 99352-0968

April 28, 1997  
GO2-97-081

Docket No. 50-397

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D. C. 20555


Gentlemen:

Subject: **NUCLEAR PLANT WNP-2, OPERATING LICENSE NPF-21  
LICENSEE EVENT REPORT NO. 97-004-00**

Transmitted herewith is Licensee Event Report No. 97-004-00 for WNP-2. This report is submitted pursuant to 10 CFR 50.73 and discusses the items of reportability, corrective action taken, and action to preclude recurrence.

Should you have any questions or desire additional information regarding this matter, please call me or D.A. Swank at (509) 377-4563.

Respectfully,

  
P.R. Bemis  
Vice President, Nuclear Operations  
Mail Drop PE23

Enclosure

cc: EW Merschoff - NRC RIV  
KE Perkins, Jr. - NRC RIV, Walnut Creek Field Office  
TG Colburn - NRR  
NRC Senior Resident Inspector - 927N  
DL Williams - BPA/399  
PD Robinson - Winston & Strawn

050108

IE221

9705060047 970428  
PDR ADDCK 05000397  
S PDR



# LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET NUMBER (2)	PAGE (3)
Washington Nuclear Plant - Unit 2	0   5   0   0   0   3   9   7	1   of   5

TITLE (4) TECHNICAL SPECIFICATION REQUIRED MANUAL SCRAM DUE TO ENTRY INTO REGION A OF THE POWER-TO-FLOW MAP

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)														
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER			REVISION NUMBER			MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBER(S)								
03	27	97	97	-	0	0	4	-	0	0	04	28	97	N/A		0	5	0	0	0			
															0	5	0	0	0				

OPERATING MODE (9)		1	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR (11)											
POWER LEVEL (10)	0   9   7		20.402(b)			20.405(c)			<input checked="" type="checkbox"/> 50.73(a)(2)(iv)			73.71(b)		
			20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)		
			20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 386A)		
			20.405(a)(1)(iii)			<input checked="" type="checkbox"/> 50.73(a)(2)(i)			50.73(a)(2)(vii)A					
			20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(vii)B					
			20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(x)					

LICENSEE CONTACT FOR THIS LER (12)										TELEPHONE NUMBER			
J.D. Arbuckle, Licensing Technical Specialist										AREA CODE		377-4601	
										509			

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	

SUPPLEMENTAL REPORT EXPECTED (14)						EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
<input checked="" type="checkbox"/> YES (if yes, complete EXPECTED SUBMISSION DATE)						<input type="checkbox"/> NO		06	30	97

**ABSTRACT (16)**  
 On March 27, 1997 at 0907 hours with the plant in Mode 1, plant operators manually scrammed the reactor as required by the Technical Specifications due to entry into Region A of the power-to-flow map following the planned trip of a single main feedwater pump from approximately 97 percent power during Reactor Recirculation (RRC) and Reactor Feedwater (RFW) System testing. The post-modification testing was being performed to demonstrate that the feedwater level control system and recirculation flow runback feature would prevent a scram following the trip of a single feedwater pump during power operation.

During the test and after the planned trip of pump RFW-P-1B, an expected reactor recirculation pump speed runback to 27 Hz was observed. Following this planned runback, a second unexpected runback to 15 Hz occurred, which placed the reactor into Region A of the power-to-flow map. The second runback was caused by a reactor recirculation pump differential temperature cavitation interlock condition.

Plant operators responded immediately by manually scramming the reactor and maneuvering the plant to a safe shutdown condition in accordance with procedures.

The preliminary root cause of this event is unanticipated interaction of systems or components. A preliminary contributing cause is analysis deficiency. The differential temperature cavitation interlock was not expected. Corrective actions include the establishment of internal and external event evaluation teams to investigate the event.

This event posed no threat to the health and safety of the public or plant personnel. The plant was in the area of increased awareness for a short time. Stable, non-oscillatory core power conditions were observed at all times during the event.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)	
Washington Nuclear Plant - Unit 2	0   5   0   0   0   3   9   7	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				2	OF 5
		97	- 0   0   4	- 0   0					

TEXT (17)

## Event Description

On March 27, 1997 at 0907 hours with the plant in Mode 1, plant operators manually scrambled the reactor as required by the Technical Specifications due to entry into Region A of the power-to-flow map following the planned trip of a single main feedwater pump from approximately 97 percent power during during Reactor Recirculation (RRC) System [AD] and Reactor Feedwater (RFW) System [JB] testing.

At the time of the event, post-modification testing of the digital feedwater level control and RRC adjustable speed drive systems was being conducted to demonstrate that the level control system and recirculation flow runback feature would prevent a scram following the trip of a single feedwater pump during power operation.

During the test and after the trip of pump RFW-P-1B [P], a reactor recirculation pump speed runback to 27 Hz was observed as expected. Following this runback, a second unexpected runback to 15 Hz occurred, which placed the reactor into Region A of the power-to-flow map. The second runback to 15 Hz was caused by a reactor recirculation pump differential temperature cavitation interlock condition existing for greater than 15 seconds.

As expected in response to the manual scram, reactor vessel water level decreased to just below +13 inches. In response to the low level condition, reactor feedwater flow increased and level was recovered to above +13 inches. During this evolution and at approximately +18 inches, pump RFW-P-1A [P] speed failed to decrease in response to the increasing level control signal. As a result, reactor vessel water level reached +54 inches (Reactor Vessel Water Level - High: Level 8) and the pump tripped on high level.

Plant operators successfully returned both reactor feedwater pumps to operation and restored level to within normal limits.

## Immediate Corrective Action

Plant operators maneuvered the plant to a safe shutdown condition in accordance with procedures.

## Further Evaluation

1. Pursuant to 10 CFR 50.73(a)(2)(i)(A) this event is reportable as, "The completion of any nuclear plant shutdown required by the Technical Specifications." Technical Specification 3.4.1, "Recirculation Loops Operating," requires that the reactor mode switch be placed in the shutdown position within 15 minutes of operation in Region A of the Power-to-Flow map.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
Washington Nuclear Plant - Unit 2	0   5   0   0   0   3   9   7	YEAR	LER SEQUENTIAL NUMBER	REVISION NUMBER	3   OF   5
		97	-   0   0   4	-   0   0	

TEXT (17)

This event was originally determined to be reportable as a four-hour Reactor Protection System actuation in accordance with 10 CFR 50.72(b)(2)(ii). The initial notification to the NRC Operations Center was made on March 27, 1997 at 1013 hours (66 minutes after the event). Upon further review, it was determined that the event should have also been reported within one hour as an initiation of a plant shutdown required by the Technical Specifications in accordance with 10 CFR 50.72(b)(1)(i)(A).

On March 27, 1997 at 1308 hours, the NRC Operations Center was notified of the change in reportability criteria to reflect that the event was also reportable within one hour.

2. Plant design includes an interlock to reduce RRC pump drive flow during conditions which could cause cavitation in the RRC system. A low temperature differential between the RRC pump suction and the vessel steam dome indicates a reduction in subcooling of reactor coolant in the reactor vessel annulus region. A reduction in RRC drive flow under these conditions prevents system cavitation and avoids equipment damage from prolonged vibration.

The reduction in drive flow initiates if the differential temperature is less than or equal to 9.9 degrees Fahrenheit for more than 15 seconds. If this occurs, the control logic automatically reduces drive speed to 15 Hz, and RRC pump flow reduces to 25 percent.

3. Evaluation of plant data validated that a differential temperature condition of less than 9.9 degrees Fahrenheit was present for longer than 15 seconds, and this condition caused the RRC runback to 15 Hz as designed.
4. The digital feedwater level control and adjustable speed drive systems performed as designed to the planned trip of the reactor feedwater pump up to the point of the second runback to 15 Hz. Following the manual scram, the digital feedwater level control system did not respond as designed to control vessel level below the Reactor Vessel Water Level - High (Level 8) setpoint of +54 inches.

## Root Cause

The root cause analysis effort is still in progress. The preliminary root cause of this event is unanticipated interaction of systems or components. A preliminary contributing cause is analysis deficiency.

The differential temperature cavitation interlock was not expected. The digital feedwater level control and adjustable speed drive systems were previously modeled in the plant simulator and in simulation programs used by General Electric and the Supply System. There was no previous simulator indication that the cavitation interlock would be initiated due to a reactor feedwater pump trip from 100 percent reactor power.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
Washington Nuclear Plant - Unit 2	05000397	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	4 OF 5	
		97	-004	-00		

TEXT (17)

## Further Corrective Action

An event evaluation team, composed primarily of Supply System personnel, was established to investigate the event and present the results and conclusions to plant management. Specific areas that will be evaluated by the team include analytical results of testing performed, performance of the on-shift Operations personnel during this event, performance of the digital feedwater level control and adjustable speed drive systems, the adequacy of the test procedure as it relates to the conditions surrounding the scram, and the adequacy of the design related to the installation of the adjustable speed drive and digital feedwater level control systems.

A second independent evaluation team, made up of primarily non-Supply System personnel, will evaluate the event and perform a critical review of the investigation conducted by the Supply System event evaluation team. Specific items that will be evaluated by this team are identical to those of the other team.

At the completion of these evaluations, the results will be provided in a supplement to this report.

## Assessment of Safety Consequences

The probability of thermal-hydraulic oscillations is greatly increased if the plant is operating in Region A of the power-to-flow map.

In response to this event, plant operators performed a manual reactor scram to exit Region A well within the 15 minute time-frame required by the Technical Specifications. Subsequent operator actions were prompt and correct to maneuver the plant to a safe shutdown condition.

During the short time the plant was operating in Region A of the power-to-flow map, stable, non-oscillatory core power conditions were observed. Therefore, this event posed no threat to the health and safety of the public or plant personnel.

## Similar Events

Licensee Event Report 96-004 reported a problem involving a manual reactor scram due to a reactor water level transient during testing of the digital feedwater system. After performing a step of the test procedure which reduced reactor water level by six inches, level continued to decrease past the intended value.

The cause of this event was determined to be a manufacturer's programming error in the digital feedwater system testing software which caused mismatches to occur in the feed/steam signal, resulting in unwanted level step changes. The software was modified by the vendor to delete the possibility of unwanted step changes. The software change was verified and validated and functionally tested on the plant simulator prior to intallation in the plant.

# LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)
		YEAR		SEQUENTIAL NUMBER		REVISION NUMBER
Washington Nuclear Plant - Unit 2	0 5 0 0 0 3 9 7	97	-	0 0 4	-	0 0
						5  OF  5

TEXT (17)

Corrective action taken in response to the previous event would not have been expected to preclude this event. The action was designed to correct a specific software problem that was causing mismatches in the feed/steam signal.