

# REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8102180454 DOC. DATE: 81/02/06 NOTARIZED: NO DOCKET #  
 FACIL: 50-528 Palo Verde Nuclear Station, Unit 1, Arizona Public 05000528  
 AUTH. NAME: AUTHOR AFFILIATION  
 VAN BRUNT, E.E. Arizona Public Service Co.  
 RECIP. NAME: RECIPIENT AFFILIATION  
 SPENCER, G.S. Region 5, San Francisco, Reactor Construction & Engineer

SUBJECT: Revision 1 to final deficiency rept re mechanical interlock  
 device on 48/125 volt dc battery charger cabinet supplied by  
 Power Conservation Products, initially reported on 801023.  
 Design change packages issued to implement design fix.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR / ENCL / SIZE: 3  
 TITLE: Construction Deficiency Report (10CFR50.55E)

NOTES: Standardized Plant.

05000528

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
ACTION:	A/D LICENSNG 04	1	1	MIRAGLIA, F. 05	1	1
	LEE, J. 06	1	1	KERRIGAN, J. 07	1	1
INTERNAL:	AD/RCI/IE 17	1	1	ASLBP/J. HARD	1	1
	D/DIR HUM FAC 15	1	1	DIR, DIV OF LIC	1	1
	EDU & STAFF 19	1	1	EQUIP QUAL BR 11	1	1
	HYD/GEO BR 22	1	1	I&E 09	1	1
	LIC QUAL BR 12	1	1	MPA 20	1	1
	NRC PDR 02	1	1	OELD 21	1	1
	PROC/TST REV 13	1	1	QA BR 14	1	1
	<u>REG FILE</u> 01	1	1	RUTHERFORD, W. IE	1	1
STANDRDS DEV 21	1	1				
EXTERNAL:	ACRS 16	16	16	LPDR 03	1	1
	NSIC 08	1	1			

FEB 19 1981

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39



ARIZONA



PUBLIC SERVICE COMPANY

P. O. BOX 21666 • PHOENIX, ARIZONA 85036

February 6, 1981  
ANPP-17245-BSK/JAR

U. S. Nuclear Regulatory Commission  
Region V

Walnut Creek Plaza - Suite 202  
1990 North California Boulevard  
Walnut Creek, California 94596

Attention: Mr. G. S. Spencer, Chief  
Reactor Construction and  
Engineering Support Branch

Subject: Final Report  
A 50.55(e) Reportable Condition Relating to the Mechanical  
Interlock Device on the 48/125 Volt DC Battery Charger  
Cabinet Supplied by Power Conversation Products  
File: 81-019-026; D.4.33.2

Reference: (1) Telephone Conversation between J. Eckhardt and  
J. E. Cook on October 23, 1980 (DER 80-31)  
(2) Final Report, Letter ANPP-16692-BSK/JAR, dated  
November 5, 1980

Dear Sir:

Attached, is Revision 1 of the final written report of the reportable deficiency, under 10CFR50.55(e), referenced above. Revision 1 incorporates the second battery-charger cabinet which was inadvertently overlooked during preparation of the original final report. Therefore, Revision 1 replaces the original final report transmitted by Reference (2).

Very truly yours,

*E. E. Van Brunt/JAR*

E. E. Van Brunt, Jr.  
APS Vice President  
Nuclear Projects  
ANPP Project Director

EEVBJr/BSK;skc

Attachment

8102180454

5

Boia  
5/11





U. S. Nuclear Regulatory Commission  
Attention: Mr. G. S. Spencer, Chief  
ANPP-17245-BSK/JAR  
February 6, 1981  
Page 2

cc: Victor Stello, Jr., Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

A. C. Gehr  
Snell & Wilmer

R. L. Robb  
D. B. Fasnacht  
W. E. Ide  
A. C. Rogers  
J. M. Allen  
J. A. Brand  
W. H. Wilson  
W. G. Bingham  
W. J. Stubblefield  
R. L. Patterson  
R. W. Welcher  
D. R. Hawkinson



FINAL REPORT, REVISION 1  
REPORTABLE DEFICIENCY 50.55(e)  
ARIZONA PUBLIC SERVICE COMPANY (APS)  
PVNGS UNIT #1

I. Description of Deficiency

It is possible to inadvertently defeat the mechanical interlock device on the Battery Charger Cabinet, Tag Nos. 1-E-PKA-H15 and I-E-PKB-H15, and close both breakers at the same time. This condition is due to lack of rigidity of the interlock device. The deficiency was discovered during a routine review of jobsite conditions by Bechtel Management.

The Specification (13-EM-051) for the safety-related battery chargers requires that the output circuit breakers in the battery charger be mechanically interlocked to prevent both breakers from being closed simultaneously. The breakers shall offer the possibility to be either both open or one closed and one open at any time.

II. Analysis of Safety Implications

This condition is considered reportable based on the following considerations:

- o If both circuit breakers are closed, the system is reduced to single mode failure in violation of IEEE and licensing requirements.
- o The supplier, Power Conversation Products, recognized the condition and has provided an improved design for the Units #2 and #3 battery chargers. This design increases the rigidity of the mechanical interlock device so that both breakers cannot be inadvertently closed.

III. Corrective Action

The necessary action to implement the supplier provided design fix will be incorporated in Unit #1 following established field change procedures prior to system start-up. Design Change Packages (DCP's) ICE-PK-012 and ICE-PK-013, has been issued for this purpose.

The Power Conversation Products representative has indicated that this condition is isolated to the above identified battery chargers.

