

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8808110309 DOC.DATE: 88/08/04 NOTARIZED: NO DOCKET #
 FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528
 AUTH.NAME AUTHOR AFFILIATION
 SHRIVER,T.D. Arizona Nuclear Power Project (formerly Arizona Public Serv
 HAYNES,J.G. Arizona Nuclear Power Project (formerly Arizona Public Serv
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 88-010-00:on 880706,ground fault in 13.8 kV bus causes
 fire in unit auxiliary transformer & reactor trip.
 W/8 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 16
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:Standardized plant.


05000528 S

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD5 LA	1 1	PD5 PD	1 1
LICITRA,E	1 1	DAVIS,M	1 1
INTERNAL: ACRS MICHELSON	1 1	ACRS MOELLER	2 2
AEOD/DOA	1 1	AEOD/DSP/NAS	1 1
AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1
ARM/DCTS/DAB	1 1	DEDRO	1 1
NRR/DEST/ADS 7E	1 0	NRR/DEST/CEB 8H	1 1
NRR/DEST/ESB 8D	1 1	NRR/DEST/ICSB 7	1 1
NRR/DEST/MEB 9H	1 1	NRR/DEST/MTB 9H	1 1
NRR/DEST/PSB 8D	1 1	NRR/DEST/RSB 8E	1 1
NRR/DEST/SGB 8D	1 1	NRR/DLPQ/HFB 10	1 1
NRR/DLPQ/QAB 10	1 1	NRR/DOEA/EAB 11	1 1
NRR/DREP/RAB 10	1 1	NRR/DREP/RPB 10	2 2
NRR/DRIS/SIB 9A	1 1	NUDOCS-ABSTRACT	1 1
REG FILE 02	1 1	RES TELFORD,J	1 1
RES/DSTR DEPY	1 1	RES/DSIR/EIB	1 1
RES/DSR DEPY	1 1	RGN5 FILE 01	1 1
EXTERNAL: EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
H ST LOBBY WARD	1 1	LPDR	1 1
NRC PDR	1 1	NSIC HARRIS,J	1 1
NSIC MAYS,G	1 1		

NOTES: 1 1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 48 ENCL 47

R
I
D
S
/
A
D
D
S



LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Palo Verde Unit 1										DOCKET NUMBER (2) 0 5 0 0 0 5 2 8										PAGE (3) 1 OF 1	
TITLE (4) Ground Fault In 13.8 kV Bus Causes Fire in Unit Auxiliary Transformer And Reactor Trip																					
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)											
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES			DOCKET NUMBER(S)									
07	06	88	88	01	0	08	04	88	N/A			0 5 0 0 0									
OPERATING MODE (9) 1			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									DOCKET NUMBER(S)									
POWER LEVEL (10) 1, 0, 0			20.402(b)			20.405(e)			X 50.73(a)(2)(iv)			73.71(b)									
			20.405(a)(1)(i)			50.38(c)(1)			50.73(a)(2)(v)			73.71(c)									
			20.405(a)(1)(ii)			50.38(c)(2)			50.73(a)(2)(vii)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)									
			20.405(a)(1)(iii)			X 50.73(a)(2)(i)			50.73(a)(2)(viii)(A)												
			20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(viii)(B)												
			20.405(a)(1)(v)			50.73(a)(2)(iii)			X 50.73(a)(2)(x)												
LICENSEE CONTACT FOR THIS LER (12)																					
NAME Timothy D. Shriver, Compliance Manager										TELEPHONE NUMBER AREA CODE 602 393-2521											
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																					
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC											
X	EIA	NSBU	G080	N		X	BI	HCV	L200	Y											
X	EIA	XFMR	W005	Y		X	SB	HCV	D263	Y											
SUPPLEMENTAL REPORT EXPECTED (14)																					
X YES (If yes, complete EXPECTED SUBMISSION DATE)										NO		EXPECTED SUBMISSION DATE (15)			MONTH	DAY	YEAR				
															10	31	88				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

On July 6, 1988, Palo Verde Unit 1 was in Mode 1 (POWER OPERATION) at approximately 100 percent power when the reactor tripped on a Low Departure from Nucleate Boiling Ratio (DNBR).

The non-class 1E 13.8 kV bus 1E-NAN-S02 faulted to ground exacerbating an existing fault in the Unit Auxiliary Transformer causing the Unit Auxiliary Transformer to rupture and catch fire. This caused a loss of electrical power to the Reactor Coolant Pumps initiating the low DNBR trip. The reactor was stabilized in Mode 3 (HOT STANDBY) on Natural Circulation. A Notification of Unusual Event (NUE) was declared at 1215 MST due to the fire. The fire was extinguished and the NUE terminated at 1221 MST.

At 1303 MST an attempt was made to reenergize the faulted bus 1E-NAN-S02 and a fire started in the switchgear. An NUE was declared due to the fire and loss of non-class 13.8 kV electrical power. This fire was extinguished at 1322 MST.

Following visual inspections, cleaning, and meggering, 1E-NAN-S01 was reenergized at 1749 MST. Reactor Coolant Pump 1A was started at 0033 MST on July 7, 1988, and forced circulation was reestablished. The NUE was terminated at 0102 MST on July 7, 1988 and a cooldown was commenced.

Corrective actions taken to prevent recurrence include the rework of bus 1E-NAN-S02 and the replacement of the Unit Auxiliary Transformer.

IE22
1/1

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)		
		YEAR		SEQUENTIAL NUMBER		DIVISION NUMBER			OF	
Palo Verde Unit 1	0 5 0 0 0 5 2 8	8 8	—	0 1 0	—	0 0	0 2	OF	1 5	

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

[illegible]

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1) Palo Verde Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 5 2 8 8 8 — 0 1 0 — 0 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
					0 3	OF	1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

I. DESCRIPTION OF WHAT OCCURRED:

A. Initial Conditions:

On July 6, 1988, Palo Verde Unit 1 was in Mode 1 (POWER OPERATION) at approximately 100 percent power.

B. Reportable Event Description (Including Dates and Approximate Times of Major Occurrences):

Event Classification:

Event or condition that resulted in manual or automatic actuation of any Engineered Safety Feature (ESF)(JE) including the Reactor Protection System (RPS)(JC). Event that posed an actual threat to the safety of the nuclear power plant or significantly hampered site personnel in the performance of duties necessary for the safe operation of the nuclear power plant including fires, toxic gas releases, or radioactive releases. Operation or condition prohibited by the plant's Technical Specifications.

At approximately 1208 MST on July 6, 1988, a phase B to ground fault occurred on non-class 1E 13.8 kV bus (BU)(EA) 1E-NAN-S02. This fault ionized the air in the immediate vicinity causing all three phases to short to ground. The feeder breakers (BKR)(EA) to non-class 1E buses 1E-NAN-S01 and 1E-NAN-S02 did not trip immediately because they trip on a time overcurrent protection scheme. The overcurrent protection on these breakers is set to trip in .7 second (42 cycles) on a three phase bus fault, corresponding to a 24000 Ampere fault. The Unit Auxiliary Transformer (UAT)(XFMR)(EA) started to fail at 12 cycles and ruptured, ignited, somewhere between 17.5 and 20.5 cycles which caused the 1E-NAN-S01 and 1E-NAN-S02 supply breakers, as well as the generator (GEN)(TB) output breakers, to open due to the transformer "sudden overpressure". Due to the loss of the transformer, electrical power was lost to the Reactor Coolant Pumps (RCP)(AB) which caused a reactor trip on Low Departure from Nucleate Boiling Ratio (DNBR). The low DNBR trip was due to the RCP's speed decreasing below their setpoint. The Fast Bus Transfer (FBT) did not take place during this event. The sync-check relay checks voltages on 1E-NAN-S03/S04 and on 1E-NAN-S01/S02 and completes the transfer if both buses are in sync and have the required voltages. In this event, 1E-NAN-S01 and 1E-NAN-S02 bus voltage sensed by the sync-check relay was below the minimum value. At 14.5 cycles into the event the FBT signal was initiated but was not completed because 1E-NAN-S01 bus potential was zero due to the UAT failure and 1E-NAN-S02 bus potential was zero due to the 1E-NAN-S02 bus fault.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Palo Verde Unit 1	0 5 0 0 0 5 2 8 8 8	—	0 1 0	—	0 0	0 4	OF 1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The event was diagnosed as a Loss of Forced Circulation and the Control Room staff (utility, licensed) entered the appropriate recovery procedure 41R0-1ZZ04 (Loss of Forced Circulation). The Control Room staff responded appropriately using the correct Abnormal and Recovery Operating Procedures. A Notification of Unusual Event (NUE) was declared at 1215 MST due to the fire in the UAT. The reactor (RCT)(AC) was stabilized in Mode 3 (HOT STANDBY) at approximately 1230 MST. There were no automatically initiated Engineered Safety Feature Actuation System (ESFAS)(JE) actuations, and none were required.

Secondary heat removal was maintained by Operator action utilizing Atmospheric Dump Valves (ADV)(SB). The secondary operator observed that ADV SGB-HV-179 exhibited erratic control response and did not use it after the initial attempt. The ADVs SGA-HV-178 and SGB-HV-185 were utilized to maintain an adequate secondary heat removal rate throughout the event and subsequent cooldown to Shutdown Cooling Entry. The Main Steam Isolation Valves (MSIVs) were closed after condenser vacuum was broken. The "B" train handswitch for MSIV-180 in the control room indicated dual position but was verified closed by local position indication. The "A" train handswitch for MSIV-180 in the control room indicated the valve to be closed.

The Pressurizer Level Control System (PLCS) functioned as designed. Minimum level was reached at 26% due to the Reactor Coolant System (RCS) cooldown. Primary operator action was required to stop letdown oscillations experienced due to flashing in the letdown line. This action was taken because the isolation valve (ISV), CHB-UV-523 (CB) did not close as expected on loss of Nuclear Cooling water flow to the Letdown Heat Exchanger (HX)(SB). Following closure of the letdown isolation valve, the pressurizer level started to increase due to normal charging flow which was maintained to assure adequate RCP seal closing. Subsequently, the pressurizer level exceeded LCO 3.4.3.1 requirements and, therefore, ACTION b was entered at 1315 MST and exited at 1350 MST when pressurizer level was restored to less than 56 percent.

An Engineering Evaluation Request (EER) was initiated to evaluate this condition and identified a drawing discrepancy on the electrical elementary (13-E-CHB-013). This drawing shows contact point FSL-613 open in the deenergized state which would cause CHB-UV- 523 to close on a loss of power. (FSL-613 in the low nuclear water flow interlock for CHB-UV-523 closure). The FSL-613 contact actually defaults in the closed position on a loss of power. This causes the valve to remain open on a loss of power and to close on a restoration of power. A Plant Change Request (PCR) has been initiated to correct the wiring configuration of FSL-613 to allow CHB-UV-523 to close on a loss of power.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Palo Verde Unit 1	0 5 0 0 0 5 2 8 8 8	—	0 1 0	—	0 0	0 5	OF 1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The Control Room was notified that a fire was in progress at the UAT and the Area 2 Auxiliary Operator (AO)(utility, non-licensed) proceeded to his area to check equipment and saw smoke at the southeast end of the Turbine Building. (Area 2 comprises the 100 foot and 120 foot levels of the Turbine Building.) The panel to verify deluge flow to the sprinklers (SRNK)(KP), for the transformers is located inside the wall that was damaged by the explosion making it unsafe for flow verification. Therefore, the Area 2 AO proceeded to activate the deluge valves to all transformers and quickly left the area. Flow was then verified at the sprinklers of the various transformers. The deluge system is activated by the electrical portion of the fire protection system that was lost due to the transformer failure. There is no DC backup for the fire panels in the Turbine Building as there is for the fire panels in the Auxiliary Building. Hence, when power was lost to the deluge valves, they could not be opened electrically. Therefore, the AO's action was both prudent and required.

Fire protection personnel (utility, non-licensed) responded immediately when they heard the explosion. At 1221 MST the fire was reported out and the NUE was terminated.

At 1230 MST Train "A" and "B" Control Room Essential Filtration Actuation Signals (CREFAS)(VI) were manually initiated to restore ventilation to the Control Room since normal ventilation was not available due to loss of power. Control Room personnel knew that without non-class power the normal source of Instrument Air (IA)(LD) was not available and the nitrogen system (LK) should automatically provide the backup source of air. The Area 5 AO (utility, non-licensed) was directed to verify that the nitrogen supply was in service. (Area 5 comprises all levels of the Control and Diesel Buildings and all outside areas within the protected area except areas inside the radiological control fence.) The AO reported that everything was operating as expected at the nitrogen skid. A consequence of utilizing nitrogen to supply air operated valves (V) was the potential effect on habitability of the lower levels of the Auxiliary Building. It was reported that air in the lower levels of the Auxiliary Building was stale and breathing was becoming difficult. Unit wide announcements were made by Control Room personnel announcing the use of nitrogen and its possible effects. Radiation Protection personnel were notified that individuals entering the Auxiliary Building should be provided with oxygen monitors. At 1655 MST Control Room personnel also manually initiated the Essential Fuel Building Ventilation system to the lower levels of the Auxiliary Building to increase circulation and improve habitability.

At 1250 and 1254 MST, Emergency Diesel Generators "B" and "A" respectively (DG)(EK) were manually started and placed on-line to

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104
EXPIRES: 8/31/88

FACILITY NAME (1) Palo Verde Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 5 2 8 8 8 — 0 1 0 — 0 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
					0 6	OF	1 5

TEXT (If more space is required, use additional NRC Form 368A's) (17)

supply power to the Class 1E 4.16 kV buses (EB) 1E-PBB-S04 and 1E-PBA-S03. This action was taken as a conservative measure because the Engineered Safety Features (ESF) transformers were being sprayed from the deluge system and to protect the 4.16 kV class buses from the switchyard while attempting to reenergize the 1E-NAN-S01 or 1E-NAN-S02 buses. The class 1E 4.16 kV buses power supplies are from the startup transformers (XFMR)(EA) via buses 1E-NAN-S05, 1E-NAN-S03 and 1E-NAN-S06, 1E-NAN-S04 which also supply 1E-NAN-S01 and 1E-NAN-S02 respectively. The 1E-NAN-S05A breaker, which is the supply breaker for 1E-NAN-S03, could not be opened electrically from the Control Room or locally. The breaker had to be manually opened at the switchgear. The class 1E 4.16 kV buses were supplied power from their respective diesel generators and then isolated from the electrical distribution system to ensure they remained OPERABLE during reenergization of buses 1E-NAN-S01 and 1E-NAN-S02.

Protective Relaying and Control (PR&C) personnel were requested by Operations personnel to determine if 1E-NAN-S02 could be reenergized. PR&C and Operational personnel proceeded to the Switchgear (SWGR) room. Upon arriving in the switchgear room, the lights were out and the presence of smoke was detected. At that time it was believed that the smoke was coming from the UAT since the roll-up door which is on the east wall of the switchgear room was open to the area affected by the UAT fire. The only targets noted on the 1E-NAN-S02 bus were the Undervoltage Relays (27)(EA) due to the fact that the bus was deenergized. All trip flags were recorded and reset prior to reenergization. Based on this information it was thought that the 1E-NAN-S02 bus was fully capable of being reenergized. At 1303 MST an attempt was made to reenergize the 1E-NAN-S02 bus. However, after closing the breaker to energize the bus, the breaker tripped open and it was reported that the bus was on fire. At about the same time of the fire in 1E-NAN-S02 the Emergency Coordinator (utility, licensed) realized that he had misread the requirements for an NUE concerning loss of power to class and non-class 1E electrical loads. He misread it as a loss of class 1E and non-class 1E power requiring an NUE instead of a loss of class 1E or non-class 1E power requiring an NUE. That is why the earlier NUE was terminated. At this time an NUE was declared again because of the fire and due to recognition of the fact that 13.8 kV non-class 1E electrical power was not available. The fire was extinguished at 1322 MST.

The non-class Nuclear Cooling Water (NC) system which provides coolant water to the RCP's was not available due to the loss of non-class electrical power. At 1336 MST the Essential Cooling Water (EW) system Train "A" was cross-tied to the non-class NC system train "A". Due to the EW/NC cross-tie the EW system was declared inoperable and the Technical Specification Limiting Condition for

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1) Palo Verde Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 5 2 8 8 8 — 0 1 0 — 0 0	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8	0 1 0	0 0	0 7	OF	1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Operation (LCO) 3.7.3 ACTION was entered. This was determined to render Essential Chilled Water (EC) system inoperable per Technical Specification 3.7.6. The one (1) hour conditions of LCO 3.7.6 could not be satisfied since there was no normal Heating, Ventilating, Air-Conditioning (HVAC) available to the vital power distribution room due to the loss of non-class power. Therefore, the unit was in an ACTION statement that required the unit to be in Cold Shutdown within 30 hours.

While opening EW/NC cross-tie valve EWA-UV-145, a dual indication was noticed on the valve. An AO (utility, non-licensed) was directed to open the valve. Upon reaching the valve and after manually opening the valve approximately one half of a turn he could hear the flow thru the valve indicating that it had been shut. He then fully opened the valve.

During the performance of maintaining pressurizer level control, the primary operator isolated RCP seal bleed-off flow to minimize the pressurizer level decrease. He noted that three of the four flow indicators continued to indicate flow. After notifying the CRS, he then monitored VCT level in order to ensure the continued flow indications were indeed false (VCT level would be expected to remain stable with letdown isolated, RCP seal bleed-off isolated, and charging pumps off). After monitoring the VCT, he was satisfied that the indicators were just not reaching full downscale indication and he continued to monitor safety functions.

Surveillance Requirement 4.1.2.7.a.2.a was not performed within the required time limits. This Surveillance Requirement requires that the startup channel high neutron flux alarm be demonstrated OPERABLE within 1 hour of a reactor trip. The Control Room Supervisor (CRS) (utility, licensed) stated during an interview subsequent to the event, that when he reached step 5.17 in 41RO-1ZZ04 that stated to..."Perform Appendix A and B of 41OP-1ZZ08 (T.S. 3.1.2.7)", he noted that they were steps in an Operating Procedure (OP). Therefore, he didn't place as high a priority on performing the step in the Recovery Operating Procedure (RO), as on the performance of other RO and AO procedure related tasks. At 1645 MST the surveillance test was performed and it was determined that channel "A" was inoperable and LCO 3.1.2.7 ACTION a.1 was entered.

Following visual inspections, cleaning, and meggering, 1E-NAN-S01 was reenergized at 1749 MST. Various plant equipment was energized at 1920 MST. At 1922 MST train "A" EW was isolated from train "A" NC and LCO ACTIONS 3.7.3 and 3.7.6 were exited. EW and EC were inoperable for 5 hours and 46 minutes. Diesel Generator "A" was paralleled with the normal power supply to PBA-S03 and unloaded. The diesel was shutdown at 2201 MST.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)				PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Palo Verde Unit 1	0 5 0 0 0 5 2 8 8 8	—	0 1 0	—	0 0	0 8	OF	1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

At 2310 MST, RCP 1A was restarted but tripped shortly thereafter. Operators performed a review of the cause of the trip. It was determined to be a speed sensor relay trip resulting in an 86 lockout. RCP 2A was then started, but also tripped as a result of the speed sensor relay.

Further investigation was performed by Operations personnel to determine the cause for a similar trip on separate RCPs. After reviewing the electrical prints for the RCPs it was determined that the voltage reduction on non-class 125 VDC bus (EI) 1E-NKN-M46 was enough to affect the accuracy of the Agastat relay (RLY) on the RCP that trips the pump if it is not greater than 600 rpm within 14 seconds. The Control Room staff had previously determined that the 'F' battery (BTRY)(EI) was, due to its low voltage condition, too great of a load on the battery charger (BYC)(EI) 1E-NKN-H18 and had decreased the charger voltage to stay within the charging parameters of the battery. To ensure and maintain adequate voltage on the 1E-NKN-M46 and enable an RCP start attempt, it was then decided to remove the battery from the battery charger and raise the charger voltage. When the battery was removed from 1E-NKN-M46, DC voltage was restored to normal levels and RCP 1A was successfully started. The NUE was terminated at 0102 MST on July 7, 1988 after the forced circulation was re-established. A Reactor Coolant System cooldown was commenced at 0112 MST on July 7, 1988.

Power to the RCPs was lost due to the deenergization of 1E-NAN-S01 and 1E-NAN-S02. The Control Room staff recognized the impact on the capability to maintain forced circulation. Investigation has determined the Control Room staff did not identify the need to enter the ACTION, and did not log the entrance into LCO 3.4.1.2 ACTION b for "no Reactor Coolant loop in operation...". NOTE: There is no guidance within 41RO-1ZZ04 (Loss of Forced Circulation) denoting the entrance into LCO 3.4.1.2. The Control Room staff complied with the ACTION fortuitously and immediately initiated "...corrective action to return the required Reactor Coolant loop to operation". LCO ACTION 3.4.1.2.a was entered and 3.4.1.2.b was exited when RCP 1A was restarted at 0033 MST on July 7, 1988. LCO ACTION 3.4.1.2.a was exited when the Unit entered Mode 4 at 1323 on July 7, 1988. The ACTION was complied with at all times.

Diesel Generator "B" was paralleled with the normal power supply to PBB-S04 and unloaded. The diesel was shutdown at 0225 MST on July 7, 1988.

The unit entered Mode 4 (HOT SHUTDOWN) at 1323 MST on July 7, 1988 and Mode 5 (COLD SHUTDOWN) at 0546 MST on July 12, 1988.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1) Palo Verde Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 5 2 8 8 8 —	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0 1 0 —	0 0	0 9			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The Control Room (CR) staff reacted to and mitigated the event in a professional and efficient manner. Communications within the "controls" area were clear and concise. Overall communications were hampered slightly by some interfering phone calls and unauthorized use of the radio channels. Communications between the Control Room and Field AOs included repeat backs and clarifications when appropriate.

Initial declaration of the Reactor Trip and notification of electrical distribution abnormalities were made by the Senior Reactor Operator-in Training (SRO/OJT) (utility, licensed). The event was correctly diagnosed as a Loss of Forced Circulation by the Control Room Supervisor (CRS) (utility, licensed). The appropriate procedures for event mitigation were applied. The emergency classification as a Notification of Unusual Event (NUE) was performed correctly by the Emergency Coordinator, although early termination of the NUE was made. Subsequent review of the EPIP-02 requirements for NUE Classification prompted the Emergency Coordinator to reinitiate the NUE concurrent with the 1E-NAN-S02 switchgear fire.

The Control Room operators were successful at maintaining their respective safety functions. Natural circulation was verified and maintained throughout the event. Plant stabilization, maintenance of adequate subcooled margin for greater than 12 hours, and subsequently, a slight cooldown were all achieved while on natural circulation without incident.

Technical Specification requirements were addressed as required except as noted above. When problems such as the Startup channel and the Essential Chilled Water surveillances were identified they were dealt with properly. Minor problems in board indications or equipment response were identified and addressed properly. The primary operator's response to the loss of letdown, pressurizer level control, and maintenance of RCP seals was efficient. The secondary operator's response to ADV-179 control and MSIV-180 indication abnormalities was similarly effective. The Control Room Operators also promptly addressed the failure of the RCPs to restart. After considerable investigation, an action plan addressing the degraded 125 vdc bus voltage was developed and implemented to increase the available current and voltage on 1E-NKN-M46.

Support Group performance was also professional and efficient. Problems in their respective fields of expertise were identified and addressed effectively. Initial response during the dayshift provided much needed support from the Protective Relaying and Control Group (PR&C), Engineering Evaluations Department (EED), and Fire Protection (FP). PR&C provided a review of "flags" received on the 13.8 kV switchgear and made the reenergization recommendation to Operations. In retrospect, a more in depth evaluation of 1E-NAN-S02 or the

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1) Palo Verde Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 5 2 8	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8	0 1 0	0 0	1 0	OF	1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Digital Fault Recorder (DFR) should have been performed. However, PR&C was available for consultation and support throughout the event. EED personnel, Mechanical and particularly Electrical, responded to the fire both expediently and professionally.

Excellent direction and control of the fire department's activities, as well as the number of personnel available to assist in firefighting, helped prevent a possibly much more severe event. In addition to the prudent activation of the OSC, the development of a technical liaison group by the EED Manager was beneficial in maintaining overall engineering support group perspective.

- C. Status of structures, systems, or components that were inoperable at the start of the event that contributed to the event:

No structures, systems, or components were inoperable at the start of the event that contributed to the event.

- D. Cause of each component or system failure, if known:

Investigation

An evaluation was conducted to determine the Root Cause of Failure for 1E-NAN-S02. This inspection revealed that the original fault occurred in the "B" cubicle with blast damage into the "A" and "C" cubicles. Further inspection indicated that the fault initiated in the "B" phase and propagated to the "A" and "C" phases. Closer physical inspection of the damaged bus bar revealed two "bullet hole" point faults (one per bar) in the "B" phase bus directly adjacent to the support bar. This type of point fault is common for failures at this voltage, and it is postulated that they were the point of the original failure. It was noted that the bus insulation (Noryl) was cracked and brittle in the area of the point fault. Additionally, arc tracking was noted on the support bar adjacent to the point faults. Lastly, inspection of 1E-NAN-S02 showed build-ups of dirt on the floor of the "B" cubicle (1E-NAN-S01B contains similar material).

Results

The initial fault current path was apparently from the "B" phase bus across the support bar to ground, which initiated a three-phase fault to ground. [Although this is indicated by information obtained from the Digital Fault recorder, there was too much damage from the second fault to positively identify this.] Causal factors include degraded insulation and introduction of dirt and dust into the cubicle.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Palo Verde Unit 1	0 5 0 0 0 5 2 8 8 8	—	0 1 0	—	0 0	1 1	OF 1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Final Conclusion

It has been determined that the most likely cause is a combination of:

1. Cracked and brittle Noryl insulation
2. Build up of dirt in the cubicles

Both of these conditions had to exist for this fault. These two problems allowed bus insulation breakdown and arc tracking. This eventually decreased the air gap to ground enough to cause a single phase (B phase) to ground. The resultant arcing propagated into a three phase to ground fault.

Evaluation has determined the causal factors that may have led to the failure of 1E-NAN-S02B. These factors include:

1. Possible inadequacies of the Preventive Maintenance (PM) task to identify the methods to properly clean the 13.8 kV switchgear, and
2. Operation of the 13.8 kV and 4.16 kV switchgear with less than adequate environmental or housekeeping controls.

A visual inspection of Unit 1 UAT was performed to determine the Root Cause of Failure. The preliminary inspection revealed that the failure appears to have developed in the H2Y winding, (the B phase High Voltage winding for the Y [secondary] winding) in the bottom disk (the transformer is a pancake design). This apparently propagated the fault to ground, which precipitated the rupture and resultant fire. An Engineering Evaluation Request has been initiated for the root cause determination.

The cause of failure of valve EWA-UV-145 is not known at this time. An Engineering Evaluation Request has been initiated for the root cause determination.

The cause of SGA-HV-0179 not responding to control signals is not known at this time. An Engineering Evaluation Request has been initiated for the root cause determination.

The cause of circuit breaker 1E-NAN-S05A not opening electrically is not known at this time. An Engineering Evaluation Request has been initiated for the root cause determination.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)				PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER				
Palo Verde Unit 1	0 5 0 0 0 5 2 8	8 8	—	0 1 0	—	0 0	1 2	OF 1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

E. Failure mode, mechanism, and affect of each failed component, if known:

The 1E-NAN-S02 bus shorted to ground and created currents that the UAT was not able to supply. This contributed to the failure of the UAT and ensuing fire. The failure of the UAT caused a loss of non-class electrical power which supplies the Reactor Coolant Pumps initiating the low DNBR trip.

The failure of EWA-UV-145 to open increased the time it took to cross-tie the EW and NC systems. This had no affect on plant operation since the Reactor Coolant Pumps still had seal water supplied.

SGA-HV-0179 operated sluggishly when commanded to open. This had no affect on the plant since redundant ADVs were operable and were used to control the Reactor Coolant System cooldown.

Circuit breaker 1E-NAN-S05A not opening electrically delayed the isolation of bus 1E-NAN-S03 until an operator was dispatched to open the breaker locally and manually.

F. For failures of components with multiple functions, list of systems or secondary functions that were also affected:

Not applicable - the failed components do not have multiple functions.

G. For failure that rendered a train of a safety system inoperable, estimated elapsed time from the discovery of the failure until the train was returned to service:


Not applicable - no safety systems were rendered inoperable because of the component failures.

H. Method of discovery of each component or system failure or procedural error:

The UAT failure was identified by the explosion and visibility of the fire by various personnel (utility, licensed and non-licensed).

The failure of the 1E-NAN-S02 bus was identified by Control Room personnel (utility, licensed) when it tripped after the attempt to reenergize it and visually by personnel (utility, non-licensed) in the vicinity of the bus when it tripped and caught fire.

The failure of valve EWA-UV-145 was first identified by Control Room personnel (utility, licensed) when they received dual indication of valve position and then by an Auxiliary Operator (utility, non-licensed) who manually opened the valve.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Palo Verde Unit 1	0 5 0 0 0 5 2 8	8 8	— 0 1 0	— 0 0	1 3	OF	1 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

The sluggish operation of ADV SGA-HV-0179 was identified by a Control Room Operator (utility, licensed) when he attempted to open the valve and it would not respond to control signals.

The Control Room Operator (utility, licensed) identified that 1E-NAN-S05A did not open when he positioned the hand control switch to open the breaker. The operator (utility, non-licensed) sent out to locally open the breaker identified that it would not open electrically and had to be opened manually.

I. Cause of Event:

The cause of the event was a phase "B" to ground fault on the 1E-NAN-S02 bus.

The cause of the violation of Technical Specification 3.1.2.7 was cognitive personnel error by the Control Room Supervisor (CRS)(utility, licensed) in that he decided to deviate from the approved procedure. This is contrary to an approved procedure. The procedure did not have clarification as to time constraints or applicability, which may have prompted the CRS to perform the instruction. Unusual characteristics of the work location include more noise than during normal plant operations due to various alarms, more activities and procedures to perform, and loss of non-class electrical power.

J. Safety System Response:

There were no automatically initiated safety system responses and none were required. CREFAS and FBEVAS were manually initiated to provide ventilation as previously discussed.

K. Failed Component Information:

13.8 kV non-class bus 1E-NAN-S02
Metal clad switchgear type M36
Manufactured by General Electric.

Unit Auxiliary Transformer 1E-MAN-X02
Model MTZ14
Manufacturer Serial No. 77-118P17453
Manufactured by Wagner Electric

EW/NC cross-tie valve EWA-UV-145
Model SMB-000/H1BC
Manufactured by Limitorque Corp.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER						
Palo Verde Unit 1	0500052888	88	010	00				14	OF	15

TEXT (If more space is required, use additional NRC Form 366A's) (17)

ADV - SGA-HV-0179

Model 922501043

Manufacturer Serial No. 21408-1-4

Manufactured by Duff Norton

Circuit Breaker 1E-NAN-S05A

Model AM-13.8-1000-4H

Manufacturer Serial No. 269A7236-022

Manufactured by General Electric

II. ASSESSMENT OF THE SAFETY CONSEQUENCES AND IMPLICATIONS OF THIS EVENT:

As described above, the reactor tripped as designed and all safety responses necessary to place the plant in a stable condition worked properly. There were no automatic ESF actuations and none were required. Based on the above, this event had no impact on the health and safety of the public.

III. CORRECTIVE ACTIONS:


A. Immediate:

Following visual inspections, cleaning, and meggering of 1E-NAN-S01, the bus was reenergized. Bus 1E-NAN-S02 was reenergized after rework, inspections and meggering were completed satisfactorily.

B. Action to Prevent Recurrence:

The 4.16 kV and 13.8 kV switchgear should be inspected in Unit 1 prior to entering Mode 4 (HOT SHUTDOWN) and in Units 2 and 3 during their next refueling outages. Corrective actions will be initiated based upon the results of the inspections. Evaluate the electrical preventive maintenance program to ensure that solvents and petrochemicals used are compatible with the equipment. Review and update preventive maintenance tasks to ensure all sections of Magne-Blast switchgear are cleaned and inspected on a regular basis. In addition, the Unit Auxiliary Transformer was replaced.

Corrective action to prevent recurrence, the CRS will be counseled that he should consult with his supervisor when he identifies the necessity to deviate from a procedure. Evaluate the advisability of providing additional clarification within the instruction including time requirements, applicability, etc. Also, reinforce to the Operations staff, during the next routine training cycle, the use of procedures and instructions and the need to evaluate the risk of deviations from established procedures.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO 3150-0104


EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Palo Verde Unit 1	0500052888	88	010	00	15	OF	15

TEXT (If more space is required, use additional NRC Form 366A's) (17)

IV. PREVIOUS SIMILAR EVENTS:

A previous similar event was reported in LER 1-88-003-00. In the previous event the Calvert bus enclosures located outside were visually inspected for moisture tightness. To prevent moisture from entering missing bolts were replaced and Room Temperature Vulcanizing (RTV) Silicon was installed to seal moisture entry points. The buses were not inspected internally, therefore, the fault of July 6, 1988 would not have been prevented.





Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

192-00398-JGH/TDS/JEM

August 4, 1988

U. S. Nuclear Regulatory Commission
NRC Document Control Desk
Washington, D.C. 20555

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 1
Docket No. STN 50-528 (License No. NPF-41)
Licensee Event Report 1-88-010-00
File: 88-020-404

Attached please find Licensee Event Report (LER) No. 88-010-00 prepared and submitted pursuant to 10CFR 50.73. In accordance with 10CFR 50.73(d), we are herewith forwarding a copy of the LER to the Regional Administrator of the Region V office.

If you have any questions, please contact T. D. Shriver, Compliance Manager at (602) 393-2521.

Very truly yours,

J. G. Haynes
Vice President
Nuclear Production

JGH/TDS/JEM/kj

Attachment

cc: D. B. Karner (all w/a)
E. E. Van Brunt, Jr.
J. B. Martin
T. J. Polich
E. A. Licitra
A. C. Gehr
INPO Records Center

IE22
1/1

