

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8906140353 DOC.DATE: 89/06/06 NOTARIZED: NO DOCKET #
 FACIL:STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi. 05000529
 AUTH.NAME AUTHOR AFFILIATION
 SHRIVER,T.D. Arizona Public Service Co. (formerly Arizona Nuclear Power
 HAYNES,J.G., Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 89-006-00:on 890510,reactor protection sys actuation occurred.

W/8 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 6
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:Standardized plant.

05000529

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD5 LA	1 1	PD5 PD	1 1
CHAN,T	1 1	DAVIS,M	1 1
INTERNAL: ACRS MICHELSON	1 1	ACRS MOELLER	2 2
ACRS WYLIE	1 1	AEOD/DOA	1 1
AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
DEDRO	1 1	IRM/DCTS/DAB	1 1
NRR/DEST/ADE 8H	1 1	NRR/DEST/ADS 7E	1 0
NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/PEB 10	1 1
NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
RES/DSIR/EIB	1 1	RES/DSR/PRAB	1 1
RGN5 FILE 01	1 1		
EXTERNAL: EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
L ST LOBBY WARD	1 1	LPDR	1 1
NRC PDR	1 1	NSIC MAYS,G	1 1
NSIC MURPHY,G.A	1 1		


NOTES: 1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 45 ENCL 44

R
I
D
S
/
A
D
S
/
A
D
D
S



Arizona Public Service Company

PALO VERDE NUCLEAR GENERATING STATION
P O BOX 52034 • PHOENIX, ARIZONA 85072-2034

192-00489-JGH/TDS/JEM
June 6, 1989

U. S. Nuclear Regulatory Commission
NRC Document Control Desk
Washington, D.C. 20555

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 2
Docket No. STN 50-529 (License No. NPF-51)
Licensee Event Report 89-006-00
File: 89-020-404

Attached please find Licensee Event Report (LER) No. 89-006-00 prepared and submitted pursuant to 10CFR 50.73. In accordance with 10CFR 50.73(d), we are herewith forwarding a copy of the LER to the Regional Administrator of the Region V office.

If you have any questions, please contact T. D. Shriver, Compliance Manager at (602) 393-2521.

Very truly yours, :



J. G. Haynes
Vice President
Nuclear Production

JGH/TDS/JEM/kj

Attachment


cc: W. F. Conway (all w/a)
D. B. Karner
E. E. Van Brunt, Jr.
J. B. Martin
T. J. Polich
M. J. Davis
A. C. Gehr
INPO Records Center

8906140353 890606
PDR ADOCK 05000529
S PDC





bcc: J. G. Haynes (6125) (all w/a)
W. C. Marsh (6125)
W. E. Ide (6932)
D. R. Heinicke (6452)
R. J. Adney (6915)
J. M. Allen (6123)
R. F. Schaller (6932)
J. A. Bailey (6920)
Unit 3 Assistant Plant Manager (6915)
J. J. Scott (6428)
F. C. Buckingham (6451)
R. E. Gouge (6486)
M. L. Clyde (6079)
B. E. Ballard (6128)
D. N. Stover (NSG) (7202)
J. R. LoCicero (ISEG) (6144)
R. W. Page (7134)
D. B. Andrews (6345)
Source Document File (6715)
PRS File: .00246
B. F. Asher (Training) (6110)
W. F. Quinn (7035)
R. D. Baggett (6086)
J. C. Matteson (6795)
A. C. Rogers (7048)
P. J. Coffin (6148)
S. A. Shellman (6070)
C. H. Teeter (7102)
S. Karimi (6148)
J. Curran (6102)
Responsible Departments (required review):
W. M. Simko (6920)
Compliance Lead
Compliance Manager



LICENSEE EVENT REPORT (LER)


FACILITY NAME (1) Palo Verde Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 5 2 9 1					PAGE (3) 1 OF 0 4				
TITLE (4) Reactor Protection System Actuation																			
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)									
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)						
0	5	1	0	8	9	8	9	0	0	6	0	0	0	6	8	9	N/A	0 5 0 0 0 0	
OPERATING MODE (9) 5			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																
POWER LEVEL (10) 0 0 1 0			20.402(b)				20.405(c)				X 50.73(a)(2)(iv)				73.71(b)				
			20.406(a)(1)(i)				50.36(c)(1)				50.73(a)(2)(v)				73.71(c)				
			20.406(a)(1)(ii)				50.36(c)(2)				50.73(a)(2)(vi)				OTHER (Specify in Abstract below and in Text, NRC Form 365A)				
			20.406(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(vii)(A)								
			20.406(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(viii)(B)								
			20.406(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(ix)								
LICENSEE CONTACT FOR THIS LER (12)																			
NAME Timothy D. Shriver, Compliance Manager										TELEPHONE NUMBER 6 0 2 3 9 3 - 2 5 2 1									
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																			
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC									
SUPPLEMENTAL REPORT EXPECTED (14)												EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR			
X YES (If yes, complete EXPECTED SUBMISSION DATE)												NO		0	7	3	0	8	9

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

At approximately 1109 MST on May 10, 1989, Palo Verde Unit 2 was in Mode 5 (COLD SHUTDOWN) with the Reactor Coolant System (RCS) Temperature at approximately 137 degrees F and pressurizer pressure at approximately 130 psia when an automatic actuation of the Reactor Protection System (RPS) occurred.

In accordance with approved procedures the Low Steam Generator Pressure and Low RCS Flow initiation trip relays were being energized with a temporary electrical power supply to perform Control Element Assembly testing. These trips are not required to be operable in Mode 5 and were reset with the temporary power supply. The Reactor Trip Switchgear Breakers were shut when a Computer Technician plugged in a test cart into the same wall receptacle that was supplying temporary power to the relays. Plugging in the test cart caused a dip in the voltage sufficient to deenergize the initiation relays and initiate an RPS actuation opening the Reactor Trip Switchgear Breakers.

As corrective action, the computer test cart was unplugged and all outlets from the common lighting panel in the control room were yellow caution tagged with instructions to contact the Shift Supervisor before using the receptacles.



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Palo Verde Unit 2	05000529	89	006	00	02	OF	04

TEXT (If more space is required, use additional NRC Form 366A's) (17)

I. DESCRIPTION OF WHAT OCCURRED:

A. Initial Conditions:

At approximately 1109 MST on May 10, 1989, Palo Verde Unit 2 was in Mode 5 (COLD SHUTDOWN) with the Reactor Coolant System (RCS)(AB) temperature at approximately 137 degrees F and pressurizer (PZR)(AB) pressure at approximately 130 psia. Shutdown Cooling System (CP) Train "B" was in operation and no Reactor Coolant Pumps (P)(AB) were operating. Reactor Trip Switchgear Breakers (BKR)(AA) were shut for Control Element Assembly (CEA)(ROD)(AA) testing.

B. Reportable Event Description (Including Dates and Approximate Times of Major Occurrences):

Event Classification: An event that resulted in the automatic actuation of the Reactor Protection System (RPS)(JC).

At approximately 1109 MST on May 10, 1989, a Computer Technician (utility, non-licensed) plugged a test cart into an electrical receptacle (RCP)(EC) which caused a voltage dip to temporary power supplies (JX) for RPS initiation relays (RLY)(JC) and resulted in a reactor trip. The Technician was performing a test of the Emergency Response Facility Data Acquisition Display System (ERFDADS) in accordance with an approved procedure. When the technician plugged the test cart into the receptacle, the additional load caused a momentary dip in the receptacle voltage.

Prior to the event, preparations had been made to perform CEA testing. The testing requires that all RPS trips are reset and the Reactor Trip Switchgear Breakers are closed. Under the plant conditions (Mode 5) at that time, Low RCS Flow (JC) trips are normally tripped and Low Steam Generator Pressure trips are near the trip setpoint. These trips are not required to be operable in Mode 5. In accordance with an approved work control document both trips were supplied temporary power to ensure the trips would remain reset. An evaluation will be performed to determine if adequate margin to the Low Steam Generator Pressure trips exist and have appropriate procedures changed if appropriate (i.e., if adequate margin exists then the temporary power to the Low Steam Generator Pressure trips will not be required).

The source of the temporary electrical power to the initiation relays was a dual receptacle outlet box (OBX)(EC). The technician plugged the ERFDADS test cart into the same receptacle and caused a dip in voltage to the temporary power supplies for the initiation relays. This dip in the voltage tripped the initiation relays (RLY)(JC) of all four channels of Low Steam Generator Pressure and

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1) Palo Verde Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 5 2 9 8 9	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 9	0 0 6	0 0	0 3	OF	0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Low RCS Flow trips actuating the RPS and opening all four Reactor Trip Switchgear Breakers. The trip signals then reset immediately. All CEA's were fully inserted before the RPS actuation occurred. The Assistant Shift Supervisor (utility, licensed) then verified that there were no changes in Shutdown Cooling System flow, RCS temperature and pressure, and pressurizer level. The Assistant Shift Supervisor then went to check the temporary power supply and identified the Computer Technician's test cart plugged into the same receptacle outlet box. There were no operator errors that contributed to the event.

All equipment that was required to actuate actuated as designed and no other actuations occurred or were required.

- C. Status of structures, systems, or components that were inoperable at the start of the event that contributed to the event:

Not applicable - no structures, systems, or components were inoperable at the start of the event that contributed to the event.

- D. Cause of each component or system failure, if known:

Not applicable - no component or system failures were involved.

- E. Failure mode, mechanism, and effect of each failed component, if known:

Not applicable - no failed components were involved.

- F. For failures of components with multiple functions, list of systems or secondary functions that were also affected:

Not applicable - no failed components were involved.

- G. For failures that rendered a train of a safety system inoperable, estimated time elapsed from the discovery of the failure until the train was returned to service:


Not applicable - no failures were involved.

- H. Method of discovery of each component or system failure or procedural error:

Not applicable - no component or system failures or procedural errors were involved.

- I. Cause of Event:

The cause of the RPS actuation was a dip in the voltage to the



LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
Palo Verde Unit 2	05000529	89	006	00	04	OF 04

TEXT (If more space is required, use additional NRC Form 366A's) (17)

temporary power supply. An investigation is in progress to determine the root cause of the event. A supplement will be submitted by July 30, 1989 identifying the root cause after completion of the investigation.

J. Safety System Response:

Automatic actuation of the RPS occurred opening the Reactor Trip Switchgear Breakers. No other safety systems responded and none were necessary.

K. Failed Component Information:

Not applicable - no failed components were involved.

II. ASSESSMENT OF THE SAFETY CONSEQUENCES AND IMPLICATIONS OF THIS EVENT:

There were no safety consequences or implications of this event since the reactor was shutdown and in Mode 5 (COLD SHUTDOWN). There was no threat to the health and safety of the public.

III. CORRECTIVE ACTIONS:

A. Immediate:

The ERFDADS test cart was unplugged. Also as interim corrective action, all outlets from the common lighting panel in the control room were tagged with yellow caution tags with instructions not to use the receptacle without contacting the Shift Supervisor.

B. Action to Prevent Recurrence:

An investigation will be completed by June 30, 1989 to determine root cause and any other corrective actions that may be necessary. A supplement will be submitted by July 30, 1989 identifying any other corrective actions to be taken.

IV. PREVIOUS SIMILAR EVENTS:

No previous similar events have been reported.

