

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9004200523 DOC.DATE: 90/04/06 NOTARIZED: NO DOCKET #  
 FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528  
 AUTH.NAME AUTHOR AFFILIATION  
 LEVINE,J.M. Arizona Public Service Co. (formerly Arizona Nuclear Power  
 RECIP.NAME RECIPIENT AFFILIATION  
 Document Control Branch (Document Control Desk)

SUBJECT: Special rept: radiation monitor inoperable for greater than 72 h.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: 05000528

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD5 LA	1 1	PD5 PD	1 1
	PETERSON,S.	1 1	CHAN,T	1 1
INTERNAL:	ACNW	2 2	ACRS	2 2
	AEOD/DOA	1 1	AEOD/DSP/TPAB	1 1
	AEOD/ROAB/DSP	2 2	DEDRO	1 1
	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB9H3	1 1
	NRR/DET/ESGB 8D	1 1	NRR/DLPQ/LHFB11	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB11	1 1
	NRR/DREP/PRPB11	2 2	NRR/DST/SELB 8D	1 1
	NRR/DST/SICB 7E	1 1	NRR/DST/SPLB8D1	1 1
	NRR/DST/SRXB 8E	1 1	<del>REG FILE 02</del>	1 1
	RES/DSIR/EIB	1 1	RGN5 FILE 01	1 1
EXTERNAL:	EG&G STUART,V.A	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS,G	1 1	NSIC MURPHY,G.A	1 1
	NUDOCS FULL TXT	1 1		
NOTES:		1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 39 ENCL 39

IA2



Arizona Public Service Company  
PALO VERDE NUCLEAR GENERATING STATION  
P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

192-00645-JML/TRB/SBJ  
April 6, 1990

U. S. Nuclear Regulatory Commission  
NRC Document Control Desk  
Washington, D.C. 20555

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)  
Unit 1  
Docket No. STN 50-528 (License No. NPF-41)  
Special Report 1-SR-90-001  
File: 90-020-404

Attached please find Special Report 1-SR-90-001 prepared and submitted pursuant to Technical Specifications 3.3.3.8 ACTION 42(b) and 6.9.2. This report discusses a radiation monitor inoperable for greater than 72 hours. Additionally, a copy of this report is being sent to the Regional Administrator.

If you have any questions, please contact T. R. Bradish, (Acting) Compliance Manager, at (602) 393-2521.

Very truly yours,

*James M. Levine*


JML/TRB/SBJ/tlg

Attachment

cc: W. F. Conway (all w/attachment)  
J. B. Martin  
E. E. Van Brunt, Jr.  
T. L. Chan  
D. H. Coe  
A. C. Gehr  
INPO Records Center

9004200523 900406  
PDR ADDCK 05000528  
S PNU

*JE22*  
*11*



PALO VERDE NUCLEAR GENERATING STATION UNIT 1

Radiation Monitoring Unit Inoperable Greater Than 72 Hours

License No. NPF-41

Docket No. 50-528

Special Report 1-SR-90-001

I. DESCRIPTION OF WHAT OCCURRED

A. Initial Conditions:

On March 7, 1990 Palo Verde Unit 1 was in mode 5 with the reactor coolant system (RCS)(AB) at atmospheric pressure and approximately 90 degrees fahrenheit.


B. Reportable Event Description (Including Dates and Approximate Times of Major Occurrences):

Event Classification: Special Report Submitted in accordance with Technical Specification 3.3.3.8 ACTION 42(b)

On March 7, 1990 at approximately 0546 MST, the fuel building normal ventilation (VG) and essential ventilation systems (VG) were taken out of service for a scheduled maintenance outage on fans and dampers (DMP). This caused all fuel building ventilation exhaust flow to stop, thereby preventing the fuel building exhaust low range (RU-145) and high range (RU-146) radiation monitors (IL) from obtaining a representative air sample. The radiation monitors were therefore declared inoperable at approximately 0546 MST.

Technical Specification 3.3.3.8 requires RU-145 and RU-146 to be operable in Modes 1,2,3, and 4 or when there is irradiated fuel in the fuel storage pool. Since the effluent releases via the fuel building ventilation were stopped, alternate sampling of the release pathway was not necessary. In order to monitor potential releases, particulate and iodine samples were taken during the duration of the maintenance. Additionally, the fuel building doors on the 120 foot elevation to the auxiliary building were opened in order to maintain a negative pressure in the fuel building using the auxiliary building ventilation.

Technical Specification 3.9.12 requires the fuel building essential ventilation systems operable whenever there is irradiated fuel in the storage pool. If neither essential ventilation system is operable, all operations involving movement of fuel within the storage pool or crane operation with loads over the storage pool must be suspended. Therefore, in accordance with



TS 3.9.12(b), all activities in the fuel storage pool and over the fuel storage pool were suspended.

On March 10, 1990 at approximately 0546 MST, RU-146 had been inoperable for greater than 72 hours. Therefore, this report is being submitted in accordance with Technical Specification 3.3.3.8 Action 42(b).

On April 1, 1990 at approximately 0208 MST the fuel building normal ventilation was returned to service. At approximately 0345 MST on April 1, 1990, RU-145 and RU-146 were declared operable after completion of surveillance testing.

- C. Status of structures, systems, or components that were inoperable at the start of the event that contributed to the event:

Not applicable - no structures, systems or components were inoperable at the start of the event which contributed to this event.

- D. Cause of each component or system failure, if known:

Not applicable - there were no component or system failures.

- E. Failure mode, mechanism, and effect of each failed component, if known:

Not applicable - there were no component failures.

- F. For failures of components with multiple functions, list of systems or secondary functions that were also effected:

Not applicable - there were no component failures with multiple functions.

- G. For failures that rendered a train of a safety system inoperable, estimated time elapsed from the discovery of the failure until the train was returned to service:

RU-145 and RU-146 were inoperable for approximately 24 days and 22 hours.

- H. Method of discovery of each component of system failure or procedural error:

Not applicable - there were no component or equipment failures.





I. Cause of Event:

RU-145 and RU-146 were inoperable because of the inability to sample refueling building ventilation exhaust since all fuel building ventilation had been taken out of service to perform scheduled maintenance.

J. Safety System Response:

Not applicable - No safety system actuated due to this event.

K. Failed Component Information:

Not applicable - there were no component failures.

II. ASSESSMENT OF THE SAFETY CONSEQUENCES AND IMPLICATIONS OF THIS EVENT:

There were no safety consequence or implications resulting from this event. No irradiated fuel was moved and air samples were taken to the monitor fuel building atmosphere for unusual radiological conditions. No abnormal radiological conditions were identified during this event.

III. CORRECTIVE ACTIONS:

A. Immediate

The fuel building air was sampled for particulate and iodine during the ventilation outage. The maintenance on the ventilation system was performed and the ventilation systems returned to service.

IV. Previous Event

There have been no previous events in which RU-145/146 were inoperable because the ventilation systems were inoperable.

