

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9803100025 DOC.DATE: 98/03/05 NOTARIZED: NO DOCKET #
 FACIL:STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530
 AUTH.NAME AUTHOR AFFILIATION
 MARKS,D.G. Arizona Public Service Co. (formerly Arizona Nuclear Power
 OVERBECK,G.R. Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 93-005-00:on 930309,missed TS ACTION statement occurred
 due to personnel.Independent investigation of event was
 conducted.W/980305 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:Standardized plant.

05000530

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD4-2 PD	1 1	CLIFFORD, J	1 1	
INTERNAL:	ACRS	1 1	AEOD/SPD/RAB	2 2	
	AEOD/SPD/RRAB	1 1	<u>FILE CENTER</u>	1 1	
	NRR/DE/ECGB	1 1	NRR/DE/EELB	1 1	
	NRR/DE/EMEB	1 1	NRR/DRCH/HHFB	1 1	
	NRR/DRCH/HICB	1 1	NRR/DRCH/HOLB	1 1	
	NRR/DRCH/HQMB	1 1	NRR/DRPM/PECB	1 1	
	NRR/DSSA/SPLB	1 1	NRR/DSSA/SRXB	1 1	
	RES/DET/EIB	1 1	RGN4 FILE 01	1 1	
EXTERNAL:	L ST LOBBY WARD	1 1	LITCO BRYCE, J H	1 1	
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1	
	NRC PDR	1 1	NUDOCS FULL TXT	1 1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

AD4



Palo Verde Nuclear
Generating Station

Gregg R. Overbeck
Vice President
Nuclear Production

TEL 602/393-5148
FAX 602/393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01013 – GRO/DGM/KR
March 5, 1998

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 3
Docket No. STN 50-530
License No. NPF-74
Licensee Event Report 93-005-00

Attached please find Licensee Event Report (LER) 93-005-00 prepared and submitted pursuant to 10CFR50.73. This LER reports a Technical Specification (TS) violation due to a missed TS Limiting Condition for Operation ACTION statement due to personnel error.

In accordance with 10CFR50.73(d), a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV. If you have any questions, please contact Daniel G. Marks, Section Leader, Nuclear Regulatory Affairs, at (602) 393-6492.

Sincerely,



GRO/DGM/KR/mah

Attachment

cc: E. W. Merschoff (all with attachment)
K. E. Perkins
J. H. Moorman
INPO Records Center

9803100025 980305
PDR ADOCK 05000530
S PDR



LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Palo Verde Unit 3	DOCKET NUMBER (2) 0 5 0 0 0 5 3 0	PAGE (3) 1 OF 0 3
---	---	-----------------------------

TITLE (4)
Missed Technical Specification ACTION Statement due to Personnel Error

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		DOCKET NUMBERS
									N/A		0 5 0 0 0 0
0 3	0 9	9 3	9 3	- 0 0 5	- 0 0	0 3	0 5	9 8	N/A		0 5 0 0 0 0

OPERATING MODE (9) **THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § (Check one or more of the following) (11)**

POWER LEVEL (10)	20.402(b)	20.405(c)	50.73(a)(2)(v)	73.71(b)
	20.405(a)(1)(i)	50.38(c)(1)	50.73(a)(2)(v)	73.71(c)
	20.405(a)(1)(ii)	50.38(c)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 368A)
	20.405(a)(1)(iii)	<input checked="" type="checkbox"/> 50.73(a)(2)(i)	50.73(a)(2)(vii)(A)	
	20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii)(B)	
	20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME Daniel G. Marks, Section Leader, Nuclear Regulatory Affairs	TELEPHONE NUMBER AREA CODE 6 0 2 3 9 3 - 6 4 9 2
--	---

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDOS

SUPPLEMENTAL REPORT EXPECTED (14)

<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input checked="" type="checkbox"/> NO	EXPECTED SUBMISSION DATE (15)
--	--	-------------------------------

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On March 9, 1993, at approximately 2010 MST, Palo Verde Unit 3 was in Mode 1 (POWER OPERATION), operating at approximately 100 percent power when the requirement of Technical Specification Limiting Condition for Operation (TS LCO) 3.8.1.1 ACTION b for one emergency diesel generator inoperable was not met within the one hour allowed by TS. Between 0200 MST and 0400 MST on March 10, 1993, Control Room personnel discovered the missed TS LCO ACTION and subsequently performed the surveillance satisfactorily.

The cause of the event was attributed to personnel error. The root cause of the personnel error was indeterminate due to limited information available after five years had lapsed since the event occurred. The NRC initially identified the event in late 1997. The APS investigation surrounding the event was completed by APS on February 10, 1998. The APS investigation determined that an LER was required to be submitted to report the event. As corrective action, appropriate disciplinary action was issued to applicable Control Room personnel.

No previous similar events have been reported pursuant to 10CFR50.73.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME	DOCKET NUMBER	LER NUMBER			PAGE		
Palo Verde Unit 3		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
	0 5 0 0 0 5 3 0	9 3	- 0 0 5	- 0 0	0 2	of	0 3

TEXT

1. REPORTING REQUIREMENT:

This LER 530/93-005-00 is being written to report an event that resulted in an operation or condition prohibited by the plant's Technical Specifications (TS) as specified in 10 CFR 50.73(a)(2)(i)(B).

TS Limiting Condition for Operation (LCO) 3.8.1.1 (A.C. Sources - Operating) ACTION b states that with one emergency diesel generator (EDG) (EK) inoperable, demonstrate the OPERABILITY of the OPERABLE offsite circuits by performing SR 4.8.1.1.1.a (verifying correct breaker alignment and indicated power availability for required offsite circuits) within 1 hour and once per 8 hour thereafter.

2. EVENT DESCRIPTION:

At approximately 2110 MST on March 9, 1993, Palo Verde Unit 3 was in Mode 1 (POWER OPERATION) operating at approximately 100 percent power.

At approximately 2010 MST on March 9, 1993, Control Room personnel removed the Train B emergency diesel generator (EDG-B) from service for planned maintenance. At approximately 2358 MST, Control Room personnel restored EDG-B to OPERABLE. Contrary to the requirement for TS LCO 3.8.1.1, by approximately 2110 MST on March 9, 1993, Control Room personnel had not performed the appropriate ACTION statement within the one hour allowed by TS. Between 0200 MST and 0400 MST on March 10, 1993, Control Room personnel discovered the missed TS LCO ACTION and subsequently performed the surveillance satisfactorily.

There were no safety system actuations and none were required.

3. ASSESSMENT OF THE SAFETY CONSEQUENCES AND IMPLICATIONS OF THIS EVENT:

Control Room personnel would have become immediately aware of any changes to correct breaker alignment and indicated power availability for the offsite circuits because of control room annunciation (IB). The event did not result in any challenges to the fission product barriers or result in any release of radioactive materials. Therefore, there were no adverse safety consequences or implications as a result of this event. This event did not adversely affect the safe operation of the plant or health and safety of the public.

4. CAUSE OF THE EVENT:

An independent investigation of this event was conducted. The investigation determined that Control Room personnel (utility-licensed

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME	DOCKET NUMBER	LER NUMBER			PAGE		
Palo Verde Unit 3		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0 5 0 0 0 5 3 0	9 3 - 0 0 5 - 0 0	0 3 of 0 3			

TEXT

operator) failed to promptly conduct the required TS LCO ACTION statement for one EDG inoperable (SALP Cause Codes: A: Personnel Error). The root cause of the personnel error was indeterminate due to limited information available after five years had lapsed since the event occurred. The NRC initially identified the event in late 1997. The investigation surrounding the event was completed by APS on February 10, 1998. The investigation determined that an LER was required to be submitted to report the event.

No unusual characteristics of the work location (e.g., noise, heat, poor lighting) directly contributed to this event. No procedural errors contributed to this event.

5. STRUCTURES, SYSTEMS, OR COMPONENTS INFORMATION:

There are no indications that any structures, systems, or components were inoperable at the start of the event which contributed to this event. No component or system failures were involved. No failures of components with multiple functions were involved. No failures that rendered a train of a safety system inoperable were involved.

6. CORRECTIVE ACTIONS TO PREVENT RECURRENCE:

An independent investigation of this event was conducted. Actions to prevent recurrence were developed based upon the results of the investigation. Appropriate disciplinary action was issued to applicable Control Room personnel in accordance with the APS Positive Discipline Program.

7. PREVIOUS SIMILAR EVENTS:

Although previous events have been reported pursuant to 10 CFR 50.73 in the past three years for missing TS surveillance requirements, the causes discussed in the previous events have not been similar to this event. Specific to this event, the root cause of the personnel error was indeterminate due to limited information available after five years had lapsed since the event occurred.

