

LICENSEE EVENT REPORT
DATE REPORT-PREVIOUS REPORT DATE 5-78

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	0	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4	5			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34			
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE					CAT 68	

CON'T

0	1	L	0	5	0	0	0	3	1	6	0	4	0	7	7	8	0	1	1	9	7	9	9				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34
REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE										

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 DURING NORMAL OPERATION, ROD POSITION INDICATION (RPI) FOR RODS D-12 AND H-8

0 3 EXCEEDED THE ± 12 STEP LIMIT OF T.S. 3.1.3.2. ON ELEVEN OTHER OCCASSIONS D-12

0 4 RPI WAS FOUND TO BE IN EXCESS OF THE T.S. LIMIT. IN ALL CASES THE ACTION REQUIRE-

0 5 MENTS WERE FULFILLED. PREVIOUS OCCURRENCES OF A SIMILAR NATURE INCLUDE:

0 6 RO-050/0315-78-07,04,77,34,33,28,27,76-54,44,13; RO-050/0316-78-08,07.

0 7

0 8

0	9	I	E	E	I	N	S	T	R	U	I	Z	1		
7	8	9	10	11	12	13	14	15	16	17	18	19	20		
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE		
11		12		13		14					15		16		
17		18		19		20		21		22		23		24	
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.		COMPONENT MANUFACTURER		26	
21		22		23		24		25		26		27		28	
29		30		31		32		33		34		35		36	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
33		34		35		36		37		38		39		40	
41		42		43		44		45		46		47		48	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 THE SECONDARY VOLTAGE FOR D-12 AND H-8 WAS MEASURED AND FOUND TO BE CORRECT FOR THE

1 1 INDICATED POSITION. THE OUTPUTS OF THE AMPLIFIERS THAT FEED THE CONTROL BOARD

1 2 INDICATORS WAS FOUND TO BE INCORRECT. THE AMPLIFIERS WERE CALIBRATED AND PROPER

1 3 INDICATION WAS RESTORED. THE OTHER NUMEROUS EVENTS OCCURRING TO D-12 WAS THE

1 4 RESULT OF HAVING A RECORDER CONNECTED TO THE (SEE ATTACHED SUPPLEMENT)

1	5	E	0	3	0	NA	A	OPERATOR OBSERVATION	
7	8	9	10	11	12	13	14	15	
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
28		29		30		31		32	

1	6	Z	Z	NA	NA	NA	
7	8	9	10	11	12	13	
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
33		34		35		36	

1	7	0	0	0	Z	NA	
7	8	9	10	11	12	13	
PERSONNEL EXPOSURES NUMBER		TYPE		DESCRIPTION		39	
37		38		39		40	

1	8	0	0	0	NA		
7	8	9	10	11	12		
PERSONNEL INJURIES NUMBER		DESCRIPTION		41		42	
40		41		42		43	

1	9	Z	NA				
7	8	9	10				
LOSS OF OR DAMAGE TO FACILITY TYPE		DESCRIPTION		43		44	
42		43		44		45	

2	0	N	NA				
7	8	9	10				
PUBLCITY ISSUED DESCRIPTION		45		46		47	
44		45		46		47	

NAME OF PREPARER Jack Rischling

PHONE: 616-465-5901

NRC USE ONLY

100

100

LICENSEE EVENT REPORT #78-022/03X-1

SUPPLEMENT TO CAUSE DESCRIPTION

OUTPUT OF THE RPI CABINET (MONITORING D-12). THIS RECORDER WAS CONNECTED IN PREPARATION FOR THE NEGATIVE RATE TRIP ASSOCIATED WITH THE POWER ASCENSION PROGRAM. SINCE THIS RECORDER WAS DISCONNECTED ON APRIL 19, 1978 NO FURTHER PROBLEMS HAVE BEEN ENCOUNTERED WITH RPI FOR ROD D-12.

