

LICENSEE EVENT REPORT

CONTROL BLOCK: ☒ 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
M I D C C 2 0 0 - 0 0 0 0 0 - 0 0 0 4 1 1 1 1 4 5
LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
0 1 REPORT SOURCE L 0 5 0 - 0 3 1 6 7 0 3 0 6 7 9 8 0 4 0 3 7 9 9
DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WHILE PERFORMING SURVEILLANCE TEST ON THE TURBINE DRIVEN AUX.
0 3 FEED PUMP, THE PUMP OUTBOARD BEARING TEMP. WAS OBSERVED TO BE
0 4 195°F. MAXIMUM RECOMMENDED TEMP IS 185°F. THE PUMP WAS REMOVED
0 5 FROM SERVICE, THE BEARING WAS REPLACED AND THE PUMP RETESTED SATISFACTORILY.
0 6 REDUNDANT AUX. FEED CAPABILITY WAS AVAILABLE. THIS EVENT HAD NO AFFECT
0 7 ON PUBLIC HEALTH AND SAFETY.
0 87 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
C H 11 E 12 B 13 P U M P X X 14 B 15 Z 16
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
7 9 0 1 0 0 3 L 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
A 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 A 25 I 0 7 5 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 ROOT CAUSE COULD NOT BE DETERMINED. POSSIBLE CAUSE WAS FOREIGN MATERIAL
1 1 IN BEARING OIL SINCE THE TIP OF A HAND HELD TACH. HAD FALLEN OFF INTO THE
1 2 OIL RESERVOIR JUST PRIOR TO THIS EVENT AND THE RUBBER PORTION OF THE TIP
1 3 APPARENTLY DISOLVED. HOWEVER THE METAL PORTION OF THE TIP WAS RETRIEVED
1 4 AND OIL WAS CHANGED PRIOR TO THE HIGH TEMPERATURE OBSERVATION.
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 807 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
E 28 1 0 0 29 N/A B 31 OPERATOR OBSERVATION 32
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
Z 33 Z 34 N/A N/A 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
0 0 0 37 Z 38 N/A 39
PERSONNEL INJURIES NUMBER DESCRIPTION
0 0 0 40 N/A 41
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
Z 42 N/A 43
PUBLCITY ISSUED DESCRIPTION
N 44 N/A 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER D. G. WIZNER

PHONE: (616) 465-5901, EXT. 398

Rev.
Mr. A. J. ...