

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	5	7	0	3	2	6	7	9	8	0	4	2	4	7	9	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE								REPORT DATE						

WHILE TROUBLESHOOTING A PROBLEM ON AN ADJACENT ROD POSITION INDICATION CIRCUIT

RENDERING THE CHANNEL INOPERABLE. ROD K-10 INDICATION WAS RESTORED TO OPERABLE

STATUS WITHIN THE TIME LIMIT SPECIFIED BY T.S. 3.1.3.2.

09		SYSTEM CODE I E		CAUSE CODE A		CAUSE SUBCODE B		COMPONENT CODE I N S T R U				COMP. SUBCODE I		VALVE SUBCODE Z	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22
LER/RO REPORT NUMBER		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 2 3		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0		ACTION TAKEN A		FUTURE ACTION H	
17		21		24		28		30		32		33		34	
EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER N		COMPONENT MANUFACTURER W 1 2 0		26	
19		21		22		23		24		25		26		27	

THE EVENT WAS CAUSED BY SHORTING THE SECONDARY COIL VOLTAGE TERMINALS TO THE LINE.

VOLTAGE TERMINALS AT THE REAR OF THE INDICATOR PANEL. TO PREVENT RECURRENCE, THE

METHOD OF OBTAINING VOLTAGE MEASUREMENTS HAS BEEN REVISED.

7 8 9 FACILITY STATUS (28) 10 11 12 % POWER (29) 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 OTHER STATUS (30) 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 METHOD OF DISCOVERY (31) 51 52 53 54 55 56 57 58 59 60 DISCOVERY DESCRIPTION (32)

[illegible]

DATE OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE	
33	Z	NA		NA	

PERSONNEL INJURIES
NUMBER DESCRIPTION (41) NA 7904300303

1 8 0 0 0 (40) 7 8 9 11 12

LOSS OF OR DAMAGE TO FACILITY (42)

SS OF OR DAMAGE TO FACILITY (43)

TYPE	DESCRIPTION	NA
42		

NAME OF PREPARER: T. P. Beilman PHONE: 616-465-5901

NAME OF PREPARER T. P. Beilman

PHONE: 616-465-5901

