

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	0	4	0	9	7	9	8	0	5	0	9	7	9	9
60	61								68	69						74	75							80

DOCKET NUMBER

EVENT DATE

REPORT DATE

0 2 | DURING PLANT STARTUP, A SMALL CRACK AND PINHOLE LEAK WAS FOUND IN THE BODY

0 3 | OF FMO-232, AUX. FEEDWATER TO #3 S/G MOV, AT THE INLET SIDE OF THE VALVE

0 4 | ADJACENT TO THE WELD. SYSTEM WAS REMOVED FROM SERVICE CONSTITUTING IN-

0 5 | OPERABLE FLOW PATH PER T.S. 3.7.1.2. THE CRACK WHICH WAS APPROX. 3/8"

0 6 | LONG WAS GROUND OUT AND THE AREA WAS REPAIRED BY WELDING. NDE INCLUDED

0 7 | PT, RT AND HYDROSTATIC TEST AT 2100 PSIG. ACTION REQUIREMENTS OF TECH.

0 8 | SPECS. WERE COMPLIED WITH. HEALTH AND SAFETY OF THE PUBLIC WAS NOT JEOPARDIZED.

SYSTEM CODE C H 11		CAUSE CODE E 12		CAUSE SUBCODE C 13		COMP. SUBCODE E 15		VALVE SUBCODE G 16	
EVENT YEAR 7 9 22		SEQUENTIAL REPORT NO. 0 1 5 26		OCCURRENCE CODE 0 3 29		REPORT TYPE L 30		REVISION NO. 0 32	
ACTION TAKEN D 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 22	
ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. Y 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER L 3 0 0 26			

1 0 CAUSE OF THE CRACK COULD NOT BE DETERMINED. RADIOGRAPHS OF THE AFFECTED AREA

1 1 WHICH WERE ON FILE WERE REVIEWED, BUT DID NOT REVEAL ANY INDICATIONS IN THE

1 2 VICINITY OF THE CRACK. NO SIMILAR PROBLEMS HAVE BEEN DETECTED ON LINES TO

1 3 THE OTHER S/G'S. NO FUTURE ACTION IS PLANNED.

[illegible]

NAME OF PREPARER DAVID G. WIZNER

PHONE: (616) 465-5901, EXT.

398

