

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

L	(6)	0	5	0	0	0	3	1	6	(7)	0	6	2	2	7	9	(8)	0	7	1	9	7	9	(9)
60	61	DOCKET NUMBER					68	69	EVENT DATE					74	75	REPORT DATE					80			

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 8 | _____ 80

SYSTEM CODE S C (11)		CAUSE CODE B (12)		CAUSE SUBCODE A (13)		COMPONENT CODE R E L A Y S (14)		COMP. SUBCODE M (15)		VALVE SUBCODE Z (16)	
LER/RO REPORT NUMBER 7 9 (17)		EVENT YEAR 7 9 (21 22)		SEQUENTIAL REPORT NO. 0 2 1 (24 25 26)		OCCURRENCE CODE 0 3 (28 29)		REPORT TYPE L (30)		REVISION NO. (32)	
ACTION TAKEN E (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 (22 23 24)		ATTACHMENT SUBMITTED Y (23)	
NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER A (25)		COMPONENT MANUFACTURER A 1 0 9 (26 27 28 29)							

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS (28) 1 5 G
 % POWER 0 0 0 (29) NA OTHER STATUS (30)
 METHOD OF DISCOVERY (31) B SURVEILLANCE TEST DISCOVERY DESCRIPTION (32)

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	7	0	0	(37) Z	(38) NA (39)

7		8		9		11		12		80	
				LOSS OF OR DAMAGE TO FACILITY		DESCRIPTION		(43)			
TYPE											
1	9	Z	(42)	NA							

	7	8	9	10							68	NRC USE ONLY												80				
			PUBLICITY ISSUED		(45)	DESCRIPTION																						
	2	0	N	(44)		NA																						
	7	8	9	10							68	69													80			

PHONE: 616-465-5901

SUPPLEMENT TO LER # 79-021/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THAT THIS EVENT REPRESENTS A REPEATABLE PATTERN WARRANTING FURTHER ACTION AT THIS TIME.

THE POST-LOCA HYDROGEN ANALYSIS HAS BEEN REEVALUATED TO DETERMINE THE EFFECTS OF A 10 MINUTES 13 SECONDS DELAY IN SYSTEM ACTUATION ON PEAK HYDROGEN CONCENTRATIONS. THE RESULTS INDICATE THAT THE PEAK LOCAL HYDROGEN CONCENTRATION WOULD HAVE BEEN MAINTAINED BELOW THE REGULATORY LIMIT OF 4.0 V/O.