


**INDIANA & MICHIGAN POWER COMPANY**

DONALD C. COOK NUCLEAR PLANT  
P.O. Box 458, Bridgman, Michigan 49106

November 26, 1979

Mr. J.G. Keppler, Regional Director  
Office of Inspection and Enforcement  
United States Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Operating License DPR-58  
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,  
the following report/s are submitted:

RO 79-056/03L-0.

Sincerely,

D.V. Shaller  
Plant Manager

/bab

cc: J.E. Dolan  
R.W. Jurgensen  
R.F. Kroeger  
R.W. Kilburn  
R.J. Vollen BPI  
R.E. Masse RO:III  
R.C. Callen MPSC  
P.W. Steketee, Esq.  
R. Walsh, Esq.  
G. Charnoff, Esq.  
G. Olson  
J.M. Hennigan  
PNSRC  
J.F. Stietzel  
E.L. Townley  
Dir., IE (30 copies)  
Dir., MIPC (3 copies)

NOV 28 1979

DUPLICATE

A002  
S  
1/1

7912040384

30-28-104

1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

**CONTROL BLOCK:**

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5													
7	8	9						14						15						25						26						30						57		58	
		LICENSEE CODE						LICENSE NUMBER												LICENSE TYPE																					

**CON'T**

REPORT SOURCE 0 1 7 8

DOCKET NUMBER 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DATE 1 0 2 7 7 9 8

REPORT DATE 1 1 2 6 7 9 9

**EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)**

0	2	DURING THE PERFORMANCE OF A SURVEILLANCE TEST PROCEDURE, THE OPENING
0	3	TORQUE ON TWO OF THE ICE CONDENSER LOWER INLET DOOR (17L AND 21R)
0	4	EXCEEDED THE MAXIMUM LIMITS AS SPECIFIED IN T.S. 4.6.5.3.1 ITEM 3.
0	5	
0	6	
0	7	
0	8	

SYSTEM CODE S A (11)		CAUSE CODE B (12)		CAUSE SUBCODE A (13)		COMPONENT CODE X X X X X X (14)				COMP. SUBCODE X (15)		VALVE SUBCODE Z (16)	
LER/RO REPORT NUMBER 7 9 (17)		EVENT YEAR 7 9 (21, 22)		SEQUENTIAL REPORT NO. 0 5 6 (24, 25, 26)		OCCURRENCE CODE 0 3 (28, 29)		REPORT TYPE L (30)		REVISION NO. 0 (32)			
ACTION TAKEN E (18)		FUTURE ACTION F (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 (22, 23, 24)		ATTACHMENT SUBMITTED Y (25)		NPRD-4 FORM SUB. N (26)	
PRIME COMP. SUPPLIER N (27)		COMPONENT MANUFACTURER W 1 2 0 (28, 29, 30, 31)											

### CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 IT HAS BEEN FOUND THAT THE SPRINGS USED ON THESE DOORS ARE SLIGHTLY

1 1 STIFFER THAN THOSE ON THE DOORS IN OTHER BAYS. THE SPRING TENSION

1 2 ADJUSTMENT BOLTS ON DOORS 17L AND 21R WERE BACKED OUT TO BRING THE

1 3 OPENING TORQUE TO WITHIN ALLOWABLE VALUES.

1 4 SEE ATTACHED SUPPLEMENT.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION														
1	5	G	28	0	0	0	29	B	31	SURVEILLANCE TEST	32											
7	8	9	10	11	12	13	14	15	16	17	18											
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE																
1	6	Z	33	Z	34	NA	35	NA	36													
7	8	9	10	11	12	13	14	15	16	17	18											
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION																
1	7	0	0	0	37	Z	38	NA	39													
7	8	9	10	11	12	13	14	15	16	17	18											
PERSONNEL INJURIES		NUMBER		DESCRIPTION																		
1	8	0	0	0	40	NA	41															
7	8	9	10	11	12	13	14	15	16	17	18											
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION																		
1	9	Z	42	NA	43																	
7	8	9	10	11	12	13	14	15	16	17	18											
PUBLICITY ISSUED		DESCRIPTION																				
2	0	N	44	NA	45																	
7	8	9	10	11	12	13	14	15	16	17	18											
										NRC USE ONLY												
										68	69	70	71	72	73	74	75	76	77	78	79	80

NAME OF PREPARER S. D. DeLong

PHONE: 616-465-5901

SUPPLEMENT TO LER #79-056/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

A DESIGN CHANGE HAS BEEN INITIATED TO REPLACE THE SPRING  
ADJUSTMENT BOLTS WITH LONGER BOLTS IN ORDER TO RELIEVE THE  
SPRING TENSION ON THE LOWER DOORS, (RFC 12-1762).  
THE DOORS WERE IMMEDIATELY READJUSTED WHEN THE PROBLEM WAS  
FOUND AND NO ACTION WAS REQUIRED BY TECHNICAL SPECIFICATIONS.

