



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

June 25, 1980

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,
the following report/s are submitted:

RO 80-011/03L-0.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.S. Hunter
R.W. Jurgensen
R.F. Kroeger
R.W. Kilburn
R.E. Masse RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
G. Olson
J.M. Hennigan
W. Lavallee EPRI
PNSRC
J.F. Stietzel
E.L. Townley
Dir.; IE (30 copies)
Dir.; MIPC (3 copies)

JUN 27 1980

8006300502

1002
5/11

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6 (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4		5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0	1	L	6	0	5	0	0	0	3	1	5	7	0	5	3	1	8	0	8	0	6	2	5	8	0	9	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 WITH THE UNIT IN A SHUTDOWN MODE (3) THE CONTAINMENT ATMOSPHERE AIR PARTICULATE

0 3 AND GASEOUS RADIATION MONITORING SYSTEM PUMP TRIPPED ON LOW FLOW. THE PUMP WOULD

0 4 NOT RESTART WITHOUT GIVING A LOW FLOW ALARM AND WAS DECLARED INOPERABLE. CON-

0 5 TAINMENT PURGE WAS IMMEDIATELY ISOLATED. THIS CONDITION IS NON-CONSERVATIVE WITH

0 6 RESPECT TO T.S. 3.3.3.1 AND T.S. 3.4.6.1. THE APPLICABLE ACTION REQUIREMENTS

0 7 WERE FULFILLED. PREVIOUS SIMILAR EVENTS INCLUDE : 050-315/79-8,12,48 AND 050-

0 8 316/80-13,18,22,23, 79-34.

0	9	B	B	11	E	12	F	13	I	N	S	T	R	U	14	X	15	Z	16	17	8	0	1	1	0	3	L	0	C	X	Z	Z	0	0	0	0	Y	Y	N	F	1	2	0
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE INVESTIGATION REVEALED THAT THE FLOWMETER WAS INACCURATE AND CAUSING THE

1 1 PUMP TRIPS. THE FLOWMETER MANUFACTURED BY FISHER AND PORTER-MODEL NO. 10A2235,

1 2 WAS REPLACED AND THE SAMPLE SYSTEM WAS DECLARED OPERABLE. UPON INSPECTION, THE

1 3 FLOWMETER INDICATED SIGN OF WEAR. THE SAMPLE PUMP FLOWMETERS FOR BOTH UNITS HAVE

1 4 BEEN ADDED TO A PREVENTATIVE MAINTENANCE PROGRAM, (SEE ATTACHED SUPPLEMENT)

1	5	G	28	0	0	0	29	NA	A	31	AUDIBLE ALARM	32	33	Z	34	NA	35	NA	36	37	0	0	0	38	Z	39	NA	40	0	0	0	41	NA	42	NA	43	NA	44	N	45	NA		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION
PERSONNEL INJURIES NUMBER DESCRIPTION
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION
PUBLCITY DESCRIPTION
ISSUED DESCRIPTION

NAME OF PREPARER S. D. DeLong

PHONE: 616-465-5901

NRC USE ONLY

ATTACHMENT TO LER #80-011/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

WHICH WILL INSURE THE FLOWMETERS ARE INSPECTED ON A ROUTINE BASIS.