

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8706240019 DOC. DATE: 87/06/17 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316
 AUTH. NAME AUTHOR AFFILIATION
 SMITH, W. G. Indiana & Michigan Electric Co.
 RECIP. NAME RECIPIENT AFFILIATION
 DAVIS, A. B. Document Control Branch (Document Control Desk)

SUBJECT: RO: on 840707, part of Unit 1 inside fire protection ring
 header removed from svc for repairing valves in fire sys.
 Isolation removed Tech Spec fire hose standpipe. Addl hose
 used for backup. Verbal rept made & sys repaired within 24 h.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-3 LA	1	PD3-3 PD	1
	WIGGINGTON, D	1		
INTERNAL:	ACRS MICHELSON	1	ACRS MOELLER	2
	AEOD/DOA	1	AEOD/DSP/ROAB	2
	AEOD/DSP/TPAB	1	DEDRO	1
	NRR/DEST/ADE	1	NRR/DEST/ADS	1
	NRR/DEST/CEB	1	NRR/DEST/ELB	1
	NRR/DEST/ICSB	1	NRR/DEST/MEB	1
	NRR/DEST/MTB	1	NRR/DEST/PSB	1
	NRR/DEST/RSB	1	NRR/DEST/SGB	1
	NRR/DLPQ/HFB	1	NRR/DLPQ/QAB	1
	NRR/DOEA/EAB	1	NRR/DREP/RAB	1
	NRR/DREP/RPB	2	NRR/PMAS/ILRB	1
	NRR/PMAS/PTSB	1	REG FILE 02	1
	RES DEPY GI	1	RGN3 FILE 01	1
EXTERNAL:	EG&G GROH, M	5	H ST LOBBY WARD	1
	LPDR	1	NRC PDR	1
	NSIC HARRIS, J	1	NSIC MAYS, G	1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 42 ENCL 40



INDIANA & MICHIGAN ELECTRIC COMPANY

Donald C. Cook Nuclear Plant
P.O. Box 458, Bridgman, Michigan 49106

June 17, 1987

Donald C. Cook Nuclear Plant Unit Nos. 1 and 2
Docket Nos. 50-315 and 50-316
License Nos. DPR-58 and DPR-74

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Attn: A. B. Davis


Dear Mr. Davis:

On July 7, 1984, a portion of the Unit 1 inside fire protection ring header was removed from service to facilitate repairs on three valves in the Fire System. This isolation removed numerous non-Technical Specification Fire Hose Standpipe and Suppression Systems from service, as well as one Technical Specification fire hose standpipe. The requirements of Technical Specification 3.7.9.5, Fire Hose Stations, were met in that an additional fire hose of equivalent capacity was routed to the area of the inoperable Technical Specification fire hose standpipe within one hour, and the entire Fire Protection System was returned to service within 24 hours.

The requirements of Technical Specification 3.7.9.1 Action b2a were met in that a verbal report was made by telephone to the NRC Operations Center within 24 hours of the isolation. However, due to a weakness in our administrative tracking procedures, which existed at that time, and the fact that the incident was internally categorized as non-reportable, the follow-up reports as required by Technical Specification 3.7.9.1 Action b2b and c were never made. Following a recent review of this incident, it was determined that a follow-up report should be filed.

Prior to discovery of this reporting error, we had already implemented internal policies that will more effectively track system impairments and reporting requirements and will help to minimize the chances of this type of error happening in the future.

Respectfully,


W.G. Smith, Jr.

cc: See Attached Distribution

8706240019 870617
PDR ADDCK 05000315
S PDR

IE22
1/0

cc: A. B. Davis, Region III
R. C. Callen, MPSC
D. Hahn, MDPH
G. Charnoff, Esq.
Dottie Sherman, ANI Library
INPO
J. E. Dolan
M. P. Alexich
R. F. Kroeger
H. B. Brugger
R. W. Jurgensen
NRC Resident Inspector
PNSRC
A. A. Blind
D. L. Wigginton, NRC