

ACCESSION NBR: 8805270021 DDC DATE 88/05/19 NOT INDEXED NO
 FACIL. 50-315 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana 3 000. 11
 AUTH. NAME AUTHOR AFFILIATION
 POSTLEWAIT, T. K. American Electric Power Co., Inc.
 SMITH, W. G. American Electric Power Co., Inc.
 SMITH, W. G. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 88-005-00: on 880426, insp revealed ice buildup in ice
 condenser flow passages. Caused by sublimation of ice or high
 humidity in containment air. Flow passages were manually
 cleaned & impact of buildup studied. W/880519 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 7
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1 1	PD3-1 PD	1 1
	STANG, J	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	AEOD/DOA	1 1	AEOD/DSP/NAS	1 1
	AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1
	ARM/DCTS/DAB	1 1	DEDRO	1 1
	NRR/DEST/ADS 7E	1 0	NRR/DEST/CEB 8H	1 1
	NRR/DEST/ESB 8D	1 1	NRR/DEST/ICSB 7	1 1
	NRR/DEST/MEB 9H	1 1	NRR/DEST/MTB 9H	1 1
	NRR/DEST/PSB 8D	1 1	NRR/DEST/RSB 8E	1 1
	NRR/DEST/SGB 8D	1 1	NRR/DLPQ/HFB 10	1 1
	NRR/DLPQ/QAB 10	1 1	NRR/DOEA/EAB 11	1 1
	NRR/DREP/RAB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS/SIB 9A	1 1	NRR/PMAS/ILRB12	1 1
	NUDOCS-ABSTRACT	1 1	REG FILE 02	1 1
	RES TELFORD, J	1 1	RES/DE/EIB	1 1
	RES/DRPS DEPY	1 1	RGN3 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS, S	4 4	FORD BLDG HOY, A	1 1
	H ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC HARRIS, J	1 1
	NSIC MAYS, G	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 ENCL 45

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) D. C. Cook Nuclear Plant - Unit 2										DOCKET NUMBER (2) 0 5 0 0 0 3 1 6					PAGE (3) 1 OF 0 7								
TITLE (4) Ice Buildup in Ice Condenser Flow Passages Due to Sublimation																							
EVENT DATE (5)			LER NUMBER (6)				REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)													
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBER(S)										
0	4	2	6	8	8	8	8	0	0	5	0	0	0	5	1	9	8	8	0	5	0	0	0
OPERATING MODE (9)		5		THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																			
POWER LEVEL (10)		0 0 0		20.402(b)				20.406(e)				50.73(a)(2)(iv)				73.71(b)							
				20.406(a)(1)(i)				50.38(e)(1)				50.73(a)(2)(v)				73.71(e)							
				20.406(a)(1)(ii)				50.38(e)(2)				50.73(a)(2)(vi)				<input checked="" type="checkbox"/> OTHER (Specify in Abstract below and in Text, NRC Form 364A)							
				20.406(a)(1)(iii)				50.73(a)(2)(i)				50.73(a)(2)(vii)(A)											
				20.406(a)(1)(iv)				50.73(a)(2)(ii)				50.73(a)(2)(vii)(B)											
				20.406(a)(1)(v)				50.73(a)(2)(iii)				50.73(a)(2)(x)											
LICENSEE CONTACT FOR THIS LER (12)																							
NAME T. K. Postlewait - Technical Engineering Superintendent										TELEPHONE NUMBER AREA CODE 6 1 6 4 6 5 - 5 9 0 1													
COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)																							
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC				
SUPPLEMENTAL REPORT EXPECTED (14)										EXPECTED SUBMISSION DATE (15)			MONTH DAY YEAR										
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)										<input checked="" type="checkbox"/> NO													
ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)																							
<p>On April 26, 1988, with Unit 2 in Mode 5 (Cold Shutdown), flow passage inspections of the ice condenser revealed frost and ice buildup on the lattice frames of greater than 3/8 inch in a total of four flow passages in one of the twenty-four ice condenser bays.</p> <p>Technical Specification (T/S) 4.6.5.1.b.3 limits frost or ice buildup in flow passages to a nominal thickness of 3/8 inch. According to this T/S, buildup exceeding this limit in two or more flow passages per bay is evidence of abnormal degradation. Though our evaluation has concluded that the degradation is not serious, we believe issuance of this voluntary LER is appropriate since some degradation has been identified.</p> <p>Actions taken to correct the abnormal degradation included manual cleaning of the flow passages and an internal investigation of the event. The results of T/S Surveillances regarding frost and ice that forms in the flow passages is being monitored to ensure that any adverse trends in the amount of ice and frost buildup between surveillances will be identified. The impact of frost and ice buildup in the flow passages is also being studied in conjunction with the other utilities with ice condenser containments.</p>																							
8805270022 880519 PDR ADDOCK 05000316 S PDR																							

FACILITY NAME (1) D. C. Cook Nuclear Plant - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 1 6 8 8 - 0 0 5 - 0 0 0 2 OF 0 7	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 368A's) (17)

Conditions Prior to Occurrence

Unit 2 in Mode 5 (Cold Shutdown)

Description of Event

The as-found visual inspection ice condenser (EIIS/COND) flow passages conducted on April 26, 1988, indicating frost and ice accumulation greater than 3/8 inch in two flow passages in Bay 4. Subsequently, the inspection was expanded to include at least twenty additional flow passages in that bay. This inspection revealed an additional two flow passages with more than 3/8 inch frost and ice buildup. A total of 4 flow passages were affected. There are a total of 3072 flow passages in the Ice Condenser. Attachments 1 through 6 graphically describe the geometry of the flow passages and the location of the ice/frost accumulation.

Technical Specification (T/S) 4.6.5.1.b.3 requires that the ice condenser be determined operable at least once per 9 months by verifying, via visual inspection of at least two flow passages per ice condenser bay, that accumulation of frost or ice on flow passages between ice condenser bay, that accumulation of frost or ice on flow passages between ice baskets (EIIS/COND-BSKT), past lattice frames (EIIS/COND-FRM), through the intermediate and top deck floor grating, or past the lower inlet plenums support structures (EIIS/COND-SPT) and turning vanes is restricted to a nominal thickness of 3/8 inch. If one flow passage per bay is found to have an accumulation of frost or ice greater than this thickness, a representative sample of twenty additional flow passages from the same bay shall be visually inspected. If these additional flow passages are found acceptable, the surveillance program may proceed considering the single deficiency as unique and acceptable. More than one restricted flow passage per bay is evidence of abnormal degradation of the ice condenser.

The affected flow passages were manually cleaned to remove the accessible frost and ice buildup.

During the surveillance interval prior to the April 26, 1988, test several of the 60 air handling units (AHU) (EIIS/AHU) (used to maintain ice condenser temperature) were intermittently inoperable for maintenance and/or repair. However, it has been concluded that the inoperability of the AHU's did not significantly contribute to the frost and ice formation experienced.

With the exception of the AHU's, there were no inoperable structures, components or systems that contributed to this event.

FACILITY NAME (1) D. C. Cook Nuclear Plant - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 1 6 8 8 — 0 0 5 — 0 0	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		8 8	0 0 5	0 0	0 3	OF	0 7

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Cause of Event

It is believed that sublimation of ice or high humidity in the containment air could have contributed to this problem. Further investigation of this event is ongoing.

Analysis of Event

The Westinghouse evaluation indicated that lattice frost/ice formation of up to 20 percent of the total flow passage area could be present without the peak Ice Condenser Compartment Pressure exceeding the design limit. Since the frost/ice buildup identified in Bay 4 constitute a total flow blockage area which is less than 20 percent limit, this situation is bounded by the Westinghouse evaluation.

Our evaluation indicates that the amount of flow blockage due to frost and ice buildup noted in the Ice Condenser can be tolerated without adversely affecting the Ice Condenser function during a Loss of Coolant Accident.

Based on the above information and the Westinghouse evaluation, it is concluded that the abnormal degradation event does not constitute an unreviewed safety question as defined in 10CFR50.59(a)(2), nor does it adversely impact health and safety.

Though our evaluation has concluded that the degradation is not serious, we believe issuance of this voluntary LER is appropriate since some degradation has been identified.

Corrective Actions

The corrective action was to manually clean the flow passages to remove the accessible frost and ice buildup.

The results of Technical Specification Surveillances regarding frost and ice that forms in the flow passages is being monitored to ensure that any adverse trends in the amount of ice and frost buildup between surveillances will be identified. The impact of frost and ice buildup in the flow passages is also being studied in conjunction with the other utilities with ice condenser containments.

Failed Component Identification

No component failures were identified during this event.

FACILITY NAME (1) D. C. Cook Nuclear Plant - Unit 2	DOCKET NUMBER (2) 0 5 0 0 3 1 6 8 8 - 0 0 5 - 0 0 0 4 OF 0 7	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Previous Similar Events

LER 50-316/85-013
LER 50-316/86-002
LER 50-315/86-013
LER 50-316/87-002
LER 50-315/87-013
LER 50-316/87-010
LER 50-315/88-002

FACILITY NAME (1) D. C. Cook Nuclear Plant - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 1 6 8 8	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		0	0	5	0	0	7

TEXT (If more space is required, use additional NRC Form 366A's) (17)

ATTACHMENT 1

Description of Flow Passage Blockage by Category (affected Flow Passages are indicated by the boxed areas on the following attachments).

Category	Description*
A	Maximum Flow Passage Ice/Frost Blockage greater than 75 percent.
B	Maximum Flow Passage Ice/Frost Blockage between 50 and 75 percent.
C	Maximum Flow Passage Ice/Frost Blockage between 25 and 50 percent.
D	Maximum Flow Passage Ice/Frost Blockage less than 25 percent (but greater than 3/8" buildup).


* NOTE: These are generalized categories which reflect the maximum ice/frost blockage found in a particular flow passage and in general was limited to one or two lattice frameworks in the flow passage. This does not indicate that the flow passage was blocked it's entire length. Lattice Framework is located at the positions of cruciforms in the ice basket. Cruciforms are installed every six feet within the 48 foot ice basket (for convention the "top" lattice framework is referred to as number 1, etc.). The specific lattice frameworks affected are indicated on the individual Bay drawings (Attachment 3).

FACILITY NAME (1) D. C. Cook Nuclear Plant - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 1 6 8 8 — 0 0 5 — 0 0	LER NUMBER (6)			PAGE (3)				
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER					
		8	8	—	0	0	5	—	0

TEXT (If more space is required, use additional NRC Form 368A's) (17)

ATTACHMENT 2

Representative Diagram of Ice/Frost Buildup in Two Flow Passages



Scale:

1/2 inch equals 1 inch


FACILITY NAME (1) D. C. Cook Nuclear Plant - Unit 2	DOCKET NUMBER (2) 0 5 0 0 0 3 1 6 8 8 - 0 0 5 - 0 0 0 7 OF 0 7	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

ATTACHMENT 3

Bay 4 (of 24 total)

Azimuthal Row (Basket)



NOTE: The Lattice Frameworks affected are indicated in parenthesis after the category description number (see ATTACHMENT 1).



May 19, 1988

United States Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Operating License DPR-58
Docket No. 50-316

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73
entitled Licensee Event Reporting System, the following
report is being submitted:

88-005-00

Sincerely,

W. G. Smith, Jr.
Plant Manager

WGS:clw

Attachment

cc: D. H. Williams, Jr.
A. B. Davis, Region III
M. P. Alexich
R. F. Kroeger
H. B. Brugger
R. W. Jurgensen
NRC Resident Inspector
J. F. Stang, NRC
R. C. Callen
G. Charnoff, Esq.
Dottie Sherman, ANI Library
D. Hahn
INPO
PNSRC
A. A. Blind
P. A. Barrett/P. Lauzau

IE22
1/1