

LICENSEE EVENT REPORT (LER)

(See reverse for required number of
digits/characters for each block)ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS MANDATORY
INFORMATION COLLECTION REQUEST: 500 HRS. REPORTED LESSONS LEARNED ARE
INCORPORATED INTO THE LICENSING PROCESS AND FED BACK TO INDUSTRY.
FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE INFORMATION AND
RECORDS MANAGEMENT BRANCH (7-6 F33), U.S. NUCLEAR REGULATORY
COMMISSION, WASHINGTON, DC 20555-0001, AND TO THE PAPERWORK REDUCTION
PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC
20503

FACILITY NAME (1) Cook Nuclear Plant Unit 1					DOCKET NUMBER (2) 05000-315		PAGE (3) 1 of 1	
--	--	--	--	--	--------------------------------	--	--------------------	--

TITLE (4) Calculations Show that the Divider Barrier Between Upper and Lower Containment Volumes May Be Overstressed								
---	--	--	--	--	--	--	--	--

EVENT DATE (5)			LER NUMBER (6)					REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER		REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAME Cook Unit 2	DOCKET NUMBER 05000-316	
10	20	1998	1999	--	007	--	00	04	01	1999	FACILITY NAME DOCKET NUMBER	
OPERATING MODE (9)		5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more) (11)									
			20.2201 (b)				20.2203(a)(2)(v)			50.73(a)(2)(i)	50.73(a)(2)(viii)	
POWER LEVEL (10)		00	20.2203(a)(1)				20.2203(a)(3)(i)		X	50.73(a)(2)(ii)	50.73(a)(2)(x)	
			20.2203(a)(2)(i)				20.2203(a)(3)(ii)			50.73(a)(2)(iii)	73.71	
			20.2203(a)(2)(ii)				20.2203(a)(4)			50.73(a)(2)(iv)	OTHER	
			20.2203(a)(2)(iii)				50.36(c)(1)			50.73(a)(2)(v)	Specify in Abstract below or on NRC Form 366A	
			20.2203(a)(2)(iv)				50.36(c)(2)			50.73(a)(2)(vii)		

LICENSEE CONTACT FOR THIS LER (12)

NAME Mr: Donald C. Kosloff, Compliance Engineer					TELEPHONE NUMBER (Include Area Code) 616/465-5901, X2129				
--	--	--	--	--	---	--	--	--	--

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

SUPPLEMENTAL REPORT EXPECTED (14)

X	YES (If Yes, complete EXPECTED SUBMISSION DATE).	NO	EXPECTED SUBMISSION DATE (15)		MONTH 08	DAY 20	YEAR 1999
---	---	----	-------------------------------------	--	-------------	-----------	--------------

Abstract (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) (16)

While working on a preliminary calculation for the Unit 1 steam generator replacement project, it was concluded that some of the structural load cases indicated overstressed conditions in the steam generator enclosures. Based on these preliminary analyses, on October 20, 1998, with both units in Mode 5, engineering personnel determined that a postulated steam line break could result in calculated stresses exceeding the code allowable stresses for the Unit 1 steam generator enclosures. These reinforced concrete enclosures are part of the divider barrier between the upper and lower containment volumes. Overstressed conditions in these enclosures could allow increased steam bypass flow around the ice condensers which could result in higher than expected containment pressure.

When the potential overstress conditions were identified, it was concluded that the conditions could be due to significant conservatism in the preliminary calculation and in its interpretation. Engineering continued their evaluation of this issue. However, as evaluations continued, a lack of information confirming an acceptable condition led to the conclusion that there was no longer a reasonable expectation that the structures would not be overstressed. On March 2, 1999, with both units still in Mode 5, the apparent overstress conditions were determined to be reportable under 10CFR50.72(b)(2)(i) and 50.73(a)(2)(ii). Based on this determination, an ENS notification was made on March 2, 1999, at 1314 hours in accordance with 10CFR50.72(b)(2)(i).

Structural engineers are currently developing appropriate analyses of the loads and stresses on the enclosures. The results of these analyses will determine if an overstressed condition could have occurred and, if so, the safety significance of the overstressed condition. Appropriate corrective action will be developed based on an evaluation of the analytical results.

9904070426 990401
PDR ADOCK 05000315
S PDR