

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5					
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT	58			59

CON'T

0 1
7 8

REPORT SOURCE L 6 0 5 0 0 0 3 1 6 7 0 9 1 1 7 9 8 1 0 1 0 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | DURING A SURVEILLANCE TEST ON PRESSURIZER PRESSURE-PROTECTION SET I,
0 3 | THE HIGH PRESSURE REACTOR TRIP BISTABLE WAS FOUND TO TRIP AT A SET-
0 4 | POINT CORRESPONDING TO 2417 PSIG. THIS EXCEEDED THE REACTOR TRIP
0 5 | VALUE SPECIFIED IN T.S. TABLE 2.2-1.
0 6 |
0 7 |
0 8 |
7 8 9

09		SYSTEM CODE IA		11	CAUSE CODE E		12	CAUSE SUBCODE G		13	COMPONENT CODE INSTRUR				14	COMP. SUBCODE S		15	VALVE SUBCODE Z		16																																						
7	8	9	10		11			12		13					14		15		16																																								
17		LER/RO REPORT NUMBER		EVENT YEAR 79		21	22	SEQUENTIAL REPORT NO. 032		24	25	26	OCCURRENCE CODE 03		28	29	REPORT TYPE L		30	31	REVISION NO. 0		32																																				
33		ACTION TAKEN C		FUTURE ACTION Z		34	35	EFFECT ON PLANT Z		36	SHUTDOWN METHOD Z		37	HOURS 000		40	ATTACHMENT SUBMITTED Y		41	NPRD-4 FORM SUB. Y		42	PRIME COMP. SUPPLIER A		43	COMPONENT MANUFACTURER F180		44	45	46	47																												
18		19		20		21		22		23		24		25		26		27		28		29		30		31		32		33		34		35		36		37		38		39		40		41		42		43		44		45		46		47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 ON SEPTEMBER 11, THE BISTABLE WAS ADJUSTED TO WITHIN ALLOWABLE VALUES

1 1 AND RETURNED TO OPERATION. ON SEPTEMBER 18, A RECHECK OF THE BISTABLE

1 2 TRIP VALUE INDICATED THAT THE BISTABLE HAD AGAIN DRIFTED, THIS TIME

1 3 IN A CONSERVATIVE DIRECTION. THIS BISTABLE WAS DETERMINED TO BE

1 4 INOPERABLE AND THE ACTION REQUIREMENT (SEE SUPPLEMENT)

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION									
1	5	E (28)	1	0	0	29	NA	30	B	31	SURVEILLANCE TEST			32							
7	8	9	10	11	12	13	14	15	16	17	18	19	20								
ACTIVITY CONTENT			AMOUNT OF ACTIVITY			LOCATION OF RELEASE															
1	6	Z (33)	Z	34	35	NA	36	37	38	39	40	41	42								
7	8	9	10	11	12	13	14	15	16	17	18	19	20								
PERSONNEL EXPOSURES			DESCRIPTION																		
1	7	0	0	0	37	Z	38	39													
7	8	9	10	11	12	13	14	15	16	17	18	19	20								
PERSONNEL INJURIES			DESCRIPTION																		
1	8	0	0	0	40	NA	41														
7	8	9	10	11	12	13	14	15	16	17	18	19	20								
LOSS OF OR DAMAGE TO FACILITY			DESCRIPTION																		
1	9	Z	42	43	NA	44															
7	8	9	10	11	12	13	14	15	16	17	18	19	20								
PUBLICITY			DESCRIPTION																		
2	0	N	44	45	NA	46															
7	8	9	10	11	12	13	14	15	16	17	18	19	20								
ISSUED										NRC USE ONLY											
2	0																				
7	8	9	10	11	12	13	14	15	16	17	18	19	20								

NAME OF PREPARER

J. L. Rischling

PHONE:

616-465-5901

SUPPLEMENT TO LER #79-032/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

OF T.S. TABLE 3.3-1 ITEM 10 WAS MET. THE DEFECTIVE BISTABLE, MANUFACTURED BY FOXBORO-MODEL NUMBER 63U-AC-OHBA-F, WAS REPLACED. THE NEW BISTABLE WAS CALIBRATED AND SET TO TRIP AT THE PROPER VALUE. A RECHECK OF THE NEW BISTABLE TRIP SETPOINT ON SEPTEMBER 20, INDICATED THAT THIS BISTABLE WAS FUNCTIONING PROPERLY.

