

## LICENSEE EVENT REPORT

[illegible]

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	0	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER													25	26	LICENSE TYPE					30	57	CAT		58

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	3	1	6	7	1	0	1	1	7	9	8	1	1	0	9	7	9	9
60	61								68	69						74	75							80
DOCKET NUMBER										EVENT DATE								REPORT DATE						

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | WHILE DEVELOPING AND TESTING A NEW PROGRAM ON THE P-250 COMPUTER.

0 3 | A SECTOR OF DISC WHERE THE CONSTANTS FOR THE DELTA FLUX PROGRAM

0 4 | ARE STORED, WAS ACCIDENTLY WRITTEN OVER. THIS RESULTED IN AN

0 5 | INOPERABLE AXIAL FLUX DIFFERENCE ALARM FOR 18 HOURS AND 39 MINUTES.

0 6 | THE CONTROL ROOM PERSONNEL WERE UNAWARE OF THIS INOPERABILITY AND

0 7 | THEREFORE THE SURVEILLANCE REQUIREMENTS OF T.S. 4.2.1.1.b WERE

0 8 | MISSED DURING THIS TIME PERIOD.

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE	
I D		A		C		X	X	X	X	X	X	Z	Z		
(11)		(12)		(13)		(14)						(15)		(16)	
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
7 9		0 3 6		0 3		L		0							
(17)		(22)		(23)		(24)		(25)							
ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER							
H	Z	Z	Z	0 0 0 0	Y	N	N	W 1 2 0							
(18)	(19)	(20)	(21)	(22)	(23)	(24)	(25)	(26)							

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE DISC AREA BEING USED FOR THE NEW PROGRAM DEVELOPMENT WAS

1 1 ADJACENT TO THE STORAGE AREA WHERE THE CONSTANTS FOR THE

1 2 DELTA-FLUX PROGRAM ARE STORED. THESE CONSTANTS WERE ACCIDENTLY

1 3 WRITTEN OVER. UPON DISCOVERY THE PROGRAM WAS IMMEDIATELY

1 4 DISABLED. SEE SUPPLEMENT.

7	8	9											80			
FACILITY STATUS		% POWER			OTHER STATUS (30)			METHOD OF DISCOVERY		DISCOVERY DESCRIPTION (32)					80	
1	5	E	28	1	0	0	29	NA	B	31	ROUTINE INSPECTION					80
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	

ACTIVITY CONTENT  
RELEASED OF RELEASE

1 6 7 8 9 10 11

7 8 9 10 11

NA

AMOUNT OF ACTIVITY (35)

45 80

LOCATION OF RELEASE (36)

PERSONNEL EXPOSURES									
NUMBER				TYPE	DESCRIPTION				
1	7	0	0	0	37	Z	38	NA	39

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	NA

8		9		11		12	
1		9		Z		(42)	
TYPE		DESCRIPTION		(43)			
NA						7911160432	

7 8 9 10 68 69 80

PUBLICITY  
ISSUED (44) DESCRIPTION (45) NA

NRC USE ONLY

NAME OF PREPARER J. L. Rischling

PHONE: 616-465-5901



SUPPLEMENT TO LER #79-036/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THE CORRECT VALUES FOR THE DELTA-FLUX PROGRAM WERE RESTORED AND THE AXIAL FLUX DIFFERENCE ALARM WAS RETURNED TO AN OPERABLE STATUS. THE NEW PROGRAM WAS THEN MODIFIED, AND SUBSEQUENT TESTS INDICATED THE PROBLEM HAS BEEN RESOLVED. TO PREVENT RECURRENCE, FUTURE PROGRAM DEVELOPMENT WILL BE CONDUCTED ON DISC AREAS THAT ARE NOT ADJACENT TO WORKING FILE AREAS.

