



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

November 15, 1979

Mr. J.G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-74
Docket No. 50-316

Dear Mr. Keppler:

This is to confirm our verbal report to NRC Region III Inspector,
Mr. R.E. Masse, at 1035 hours on November 15, 1979.

At that time we reported that with the unit in Mode 6 the charging
flow path was found isolated at the Boron Injection Tank at both
inlet and outlet valves. Since the normal charging flow path was
already isolated, this constituted an unavailable flow path.
Upon discovery of this situation, we immediately returned the
valve lineup to service and verified flow.

A followup report will be submitted by November 28, 1979, as
required by Technical Specification Section 6.9.1.8.

Sincerely,

D.V. Shaller
Plant Manager

/bab

cc: J.E. Dolan
R.W. Jurgensen
R.F. Kroeger
R.W. Kilburn
R.J. Vollen BPI
R.E. Masse RO:III
R.C. Callen MPSC
P.W. Steketee, Esq.
R. Walsh, Esq.
G. Charnoff, Esq.

G. Olson
J.M. Hennigan
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (40 copies)
Dir., MIPC (4 copies)

1007
5/10

MA
K

60
356

S 7911200