

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | I | D | C | C | 2 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | | 5

7 8 9 14 15 25 26 30 57 58

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT

L	6	0	5	0	0	0	3	1	6	7	1	0	1	9	7	9	8	1	1	1	9	7	9	9
60	61	DOCKET NUMBER						68	EVENT DATE						74	REPORT DATE						80		

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | THE 600 VOLT FEED BREAKER TO CENTRIFUGAL CHARGING PUMP EMERGENCY LEAKOFF VALVE

0 3 | QMO-225 WAS FOUND OPEN AT 0135 HOURS. THIS IS CONTRARY TO T.S. 3.5.2. THIS

0 4 | BREAKER HAD BEEN VERIFIED CLOSED 10 HOURS PREVIOUSLY. REDUNDANT VALVE QMO-226

0 5 | WAS POWERED AND FULLY OPERABLE DURING THIS TIME.

0 6 |

0 7 |

0 8 |

7 8 9 8

7 8 9		SYSTEM CODE E B (11)		CAUSE CODE X (12)		CAUSE SUBCODE Z (13)		COMPONENT CODE Z Z Z Z Z (14)				COMP. SUBCODE Z (15)		VALVE SUBCODE Z (16)	
0 9 7 8		9 10		11		12		13 18				19		20	
(17) LER/RO REPORT NUMBER		EVENT YEAR 7 9 21 22		23		SEQUENTIAL REPORT NO. 0 3 7 24 26		27		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		31	
ACTION TAKEN H (18)		FUTURE ACTION Z (19)		EFFECT ON PLANT Z (20)		SHUTDOWN METHOD Z (21)		HOURS 0 0 0 22 40		ATTACHMENT SUBMITTED Y (23)		NPRD-4 FORM SUB. N (24)		PRIME COMP. SUPPLIER Z (25)	
33		34		35		36		37		41		42		43	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER	
Z 9 9 (26)															
44		45		46		47		48		49		50		51	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A CONSTRUCTION ELECTRICIAN WAS IDENTIFIED WHO HAD BEEN WORKING ON A LADDER VERY
1 1 CLOSE TO THE FRONT OF THE BREAKER PANEL. IT IS APPARENT THAT AS HE CAME DOWN THE
1 2 LADDER HIS FOOT ACCIDENTLY OPERATED THE BREAKER. ALL BREAKER PANELS HAVE A
1 3 MARKED OFF FLOOR AREA 'IN FRONT AND REAR MARKED "KEEP CLEAR". THIS MAN'S JOB
1 4 REQUIRED FOR HIM TO WORK IN THE "KEEP CLEAR" AREA. HE AND ALL (CONTINUED PG.2)

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	1	0	0	29	NA	30
7	8	9	10	11	12	13	14	15	16
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		OPERATOR OBSERVATION	
1	6	7	33	8	34	35	36	37	38
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	8	37	9	38	39	40	41	42
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	9	40	41	42	43	44	45	46
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	10	42	43	44	45	46	47	48
7	8	9	10	11	12	13	14	15	16
PUBLICITY		ISSUED		DESCRIPTION					
2	0	1	44	45	46	47	48	49	50
7	8	9	10	11	12	13	14	15	16

NAME OF PREPARER H. M. CHADWELL

PHONE: (616) 465-5901 X-316



10-10-10

CONTINUATION OF LER # 79-037/03L-0
PAGE 2

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS:

OTHER ELECTRICIANS HAVE BEEN AGAIN VERBALLY INFORMED TO USE EXTREME CAUTION WHEN WORKING WITHIN THESE AREAS.

A DEDICATED INSPECTOR WILL BE ASSIGNED TO CONTINUOUSLY MONITOR CONSTRUCTION WORK IN THE AUXILIARY BUILDING. HE HAS BEEN INSTRUCTED TO SEE THAT CONSTRUCTION PERSONNEL OBSERVE THE "KEEP CLEAR" AREAS AND THAT THE MOTOR CONTROL CENTERS ARE NOT DISTURBED. THIS ASSIGNMENT WILL BECOME EFFECTIVE NOVEMBER 20, 1979.

