

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 1 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 1 1 0 8 7 9 8 1 2 0 7 7 9 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 DURING THE PERFORMANCE OF A SURVEILLANCE TEST PROCEDURE, ECR-31 (CONTAINMENT
0 3 ISOLATION VALVE FOR THE CONTAINMENT AIR PARTICULATE DETECTOR) WOULD NOT CLOSE.
0 4 THIS CONDITION IS NON-CONSERVATIVE WITH RESPECT TO T.S. 3.6.3.1.
0 5
0 6
0 7
0 8

0 9 SYSTEM CODE S D 11 CAUSE CODE E 12 CAUSE SUBCODE X 13 COMPONENT CODE V A L V E X 14 COMP. SUBCODE X 15 VALVE SUBCODE X 16
7 8 9 10 11 12 13 18 19 20
17 LER/RO REPORT NUMBER 7 9 21 22 EVENT YEAR 23 24 25 26 27 SEQUENTIAL REPORT NO. 28 29 OCCURRENCE CODE 30 31 REPORT TYPE 32 REVISION NO. 0
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS 22 ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
D 18 Z 19 Z 20 Z 21 0 0 0 0 Y 23 Y 24 N 25 A 4 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE FAILURE OF ECR-31 WAS FOUND TO BE AN ASCO SOLENOID AIR SUPPLY VALVE LEAKING
1 1 BY, AND A 1/4 INCH TUBE ON THE VENT PORT OF THE SAME ASCO CAUSING A RESTRICTION
1 2 IN AIR FLOW. THE COMBINATION OF THESE TWO CONDITIONS KEPT AIR ON THE DIAPHRAM
1 3 OF ECR-31 NOT ALLOWING IT TO CLOSE.
1 4 SEE ATTACHED SUPPLEMENT.

1 5 FACILITY STATUS G 28 % POWER 0 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 SURVEILLANCE TEST 32 DISCOVERY DESCRIPTION
7 8 9 10 12 13 44 45 46 80
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 44 45 80
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
7 8 9 10 11 12 13 80
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8 9 10 11 12 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
7 8 9 10 80
2 0 ISSUED DESCRIPTION 45
7 8 9 10 80

NAME OF PREPARER S. D. DeLong

PHONE: 616-46-5901

NRC USE ONLY

SUPPLEMENT TO LER #79-059/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THE ASCO SOLENOID VALVE WAS CLEARED OF DIRT BUILD-UP AND THE ¼ INCH
VENT LINE WAS REMOVED. TO INCREASE THE VENT AREA.

NO FURTHER ACTION IS PLANNED.

