

## LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 1 2 0 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 5 7 1 1 1 1 7 9 8 1 2 1 1 7 9 9  
7 8 60 61 68 69 74 75 80

## EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 AN INOPERABLE STEAM FLOW CHANNEL (CHANNEL I) WAS TAKEN OUT OF THE TRIP CONDITION  
0 3 FOR A PERIOD OF 25 MINUTES.  
0 4 THIS ACTION WAS NON CONSERVATIVE WITH RESPECT TO T.S. TABLE 3.3-1 ITEM 15  
0 5 AND TABLE 3.3-3 ITEMS 1f AND 4d.  
0 6  
0 7  
0 8

0 9 SYSTEM CAUSE CAUSE COMPONENT COMP. VALVE  
CODE CODE SUBCODE CODE SUBCODE SUBCODE  
I A 11 A 12 C 13 I N S T R U 14 X 15 Z 16  
9 10 11 12 13 18 19 20  
17 LER/RO EVENT YEAR SEQUENTIAL OCCURRENCE REPORT REVISION  
NUMBER 17 9 0 6 2 0 3 L 0  
21 22 23 24 26 27 28 29 30 31 32  
ACTION FUTURE EFFECT SHUTDOWN HOURS ATTACHMENT NPRD-4 PRIME COMP. COMPONENT  
TAKEN ACTION ON PLANT METHOD 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURER  
X 18 F 19 Z 20 Z 21 0 0 0 0 Y 23 N 24 A 25 B 0 8 0 26  
33 34 35 36 37 40 41 42 43 44 47

## CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 DURING THE INVESTIGATION OF OUT OF SPECIFICATION READING ON MFC140 (CHANNEL I  
1 1 STEAM FLOW) THE BISTABLES FOR THAT CHANNEL WERE PLACED IN THE TRIP MODE. DUE  
1 2 TO INCORRECT LABELING OF THE PANEL INDICATORS IT WAS THOUGHT THAT THE WRONG  
1 3 CHANNEL HAD BEEN PLACED IN THE TRIP MODE, SUBSEQUENTLY CHANNEL I WAS PLACED BACK  
1 4 TO NORMAL AND CHANNEL II WAS PLACED INTO TRIP. SEE ATTACHED SUPPLEMENT.

1 5 FACILITY % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
STATUS 28 0 4 6 29 NA A 31 TROUBLE SHOOTING 32  
7 8 9 10 12 13 44 45 46 80  
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
33 34 NA 35 NA 36  
7 8 9 10 11 44 45 80  
1 7 PERSONNEL EXPOSURES PERSONNEL INJURIES  
NUMBER TYPE DESCRIPTION 39 40 NA 41  
7 8 9 10 11 12 13 80  
1 8 LOSS OF OR DAMAGE TO FACILITY  
TYPE DESCRIPTION 43 NA 44  
7 8 9 10 80  
1 9 PUBLICITY  
ISSUED DESCRIPTION 45 NA 46  
7 8 9 10 80

NAME OF PREPARER S. D. DeLong

PHONE: 616-465-5901

NRC USE ONLY



22

SUPPLEMENT TO LER # 79-062/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

FURTHER INVESTIGATION REVEALED THAT CHANNEL I WAS INFACIT THE INOPERABLE CHANNEL AND IT WAS PLACED BACK IN TRIP WITH CHANNEL II RETURNED TO NORMAL.

THE NAME PLATES FOR PANEL INDICATORS WERE CORRECTED AND THE NAME PLATES FOR THE OTHER STEAM FLOW CHANNELS, IN BOTH UNITS WERE VERIFIED.

A DESIGN CHANGE HAS BEEN INITIATED WHICH WILL IMPROVE THE CONSISTENCY OF AEP LABELING FOR THE STEAM FLOW CHANNELS AND ELIMINATE ANY CONFUSION IN LABELING. THE ACTION REQUIREMENTS OF T.S. TABLES 3.3-1 AND 3.3-3 WERE FULFILLED.