

## LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M I D C C 2 | 2 0 0 - 0 0 0 0 0 - 0 0 | 3 4 1 1 1 1 | 4 | 5  
 7 8 | 9 | 14 | 15 | 25 | 26 | 30 | 57 CAT 58  
 LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE

REPORT SOURCE: 01 L 6 0 5 0 0 0 3 1 6 7 0 1 2 4 8 0 8 0 2 2 2 8 0 9

### EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | DURING SURVEILLANCE TEST, THE TURBINE DRIVEN AUX. FEED PUMP TRIP AND

03 | THROTTLE VALVE BECAME UNLATCHED FOR NO APPARENT REASON. AFTER RESETTING,

04 THE UNIT WAS TESTED AND PERFORMED PROPERLY ON TWO ATTEMPTS. LATER THE

10 SAME DAY, THE UNIT FAILED TO START AS REQUIRED ON A LOW S/G LEVEL SIGNAL

10 DURING A REACTOR TRIP CAUSED BY A LOSS OF CONDENSER VACUUM. THE UNIT WAS

11 , DECLARED INOPERABLE AGAIN PER T.S. 3.7.1.2. THE ACTION REQUIREMENTS WERE

\_\_\_\_ MET. S/G LEVEL WAS RESTORED USING THE MOTOR DRIVEN AUX. FEED PUMPS.

7	8	9	SYSTEM	CAUSE	CAUSE	COMP.	VALVE
---	---	---	--------	-------	-------	-------	-------

0 9 C H (11) E (12) B (13) T U R B I N (14) L (15) L (16)

LER/RO	EVENT YEAR	SEQUENTIAL REPORT NO.	OCCURRENCE CODE	REPORT TYPE	REVISION NO.
01	81	1	1	1	1

NUMBER	<div></div> 21 <div></div> 22	<div></div> 23	<div></div> 24 <div></div> 26	<div></div> 27	<div></div> 28 <div></div> 29	<div></div> 30	<div></div> 31	<div></div> 32
					ATTACHMENT	MURDER	PRIME COMP.	COMPONENT

TAKEN		ACTION		ON PLANT		METHOD		HOODS				SUMMITTES		TERRACES		SLOPES		TOTAL	
A	(18)	A	(19)	Z	(20)	Z	(21)	0	0	0	0	Y	(23)	N	(24)	A	(25)	T	147

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | THE CAUSE OF THE FAILURES WAS A BURNED UP RESET COIL (SCHUTTE & KOERTING,

111 | DWG. 69-XC-113, ITEM 6) ON THE TRIP AND THROTTLE VALVE LINKAGE. THE COIL

1 2 | HAD SHORTED TO ITS COVER. ALSO, THE LINKAGE (SCHUTTE & KOERTING, DWG.

69-XC-113. ITEMS 23 AND 27) WAS NOT ENGAGING PROPERLY DUE TO WEAR OF

TWO MATING SURFACES. THE RESET COIL WAS REPLACED AND THE WORN SURFACES WERE

	FACILITY	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
7 8 9		(30)	(32)

STATUS		% POWER		OTHER STATUS		DISCOVERY	DISCOVERY DESCRIPTION		
1	5	X	(28)	0	4	8	(29) DURING REACTOR TRIB	A	(31) FAILURE TO START

7	8	9	10	12	13	44	45	46
ACTIVITY		CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		
						(35)		(36)

RELEASED OF RELEASE				AMOUNT OF ACTIVITY	LOCATION OF RELEASE
1	6	7	33	N/A	N/A

[illegible]

NUMBER				TYPE	DESCRIPTION
1	7	0	0	(37) Z	(38) N/A

7	8	9	11	12	13
PERSONNEL INJURIES			DESCRIPTION		
NUMBER					
	(41)				

1	8	0	0	0	(40)	N/A																		
7	8	9	10	11	12																			8

TYPE		DESCRIPTION	(43)
71	(10)	N/A	

8003030399

7 8 9 10  
PUBLCITY (15) NRC USE ONLY

ISSUED		DESCRIPTION	(45)
6	6	N/A	

7 8 9 10 DAVID G. WIZNER 616-465-5901

NAME OF PREPARER DAVID G. WIZNER

PHONE: 616-465-5901



202

SUPPLEMENT TO LER #80-003/03L-0

SUPPLEMENT TO EVENT DESCRIPTION

PUBLIC HEALTH AND SAFETY WERE NOT JEOPARDIZED.

SUPPLEMENT TO CAUSE DESCRIPTION

SMOOTHED AND FLATTENED TO PROVIDE POSITIVE ENGAGEMENT. A NEW COIL COVER WHICH WILL PROVIDE LARGER CLEARANCE IS BEING FABRICATED. ARRANGEMENTS ARE BEING MADE FOR A MANUFACTURER SERVICE REPRESENTATIVE TO AID IN INSPECTION AND POSSIBLE REPLACEMENT OF THE LINKAGE.