

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	1	2	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5	
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE				30	57	CAT		58

CON'T

0	1	REPORT SOURCE										DOCKET NUMBER										EVENT DATE										REPORT DATE									
7	8	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80																			
		L	6	0	5	0	0	0	3	1	5	7	0	2	1	9	8	0	8	0	3	1	1	8	0	9															

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 FOUND THE SPENT FUEL PIT AREA MONITOR INDICATING ERRATICALLY, AND THE HIGH
0 3 RADIATION ALARM ON. THE AREA SURVEYS SHOWED NORMAL AREA READINGS, INDICATING
0 4 A FAILURE OF THE RMS CHANNEL. THIS CONDITION WAS NONCONSERVATIVE WITH RESPECT
0 5 TO T.S. TABLE 3.3-6 ITEM 1a.
0 6
0 7
0 8
7 8 9 80

[illegible]

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	THE FAILURE OF THE RADIATION MONITORING CHANNEL WAS DUE TO A BAD DETECTOR TUBE.
1	1	THE DETECTOR TUBE WAS REPLACED AND NORMAL CHANNEL OPERATION WAS VERIFIED. THE
1	2	CAUSE OF THE DETECTOR TUBE FAILURE WAS NORMAL END OF LIFE. THE ACTION REQUIREMENT
1	3	FOR T.S. TABLE 3.3-6 ITEM 1a WAS FULFILLED.
1	4	SEE ATTACHED SUPPLEMENT.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	5	7	29	NA	30
7	8	9	10	11	12	13	14	15	16
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		OPERATOR OBSERVATION		DISCOVERY DESCRIPTION	
1	6	Z	33	Z	34	NA	35	NA	36
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION		LOCATION OF RELEASE	
1	7	0	0	0	37	Z	38	NA	39
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION		LOSS OF OR DAMAGE TO FACILITY		NRC USE ONLY	
1	8	0	0	0	40	NA	41	NA	42
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		PUBLCITY ISSUED		NRC USE ONLY	
1	9	Z	42	NA	43	NA	44	NA	45
7	8	9	10	11	12	13	14	15	16
PUBLCITY ISSUED		DESCRIPTION		NRC USE ONLY		NRC USE ONLY		NRC USE ONLY	
2	0	N	44	NA	45	NA	46	NA	47
7	8	9	10	11	12	13	14	15	16

NAME OF PREPARER S. D. DeLong

PHONE: 616-465-5901

NRC USE ONLY

GPO 917-926

SUPPLEMENT TO LER # 80-003/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THE DETECTOR TUBE REPLACEMENT IS PART NUMBER 605519G01 MANUFACTURED
BY WESTINGHOUSE.

NO FURTHER ACTION IS PLANNED.

