

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	C	C	2	2	0	0	0	0	0	0	0	0	0	0	0	0	3	4	1	1	1	1	4			5
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER											25	26	LICENSE TYPE				30	57	CAT	58

CON'T

REPORT SOURCE 7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | WHILE PERFORMING ROUTINE PANEL INSPECTIONS, THE CONTROL ROOM OPERATOR DISCOVERED

0 3 | THE BREAKER FOR IMO-310 (EAST RHR PUMP SUCTION) OPEN. THIS IS CONTRARY TO T.S.3.5.2.

0 4 | HOWEVER, THE VALVE WAS FOUND IN ITS NORMAL SAFETY SYSTEM POSITION (OPEN). THE BREAKER

0 5 | WAS RECLOSED AND THE VALVE CYCLED TO INSURE PROPER OPERATION. THE SAFETY SYSTEM'S

0 6 | PERFORMANCE WOULD NOT HAVE BEEN AFFECTED. THE PUBLIC HEALTH AND SAFETY WAS NOT

0 7 | AFFECTED.

08		9		SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE				COMP. SUBCODE		VALVE SUBCODE						
0	8			E	B	11	X	12	Z	13	Z	Z	Z	Z	Z	14	Z	15	Z	16		
7	8			9	10		11		12		13					18	19		20			
09		17		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.										
0	9	17	LER/RO REPORT NUMBER	8	0	22	0	1	6	26	0	3	29	L	30	0	32					
7	8			21	22		23			27					31							
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER						
H	18	Z	19	Z	20	Z	21	0	0	0	22	N	23	N	24	Z	25	Z	9	9	9	26
33	34			35		36		37			40	41		42		43		44				47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | UPON INVESTIGATION, NO REASON FOR THIS BREAKER BEING OPEN COULD BE IDENTIFIED.

1 1 | OPERATORS HAVE BEEN ISSUED INSTRUCTIONS TO BE ESPECIALLY ALERT ON THEIR CONTROL

1 2 | PANEL CHECKS TO ASSURE ALL EQUIPMENT INDICATION IS CORRECT.

[illegible]

NAME OF PREPARER C. E. MURPHY

PHONE: 465-5901

