

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8905100082 DOC.DATE: 89/04/28 NOTARIZED: NO DOCKET #  
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 AUTH.NAME AUTHOR AFFILIATION  
 POSTLEWAIT,T.K. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 SMITH,W.G. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 89-006-00:on 890405,ECCS flow balance out of spec.  
 W/8 ltr.

DISTRIBUTION CODE: IE22D COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1 1	PD3-1 PD	1 1
	STANG,J	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	ACRS WYLIE	1 1	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	IRM/DCTS/DAB	1 1
	NRR/DEST/ADE 8H	1 1	NRR/DEST/ADS 7E	1 0
	NRR/DEST/CEB 8H	1 1	NRR/DEST/ESB 8D	1 1
	NRR/DEST/ICSB 7	1 1	NRR/DEST/MEB 9H	1 1
	NRR/DEST/MTB 9H	1 1	NRR/DEST/PSB 8D	1 1
	NRR/DEST/RSB 8E	1 1	NRR/DEST/SGB 8D	1 1
	NRR/DLPQ/HFB 10	1 1	NRR/DLPQ/QAB 10	1 1
	NRR/DOEA/EAB 11	1 1	NRR/DREP/RPB 10	2 2
	NRR/DRIS/SIB 9A	1 1	NUDOCS-ABSTRACT	1 1
	<del>REG FILE 02</del>	1 1	RES/DSIR/EIB	1 1
	RES/DSR/PRAB	1 1	RGN3 FILE 01	1 1
EXTERNAL:	EG&G WILLIAMS,S	4 4	FORD BLDG HOY,A	1 1
	L ST LOBBY WARD	1 1	LPDR	1 1
	NRC PDR	1 1	NSIC MAYS,G	1 1
	NSIC MURPHY,G.A	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 44 ENCL 43

R  
I  
D  
S  
/  
A  
D  
D  
S  
/  
A  
D  
D  
S

## - LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)	DOCKET NUMBER (2)	PAGE (3)
D. C. Cook Nuclear Plant, Unit 1	0   5   0   0   0   3   1   5	1   OF   0   3

TITLE (4)  
ECCS Flow Balance Out of Specification

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)															
MONTH	DAY	YEAR	YEAR		SEQUENTIAL NUMBER		REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES				DOCKET NUMBERS:									
0	4	0	5	8	9	8	9	-	0	0	6	-	0	0	0	4	2	8	8	9				
			THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR § . (Check one or more of the following) (11)																					
OPERATING MODE (9)			6																					
POWER LEVEL (10)			0 0 0																					
			<div style="display: flex; justify-content: space-between;"> <div>           20.402(b)            20.406(a)(1)(i)            20.406(a)(1)(ii)            20.406(a)(1)(iii)            20.406(a)(1)(iv)            20.406(a)(1)(v)         </div> <div> <input type="checkbox"/>     X      </div> <div>           20.406(c)            50.36(c)(1)            50.36(c)(2)            50.73(a)(2)(i)            50.73(a)(2)(e)            50.73(a)(2)(iii)         </div> <div> <input type="checkbox"/>            </div> <div>           50.73(a)(2)(iv)            50.73(a)(2)(v)            50.73(a)(2)(vi)            50.73(a)(2)(vii)(A)            50.73(a)(2)(vii)(B)            50.73(a)(2)(ix)         </div> <div> <input type="checkbox"/>            </div> <div>           73.71(b)            73.71(c)            OTHER (Specify in Abstract below and in Text NRC Form 356A)         </div> </div>																					

LICENSEE CONTACT FOR THIS LER (12)			
NAME		TELEPHONE NUMBER	
		AREA CODE	
T. K. Postlewait - Technical Engineering Superintendent		616	465-5901

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)											
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS		CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	
	I	I I I I	I I I I				I	I I I I	I I I I		
	I	I I I I	I I I I				I	I I I I	I I I I		

SUPPLEMENTAL REPORT EXPECTED (14)		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/> YES <i>if ver. complete EXPECTED SUBMISSION DATE!</i>	<input checked="" type="checkbox"/> NO				

ABSTRACT (Limit to 1400 spaces, i.e. approximately fifteen single space typewritten lines) (19)

On April 5, 1989, with Unit 1 in Mode 6 (refueling) during flow balance testing of the North Safety Injection (SI) Pump, the flow rates were found to exceed Technical Specification 4.5.2.H allowable flow. The combined flow to the reactor coolant loops was 644 GPM (gallons per minute), which exceeded the Technical Specification limit of 640 GPM.

No cause, other than normal system fluctuations combined with standard Instrument/Measurement error could be identified. The flow control values were adjusted to meet the required flows.

8905100082 390423  
PDR ADOCK 05000315  
S PDC

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
D. C. Cook Nuclear Plant, Unit-1	0 5 0 0 0 3 1 5	8 9	0 0 6	0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 368A's) (17)

Description of Event:

On April 5, 1989, with Unit 1 in Mode 6 (refueling) during flow balance testing of the North Safety Injection (SI) Pump, the flow rates were found to exceed Technical Specification 4.5.2.H requirement. This Technical Specification limits the combined SI System (EIIS:BQ) flow to the loops be less than 640 gpm (gallons per minute). The as found flows for the North Safety Injection Pump were found to be 639.1 gpm. Following recalibration of the test instrumentation, a recalculation of the flow data was performed to account for instrument inaccuracies. The actual flows were calculated to be 322.3 gpm to loops 1 and 4 and 321.7 gpm to loops 2 and 3, for a total flow to the loops of 644 gpm.

Cause of Event

No cause, other than normal system fluctuations combined with standard instrument/measurement error could be identified. The Technical Specification limits are considered to be very tight and the system fluctuations due to such factors as internal hydraulics and instrument tolerances are felt to be responsible for the small deviations from one surveillance period to another.

Analysis of Event

The position of the throttle valves (EIIS:FCV) would have resulted in reduced safety injection flow had a break occurred in the loop with the highest flow. This would have increased the peak clad temperature for a small-break loss-of-coolant accident (LOCA). (The large-break LOCA analysis is only slightly affected because SI flow is a small fraction of the total).

It is judged that the effect on the peak clad temperature for a small-break LOCA would have been minimal, and the peak clad temperature limit of 2200 degrees Fahrenheit, specified in 10 CFR 50.46 would not have been exceeded. This judgement is based on the fact that the deviation from the Technical Specification value of 640 gpm for four loops was exceeded by 0.6 percent and there is a large margin between the peak clad temperature calculated for a small-break LOCA, approximately 1427 degrees Fahrenheit, and the 10 CFR 50.46, limit of 2200 degrees Fahrenheit.

A run out condition of the pumps would not have been expected to occur as a result of the flow imbalance because the total measured flow was 0.6 percent above the maximum Technical Specification value for the safety injection flow.

Based on the above, it is believed that there would have been no adverse impact on the health and safety of the public.

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

U.S. NUCLEAR REGULATORY COMMISSION

APPROVED OMB NO. 3150-0104

EXPIRES: 8/31/88

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (8)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
D. C. Cook Nuclear Plant, Unit-1	0 5 0 0 0 3 1 5	8 9	- 0 0 6	- 0 0	0 3	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Corrective Actions

The flow control values were adjusted so that the North safety injection pump flows to the reactor coolant loops are within the requirements of Technical Specification 5.4.2.H. As-left flows were 310.8 gpm to loops 1 and 4 and 312.6 gpm to loops 2 and 3; for a total flow to the RC loops of 623.4 gpm.

The Technical Specification Limit concern will be integrated into our Technical Specification upgrade program.

Previous Similar Events

050-316/86-12

Indiana Michigan  
Power Company  
Cool Nuclear Plant  
PO Box 458  
Bridgman, MI 49106  
616 465 5901



April 28, 1989

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Operating License DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73  
entitled Licensee Event Reporting System, the following  
report is being submitted:

89-006-00

Sincerely,

W. G. Smith, Jr.  
Plant Manager

WGS:clw

Attachment

cc: D. H. Williams, Jr.  
A. B. Davis, Region III  
M. P. Alexich  
P. A. Barrett  
J. E. Borggren  
R. F. Kroeger  
NRC Resident Inspector  
J. F. Stang, NRC  
R. C. Callen  
G. Charnoff, Esq.  
Dottie Sherman, ANI Library  
D. Hahn  
INPO  
PNSRC  
A. A. Blind  
S. J. Brewer/B. P. Lauzau

IEP2  
11

