

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9005220273 DOC. DATE: 90/05/10 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH. NAME AUTHOR AFFILIATION
 SAMPSON, J.R. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 BLIND, A.A. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 90-003-00: on 900410, pyralarm fire detection zone
 inoperable w/o required roving fire watch.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 5
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1 1	PD3-1 PD	1 1
	GIITTER, J.	1 1		
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	DEDRO	1 1	NRR/DET/ECMB 9H	1 1
	NRR/DET/EMEB9H3	1 1	NRR/DLPQ/LHFB11	1 1
	NRR/DLPQ/LPEB10	1 1	NRR/DOEA/OEAB11	1 1
	NRR/DREP/PRPB11	2 2	NRR/DST/SELB 8D	1 1
	NRR/DST/SICB 7E	1 1	NRR/DST/SPLB8D1	1 1
	NRR/DST/SRXB 8E	1 1	REG FILE 02	1 1
	RES/DSIR/EIB	1 1	RGN3 FILE 01	1 1
EXTERNAL:	EG&G STUART, V.A	4 4	L ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC MAYS, G	1 1	NSIC MURPHY, G.A	1 1
	NUDOCS FULL TXT	1 1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 34 ENCL 34

Indiana Michigan
Power Company
Cook Nuclear Plant
P.O. Box 458
Bridgman, MI 49106
616 465 5901



May 7, 1990

United States Nuclear Regulatory Commission
Document Control Desk
Rockville, Maryland 20852


Operating Licenses DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by 10 CFR 50.73
entitled Licensee Event Reporting System, the following
report is being submitted:

90-003-00

Sincerely,


A.A. Blind
Plant Manager

AAB:clw

Attachment

cc: D.H. Williams, Jr.
A.B. Davis, Region III
M.P. Alexich
P.A. Barrett
J.E. Borggren
R.F. Kroeger
NRC Resident Inspector
J.G. Gitter, NRC
J.G. Keppler
R.C. Callen
G. Charnoff, Esq.
Dottie Sherman, ANI Library
D. Hahn
INPO
S.J. Brewer/B.P. Lauzau

9005220273 900510
PDR ADOCK 05000315
S PDC

IE22

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

D. C. Cook Nuclear Plant, Unit 1

DOCKET NUMBER (2)

0 5 0 0 0 3 1 5

PAGE (3)

1 OF 0 4

TITLE (4)

Pyralarm Fire Detection Zone Inoperable Without
Required Roving Fire Watch Due to Personnel Error

EVENT DATE (5)

LER NUMBER (6)

REPORT DATE (7)

OTHER FACILITIES INVOLVED (8)

MONTH

DAY

YEAR

YEAR

SEQUENTIAL

NUMBER

REVISION

NUMBER

MONTH

DAY

YEAR

FACILITY NAMES

DOCKET NUMBER(S)

0 4

1 0

9 0

9 0

0 0

0 3

0 0

0 0

5 1

0 9

0 0

0 5 0 0 0 0

0 5 0 0 0 0

OPERATING
MODE (9)

1

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)

20.402(b)

20.405(c)

50.73(a)(2)(iv)

73.71(b)

20.405(a)(1)(i)

50.36(c)(1)

50.73(a)(2)(v)

73.71(c)

20.405(a)(1)(ii)

50.36(c)(2)

50.73(a)(2)(vi)

OTHER (Specify in Abstract
below and in Text, NRC Form
366A)

20.405(a)(1)(iii)

X

50.73(a)(2)(i)

50.73(a)(2)(viii)(A)

20.405(a)(1)(iv)

50.73(a)(2)(ii)

50.73(a)(2)(viii)(B)

20.405(a)(1)(v)

50.73(a)(2)(iii)

50.73(a)(2)(x)

LICENSEE CONTACT FOR THIS LER (12)

NAME

J. R. Sampson, Operations Department Superintendent

TELEPHONE NUMBER

AREA CODE

6 1 6 4 6 5 1 - 5 9 0 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC

SUPPLEMENTAL REPORT EXPECTED (14)

EXPECTED
SUBMISSION
DATE (15)

MONTH

DAY

YEAR

YES (If yes, complete EXPECTED SUBMISSION DATE)

X NO

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On 04-10-90 at about 1310, a pyralarm fire detection zone was rendered inoperable when the detection control panel was permeated by steam and water from a steam generator blowdown system safety valve. The Unit Supervisor failed to declare the zone inoperable and post a roving fire watch. At about 1645, the error was noted. The zone was declared inoperable and a roving fire watch was posted to satisfy the Technical Specification Action Statement. The zone was inoperable without the required roving fire watch for 3 hours 35 minutes.

This event was reviewed with the involved personnel and an Operations Standing Order was written to provide guidelines for the posting of fire watches.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

YEAR SEQUENTIAL NUMBER REVISION NUMBER

D. C. Cook Nuclear Plant, Unit 1

0 5 0 0 0 3 1 5 9 0 — 0 0 3 — 0 0 0 2 OF 0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Conditions Prior to Occurrence

Unit 1 (U-1) in Mode 1 operating at 100%.

Unit 2 (U-2) in Mode 2 operating at 100%.

Description of Event

On 04-10-90 at about 1310, the pyralarm fire detection (EIIS/IC-DET) zone for the Auxiliary Building East Valve Enclosure Non-Essential Service Water Area (EFR ZN 28) was rendered inoperable when the Fire Detection Panel (EIIS/IC-PL) was permeated by steam and water from a steam generator blowdown system safety valve (EIIC-WI/RV). With EFR ZN 28 inoperable, the Unit Supervisor failed to post a roving fire watch patrol to tour the inoperable fire detection zone per Technical Specification (TS) 3.3.3.7 (Fire Detection Instrumentation). The following is a review of the events associated with this finding.

On 04-10-90 at about 1222, the U-1 Steam Generator Blowdown System was placed on the Normal Blowdown Flash Tank (EIIC-WI/TK) per 1-OHP 4021.025.001 (Operation of Steam Generator Blowdown System). This blowdown lineup required 1-DRV-350 (Steam Generator Blowdown Tanks Drain Valve) control switch (EIIC-WI/HC) to be placed in auto.

At about 1300, U-1 Annunciator Pyralarm Abnormal for Fire Alarm (EIIC-IB/ALM) for EFR ZN 1 (573' Elevation Auxiliary Building), EFR ZN 28 and EFR ZN 4 (633' Elevation Auxiliary Building) came in. An operator was dispatched to each Auxiliary Building zone area to investigate. The operator touring EFR ZN 4 area noted that the Steam Generator Blowdown Tank Safety was lifting. Following a report to the Control Room, the Control Room closed the Blowdown Isolation Valves (EIIC-WI/ISV). It was subsequently found that 1-DRV-350 was in the closed position due to its control switch not being fully in the automatic position.

The 1-DRV-350 control switch was placed in auto and the U-1 Steam Generator Blowdown System was restored to normal.

Within about 10 minutes of receiving the three fire detection zone alarms, EFR ZN 1 and EFR ZN 4 cleared. The Unit Supervisor (US), believing that the zone alarms were caused by steam, felt that the EFR ZN 28 would also clear within a short time. The US decided to observe the EFR ZN 28 alarm for a short time before declaring the zone inoperable. The US, however, became involved with other items and forgot about the need to post a fire watch if the alarm did not promptly clear.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 500 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

D. C. Cook Nuclear Plant, Unit 1

0 5 0 0 0 3 1 5

YEAR

SEQUENTIAL
NUMBERREVISION
NUMBER

9 0

—

0 0 3

—

0 0

0 3

OF

0 4

TEXT (If more space is required, use additional NRC Form 366A's) (17)

At about 1420, the involved US was relieved. The Steam Generator Blowdown event was discussed during the turnover. As the second US prepared to turnover to the next shift, he noted that EFR ZN 28 had not been declared inoperable. The US declared EFR ZN 28 inoperable per TS 3.3.3.7 and notified the fire watch to patrol the area protected by EFR ZN 28.

Cause Of Event

The cause of this event was personnel error. The involved US failed to declare the EFR ZN 28 fire detection zone inoperable and post a roving fire watch per TS 3.3.3.8.

Contributing to this event was a mind set developed by the US set following the clearing of EFR ZN 1 and EFR ZN 4 alarm within about 10 minutes. It was believed that the EFR ZN 28 alarm would also clear within a period of time which would satisfy the TS 3.3.3.7 action statement.

Analysis of Event

The failure to assign a fire watch patrol within one hour to tour the inoperable fire detection area was a violation of TS 3.3.3.7 and therefore, reportable under 10 CFR 50.73(a)(2)(i)(b).

The EFR ZN 28 pyralarm detection system was inoperable from about 1310 to 1645, 3 hours 35 minutes, without a roving fire watch assigned to patrol the area.

Following a review of this event, the analysis of this event concludes that in the unlikely event of a fire, personnel would have been promptly alerted and would have been able to control and extinguish the fire without significant spreading of the fire or equipment damage. This conclusion is based on the following.

Although a roving fire watch was not assigned specifically to tour the area protected by EFR ZN 28 fire detection, a trained fire watch was assigned to monitor two non-Technical Specification fire doors located within the detection zone each 30 minutes. The location of the two doors required the roving fire watch to pass through a major part of the area protected by EFR ZN 28. Had a fire occurred within a portion of the EFR ZN 28 being toured by the fire watch, the fire would have been noted by the roving fire watch and corrective action would have been taken. Had a fire occurred within

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) D. C. Cook Nuclear Plant, Unit 1	DOCKET NUMBER (2) 0 5 0 0 0 3 1 5	LER NUMBER (6)			PAGE (3)		
		YEAR 9 0	SEQUENTIAL NUMBER 0 0 3	REVISION NUMBER 0 0			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

the portion of EFR ZN 28 not being patrolled, smoke would have passed through open deck grating and stairs to alert the fire watch touring the area. Following the observance of a fire by smoke and/or smell of smoke, corrective actions would have been taken.

Based on this analysis, this event is not considered to have created a significant safety concern, nor did it create a significant hazard to the health and safety of the general public.

Corrective Action

1. When the US recognized that EFR ZN 28 had not been declared inoperable and that a roving fire watch had not been posted, EFR ZN 28 was declared inoperable and a roving fire watch was posted.
2. This event was discussed with the involved personnel by their Shift Supervisor. The personnel are fully aware of the TS 3.3.3.7 requirements for inoperable fire detection instrumentation.
3. The involved US was counselled by his Shift Supervisor. The US is fully aware of his responsibility to promptly declare TS equipment inoperable and to promptly take action to satisfy the applicable TS action statement.
4. An Operations Standing Order for the posting of continuous and roving fire watches was written to provide a guidance for posting continuous and roving fire watches.
5. A training memo was sent to Operations personnel to review the Operations Standing Order.
6. A job order was written to inspect and repair the detection control panel.

Previous Similar Events

LER 89-015
LER 90-001

11
12
13