

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9101280157 DOC.DATE: 91/01/21 NOTARIZED: NO DOCKET #
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH.NAME AUTHOR AFFILIATION
 BIELMAN,T.P. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 BLIND,A.A. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 90-016-00:on 901221,two of three pressurizer safety
 valves sent to test lab required by Tech Spec 4.4.3 found w/
 lift settings outside criteria.Cause being investigated.W/
 910121 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD3-1 LA	1 1	PD3-1 PD	1 1
	COLBURN,T.	1 1		
INTERNAL:	ACNW	2 2	AEOD/DOA	1 1
	AEOD/DSP/TPAB	1 1	AEOD/ROAB/DSP	2 2
	NRR/DET/ECMB 9H	1 1	NRR/DET/EMEB 7E	1 1
	NRR/DLPQ/LHFB11	1 1	NRR/DLPQ/LPEB10	1 1
	NRR/DOEA/OEAB	1 1	NRR/DREP/PRPB11	2 2
	NRR/DST/SELB 8D	1 1	NRR/DST/SICB 7E	1 1
	NRR/DST/SPLB8D1	1 1	NRR/DST/SRXB 8E	1 1
	REG FILE 02	1 1	RES/DSIR/EIB	1 1
	RGN3 FILE 01	1 1		
EXTERNAL:	EG&G BRYCE,J.H	3 3	L ST LOBBY WARD	1 1
	NRC PDR	1 1	NSIC MAYS,G	1 1
	NSIC MURPHY,G.A	1 1	NUDOCS FULL TXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 31

A04

Indiana Michigan
Power Company
Cook Nuclear Plant
One Cook Place
Bridgman, MI 49106
616 465 5901



January 21, 1991

United States Nuclear Regulatory Commission
Document Control Desk
Rockville, Maryland 20852

Operating Licenses DPR-58
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by
10 CFR 50.73 entitled Licensee Event Reporting System,
the following report is being submitted:

90-016-00

Sincerely,

A handwritten signature in cursive script, appearing to read 'A.A. Blind'.

A.A. Blind
Plant Manager

AAB:sb

Attachment

c: D.H. Williams, Jr.
A.B. Davis, Region III
M.P. Alexich
P.A. Barrett
J.E. Borggren
R.F. Kroeger
B. Walters - Ft. Wayne
NRC Resident Inspector
T. Colburn - NRC
J.G. Keppler
M.R. Padgett
G. Charnoff, Esq.
Dottie Sherman, ANI Library
D. Hahn
INPO
S.J. Brewer/B.P. Lauzau
B.A. Svensson

9101280157 910121
PDR ADOCK 05000315
S PDR

28:11

TS22
11

LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

D. C. Cook Nuclear Plant - Unit 1

DOCKET NUMBER (2)

0 5 0 0 0 3 1 5 1 OF 0 3

PAGE (3)

TITLE (4) Failure of two pressurizer safety valves to meet Technical Specification required surveillance test criteria.

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)																	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)																
1	2	2	1	9	0	9	0	0	0	1	6	0	0	1	2	1	9	1		0	5	0	0	0		
OPERATING MODE (9)		5	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)																							
POWER LEVEL (10)		0	20.402(b)			20.405(c)			50.73(a)(2)(iv)			73.71(b)														
			20.405(a)(1)(i)			50.36(c)(1)			50.73(a)(2)(v)			73.71(c)														
			20.405(a)(1)(ii)			50.36(c)(2)			50.73(a)(2)(vi)			OTHER (Specify in Abstract below and in Text, NRC Form 366A)														
			20.405(a)(1)(iii)			X 50.73(a)(2)(i)			50.73(a)(2)(viii)(A)																	
			20.405(a)(1)(iv)			50.73(a)(2)(ii)			50.73(a)(2)(vi)(B)																	
			20.405(a)(1)(v)			50.73(a)(2)(iii)			50.73(a)(2)(ix)																	

LICENSEE CONTACT FOR THIS LER (12)

NAME

T. P. Bielman - Maintenance Superintendent

TELEPHONE NUMBER

AREA CODE

6 1 6 4 6 5 1 5 9 1 0 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
X	A/B	I R V C	7 1 1 0	Y					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)		NO		EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
X					0	6	0 1 1 9 1

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On December 21, 1990 it was determined that two of three pressurizer safety valves sent to a test laboratory off site for testing required by Technical Specification 4.4.3 had been found with lift settings outside of the acceptance criteria. Acceptable settings are between 2461 psig and 2509 psig. Valve 1-SV-45B lifted at 2451 psig and valve 1-SV-45C at 2548 psig.

An evaluation of the test data revealed that the valve with a lift setting of 10 psi below acceptance criteria would have had no impact on the operability of affected components, as it would have lifted prematurely. The valve with a lift setting exceeding the acceptable range did so by 39 psi. Calculations performed indicate that if the reactor coolant system pressure had reached 2548 psig, no damage would have been incurred by pipe, fittings, valves and/or the pressurizer. The UFSAR was reviewed for impact of the as-found setpoints. The high setpoint would have been offset by the additional capacity of power operated relief valves and full safety valve capacity is not required. Also reviewed were criteria associated with Departure from Nucleate Boiling. No adverse consequences applied to safety analyses.

An investigation into the cause is being conducted by the valve manufacturer.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
D. C. Cook Nuclear Plant - Unit 1	0 5 0 0 0 3 1 5	9 0	0 1 6	0 0	0 2	OF	0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Conditions Prior to Occurrence

Unit One - Mode 5 (Cold Shutdown).

Unit Two - Mode 1 (Power Operation).

Description of Event

On December 21, 1990 it was determined that two of the three pressurizer safety valves (EIIS/AB-RV) sent off site to a test laboratory for testing required by Technical Specification 4.4.3 had been found with lift settings outside acceptance criteria. The valves are required by Technical Specification 4.4.3 to lift between 2461 and 2509 psig. Replacement valves tested by the same laboratory have been installed in place of the three valves removed for testing. Valve 1-SV-45B lifted at 2451 psig and 1-SV-45C lifted at 2548 psig. The third valve, 1-SV-45A, was acceptable. Technical Specification 4.4.3 requires that each pressurizer code safety valve be demonstrated operable per Section XI of the ASME Boiler and Pressure Vessel Code, 1974 Edition.

Cause of Event

An investigation into the cause for the change in lift setting from acceptable at installation to out-of-range when tested is being conducted by the valve manufacturer. Upon receipt of their report, we will submit an updated LER. The expected submittal date for the updated LER is June 1, 1991.

Analysis of Event

Test data was assessed following receipt. The valve which was found with a lift setting of 10 psi below acceptance criteria would have had no impact on the operability of affected components. It would have lifted prematurely and the plant maintained in a safe condition. The valve with a lift setting which exceeded acceptance criteria did so by 39 psi. Calculations subsequently performed indicate that, had the reactor coolant system reached the setpoint lift pressure of 1-SV-45C, no damage would have been incurred by the pipe, fittings, valves and/or the pressurizer.

The UFSAR Chapter 14 safety analyses applicable to Unit 1 were reviewed for the impact of "as found" safety valve opening setpoints of 2451 psig for 1-SV-45B and 2548 psig for 1-SV-45C.

LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)

DOCKET NUMBER (2)

LER NUMBER (6)

PAGE (3)

D. C. Cook Nuclear Plant - Unit 1

0 5 0 0 0 3 1 5 9 0 - 0 1 6 - 0 0 0 3 OF 0 3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

For over-pressurization cases, the additional capacity of the PORVs would offset the higher final setpoint, and the full safety valve capacity is not required for any case. Therefore, the increased setpoint of the higher valve is of no concern.

For Departure from Nucleate Boiling (DNB) cases, the lowered setpoint would have been reached for only one case, the loss of external load/turbine trip case, minimum feedback, with pressure control. The accident analysis minimum DNBR for this case is approximately 1.79, and the acceptable value is 1.45, so the slight pressure reduction is easily offset by the existing margin.

In conclusion, the specified "as found" pressurizer safety valve setpoint would have no consequence on the applicable safety analyses. The failures of the valves to meet the surveillance test criteria are being reported under 10CFR50.73 (a)(2)(i)(B), "Any operation or condition prohibited by the plant's Technical Specifications."

Corrective Action

Considerations concerning corrective/preventive action will be addressed following completion of the valve manufacturer's cause analysis.

Failed Component Identification

Pressurizer Safety Valve
Plant Designation: 1-SV-45B and 1-SV-45C
Manufacturer: Crosby Valve Company
Model: HB-86-BP
EIIIS Code: AB-RV

Previous Similar Events

LER 89-004

