

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9102120111 DOC.DATE: 91/02/04 NOTARIZED: NO DOCKET #  
 FACIL:50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 AUTH.NAME AUTHOR AFFILIATION  
 SAMPSON,J.R. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 BLIND,A.A. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele  
 RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: LER 91-001-00:on 910112,discovered that fire hose station,  
 use as backup compensatory backup fire suppression  
 capability,isolated by red tag clearance,placed on 901230.  
 Fire hose rerouted to transformer room.W/910204 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 5  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

### NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME		LTTR	ENCL
	PD3-1 LA		1	1		PD3-1 PD		1	1
	COLBURN,T.		1	1					
INTERNAL:	ACNW		2	2		AEOD/DOA		1	1
	AEOD/DSP/TPAB		1	1		AEOD/ROAB/DSP		2	2
	NRR/DET/ECMB 9H		1	1		NRR/DET/EMEB 7E		1	1
	NRR/DLPQ/LHFB11		1	1		NRR/DLPQ/LPEB10		1	1
	NRR/DOEA/OEAB		1	1		NRR/DREP/PRPB11		2	2
	NRR/DST/SELB 8D		1	1		NRR/DST/SICB 7E		1	1
	NRR/DST/SPLB8D1		1	1		NRR/DST/SRXB 8E		1	1
	REG FILE 02		1	1		RES/DSIR/EIB		1	1
	RGN3 FILE 01		1	1					
EXTERNAL:	EG&G BRYCE,J.H		3	3		L ST LOBBY WARD		1	1
	NRC PDR		1	1		NSIC MAYS,G		1	1
	NSIC MURPHY,G.A		1	1		NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED  
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 31 ENCL 31

mb A04



Indiana Michigan  
Power Company  
Cook Nuclear Plant  
One Cook Place  
Bridgman, MI 49106  
616 465 5901



February 4, 1991

United States Nuclear Regulatory Commission  
Document Control Desk  
Rockville, Maryland 20852


Operating Licenses DPR-58  
Docket No. 50-315

Document Control Manager:

In accordance with the criteria established by  
10 CFR 50.73 entitled Licensee Event Reporting System,  
the following report is being submitted:

91-001-00

Sincerely,

  
for A.A. Blind  
Plant Manager

AAB:sb

Attachment

c: D.H. Williams, Jr.  
A.B. Davis, Region III  
M.P. Alexich  
P.A. Barrett  
J.E. Borggren  
R.F. Kroeger  
B. Walters - Ft. Wayne  
NRC Resident Inspector  
T. Colburn - NRC  
J.G. Keppler  
M.R. Padgett  
G. Charnoff, Esq.  
Dottie Sherman, ANI Library  
D. Hahn  
INPO  
S.J. Brewer/B.P. Lauzau  
B.A. Svensson

9102120111 910204  
PDR ADOCK 05000315  
S PDR

LE22  
11

## LICENSEE EVENT REPORT (LER)

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1) D. C. Cook Nuclear Plant - Unit 1 DOCKET NUMBER (2) 0 5 0 0 0 3 1 1 5 PAGE (3) 1 OF 0 4

TITLE (4) TS 3.7.9.5 Required Fire Hose Station Inoperable without Required Backup Fire Suppression Hose Due to Inadequate Administrative Controls

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)							
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)						
0	1	1	2	9	1	9	1	0	0	1	0	0	0	0	0	0
0	1	1	2	9	1	9	1	0	0	0	2	0	4	9	1	0

OPERATING MODE (9)	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)
3	20.402(b) <input type="checkbox"/> 20.405(c) <input type="checkbox"/> 50.73(a)(2)(iv) <input type="checkbox"/> 73.71(b) <input type="checkbox"/>
POWER LEVEL (10) <u>0 0 0</u>	20.405(a)(1)(i) <input type="checkbox"/> 50.73(a)(2)(v) <input type="checkbox"/> 73.71(c) <input type="checkbox"/>
	20.405(a)(1)(ii) <input type="checkbox"/> 50.73(a)(2)(vi) <input type="checkbox"/>
	20.405(a)(1)(iii) <input type="checkbox"/> 50.73(a)(2)(vii) <input type="checkbox"/>
	20.405(a)(1)(iv) <input type="checkbox"/> 50.73(a)(2)(viii)(A) <input type="checkbox"/>
	20.405(a)(1)(v) <input type="checkbox"/> 50.73(a)(2)(viii)(B) <input type="checkbox"/>
	50.73(a)(2)(ix) <input type="checkbox"/>

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
J. R. Sampson, Operations Department Superintendent	AREA CODE <u>6 1 1 6</u> <u>4 1 6 1 5 1 - 5 1 9 1 0 1 1</u>

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPDs

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	NO	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input type="checkbox"/>	<input checked="" type="checkbox"/>				

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On January 12, 1991, at 2115, it was identified that a fire hose station (FHC) being used as compensatory backup fire suppression was isolated by a red tag clearance. On December 30, 1990, the FHC for the pressurizer (PZR) heater (HTR) transformer (XFMR) room was isolated by a clearance and a backup fire suppression hose was routed from FHC-30. On January 12, a request to remove an additional section of the fire protection water system from service, which included FHC-30, was approved. The red tag clearance for this additional work was placed at about 0400 on January 12. It was identified at about 2115 on January 12 that FHC-30 had been isolated while it was serving as a backup fire suppression. A second fire hose was routed from an operable FHC to the PZR HTR XFMR room at about 2130.

This event was caused by inadequate administrative controls to assure fire impairment reviews were based on the current status of the fire protection system. A memo was issued on January 18 to address the lessons learned from this event. The administrative controls will be revised by February 15, 1991, to add assurance that fire impairment reviews will be based on the current status of the fire protection system.



LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  D. C. Cook Nuclear Plant - Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 3 1 5	LER NUMBER (6)			PAGE (3)		
		YEAR 9 1	SEQUENTIAL NUMBER 0 0 1	REVISION NUMBER 0 0			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Conditions Prior to Occurrence

Unit One in Mode Three (Hot Standby)

Unit Two in Mode One (Power Operation) at 100% Power

Description of Event

On January 12, 1991, at 2115, it was identified that a fire hose station (FHC) (EIIS/KP-HYD) being used as compensatory backup fire suppression capability was isolated by a red tag clearance.

A red tag clearance was placed on a portion of the fire protection water system (EIIS/KP) on December 30, 1990, which isolated multiple FHCs and deluge valves (EIIS/KP-XCV). The appropriate Technical Specification (TS) compensatory actions were initiated at that time and included routing a backup fire hose from FHC-30 to the pressurizer heater transformer room as required by TS 3.7.9.5.

On January 11, 1991, a Fire Protection Impairment Request (Operations Standing Order [OSO] 071, Attachment 1) to isolate an additional section of the fire protection water system for repair of a transformer (EIIS/EL-XFMR) deluge valve was approved by the Plant fire protection coordinator. A red tag clearance was written by a licensed senior reactor operator (SRO) to isolate the deluge valve. The boundary for this work involved closing valves which resulted in also isolating the supply to FHC-30. A second SRO reviewed and approved the clearance.

The clearance for the transformer deluge valve repair was placed on January 12, 1991, at 0403, by a licensed reactor operator (RO) and included placing an out-of-service tag on FHC-30. The placement of this clearance was verified by a second RO at 0512.

At 2115 on January 12, 1991, the SRO who reviewed and approved the transformer deluge valve clearance identified that FHC-30 had been isolated while being used as TS 3.7.9.5 required backup fire suppression. This problem was identified when the SRO observed the hose laid out from FHC-30 to the pressurizer heater transformer room during a walkdown of the clearance boundaries in an attempt to locate the source of isolation point leakby.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 60.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)  D. C. Cook Nuclear Plant - Unit 1	DOCKET NUMBER (2)  0 5 0 0 0 3 1 5	LER NUMBER (6)			PAGE (3)	
		YEAR 9 1	SEQUENTIAL NUMBER 0 0 1	REVISION NUMBER 0 0	0 3 OF 0 4	

TEXT (If more space is required, use additional NRC Form 366A's) (17)

Cause of Event

The cause of this event was that the administrative controls did not assure that the fire impairment reviews were based on the current status of the fire protection system. The fire protection review for the work which required FHC-30 to be used as backup fire suppression was completed by an SRO at a time when the fire protection coordinator was not on site. The fire protection coordinator identified that FHC-30 would be isolated for the transformer deluge valve, but he was not cognizant that FHC-30 was being used as backup fire suppression.

Contributing to this event was the failure of the SROs writing and approving the transformer deluge valve clearance to verify that FHC-30 was not being used. Also contributing to this event was the failure of the ROs to recognize that FHC-30 was being used as backup fire suppression when they observed the hose laid out while placing and verifying the out-of-service tag for the clearance.

Analysis of Event

This event is considered reportable pursuant to 10CFR50.73(a)(2)(i)(B) as operation prohibited by the Plant's Technical Specifications. TS 3.7.9.5 requires the routing of an equivalent capacity fire hose within one hour when required hose station is inoperable. This action was initially satisfied, but was subsequently negated when the backup fire hose was isolated. The pressurizer heater transformer room was without the TS 3.7.9.5 required fire protection for a total of about 17 1/2 hours from about 0400 on January 12, 1991, until about 2130 on January 12, 1991, when a second backup fire hose was routed from FHC-28.

The pressurizer heater transformer room fire detection system was operable at the time of this event. Since the fire detection was operable, a fire in the room would have been promptly identified and the Plant Fire Brigade could have promptly responded to the event. Upon discovery of the out-of-service tag at FHC-30, the Plant Fire Brigade would have known that an alternate FHC would be needed. The Plant Fire Brigade could have routed a hose from FHC-28 located about 130 feet from the pressurizer heater transformer room. It is estimated that the hose from FHC-28 could have been routed within five minutes or less of identifying that FHC-30 was out of service.

LICENSEE EVENT REPORT (LER)  
TEXT CONTINUATION

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)	
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER		
D. C. Cook Nuclear Plant - Unit 1	05000315	91	001	00	04	OF 04

TEXT (If more space is required, use additional NRC Form 366A's) (17)

## (Analysis of Event Continued)

Since a fire in the pressurizer heater transformer room would have been promptly identified, the combustible loading in the room is low, and backup suppression could have been aligned within five minutes of arrival at the fire scene, it is concluded that this event did not create a significant safety concern, nor did it create a significant hazard to the health and safety of the general public.

Corrective Action

Immediate corrective action taken when the event was identified involved routing a backup fire hose from FHC-28 to the pressurizer heater transformer room at about 2130 on January 12, 1991.

A memo was issued to Operations Department personnel on January 18, 1991, to address the lessons learned from this event. The administrative controls (OSO.071) will be revised by February 15, 1991, to add assurance that fire impairment reviews will be based on the current status of the fire protection system.

Failed Component Identification

None

Previous Similar Events

None



